



BOILER SAFETY BUREAU  
1101 MAIL SERVICE CENTER  
RALEIGH, NC 27699-1101  
PHONE (919) 807-2760  
FAX (919) 807-2762

Information Bulletin No.: IB-05.003

Previous No.: T-00.1

Issue Date: September 29, 2005

## POLICY NOTIFICATION

### Representative Mill Test Reports

*This is a reissue of Circular Letter T-00.1 that was issued on April 3, 2000.*

Some material organization has been found to be issuing “representative” material test reports instead of specific ones. This is not acceptable for the construction, repair or modification of pressure equipment destined for use in North Carolina. A material test report must be directly traceable to pressure material if a material test report is required by the code of construction.

A “representative” material test report is also deemed unacceptable as a “certificate of compliance”. Please make your client aware of this and share this information with them.

JACK M. GIVEN, JR.  
CHIEF INSPECTOR