

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Location: (DPS-C) Columbus CI - 4355 **Location #:** 1778917 **Violations:** 5
1255 Prison Camp Rd, , Whiteville, NC 28472-4887, Phone: 910-642-3285
Contact: NC Dept Of Public Safety - 13101, Phone: 919-716-3422

Object: NC361313 - Boiler - Rbi - 2005 - Elm Dorm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 11/24/2020 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 25-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 395. Valve leaking.
CONDITION: 395. Operation of PRDs NCAC 13-13.0405: Valve leaking: Pressure relief device leaking.
REQUIREMENT: 395. Replace with a ASME/NB certified pressure relief device with a set pressure of not greater than 160 psig, with a relief capacity of not less than 638 KBH, and with a testing lever.

Object: NC362565 - Boiler - Rbi - 2006 - Fier Dorm - Active **Violations This Object:** 2

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 11/24/2020 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 07-Undefined Controls Violations
SUBCATEGORY 112. Undefined Controls Violations.
CONDITION: 112. Undefined Controls Violations. Flow switch leaking.
REQUIREMENT: 112. Undefined Controls Violations: Replace flow switch. Test to verify proper operation.

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 11/24/2020 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 25-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 395. Valve leaking.
CONDITION: 395. Operation of PRDs NCAC 13-13.0405: Valve leaking: Pressure relief device leaking
REQUIREMENT: 395. Replace with a ASME/NB certified pressure relief device with a set pressure of not greater than 160 psig, with a relief capacity of not less than 638 KBH, and with a testing lever installed.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC382455 - Boiler - Cleveland Range - 2010 - Food Service - Active

Violations This Object: 2

COMPANY:	Hartford Steam Boiler		
INSPECTOR:	Rudolph, Jay		
OPENED:	11/24/2020	ENTERED BY:	Judd, Janie
CLOSED:		CLOSED BY:	
TYPE:	Certificate Blocking		
CATEGORY:	03-Water Gauge Glass NCAC 13-13.0408		
SUBCATEGORY	058. Leaking.		
CONDITION:	058. Water Gauge Glass NCAC 13-13.0408: Leaking.		
REQUIREMENT:	058. Repair or replace the leaking gauge and test to ensure proper operation.		
COMPANY:	Hartford Steam Boiler		
INSPECTOR:	Rudolph, Jay		
OPENED:	11/24/2020	ENTERED BY:	Judd, Janie
CLOSED:		CLOSED BY:	
TYPE:	Certificate Blocking		
CATEGORY:	25-Operation of PRDs NCAC 13-13.0405		
SUBCATEGORY	395. Valve leaking.		
CONDITION:	395. Operation of PRDs NCAC 13-13.0405: Valve leaking: Pressure relief device leaking.		
REQUIREMENT:	395. Replace with a ASME/NB certified pressure relief device with a set pressure of not greater than 15 psig, with a relief capacity of not less than 266 PPH, and with a testing lever installed.		

Location: (DPS-C) Enterprise Laundry Chase - 8255

Location #: 1786752

Violations: 1

201 Stevens Mill Rd, , Goldsboro, NC 27530-1056, Phone: 919-581-1037

Contact: NC Dept Of Public Safety - 71002, Phone: 919-716-3422

Object: NC393522 - Boiler - Miura - 2011 - Blr Rm - Active

Violations This Object: 1

COMPANY:	State of North Carolina		
INSPECTOR:	Smith, Jeremy		
OPENED:	11/06/2020	ENTERED BY:	Smith, Jeremy
CLOSED:		CLOSED BY:	
TYPE:	Certificate Blocking		
CATEGORY:	23-Undefined Boiler Violations		
SUBCATEGORY	363. Undefined Boiler Violations.		
CONDITION:	363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 4/16/2019.		
REQUIREMENT:	363. Undefined Boiler Violations. An External Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.		

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Location: (DPS-C) NCCIW - 3010 **Location #:** 1779964 **Violations:** 2
1034 Bragg St, , Raleigh, NC 27610-3846, Phone: 919-733-4340
Contact: Phillip Jones, Maintenance Supervisor, NCCIW - 3010, Phone: 919-508-1690

Object: NC381483 - Boiler - PVI Industries - 2010 - Falcom Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: SORRENTINO, SEAN
OPENED: 12/08/2020 **ENTERED BY:** Keyes, Amanda
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 16-Boiler Components
SUBCATEGORY 270. Water Leaks.
CONDITION: 270. Boiler Components: Water Leaks.
REQUIREMENT: 270. Repair the water leaks identified on the inspection report. If welding is required, a qualified "R" certificate holder is necessary to perform the repair.

Object: NC401596 - Boiler - PVI Industries - 2014 - Sparrow N - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: SORRENTINO, SEAN
OPENED: 12/08/2020 **ENTERED BY:** Keyes, Amanda
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 16-Boiler Components
SUBCATEGORY 270. Water Leaks.
CONDITION: 270. Boiler Components: Water Leaks. Tank leaking at unknown location.
REQUIREMENT: 270. Repair the water leaks identified on the inspection report. If welding is required, a qualified "R" certificate holder is necessary to perform the repair.

Location: (DPS-C) Neuse CI - 3060 **Location #:** 1814142 **Violations:** 6
701 Stevens Mill Rd, , Goldsboro, NC 27530-9712, Phone: 919-731-2023
Contact: NC Dept Of Public Safety - 13101, Phone: 919-716-3422

Object: NC266530 - Boiler - Teledyne Laars - 1993 - Admin Bldg - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 12/16/2020 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 06-Thermometer NCAC 13-13.0410
SUBCATEGORY 111. Thermometer inoperative.
CONDITION: 111. Thermometer NCAC 13-13.0410: Thermometer inoperative.
REQUIREMENT: 111. Replace inoperative thermometer at/in the boiler outlet to measure the temperature in degrees Fahrenheit of the water. The thermometer shall have a range of approximately 2 times the intended operating temperature but not less than 1 1/2 times the intended operating temperature, nor more than 4 times the intended operating temperature.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC266537 - Boiler - Rheem/Ruud - 1993 - Dorm D1 - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 12/16/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 06-Thermometer NCAC 13-13.0410

SUBCATEGORY 111. Thermometer inoperative.

CONDITION: 111. Thermometer NCAC 13-13.0410: Thermometer inoperative.

REQUIREMENT: 111. Replace inoperative thermometer at/in the boiler outlet to measure the temperature in degrees Fahrenheit of the water. The thermometer shall have a range of approximately 2 times the intended operating temperature but not less than 1 1/2 times the intended operating temperature, nor more than 4 times the intended operating temperature.

Object: NC266542 - Boiler - Rheem/Ruud - 1993 - Dorm C4 - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 12/17/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 06-Thermometer NCAC 13-13.0410

SUBCATEGORY 111. Thermometer inoperative.

CONDITION: 111. Thermometer NCAC 13-13.0410: Thermometer inoperative.

REQUIREMENT: 111. Replace inoperative thermometer at/in the boiler outlet to measure the temperature in degrees Fahrenheit of the water. The thermometer shall have a range of approximately 2 times the intended operating temperature but not less than 1 1/2 times the intended operating temperature, nor more than 4 times the intended operating temperature.

Object: NC266552 - Boiler - Lochinvar - 1993 - Segregation - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 12/17/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. Boiler not operating

REQUIREMENT: 363. Undefined Boiler Violations. Reschedule inspection for a time when the boiler is operating so that safety devices can be verified to function properly or disconnect the boiler from the fuel water and electrical sources.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC320439 - Boiler - Rheem/Ruud - 1999 - Dorm C1 - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 12/17/2020 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 06-Thermometer NCAC 13-13.0410
SUBCATEGORY 111. Thermometer inoperative.
CONDITION: 111. Thermometer NCAC 13-13.0410: Thermometer inoperative.
REQUIREMENT: 111. Replace inoperative thermometer at/in the boiler outlet to measure the temperature in degrees Fahrenheit of the water. The thermometer shall have a range of approximately 2 times the intended operating temperature but not less than 1 1/2 times the intended operating temperature, nor more than 4 times the intended operating temperature.

Object: NC381334 - Boiler - Lochinvar - 2008 - Kitchen Mech Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 12/16/2020 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 06-Thermometer NCAC 13-13.0410
SUBCATEGORY 111. Thermometer inoperative.
CONDITION: 111. Thermometer NCAC 13-13.0410: Thermometer inoperative.
REQUIREMENT: 111. Replace inoperative thermometer at/in the boiler outlet to measure the temperature in degrees Fahrenheit of the water. The thermometer shall have a range of approximately 2 times the intended operating temperature but not less than 1 1/2 times the intended operating temperature, nor more than 4 times the intended operating temperature.

Location: (ISS) Third Creek Middle **Location #:** 4015749 **Violations:** 2
359 E Barkley Rd, , Statesville, NC 28677-2450, Phone:
Contact: Attn Eddie Odom, Iredell Statesville Schools, Phone: 704-873-3755

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC424669 - PV - A O Smith - 2019 - Mech Rm 1142 At Loading Dock - Active **Violations This Object:** 1

COMPANY: State of North Carolina
INSPECTOR: Hutchens, Mark
OPENED: 04/22/2020 **ENTERED BY:** Hutchens, Mark
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 04-Installation of PRDs NCAC 13-13.0405
SUBCATEGORY 452. Set pressure too high.
CONDITION: 452. Installation of PRDs NCAC 13-13.0405: Set pressure too high. Mawp is 125 psi & SV#1 is 150 psi.
REQUIREMENT: 452. Replace the pressure relieving device with one with a set pressure no higher than the maximum allowable working pressure as determined by the manufacturer.

Object: NC424670 - Boiler - A O Smith - 2019 - Mech Rm 1142 At Loading Dock - Active **Violations This Object:** 1

COMPANY: State of North Carolina
INSPECTOR: Hutchens, Mark
OPENED: 04/22/2020 **ENTERED BY:** Hutchens, Mark
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations. Boiler water heater not in operation to test controls.
REQUIREMENT: 363. Undefined Boiler Violations. Boiler water heater needs to be in operation to test safety's.

Location: (LEE) O T Sloan Park **Location #:** 1815639 **Violations:** 4
1420 Bragg St, , Sanford, NC 27330-5435, Phone: 919-775-2107
Contact: Attn Russell Spivey, Lee County Government General Services, Phone: 919-718-4622

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC419417 - Boiler - Teledyne Laars - 2017 - Outside pool house - **Violations This Object:** 2
Active

COMPANY: State of North Carolina
INSPECTOR: Gunto III, Andrew
OPENED: 10/20/2020
CLOSED:
ENTERED BY: Gunto III, Andrew
CLOSED BY:
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations.
At the time of the 10/20/2020 inspection, this boiler was not in operation.
REQUIREMENT: 363. Undefined Boiler Violations.
At follow up inspection the boiler must be firing, and an operational demonstration will be need. This includes the verification of the high-limit temperature controls and its manual reset.

COMPANY: State of North Carolina
INSPECTOR: Gunto III, Andrew
OPENED: 10/20/2020
CLOSED:
ENTERED BY: Gunto III, Andrew
CLOSED BY:
TYPE: Certificate Blocking
CATEGORY: 24-Installation of PRDs NCAC 13-13.0405
SUBCATEGORY 378. Discharge opening directed improperly.
CONDITION: 378. Installation of PRDs NCAC 13-13.0405:
The safety valve on this boiler is not piped to a safe location.
REQUIREMENT: 378. Redirect the discharge to a safe point at required in NCAC 13-13.0405.
Pipe the safety valve vent so that refrigerant is vented outside to a safe location. All repairs must satisfy the requirements of the Uniform Boiler and Pressure Vessel Act of North Carolina.

Object: NC419418 - Boiler - Teledyne Laars - 2017 - Outside pool house - **Violations This Object:** 2
Active

COMPANY: State of North Carolina
INSPECTOR: Gunto III, Andrew
OPENED: 10/20/2020
CLOSED:
ENTERED BY: Gunto III, Andrew
CLOSED BY:
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations.
At the time of the 10/20/2020 inspection, this boiler was not in operation.
REQUIREMENT: 363. Undefined Boiler Violations.
At follow up inspection the boiler must be firing, and an operational demonstration will be need. This includes the verification of the high-limit temperature controls and its manual reset.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

COMPANY: State of North Carolina
INSPECTOR: Gunto III, Andrew
OPENED: 10/20/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 24-Installation of PRDs NCAC 13-13.0405
SUBCATEGORY 378. Discharge opening directed improperly.
CONDITION: 378. Installation of PRDs NCAC 13-13.0405:
The safety valve on this boiler are not piped to a safe location.
REQUIREMENT: 378. Redirect the discharge to a safe point at required in NCAC 13-13.0405.
Pipe the safety valve vent so that refrigerant is vented outside to a safe location. All repairs must satisfy the requirements of the Uniform Boiler and Pressure Vessel Act of North Carolina.

Location: (NCCU) Heating Plant
1801 Fayetteville St, , Durham, NC 27707-3129, Phone: 919-530-6313
Location #: 1796457 **Violations:** 2
Contact: Attn Lori Blake Reid PO #P107428, NC Central University Shephard Station, Phone: 919-530-7244
Object: NC293050 - Boiler - Babcock & Wilcox - 1998 - Blr House Blr 1 - **Violations This Object:** 2
Active

COMPANY: State of North Carolina
INSPECTOR: Smith, Jeremy
OPENED: 09/04/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations. All high pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 12/11/2018.
REQUIREMENT: 363. Undefined Boiler Violations. An external Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.

COMPANY: Hartford Steam Boiler
INSPECTOR: SORRENTINO, SEAN
OPENED: 11/18/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. The boiler was not operating during this inspection per Sean Sorrentino inspection report.
REQUIREMENT: 363. You must operate this boiler for external inspection per Sean Sorrentino inspection report.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External
Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status:
Active; Order Results by: Location Name; Then Order by: Address;

Location: (NCDOT) Highway Div 12 Equipment Office **Location #:** 1782980 **Violations:** 2
1710 E Marion St, , Shelby, NC 28152-6259, Phone: 704-480-9020

Contact: Attn Jennifer Savage, Accounting, NC Dept Of Transportation, Phone: 919-835-8002

Object: NC337945 - Boiler - Peerless - 2002 - Blr Rm - Active **Violations This Object:** 2

COMPANY:	Hartford Steam Boiler	
INSPECTOR:	Possidente, James	
OPENED:	12/15/2020	ENTERED BY: Putek, Terry
CLOSED:		CLOSED BY:
TYPE:	Certificate Blocking	
CATEGORY:	13-Burners and Fuel Supply Systems	
SUBCATEGORY	232. Gas train has improper venting.	
CONDITION:	232. Burners and Fuel Supply Systems: Gas train has improper venting.	
REQUIREMENT:	232. Vent the gas train to a safe point .	
COMPANY:	Hartford Steam Boiler	
INSPECTOR:	Possidente, James	
OPENED:	12/15/2020	ENTERED BY: Putek, Terry
CLOSED:		CLOSED BY:
TYPE:	Certificate Blocking	
CATEGORY:	26-Undefined Pressure Relieving Devices Violations	
SUBCATEGORY	399. Undefined Pressure Relieving Devices Violations.	
CONDITION:	399. Undefined Pressure Relieving Devices Violations. Pressure relief valve improper installation. Horizontal configuration.	
REQUIREMENT:	399. Undefined Pressure Relieving Devices Violations. Reinstall pressure relief valve so the valve stem is in vertical position. The discharge must be piped full size to point of discharge.	

Location: (NCDOT) Highway Div 9 Equipment Shop **Location #:** 1783562 **Violations:** 1
123 Westside Dr, , Mocksville, NC 27028-8324, Phone: 336-751-2433

Contact: Attn Jennifer Savage, Accounting, NC Dept Of Transportation, Phone: 919-835-8002

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC302811 - PV - Manchester - 1992 - Comp Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Leonard, Shannon D.

OPENED: 12/17/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 04-Installation of PRDs NCAC 13-13.0405

SUBCATEGORY 453. Inlet pipe too small.

CONDITION: 453. Installation of PRDs NCAC 13-13.0405: Pressure Relief Device (PRD) Inlet pipe too small.

REQUIREMENT: 453. Replace the insufficiently sized PRD inlet piping. The replacement inlet plumbing connection must be piped full size between the air tank and the PRD inlet.

Location: (NEW HANOVER) Cape Fear Museum

Location #: 1814368

Violations: 1

814 Market St, , Wilmington, NC 28401-4731, Phone: 910-341-4350

Contact: New Hanover County Government, Phone: 910-798-4330

Object: NC419285 - Boiler - Sermeta - 2018 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 11/24/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 25-Operation of PRDs NCAC 13-13.0405

SUBCATEGORY 395. Valve leaking.

CONDITION: 395. Operation of PRDs NCAC 13-13.0405: Valve leaking: Pressure relief device leaking.

REQUIREMENT: 395. Replace with a ASME/NB certified pressure relief device with a set pressure of not greater than 160 psig, with a relief capacity of not less than 994 KBH and with a testing lever

Location: (ROWAN) Administration Bldg

Location #: 1762160

Violations: 1

130 W Innes St, , Salisbury, NC 28144-4375, Phone: 704-202-3349/704-636-1658

Contact: Rowan County Government, Phone: 704-216-7763

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC278093 - Boiler - Weil-McLain - 1996 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Leonard, Shannon D.

OPENED: 11/10/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. Boiler not operating at time of inspection; low water cutoff (LWCO) and pressure relief device (PRD) could not be tested to verify proper operation.

REQUIREMENT: 363. Undefined Boiler Violations. Schedule a reinspection at a time when the boiler is operating so that the LWCO and PRD maybe tested to verify proper operation. As an alternative a detailed service report or boiler log that includes documentation of the successful testing of these controls is also acceptable.

Location: (SAMPSON CS) Clement Elem

Location #: 1777690

Violations: 1

3220 Maxwell Rd, , Autryville, NC 28318-8779, Phone: 910-592-4111

Contact: Jason Elmore, Maintenance, Sampson County Schools, Phone: 910-592-4111

Object: NC327833 - Boiler - Peerless - 2000 - Blr Rm New Addition - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 11/06/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. Boiler not operating

REQUIREMENT: 363. Undefined Boiler Violations: Re-schedule inspection for a time when the boiler is operating so that safety devices can be verified to operate properly.

Location: (SAMPSON CS) Hobbton High

Location #: 1797773

Violations: 1

12201 Hobbton Hwy, , Newton Grove, NC 28366-7246, Phone: 910-592-4111

Contact: Jason Elmore, Maintenance, Sampson County Schools, Phone: 910-592-4111

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC375041 - Boiler - Weil-McLain - 2008 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 11/06/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 25-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 395. Valve leaking.
CONDITION: 395. Operation of PRDs NCAC 13-13.0405: Pressure relief device leaking.
REQUIREMENT: 395. Repair or replace pressure relief device. New pressure relief must be ASME/NB certified with a set pressure of not greater than 30 psig with a relief capacity of not less than 4,283,000 BTU/HR and have a testing lever.

Location: (SAMPSON CS) Plain View Elem

Location #: 1819988

Violations: 4

4140 Plain View Hwy, , Dunn, NC 28334-9012, Phone: 910-592-4111

Contact: Jason Elmore, Maintenance, Sampson County Schools, Phone: 910-592-4111

Object: NC324943 - Boiler - Teledyne Laars - 2000 - Yard - Active

Violations This Object: 2

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 11/06/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409
SUBCATEGORY 006. Low water cutoff device inoperative or bypassed.
CONDITION: 006. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device inoperative or bypassed.
REQUIREMENT: 006. Repair or replace the inoperable low water fuel cutoff control and test to ensure proper operation.

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 11/06/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations. Boiler not operating.
REQUIREMENT: 363. Undefined Boiler: Determine and correct the cause of the boiler failing to operate. Re-schedule inspection for a time when the boiler is operating so that safety devices can be verified to operate properly.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External
Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status:
Active; Order Results by: Location Name; Then Order by: Address;

Object: NC324944 - Boiler - Teledyne Laars - 2000 - Yard - Active

Violations This Object: 2

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 11/06/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409

SUBCATEGORY 006. Low water cutoff device inoperative or bypassed.

CONDITION: 006. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device inoperative or bypassed.

REQUIREMENT: 006. Repair or replace the inoperable low water fuel cutoff control and test to ensure proper operation.

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 11/06/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. Boiler not operating.

REQUIREMENT: 363. Undefined Boiler Violations. Determine and correct the cause of the boiler failing to operate. Re-schedule inspection for a time when the boiler is operating so that safety devices can be verified to operate properly.

Location: (SAMPSON CS) Salemburg Elem

Location #: 1826761

Violations: 4

404 E College St, , Salemburg, NC 28385-8577, Phone: 910-525-5547

Contact: Sampson County Schools, Phone: 910-592-4111

Object: NC324904 - Boiler - Teledyne - 2000 - YARD - Active

Violations This Object: 2

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 11/06/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409

SUBCATEGORY 006. Low water cutoff device inoperative or bypassed.

CONDITION: 006. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device inoperative or bypassed.

REQUIREMENT: 006. Repair or replace the inoperable low water fuel cutoff control and test to ensure proper operation.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 11/06/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations. Boiler not operating.
REQUIREMENT: 363. Undefined Boiler Violations. Reschedule inspection for a time when the boiler is operating so that safety devices can be verified to operate properly.

ENTERED BY: Judd, Janie
CLOSED BY:

Object: NC324905 - Boiler - Teledyne Laars - 2000 - YARD - Active

Violations This Object: 2

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 11/06/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409
SUBCATEGORY 006. Low water cutoff device inoperative or bypassed.
CONDITION: 006. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device inoperative or bypassed.
REQUIREMENT: 006. Repair or replace the inoperable low water fuel cutoff control and test to ensure proper operation.

ENTERED BY: Judd, Janie
CLOSED BY:

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 11/06/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations: Boiler not operating.
REQUIREMENT: 363. Undefined Boiler Violations. Reschedule inspection for a time when the boiler is operating so that safety devices can be verified to operate properly.

ENTERED BY: Judd, Janie
CLOSED BY:

Location: (SAMPSON CS) Union High

Location #: 2858721

Violations: 2

1189 Kader Merritt Rd, , Rose Hill, NC 28458-8842, Phone: 910-592-4111

Contact: Jason Elmore, Maintenance, Sampson County Schools, Phone: 910-592-4111

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC381589 - PV - Lochinvar - 2007 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 11/06/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 04-Installation of PRDs NCAC 13-13.0405
SUBCATEGORY 458. Discharge opening directed improperly.
CONDITION: 458. Installation of PRDs NCAC 13-13.0405: Discharge opening directed improperly.
REQUIREMENT: 458. Install a discharge pipe on pressure relief device to direct the discharge in a safe direction IAW NCAC 13-13.0405 IE within 6 inches from the ground.

ENTERED BY: Judd, Janie

CLOSED BY:

Object: NC381590 - PV - Lochinvar - 2007 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 11/06/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 04-Installation of PRDs NCAC 13-13.0405
SUBCATEGORY 458. Discharge opening directed improperly.
CONDITION: 458. Installation of PRDs NCAC 13-13.0405: Discharge opening directed improperly.
REQUIREMENT: 458. Install a discharge pipe to the pressure relief device such that it discharges in a safe direction IAW NCAC 13-13.0405, ie within 6 inches of the ground.

ENTERED BY: Judd, Janie

CLOSED BY:

Location: (SAMPSON CS) Union Middle

Location #: 1839191

Violations: 1

455 River Rd, , Clinton, NC 28328-6432, Phone: 910-592-4111

Contact: Jason Elmore, Maintenance, Sampson County Schools, Phone: 910-592-4111

Object: NC280093 - Boiler - Weil-McLain - 1996 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 11/06/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations. Boiler not operating.
REQUIREMENT: 363. Undefined Boiler Violations: Reschedule inspection for a time when the boiler can be operated so that safety devices can be verified to operate properly.

ENTERED BY: Judd, Janie

CLOSED BY:

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External
Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status:
Active; Order Results by: Location Name; Then Order by: Address;

Location: (SMS) Cruikshank Hall **Location #:** 1781296 **Violations:** 1
900 Hillsborough St, , Raleigh, NC 27603-1610, Phone: 919-424-4132
Contact: Attn Eric Poss, Director of Facilities, Saint Marys School, Phone: 919-424-4132

Object: NC384766 - Boiler - A O Smith - 2010 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 01/28/2020 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 16-Boiler Components
SUBCATEGORY 270. Water Leaks.
CONDITION: 270. Boiler Components: Water Leaks.
REQUIREMENT: 270. Determine location of leak and repair. If weld repair is required "R" stamp
certificate holder is required to perform repair.

Location: (SMS) Natatorium Pool **Location #:** 1832204 **Violations:** 1
900 Hillsborough St, , Raleigh, NC 27603-1610, Phone: 919-424-4132
Contact: Attn Eric Poss, Director of Facilities, Saint Marys School, Phone: 919-424-4132

Object: NC361042 - Boiler - Teledyne Laars - 2006 - Outside Pool - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 01/28/2020 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 25-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 393. Valve stem distorted/bent.
CONDITION: 393. Operation of PRDs NCAC 13-13.0405: Pressure Relief Device Valve stem
distorted/bent.
REQUIREMENT: 393. Repair or replace relief device. Pressure relief device must be ASME/NB
certified with a set pressure of not greater than 160 psig, with a relief capacity of at
least 780,000 Btu/hr and have a testing lever.

Location: (UNC-CH) George M Horton Res Hall-136 **Location #:** 1900509 **Violations:** 1
411 Skipper Bowles Dr, , Chapel Hill, NC 27514-3434, Phone: 919-962-1271
Contact: Attn Lawrence Peoples, Manager, UNC Chapel Hill - Giles Horney Bldg 168, Phone: 919-843-8771

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC363063 - PV - Cemline - 2005 - Mech Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: SORRENTINO, SEAN

OPENED: 07/31/2020

ENTERED BY: Keyes, Amanda

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 05-Operation of PRDs NCAC 13-13.0405

SUBCATEGORY 475. Valve leaking.

CONDITION: 475. Operation of PRDs NCAC 13-13.0405: Valve leaking.

REQUIREMENT: 475. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

Location: (UNC-CH) Rams Head Dining Ctr-390

Location #: 1900378

Violations: 1

104 Ridge Rd, , Chapel Hill, NC 27514-4387, Phone: (919)843-8771

Contact: Attn Lawrence Peoples, Manager, UNC Chapel Hill - Giles Horney Bldg 168, Phone: 919-843-8771

Object: NC357411 - PV - Cemline - 2004 - Mech Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: SORRENTINO, SEAN

OPENED: 07/14/2020

ENTERED BY: Keyes, Amanda

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 05-Operation of PRDs NCAC 13-13.0405

SUBCATEGORY 474. Valve inoperative.

CONDITION: 474. Operation of PRDs NCAC 13-13.0405: Valve inoperative.

REQUIREMENT: 474. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

Location: (WILKES CS) C B Eller Elem

Location #: 1771961

Violations: 1

1288 Cb Eller School Rd, , Elkin, NC 28621-8884, Phone: 336-835-5640

Contact: Attn Bergi Speaks, Maintenance Director, Wilkes County Schools, Phone: 336-651-4009

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC086235 - Boiler - Kewanee - 1965 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 12/10/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 25-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 395. Valve leaking.
CONDITION: 395. Operation of PRDs NCAC 13-13.0405: Valve leaking: Pressure relief device (PRD) leaking.
REQUIREMENT: 395. Replace the leaking PRD with an ASME/NB stamped PRD having a set pressure of 30 PSI or less and a relieving capacity of 2,625,000 BTU/Hour or more. The replacement PRD must be equipped with a try lever and the PRD discharge must be piped full size to a safe location (I.E. within 6" of the boiler room floor).

Location: (WILKES CS) Central Wilkes Middle

Location #: 2910852

Violations: 1

3541 S NC Highway 16, , Moravian Falls, NC 28654-9860, Phone: 336-667-7453

Contact: Attn Bergi Speaks, Maintenance Director, Wilkes County Schools, Phone: 336-651-4009

Object: NC383464 - PV - A O Smith - 2001 - Cafeteria - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 12/10/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 05-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 475. Valve leaking.
CONDITION: 475. Operation of PRDs NCAC 13-13.0405: Valve leaking: Pressure relief valve leaking.
REQUIREMENT: 475. Replace the leaking PRD with an ASME/NB stamped temperature and pressure relieving type PRD having a set pressure of not greater than 150 PSI and a relieving capacity of not less than 189,000 BTU/Hour. The replacement PRD must be equipped with a try-lever and the PRD discharge must be piped to a safe location (I.E. with 6" of the mech room floor).

Location: (WILKES CS) Wilkes Central High

Location #: 1843922

Violations: 1

1179 Moravian Falls Rd, , Wilkesboro, NC 28697-7636, Phone: 336-667-5277

Contact: Attn Bergi Speaks, Maintenance Director, Wilkes County Schools, Phone: 336-651-4009

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC192411 - Boiler - Weil-McLain - 1980 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 12/10/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 25-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 395. Valve leaking.
CONDITION: 395. Operation of PRDs NCAC 13-13.0405: Pressure relief device (PRD) leaking.
REQUIREMENT: 395.Replace the leaking PRD with an ASME/NB stamped PRD having a set pressure of 50 PSI or less and a relieving capacity of 2,040,000 BTU/Hour or more. The replacement PRD must be equipped with a try-lever and the PRD discharge must be piped full size to a safe location (I.E. with 6" of the boiler room floor).

Location: A Cleaner World #207

Location #: 1761486

Violations: 1

2290 Ten Ten Rd, , Apex, NC 27539-8115, Phone: 919-367-0200

Contact: Attn Tim Rolle, Mgr, A Cleaner World #207, Phone: 919-367-0200, Cell:919-931-9802

Object: NC323509 - Boiler - Fulton - 2000 - Blr Rm - Active

Violations This Object: 1

COMPANY: State of North Carolina
INSPECTOR: Kinney, Donald
OPENED: 12/23/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 12-Casing, Stack Breeching and Flue
SUBCATEGORY 211. Combustion gas leaks.
CONDITION: 211. Casing, Stack Breeching and Flue: Combustion gas leaks.
REQUIREMENT: 211. Repair all combustion gas leaks in the casing, stack breeching, or flue.

Location: Alberdingk Boley

Location #: 1762745

Violations: 1

6008 W Gate City Blvd, , Greensboro, NC 27407-7071, Phone: 336-821-5539

Contact: Attn Kay Jacobs, Alberdingk Boley Inc, Phone: 336-821-5539, Cell:336-862-0032

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC428650 - Boiler - Miura - 2020 - Blr Rm - Active

Violations This Object: 1

COMPANY: State of North Carolina
INSPECTOR: Johnson, Dean
OPENED: 12/23/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 09-Bottom Blow and Drain Systems NCAC 13-13.0411
SUBCATEGORY 150. Valve(s) have incorrect pressure rating.
CONDITION: 150. Bottom Blow and Drain Systems NCAC 13-13.0411: Slow opening angle valve has incorrect pressure rating. Bottom blow down valves must be rated for MAWP plus 25%.
REQUIREMENT: 150. Install a slow opening valve rated for at least 250 WSP.

Location: Aviator Brewing Co

Location #: 3208525

Violations: 3

209 Technology Park Ln, , Fuquay Varina, NC 27526-9311, Phone: 919-567-2337

Contact: Mark Doble, Brew Boss, Aviator Brewing Co, Phone: 919-567-2337, Cell:919-601-5497

Object: NC389917 - Boiler - Columbia - 2011 - Front Corner - Active

Violations This Object: 3

COMPANY: State of North Carolina
INSPECTOR: Fish, Emily
OPENED: 08/20/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409
SUBCATEGORY 005. No provision to test low water cutoff device.
CONDITION: 005. LWCO and Flow Sensing Devices NCAC 13-13.0409: No provision to test low water cutoff device. Manual reset LWCO could not be tested due to inoperative sight glass.
REQUIREMENT: 005. Repair sight glass to functioning state so the LWCO can be safely and accurately tested. Contact Emily Fish at (919) 268-0725 when repairs are complete to schedule reinspection.

COMPANY: State of North Carolina
INSPECTOR: Fish, Emily
OPENED: 11/09/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 25-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 391. Discharge piping not properly supported.
CONDITION: 391. Operation of PRDs NCAC 13-13.0405: Discharge piping not properly supported.
REQUIREMENT: 391. Support the relief valve discharge piping so it may not impose excessive stress on the relief valve.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

COMPANY: State of North Carolina
INSPECTOR: Fish, Emily
OPENED: 11/09/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 25-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 395. Valve leaking.
CONDITION: 395. Operation of PRDs NCAC 13-13.0405: Valve leaking.
REQUIREMENT: 395. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

Location: Boston Cleaners & Laundry
2182 N Church St, , Burlington, NC 27217-3004, Phone: 336-226-9803
Contact: Attn Bill Robbins, Boston Cleaners & Laundry, Phone: 336-226-9803

Location #: 1769786 **Violations:** 1

Object: NC371303 - Boiler - Parker - 2007 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 12/18/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 03-Water Gauge Glass NCAC 13-13.0408
SUBCATEGORY 058. Leaking.
CONDITION: 058. Water Gauge Glass NCAC 13-13.0408: Leaking.
REQUIREMENT: 058. Repair or replace the leaking gauge and test to ensure proper operation.

Location: Calvary Church
5801 Pineville Matthews Rd, , Charlotte, NC 28226-3432, Phone: 704-543-1200
Contact: Debbie Bordwine, Admin, Calvary Church, Phone: 704-341-5328

Location #: 1772297 **Violations:** 3

Object: NC248763 - Boiler - Teledyne Laars - 1988 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Clay, Steven D.
OPENED: 10/19/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations. Pump removed for repairs. Boiler would not run for inspection.
REQUIREMENT: 363. Undefined Boiler Violations. Repair pump and reschedule inspection when boiler is running.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC386899 - Boiler - Teledyne Laars - 2011 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Clay, Steven D.
OPENED: 10/19/2020 **ENTERED BY:** Putek, Terry
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409
SUBCATEGORY 012. Flow switch inoperative or bypassed.
CONDITION: 012. LWCO and Flow Sensing Devices NCAC 13-13.0409: Flow switch inoperative or bypassed.
REQUIREMENT: 012. Install a flow switch that will shut off the fuel supply in case of stoppage of water flow or a low-water condition and test to ensure proper operation.

Object: NC386900 - Boiler - Teledyne Laars - 2011 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Clay, Steven D.
OPENED: 10/19/2020 **ENTERED BY:** Putek, Terry
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations. Controls would not allow boiler to run due to outside temperature.
REQUIREMENT: 363. Undefined Boiler Violations. Reschedule boiler inspection when control issues are resolved or when weather allows boiler to be running.

Location: Capital Ready Mix Concrete **Location #:** 3914731 **Violations:** 1
512 Three Sisters Rd, , Knightdale, NC 27545-8202, Phone: 919-999-0923
Contact: Attn Joe Kisselburg, Plant Manager, Capital Ready Mix Concrete Llc, Phone: 919-999-0923

Object: NC418986 - Boiler - Columbia - 2017 - Red Bldg - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: SORRENTINO, SEAN
OPENED: 12/03/2020 **ENTERED BY:** Keyes, Amanda
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409
SUBCATEGORY 001. Low water cutoff device not installed.
CONDITION: 001. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device not installed.
REQUIREMENT: 001. Equip the boiler with a low water fuel cutoff device (LWCO) designed for the appropriate service (Steam or Hot Water) that is equipped with a manual reset. When the LWCO shuts off the fuel supply to the boiler in the event of a low water condition, the fuel supply must be restarted manually by an operator. Test to ensure proper operation.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Location: Car City Gas & Oil Co **Location #:** 1763833 **Violations:** 1
4019 Sylva Rd, , Franklin, NC 28734-2282, Phone: 828-524-5873
Contact: Attn Darrell Mason, Owner, Car City Gas & Oil Co, Phone: 828-524-5873

Object: NC416185 - PV - Twin Lakes Tanks - 2017 - Outside Shop - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Possidente, James
OPENED: 03/03/2020 **ENTERED BY:** Putek, Terry
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 05-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 477. Try lever inoperative.
CONDITION: 477. Operation of PRDs NCAC 13-13.0405: Try lever inoperative. Try lever pull ring not present.
REQUIREMENT: 477. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

Location: Carolina Packers **Location #:** 1773944 **Violations:** 1
2999 S Brightleaf Blvd, , Smithfield, NC 27577-5251, Phone: 919-934-2181
Contact: Carolina Packers Inc, Phone: 919-934-2181

Object: NC106918 - Boiler - BE&S - 1971 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: SORRENTINO, SEAN
OPENED: 09/29/2020 **ENTERED BY:** Keyes, Amanda
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 25-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 395. Valve leaking.
CONDITION: 395. Operation of PRDs NCAC 13-13.0405: Valve leaking.
REQUIREMENT: 395. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

Location: Cintas Corp **Location #:** 1791576 **Violations:** 1
610 Woody Dr, , Graham, NC 27253-3814, Phone: 336-228-0531
Contact: Attn Jesus Sepulveda, Maintenance Supervisor, Cintas Corp, Phone: 336-228-0531 X7222, Cell:787-438-

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC408261 - Boiler - Cleaver Brooks - 2016 - Blr Rm - Active **Violations This Object:** 1

COMPANY: State of North Carolina
INSPECTOR: Smith, Jeremy
OPENED: 11/06/2020 **ENTERED BY:** Smith, Jeremy
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 2/7/2019.
REQUIREMENT: 363. Undefined Boiler Violations. An External Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.

Location: Cleaners Express **Location #:** 1761026 **Violations:** 1
108 N Arlington St, , Salisbury, NC 28144-4615, Phone: 704-638-2344
Contact: Attn Yong Aee, Owner, Cleaners Express, Phone: 704-638-2344

Object: NC364556 - Boiler - Hurst - 2006 - Blr Rm - Active **Violations This Object:** 1

COMPANY: State of North Carolina
INSPECTOR: Smith, Jeremy
OPENED: 11/06/2020 **ENTERED BY:** Smith, Jeremy
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 7/31/2019.
REQUIREMENT: 363. Undefined Boiler Violations. An External Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.

Location: Compare Foods #1 **Location #:** 2881380 **Violations:** 2
3600 N Sharon Amity Rd, , Charlotte, NC 28205-5932, Phone: 704-536-3176
Contact: There is no contact information available for this location.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC382552 - PV - Standard - 1999 - Outside Motor Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Clay, Steven D.
OPENED: 08/17/2020 **ENTERED BY:** Putek, Terry
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 04-Installation of PRDs NCAC 13-13.0405
SUBCATEGORY 461. Incorrect pressure relieving device(s) for the application.
CONDITION: 461. Installation of PRDs NCAC 13-13.0405: Incorrect pressure relieving device(s) for the application. Broken lock wire.
REQUIREMENT: 461. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

Object: NC382553 - PV - Standard - 1999 - Outside Motor Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Clay, Steven D.
OPENED: 08/17/2020 **ENTERED BY:** Putek, Terry
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 04-Installation of PRDs NCAC 13-13.0405
SUBCATEGORY 459. Discharge piping too small.
CONDITION: 459. Installation of PRDs NCAC 13-13.0405: Discharge piping too small. Broken and disconnected discharge lines.
REQUIREMENT: 459. Repipe the discharge line full size to a safe point of discharge.

Location: Crestwood Baptist Church **Location #:** 1780999 **Violations:** 1
530 Motor Rd, , Winston Salem, NC 27105-2245, Phone: 336-767-0096
Contact: Attn David Wood, Pastor, Crestwood Baptist Church, Phone: 336-767-0096

Object: NC278720 - Boiler - Crown - 1996 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 12/01/2020 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 25-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 395. Valve leaking.
CONDITION: 395. Operation of PRDs NCAC 13-13.0405: Valve leaking: Pressure relief device (PRD) leaking.
REQUIREMENT: 395. Replace the current PRD with an ASME/NB stamped PRD having a set pressure of 75 PSI or less and relieving capacity of 240,000 BTU/HOUR or more. The replacement PRD must be equipped with a try-lever and the PRD discharge must be piped full size to a safe location (I.E. within 6" of the boiler floor).

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External
Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status:
Active; Order Results by: Location Name; Then Order by: Address;

Location: East Side Volunteer Fire Dept Station 2 **Location #:** 3776423 **Violations:** 1
805 Laton Rd, , Albemarle, NC 28001-8607, Phone: 704-982-3698

Contact: William Efrid, Fire Chief, East Side Volunteer Fire Dept Station 2, Phone: 704-982-3698

Object: NC411567 - PV - Morganton - 2011 - Rear Cooking Area - Active **Violations This Object:** 1

COMPANY: State of North Carolina
INSPECTOR: Coley, Oscar
OPENED: 11/30/2020 **ENTERED BY:** Coley, Oscar
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 07-Undefined Pressure Vessels Violations
SUBCATEGORY 479. Undefined Pressure Vessels Violations.
CONDITION: 479. Undefined Pressure Vessels Violations. Operating with an expired certificate of inspection.
REQUIREMENT: 479. Undefined Pressure Vessels Violations. NC law requires current certificate of inspection. Please contact your insurance inspector or Junior Coley (state inspector) (My phone 704-261-6873) to schedule an inspection ASAP!

Location: Elkin Laser Wash **Location #:** 1786310 **Violations:** 1
1132 N Bridge St, , Elkin, NC 28621-2408, Phone: 336-749-1338

Contact: Pat Crosby, Owner, Elkin Laser Wash, Phone: 336-749-1338

Object: NC349991 - PV - Manchester - 2000 - Equip Rm - Active **Violations This Object:** 1

COMPANY: State of North Carolina
INSPECTOR: Parker, Richard
OPENED: 10/20/2020 **ENTERED BY:** Parker, Richard
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 07-Undefined Pressure Vessels Violations
SUBCATEGORY 479. Undefined Pressure Vessels Violations.
CONDITION: 479. No access
REQUIREMENT: 479. Contact Inspector and schedule inspection.

contact Richard Parker @ 336-202-8341

Location: Ergon Asphalt & Emulsions **Location #:** 3316456 **Violations:** 2
2520 Wilco Blvd S, , Wilson, NC 27893-9020, Phone: 252-991-4692

Contact: Attn Sean Randall, Manager, Ergon Asphalt & Emulsions Inc, Phone: 580-583-6618

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC393068 - Boiler - York Shipley - 2011 - Blr Rm - Active

Violations This Object: 2

COMPANY: State of North Carolina
INSPECTOR: Harrell, Danny
OPENED: 12/07/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 13-Burners and Fuel Supply Systems
SUBCATEGORY 234. Combustion air supply inadequate.
CONDITION: 234. Burners and Fuel Supply Systems: Combustion air supply louver linkage has been disconnected and interlock bypassed. Rollup door being used to supply combustion makeup air.
REQUIREMENT: 234. Increase the combustion air supply to at least the minimums specified in NCAC 13-13.0419. Reconnect the motorized louver and insure that the interlock to the boiler is working properly.

ENTERED BY: Harrell, Danny
CLOSED BY:

COMPANY: State of North Carolina
INSPECTOR: Harrell, Danny
OPENED: 12/07/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 13-Burners and Fuel Supply Systems
SUBCATEGORY 236. Undefined Boiler Piping and Other Systems Violations.
CONDITION: 236. Burners and Fuel Supply Systems: Undefined Boiler Piping and Other Systems Violations. Caps on the adjustment openings are missing on the pilot and main fuel gas regulators.
REQUIREMENT: 236. Undefined Boiler Piping and Other Systems Violations. Install caps on the pilot and main fuel regulator adjustment openings. Contact Danny Harrell @ 919-500-3098 when all repairs are completed to schedule a re-inspection.

ENTERED BY: Harrell, Danny
CLOSED BY:

Location: Fulton Family YMCA

Location #: 1844837

Violations: 1

385 W Hanes Mill Rd, , Winston Salem, NC 27105-9626, Phone: 336-661-1093

Contact: There is no contact information available for this location.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC412588 - Boiler - Steamist - 2016 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 10/21/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations. Boiler not operating at time of inspection; could not test safety devices to verify proper operation.
REQUIREMENT: 363. Undefined Boiler Violations. Schedule a follow up inspection at a time when the boiler is operating so that the safety devices may be tested to verify proper operation. As an alternative a detailed service report or boiler log that includes documentation of the successful testing of the safety devices is also acceptable.

Location: Galloway Ridge

Location #: 1791702

Violations: 2

3000 Galloway Rdg, , Pittsboro, NC 27312-8639, Phone: 919-545-2215

Contact: Attn Jared Cargill, Galloway Ridge, Phone: 919-545-2215

Object: NC427336 - Boiler - A O Smith - 2019 - Health Care - Active

Violations This Object: 1

COMPANY: State of North Carolina
INSPECTOR: Gunto III, Andrew
OPENED: 08/18/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations.
1) This Water-Heater's cold-water inlet, safety valve vent piping and exhaust-flue condensate drain are all installed in a way that hinder access for maintenance and inspection.
2) This Water-Heater's safety valve vent is not supported and is being held in place by the safety valve.
REQUIREMENT: 363. Undefined Boiler Violations.
1) Reconfigure these lines/pipes so that they do not restrict maintenance and inspection.
2) Support the safety valve vent so that it puts no force on the safety valve.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC427337 - Boiler - A O Smith - 2020 - Health Care - Active

Violations This Object: 1

COMPANY: State of North Carolina

INSPECTOR: Gunto III, Andrew

OPENED: 08/18/2020

ENTERED BY: Gunto III, Andrew

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations.

- 1) This Water-Heater's cold-water inlet, safety valve vent piping and exhaust-flue condensate drain are all installed in a way that hinder access for maintenance and inspection.
- 2) This Water-Heater's safety valve vent is not supported and is being held in place by the safety valve.

REQUIREMENT: 363. Undefined Boiler Violations.

- 1) Reconfigure these lines/pipes so that they do not restrict maintenance and inspection.
- 2) Support the safety valve vent so that it puts no force on the safety valve.

Location: GE Global Nuclear Fuels America (Hartford)

Location #: 176064

Violations: 1

3901 Castle Hayne Rd, , Wilmington, NC 28402-1810, Phone: 910-675-5445

Contact: Attn Jeffrey Starling M/C G50, Site Maintenance Coordinator, GE Global Nuclear Fuels, Phone: 910-819-

Object: NC135849 - PV - Delta - 1973 - Outside FMO Comp Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 07/01/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 04-Installation of PRDs NCAC 13-13.0405

SUBCATEGORY 460. Seals broken/ missing.

CONDITION: 460. Installation of PRDs NCAC 13-13.0405: Pressure relief device tamper seal broken.

REQUIREMENT: 460. Replace with a new ASME/NB certified pressure relief device with a set pressure of not greater than 125 psig, with sufficient relief capacity and a testing lever.

Location: Hanes Lineberry Funeral Home

Location #: 1795417

Violations: 1

515 N Elm St, , Greensboro, NC 27401-2017, Phone: 336-272-5157

Contact: Hanes Lineberry Funeral Home, Phone: 336-272-5157

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC217427 - Boiler - Weil-McLain - 1985 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Leonard, Shannon D.

OPENED: 12/01/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. Boiler not operating at time of inspection; pressure relief device (PRD) and low water cutoff (LWCO) could not be tested to verify proper operation.

REQUIREMENT: 363. Undefined Boiler Violations. Schedule a reinspection at a time when the boiler is operating so that the PRD and LWCO may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the flow switch and PRD is also acceptable.

Location: Harrys On The Hill Llc

Location #: 1795964

Violations: 1

819 Patton Ave, , Asheville, NC 28806-3618, Phone: 828-252-3821

Contact: Jeff Barrett, Collision Repair Manager, Harrys On The Hill Llc, Phone: 828-252-3821

Object: NC344092 - PV - Penway - 2002 - Outside Rear Body Shop - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Possidente, James

OPENED: 12/09/2020

ENTERED BY: Putek, Terry

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 07-Undefined Pressure Vessels Violations

SUBCATEGORY 479. Undefined Pressure Vessels Violations.

CONDITION: 479. Undefined Pressure Vessels Violations. Vessel is out of service but has not been disconnected from all sources of potential energy including electricity.

REQUIREMENT: 479. Undefined Pressure Vessels Violations. Disconnect vessel from electricity and compressed air piping.

Location: High Country Tire & Service Station

Location #: 1797182

Violations: 1

8227 US Highway 441 S, , Sylva, NC 28779-7193, Phone: 828-586-0886

Contact: Attn Mickey & Sam McMahan, Owner, High Country Tire & Service Station, Phone: 828-586-0886

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC390660 - PV - Steel Fab - 2010 - Shop - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Possidente, James
OPENED: 12/08/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 07-Undefined Pressure Vessels Violations
SUBCATEGORY 479. Undefined Pressure Vessels Violations.
CONDITION: 479. Undefined Pressure Vessels Violations. Pressure switch cover missing. 230 volt live wires exposed.
REQUIREMENT: 479. Undefined Pressure Vessels Violations. Install a pressure switch cover.

Location: Highlands Country Club

Location #: 1797447

Violations: 1

981 Dillard Rd, , Highlands, NC 28741-0220, Phone: 828-526-2181

Contact: David Carver, Maintenance Supervisor, Highlands Country Club Inc, Phone: 828-526-2181, Cell:828-200-

Object: NC386660 - Boiler - A O Smith - 2011 - Club House Kitchen - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Possidente, James
OPENED: 11/03/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 16-Boiler Components
SUBCATEGORY 273. Shell leaks.
CONDITION: 273. Boiler Components: Shell leaks. Water on floor surrounding vessel.
REQUIREMENT: 273. Repair the leaking shell. If weld repairs are required, a qualified "R" certificate holder is necessary to perform the work.

Location: Hudson Building

Location #: 1799097

Violations: 1

118 W State St, , Black Mountain, NC 28711-3419, Phone: 828-669-8711

Contact: Attn J Richard Hudson III, Owner, Hudson Building, Phone: 828-669-8711

Object: NC148875 - Boiler - Burnham - 1975 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Possidente, James
OPENED: 12/10/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 03-Water Gauge Glass NCAC 13-13.0408
SUBCATEGORY 057. Drain inoperative.
CONDITION: 057. Water Gauge Glass NCAC 13-13.0408: Drain inoperative. Sight glass drain inoperative because sight glass is upside down.
REQUIREMENT: 057. Repair or replace the inoperable drain valve on the gauge and test to ensure proper operation.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Location: J Iverson Riddle Developmental Center **Location #:** 1843125 **Violations:** 1
300 Enola Rd, , Morganton, NC 28655-4608, Phone: 828-433-2771
Contact: Attn Todd Aderholt, Special Executive To Director, J Iverson Riddle Developmental Center, Phone: 828-433-

Object: NC412660 - PV - Reco - 2019 - Maple Bldg Mech Rm Bsmt - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Richey, Paul D.
OPENED: 09/24/2020 **ENTERED BY:** Putek, Terry
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 04-Installation of PRDs NCAC 13-13.0405
SUBCATEGORY 452. Set pressure too high.
CONDITION: 452. Installation of PRDs NCAC 13-13.0405: Set pressure too high. Mawp is set at 125 psi & SV #1 is 150 psi.
REQUIREMENT: 452. Replace the pressure relieving device with one with a set pressure no higher than the maximum allowable working pressure as determined by the manufacturer.

Location: Kernersville Family YMCA **Location #:** 1845634 **Violations:** 2
1113 W Mountain St, , Kernersville, NC 27284-2125, Phone: 336-996-2231
Contact: There is no contact information available for this location.

Object: NC399650 - Boiler - Stemist - 2013 - Suana - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 10/14/2020 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations. Boiler not operating at time of inspection; low water cutoff (LWCO) and pressure relief device (PRD) could not be tested to verify proper operation.
REQUIREMENT: 363. Undefined Boiler Violations. Schedule a reinspection at a time when the boiler is operating so that the LWCO and PRD may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the flow switch and PRD is also acceptable.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC418867 - Boiler - Teledyne Laars - 1998 - Hot Tub Wtr Htr - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Leonard, Shannon D.

OPENED: 10/14/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. Boiler not operating at time of inspection; flow switch and pressure relief device (PRD) could not be tested to verify proper operation.

REQUIREMENT: 363. Undefined Boiler Violations. Schedule a reinspection at a time when the boiler is operating so that the flow switch and PRD may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the flow switch and PRD is also acceptable.

Location: Lil Donnie Walkers Car Wash

Location #: 1806163

Violations: 1

1246 S Main St, , Graham, NC 27253-4537, Phone: 336-222-1950

Contact: Attn Pete Walker, Owner, SPG Inc, Phone: 336-222-1950, Cell:336 451 0507

Object: NC294925 - Boiler - Raypak - 1999 - Mech Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Leonard, Shannon D.

OPENED: 11/30/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409

SUBCATEGORY 006. Low water cutoff device inoperative or bypassed.

CONDITION: 006. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device inoperative or bypassed.

REQUIREMENT: 006. Repair or replace the inoperable low water fuel cutoff control and test to ensure proper operation.

Location: Milkco Inc

Location #: 482567

Violations: 1

220 Deaverview Rd, , Asheville, NC 28806-1710, Phone: 828-254-6851

Contact: Scott Willett, Maintenance, Milkco Inc, Phone: 828-400-0161

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC365428 - PV - Eisenbeck - 2005 - Maint Shop Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Possidente, James
OPENED: 10/14/2020 **ENTERED BY:** Putek, Terry
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 08-Unqual Orgs: Repair/Alteration NCAC 13-13.0401
SUBCATEGORY 491. Unauthorized Repair.
CONDITION: 491. Unauthorized Repair.
REQUIREMENT: Repairs conducted on this regulated vessel were done by an unqualified organization/individual and must be removed and replaced by a qualified organization.

Location: Monsoon Car Wash **Location #:** 2001664 **Violations:** 1
2558 Lewisville Clemmons Rd, , Clemmons, NC 27012-8711, Phone: 336-500-1937
Contact: There is no contact information available for this location.

Object: NC374671 - PV - Manchester - 1996 - Equip Rm - Active **Violations This Object:** 1

COMPANY: State of North Carolina
INSPECTOR: Parker, Richard
OPENED: 02/24/2020 **ENTERED BY:** Parker, Richard
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 07-Undefined Pressure Vessels Violations
SUBCATEGORY 479. Undefined Pressure Vessels Violations.
CONDITION: 479. No one at location.
REQUIREMENT: 479. Contact inspector and schedule inspection.

contact Richard Parker @ 336-202-8341

Location: Morris Heating & Air Conditioning Inc **Location #:** 4048752 **Violations:** 1
5122 N Causeway Rd, , Winston Salem, NC 27106-9695, Phone: 336-408-1546
Contact: Roger Morris, Morris Heating & Air Conditioning Inc, Phone: 336-408-1546

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC426511 - PV - Brunner - 1985 - Outside Shed - Active

Violations This Object: 1

COMPANY: State of North Carolina

INSPECTOR: Parker, Richard

OPENED: 12/09/2020

ENTERED BY: Parker, Richard

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 07-Undefined Pressure Vessels Violations

SUBCATEGORY 479. Undefined Pressure Vessels Violations.

CONDITION: 479. No access to inspect pressure vessel.

REQUIREMENT: 479. Remove panels for inspector.

contact Richard Parker @ 336-202-8341

Location: Mt Hope United Church Of Christ

Location #: 1812482

Violations: 2

2400 Mount Hope Church Rd, , Whitsett, NC 27377-9750, Phone: 336-697-1561

Contact: There is no contact information available for this location.

Object: NC399199 - Boiler - Giannoni - 2008 - Bsmt Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Leonard, Shannon D.

OPENED: 12/01/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. Boiler not operating at time of inspection; flow switch and pressure relief device (PRD) could not be tested to verify proper operation.

REQUIREMENT: 363. Undefined Boiler Violations. Schedule a reinspection at a time when the boiler is operating so that the flow switch and PRD may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the flow switch and PRD is also acceptable.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC399200 - Boiler - Giannoni - 2009 - Bsmt Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Leonard, Shannon D.

OPENED: 12/01/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. Boiler not operating at time of inspection; flow switch and pressure relief device (PRD) could not be tested to verify proper operation.

REQUIREMENT: 363. Undefined Boiler Violations. Schedule a reinspection at a time when the boiler is operating so that the flow switch and PRD may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the flow switch and PRD is also acceptable.

Location: National Guard Armory

Location #: 1813595

Violations: 1

1935 N Church St, , Burlington, NC 27217-2926, Phone: 336-227-7859

Contact: Attn Major Blane Boyd, Director of Facility Maintenance, Joint Forces HQ, Phone: 919-664-6094

Object: NC389334 - Boiler - Lochinvar - 2011 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Leonard, Shannon D.

OPENED: 09/02/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations: Boiler not operating at time of inspection; pressure relief device and flow switch could not be tested to verify proper operation.

REQUIREMENT: 363. SCHEDULE A REINSPECTION AT A TIME WHEN THE BOILER IS OPERATING SO THAT THE PRESSURE RELIEF DEVICE AND FLOW SWITCH MAY BE TESTED TO VERIFY PROPER OPERATION. AS AN ALTERNATIVE, A DETAILED SERVICE REPORT OR BOILER LOG THAT INCLUDES DOCUMENTATION OF THE SUCCESSFUL TESTING OF THESE CONTROLS IS ALSO ACCEPTABLE

Location: National Guard Armory

Location #: 1813513

Violations: 2

292 NC Highway 65, , Reidsville, NC 27320-8897, Phone: 336-349-4428

Contact: Lee Lewis, National Guard Armory, Phone: 984-664-8009

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC425270 - Boiler - Lochinvar - 2018 - Blr Rm - Active

Violations This Object: 1

COMPANY: State of North Carolina

INSPECTOR: Parker, Richard

OPENED: 04/08/2020

ENTERED BY: Parker, Richard

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 25-Operation of PRDs NCAC 13-13.0405

SUBCATEGORY 391. Discharge piping not properly supported.

CONDITION: 391. Operation of PRDs NCAC 13-13.0405: Discharge piping not properly supported.

REQUIREMENT: 391. Support the relief valve discharge piping so it may not impose excessive stress on the relief valve.

Object: NC425271 - Boiler - Lochinvar - 2018 - Blr Rm - Active

Violations This Object: 1

COMPANY: State of North Carolina

INSPECTOR: Parker, Richard

OPENED: 04/08/2020

ENTERED BY: Parker, Richard

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 25-Operation of PRDs NCAC 13-13.0405

SUBCATEGORY 391. Discharge piping not properly supported.

CONDITION: 391. Operation of PRDs NCAC 13-13.0405: Discharge piping not properly supported.

REQUIREMENT: 391. Support the relief valve discharge piping so it may not impose excessive stress on the relief valve.

contact Richard Parker @ 336-202-8341

Location: NCRC UNC Nutrition Research Institute

Location #: 2212698

Violations: 1

500 Laureate Way, , Kannapolis, NC 28081-3379, Phone: 704-250-5017

Contact: Charles Kraus, Facilities Operations/Zone 7 Supervisor, UNC Charlotte, Phone: 704-250-5017, Cell:980-

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC371947 - Boiler - Bryan - 2007 - Penthouse - Active

Violations This Object: 1

COMPANY: State of North Carolina

INSPECTOR: Smith, Jeremy

OPENED: 11/06/2020

ENTERED BY: Smith, Jeremy

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 2/7/2019.

REQUIREMENT: 363. Undefined Boiler Violations. An External Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.

Location: Neuse River Cleaners

Location #: 1814156

Violations: 1

2443 US Highway 117 S, , Goldsboro, NC 27530-8497, Phone: 919-735-9122

Contact: Attn Greg Foster, Neuse River Cleaners, Phone: 919-580-0279

Object: NC325275 - Boiler - Fulton - 2000 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 10/05/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. Boiler not operating.

REQUIREMENT: 363. Undefined Boiler Violations. Reschedule inspection when boiler is operating so that safety devices can be verified to be operating.

Location: NuVision Engineering Inc

Location #: 2212813

Violations: 1

184 Rolling Hill Rd Ste B, , Mooresville, NC 28117-8917, Phone: 704-799-2707

Contact: Dave Lashley, Director of Engineering, NuVision Engineering Inc, Phone: 704-799-2707, Cell:704-227-4839

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC427190 - Boiler - General - 2020 - Warehouse NW Corner - Active

Violations This Object: 1

COMPANY: State of North Carolina
INSPECTOR: Sims, Greg
OPENED: 10/05/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations. Could not perform external inspection due to natural gas line not installed and emergency cut off switch needs to be installed at the exit door.
REQUIREMENT: 363. Undefined Boiler Violations.

Location: Paul J Rizzo Conference Center

Location #: 1817817

Violations: 1

150 Dubose Home Ln, , Chapel Hill, NC 27517-8944, Phone: 919-913-2098

Contact: There is no contact information available for this location.

Object: NC364029 - Boiler - Lochinvar - 2006 - Outside Dubose House - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Ollison, Jr., James C.
OPENED: 06/11/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 25-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 396. Missing nameplate.
CONDITION: 396. Operation of PRDs NCAC 13-13.0405: Missing nameplate.
REQUIREMENT: 396. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

Location: Pilot View Baptist Church

Location #: 1819495

Violations: 2

7173 Prospect Church Rd, , Thomasville, NC 27360-8839, Phone: 336-886-5867/336-431-5872

Contact: There is no contact information available for this location.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC111138 - Boiler - American Radiator - 1971 - Blr Rm - Active **Violations This Object:** 2

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 12/15/2020 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409
SUBCATEGORY 006. Low water cutoff device inoperative or bypassed.
CONDITION: 006. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device inoperative or bypassed.
REQUIREMENT: 006. Repair or replace the inoperable low water fuel cutoff control and test to ensure proper operation.

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 12/15/2020 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409
SUBCATEGORY 007. Accumulation of sediment in float chamber.
CONDITION: 007. LWCO and Flow Sensing Devices NCAC 13-13.0409: Accumulation of sediment in float chamber.
REQUIREMENT: 007. Disassemble and clean the float chamber of the low water fuel cutoff control and test to ensure proper operation.

Location: Sharon Towers **Location #:** 1828559 **Violations:** 1
5100 Sharon Rd, , Charlotte, NC 28210-4768, Phone: 704-553-3804
Contact: Topper Amerson, Maintenance Supervisor, Sharon Towers,

Object: NC095119 - PV - J J Finnigan - 1967 - Mech Rm 1 - Active **Violations This Object:** 1

COMPANY: State of North Carolina
INSPECTOR: Snuffer, Jimmy
OPENED: 04/20/2020 **ENTERED BY:** Snuffer, Jimmy
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 07-Undefined Pressure Vessels Violations
SUBCATEGORY 479. Undefined Pressure Vessels Violations.
CONDITION: 479. Manway cover is rusting away and because of this, manway cover is loosing required thickness.
REQUIREMENT: 479. Replace Manway Cover

Location: Southminster Retirement Community **Location #:** 1831183 **Violations:** 1
8919 Park Rd, , Charlotte, NC 28210-7610, Phone: 704-551-6800
Contact: Attn Josh Noland, Environmental Services, Southminster Retirement Community, Phone: 704-930-7166

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC428920 - PV - Lochinvar - 2019 - Central Energy Plt - Active **Violations This Object:** 1

COMPANY: State of North Carolina
INSPECTOR: Snuffer, Jimmy
OPENED: 11/13/2020 **ENTERED BY:** Snuffer, Jimmy
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 04-Installation of PRDs NCAC 13-13.0405
SUBCATEGORY 452. Set pressure too high.
CONDITION: 452. Installation of PRDs NCAC 13-13.0405: Set pressure too high.

Set pressure of Safety Valve at 150 psi exceeds the MAWP of vessel at 125 psi
REQUIREMENT: 452. Replace the pressure relieving device with one with a set pressure no higher than the maximum allowable working pressure as determined by the manufacturer.

Replace safety valve with a Max. set pressure of 125 psi and rated in pressure & temperature (P&T) and shall be ASME Code Stamped.

Location: St Johns Episcopal Church **Location #:** 1832115 **Violations:** 2
1623 Carmel Rd, , Charlotte, NC 28226-5015, Phone: 704-366-3034
Contact: Attn Leslie Davis, Property Steward, St Johns Episcopal Church, Phone: 704-366-3034

Object: NC301709 - Boiler - Peerless - 1996 - Bsmt Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Clay, Steven D.
OPENED: 08/28/2020 **ENTERED BY:** Putek, Terry
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations. Boiler was not running due to control system.
REQUIREMENT: 363. Undefined Boiler Violations. Reschedule the inspection when the weather is cooler and the boiler is running.

Object: NC408472 - Boiler - BFC - 2016 - Chiller Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Clay, Steven D.
OPENED: 11/16/2020 **ENTERED BY:** Putek, Terry
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 04-Pressure Controls NCAC 13-13.0406
SUBCATEGORY 071. Operating pressure control inoperative.
CONDITION: 071. Pressure Controls NCAC 13-13.0406: Operating pressure control inoperative. Boiler would not fire for inspection.
REQUIREMENT: 071. Repair or replace the inoperative pressure control. Test to ensure proper operation.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Location: Statesville Family YMCA **Location #:** 1845601 **Violations:** 5
828 Wesley Dr, , Statesville, NC 28677-3355, Phone: 704-873-9622
Contact: Paxton Hix, Facilities Director, Statesville Family YMCA, , Cell:704-880-4915

Object: NC265007 - Boiler - Reimers - 1993 - Mens Steam Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 12/16/2020 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations. electrical steam generator not operating at time of inspection; safety controls could not be tested to verify proper operation.
REQUIREMENT: 363. Undefined Boiler Violations. Schedule a reinspection at a time when the electric steam generator is operating so that the safety controls may be tested to verify proper operation. As an alternative, a detailed service report or log that includes documentation of the successful testing of these controls is also acceptable.

Object: NC351556 - Boiler - Rheem/Ruud - 2003 - Pool Mech Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 12/16/2020 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 06-Thermometer NCAC 13-13.0410
SUBCATEGORY 111. Thermometer inoperative.
CONDITION: 111. Thermometer NCAC 13-13.0410: Thermometer inoperative.
REQUIREMENT: 111. Replace inoperative thermometer at/in the boiler outlet to measure the temperature in degrees Fahrenheit of the water. The thermometer shall have a range of approximately 2 times the intended operating temperature but not less than 1 1/2 times the intended operating temperature, nor more than 4 times the intended operating temperature.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC351557 - Boiler - Rheem/Ruud - 2003 - Pool Mech Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 12/16/2020 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 06-Thermometer NCAC 13-13.0410
SUBCATEGORY 111. Thermometer inoperative.
CONDITION: 111. Thermometer NCAC 13-13.0410: Thermometer inoperative.
REQUIREMENT: 111. Replace inoperative thermometer at/in the boiler outlet to measure the temperature in degrees Fahrenheit of the water. The thermometer shall have a range of approximately 2 times the intended operating temperature but not less than 1 1/2 times the intended operating temperature, nor more than 4 times the intended operating temperature.

Object: NC380587 - Boiler - Fulton - 2008 - Ladies Steam Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 12/16/2020 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations: electrical steam generator not operating at time of inspection; safety controls could not be tested to verify proper operation.
REQUIREMENT: 363. Undefined Boiler Violations. Schedule a reinspection at a time when the electric steam generator is operating so that the safety controls may be tested to verify proper operation. As an alternative, a detailed service report or log that includes documentation of the successful testing of these controls is also acceptable.

Object: NC409027 - Boiler - Raypak - 2014 - Pool Mech Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 12/16/2020 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 24-Installation of PRDs NCAC 13-13.0405
SUBCATEGORY 381. Incorrect pressure relieving device(s) for the application.
CONDITION: 381. Installation of PRDs NCAC 13-13.0405: Non-temperature and pressure relieving pressure relief device (PRD) installed on HLW stamped pool heater.
REQUIREMENT: 381. Replace the current PRD with an ASME/NB stamped temperature and pressure relieving type PRD having a set pressure of 160 PSI or less and a relieving capacity of 627,000 BTU/Hour or more. The replacement PRD must be equipped with a try-lever and the PRD discharge must be piped full size to a safe location (i.e. within 6" of the mech room floor.)

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Location: Storopack Packaging Systems USA **Location #:** 1839256 **Violations:** 1
2598 Empire Dr Ste G, , Winston Salem, NC 27103-6763, Phone: 336-765-7767
Contact: Attn Anne Ward, Storopack Packaging Systems USA, Phone: 336-765-7767

Object: NC279022 - Boiler - York Shipley - 1987 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 11/19/2020 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409
SUBCATEGORY 006. Low water cutoff device inoperative or bypassed.
CONDITION: 006. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device inoperative or bypassed: Both the primary and secondary low water cutoffs (LWCO) failed to secure the boiler when tested.
REQUIREMENT: 006. REPAIR OR REPLACE THE PRIMARY AND SECONDARY LWCO CONTROLS IN ORDER TO CORRECT THIS CONDITION. ONCE COMPLETE, TEST THE LWCO'S TO VERIFY PROPER OPERATION. IF THE SECONDARY LWCO REQUIRES REPLACEMENT, THE NEW LWCO MUST BE EQUIPPED WITH A MANUAL RESET SWITCH. PLEASE NOTE THAT THIS BOILER SHOULD REMAIN OUT OF SERVICE UNTIL BOTH LWCO CONTROLS ARE WORKING PROPERLY.

Location: Surry Chemicals **Location #:** 1834066 **Violations:** 1
241 Hickory St, , Mount Airy, NC 27030-2211, Phone: 336-786-4607 X17
Contact: Travis Tolbert, Surry Chemicals Inc, Phone: 336-786-4607 X17

Object: NC267195 - Boiler - Fulton - 1994 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 12/15/2020 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 25-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 395. Valve leaking.
CONDITION: 395. Operation of PRDs NCAC 13-13.0405: Valve leaking: Pressure relief device (PRD) leaking.
REQUIREMENT: 395. Replace the leaking PRD with an ASME/NB stamped PRD having a set pressure of 150 PSI or less and a relieving capacity of 2,070 pounds of steam per hour or more. The replacement PRD must be equipped with a try-lever and the PRD discharge must be piped full-size to a safe location (I.E. within 6" of the boiler room floor)

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Location: Tailored Chemical Products **Location #:** 332360 **Violations:** 1
1120 Tate Blvd SE, , Hickory, NC 28602-4025, Phone: 828-324-0149
Contact: Tom Stanek, Plant Manager, Tailored Chemical Products Inc, Phone: 828-324-0149, Cell:940-597-7305

Object: NC363847 - Boiler - Cleaver Brooks - 1994 - Blr Area - Active **Violations This Object:** 1

COMPANY: State of North Carolina
INSPECTOR: Smith, Jeremy
OPENED: 09/08/2020 **ENTERED BY:** Smith, Jeremy
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 4/12/2018.
REQUIREMENT: 363. Undefined Boiler Violations. An external Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.

Location: West German Garage **Location #:** 1842877 **Violations:** 1
5611 Hillsborough St, , Raleigh, NC 27606-1534, Phone: 919-851-1236
Contact: John Elliason, Manager, West German Garage Inc, Phone: 919-851-1236

Object: NC356708 - PV - Manchester - 1999 - Outside - Active **Violations This Object:** 1

COMPANY: State of North Carolina
INSPECTOR: Fish, Emily
OPENED: 10/15/2020 **ENTERED BY:** Fish, Emily
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 09-Pressure Gauges NCAC 13-13.0407
SUBCATEGORY 032. Incorrect range or insufficient pointer travel.
CONDITION: 032. Pressure Gauges NCAC 13-13.0407: Incorrect range or insufficient pointer travel.
REQUIREMENT: 032. Install a pressure gauge on the equipment that is visible to the operator from the floor or work platform. Gauge must be the proper range in accordance with NC Administrative Code, Title 13, Chapter 13, Section .0407. Please call Emily Fish at (919) 268-0725 when ready for reinspection.

Location: Williamson Cleaners **Location #:** 1844175 **Violations:** 1
3711 Peppermill Dr N Ste G, , Wilson, NC 27896-7390, Phone: 252-205-6180
Contact: Attn James Min, Owner, Williamson Cleaners, Phone: 252-237-1828, Cell:336-837-7025

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC342375 - Boiler - Columbia - 2002 - Blr Rm - Active

Violations This Object: 1

COMPANY: State of North Carolina

INSPECTOR: Smith, Jeremy

OPENED: 11/06/2020

ENTERED BY: Smith, Jeremy

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 2/20/2019.

REQUIREMENT: 363. Undefined Boiler Violations. An External Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.

Location: Windsor Point Retirement Community

Location #: 1844569

Violations: 1

1221 Broad St, , Fuquay Varina, NC 27526-3602, Phone: 919-552-4580

Contact: Jimmy Richardson, Maintenance Supervisor, Windsor Point Retirement Community, Phone: 919-552-4580

Object: NC382669 - PV - LTC - 2010 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: SORRENTINO, SEAN

OPENED: 11/13/2020

ENTERED BY: Keyes, Amanda

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 01-Installation

SUBCATEGORY 413. Cracking.

CONDITION: 413. Installation: Cracking.

REQUIREMENT: 413. Repair the cracking. If welding is required, a qualified "R" certificate holder is necessary to perform the work.

Location: Woodmark Originals

Location #: 1223157

Violations: 2

1920 Jarrell St, , High Point, NC 27260-8812, Phone: 336-841-6409

Contact: Attn Bobby Cook, Maintenance Supervisor, Woodmark Originals Inc, Phone: 336-841-6409 X138

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC204705 - Boiler - Riemers - 1985 - Skirting - Active

Violations This Object: 2

COMPANY: Hartford Steam Boiler

INSPECTOR: Leonard, Shannon D.

OPENED: 12/22/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409

SUBCATEGORY 015. Pipe size too small.

CONDITION: 015. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff draining piping size too small.

REQUIREMENT: 015. Replace the improperly sized section of LWCO drainage piping with proper 3/4 black steel pipe.

COMPANY: Hartford Steam Boiler

INSPECTOR: Leonard, Shannon D.

OPENED: 12/22/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 26-Undefined Pressure Relieving Devices Violations

SUBCATEGORY 399. Undefined Pressure Relieving Devices Violations.

CONDITION: 399. Undefined Pressure Relieving Devices Violations. Pressure relief device(PRD) discharge piping improper material.

REQUIREMENT: 399. Undefined Pressure Relieving Devices Violations. Replace the improper PRD discharge piping with proper black steel pipe. The replacement PRD discharge piping must be piped full size to a safe location (I.E. above the floor).

Violations This Report: 112

Locations This Report: 72