

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Location: (ASV CS) Central Office **Location #:** 1775429 **Violations:** 2
85 Mountain St, , Asheville, NC 28801-3854, Phone: 828-350-7000
Contact: Tim Holcombe, Manager, Asheville City Schools, Phone: 828-350-7000/Maint 828-350-6196

Object: NC205160 - Boiler - Weil-McLain - 1982 - Blr Rm - Active **Violations This Object:** 2

COMPANY:	State of North Carolina	
INSPECTOR:	(By Request), the Owner/User	
OPENED:	01/13/2021	ENTERED BY: Putek, Terry
CLOSED:		CLOSED BY:
TYPE:	Certificate Blocking	
CATEGORY:	01-LWCO and Flow Sensing Devices NCAC 13-13.0409	
SUBCATEGORY	005. No provision to test low water cutoff device.	
CONDITION:	005. LWCO and Flow Sensing Devices NCAC 13-13.0409: No provision to test low water cutoff device.	
REQUIREMENT:	005. Equip the low water fuel cutoff device on the boiler with a vertical drain and blow-off valve assembly of not less than 3/4-inch nominal pipe size to allow for flushing and testing of the low water cutoff while the boiler is in operation.	
COMPANY:	State of North Carolina	
INSPECTOR:	(By Request), the Owner/User	
OPENED:	01/13/2021	ENTERED BY: Putek, Terry
CLOSED:		CLOSED BY:
TYPE:	Certificate Blocking	
CATEGORY:	24-Installation of PRDs NCAC 13-13.0405	
SUBCATEGORY	372. Set pressure too high.	
CONDITION:	372. Installation of PRDs NCAC 13-13.0405: Set pressure too high. Mawp is 50 psi and SV #1 is 75 psi.	
REQUIREMENT:	372. Replace the pressure relieving device with one with a set pressure no higher than the maximum allowable working pressure as determined by the manufacturer.	

Location: (ASV CS) Claxton Elem **Location #:** 1777561 **Violations:** 3
241 Merrimon Ave, , Asheville, NC 28801-1217, Phone: 828-350-6500
Contact: Tim Holcombe, Manager, Asheville City Schools, Phone: 828-350-7000/Maint 828-350-6196

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC262601 - Boiler - Weil-McLain - 1993 - Bsmt - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Possidente, James

OPENED: 01/13/2021

ENTERED BY: Putek, Terry

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409

SUBCATEGORY 005. No provision to test low water cutoff device.

CONDITION: 005. LWCO and Flow Sensing Devices NCAC 13-13.0409: No provision to test low water cutoff device.

REQUIREMENT: 005. Equip the low water fuel cutoff device on the boiler with a vertical drain and blow-off valve assembly of not less than 3/4-inch nominal pipe size to allow for flushing and testing of the low water cutoff while the boiler is in operation.

Object: NC262602 - Boiler - Weil-McLain - 1993 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Possidente, James

OPENED: 01/13/2021

ENTERED BY: Putek, Terry

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409

SUBCATEGORY 005. No provision to test low water cutoff device.

CONDITION: 005. LWCO and Flow Sensing Devices NCAC 13-13.0409: No provision to test low water cutoff device.

REQUIREMENT: 005. Equip the low water fuel cutoff device on the boiler with a vertical drain and blow-off valve assembly of not less than 3/4-inch nominal pipe size to allow for flushing and testing of the low water cutoff while the boiler is in operation.

Object: NC388477 - PV - Lochinvar - 2006 - Cafeteria Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Possidente, James

OPENED: 01/13/2021

ENTERED BY: Putek, Terry

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 04-Installation of PRDs NCAC 13-13.0405

SUBCATEGORY 461. Incorrect pressure relieving device(s) for the application.

CONDITION: 461. Installation of PRDs NCAC 13-13.0405: Incorrect pressure relieving device(s) for the application. The current valve is pressure only mounted horizontal.

REQUIREMENT: 461. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

Location: (ASV CS) Ira B Jones Elem

Location #: 1800336

Violations: 1

544 Kimberly Ave, , Asheville, NC 28804-2560, Phone: 828-350-6700

Contact: Tim Holcombe, Manager, Asheville City Schools, Phone: 828-350-7000/Maint 828-350-6196

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC288783 - Boiler - Weil-McLain - 1996 - New Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Possidente, James

OPENED: 01/12/2021

ENTERED BY: Putek, Terry

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409

SUBCATEGORY 005. No provision to test low water cutoff device.

CONDITION: 005. LWCO and Flow Sensing Devices NCAC 13-13.0409: No provision to test low water cutoff device.

REQUIREMENT: 005. Equip the low water fuel cutoff device on the boiler with a vertical drain and blow-off valve assembly of not less than 3/4-inch nominal pipe size to allow for flushing and testing of the low water cutoff while the boiler is in operation. Recommend installing probe type LWCO with test and reset button to allow testing the device.

Location: (ASV CS) Vance Elem

Location #: 1839986

Violations: 1

98 Sulphur Springs Rd, , Asheville, NC 28806-2646, Phone: 828-250-6600

Contact: Tim Holcombe, Manager, Asheville City Schools, Phone: 828-350-7000/Maint 828-350-6196

Object: NC221780 - Boiler - Weil-McLain - 1986 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Possidente, James

OPENED: 01/13/2021

ENTERED BY: Putek, Terry

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409

SUBCATEGORY 005. No provision to test low water cutoff device.

CONDITION: 005. LWCO and Flow Sensing Devices NCAC 13-13.0409: No provision to test low water cutoff device.

REQUIREMENT: 005. Equip the low water fuel cutoff device on the boiler with a vertical drain and blow-off valve assembly of not less than 3/4-inch nominal pipe size to allow for flushing and testing of the low water cutoff while the boiler is in operation.

Location: (DPS-C) Columbus CI - 4355

Location #: 1778917

Violations: 5

1255 Prison Camp Rd, , Whiteville, NC 28472-4887, Phone: 910-642-3285

Contact: NC Dept Of Public Safety - 13101, Phone: 919-716-3422

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC361313 - Boiler - Rbi - 2005 - Elm Dorm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 11/24/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 25-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 395. Valve leaking.
CONDITION: 395. Operation of PRDs NCAC 13-13.0405: Valve leaking: Pressure relief device leaking.
REQUIREMENT: 395. Replace with a ASME/NB certified pressure relief device with a set pressure of not greater than 160 psig, with a relief capacity of not less than 638 KBH, and with a testing lever.

ENTERED BY: Judd, Janie

CLOSED BY:

Object: NC362565 - Boiler - Rbi - 2006 - Fier Dorm - Active

Violations This Object: 2

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 11/24/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 07-Undefined Controls Violations
SUBCATEGORY 112. Undefined Controls Violations.
CONDITION: 112. Undefined Controls Violations. Flow switch leaking.
REQUIREMENT: 112. Undefined Controls Violations: Replace flow switch. Test to verify proper operation.

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 11/24/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 25-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 395. Valve leaking.
CONDITION: 395. Operation of PRDs NCAC 13-13.0405: Valve leaking: Pressure relief device leaking
REQUIREMENT: 395. Replace with a ASME/NB certified pressure relief device with a set pressure of not greater than 160 psig, with a relief capacity of not less than 638 KBH, and with a testing lever installed.

ENTERED BY: Judd, Janie

CLOSED BY:

ENTERED BY: Judd, Janie

CLOSED BY:

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC382455 - Boiler - Cleveland Range - 2010 - Food Service - Active

Violations This Object: 2

COMPANY:	Hartford Steam Boiler		
INSPECTOR:	Rudolph, Jay		
OPENED:	11/24/2020	ENTERED BY:	Judd, Janie
CLOSED:		CLOSED BY:	
TYPE:	Certificate Blocking		
CATEGORY:	03-Water Gauge Glass NCAC 13-13.0408		
SUBCATEGORY	058. Leaking.		
CONDITION:	058. Water Gauge Glass NCAC 13-13.0408: Leaking.		
REQUIREMENT:	058. Repair or replace the leaking gauge and test to ensure proper operation.		
COMPANY:	Hartford Steam Boiler		
INSPECTOR:	Rudolph, Jay		
OPENED:	11/24/2020	ENTERED BY:	Judd, Janie
CLOSED:		CLOSED BY:	
TYPE:	Certificate Blocking		
CATEGORY:	25-Operation of PRDs NCAC 13-13.0405		
SUBCATEGORY	395. Valve leaking.		
CONDITION:	395. Operation of PRDs NCAC 13-13.0405: Valve leaking: Pressure relief device leaking.		
REQUIREMENT:	395. Replace with a ASME/NB certified pressure relief device with a set pressure of not greater than 15 psig, with a relief capacity of not less than 266 PPH, and with a testing lever installed.		

Location: (DPS-C) NCCIW - 3010

Location #: 1779964

Violations: 2

1034 Bragg St, , Raleigh, NC 27610-3846, Phone: 919-733-4340

Contact: Phillip Jones, Maintenance Supervisor, NCCIW - 3010, Phone: 919-508-1690

Object: NC381483 - Boiler - PVI Industries - 2010 - Falcom Blr Rm - Active

Violations This Object: 1

COMPANY:	Hartford Steam Boiler		
INSPECTOR:	SORRENTINO, SEAN		
OPENED:	12/08/2020	ENTERED BY:	Keyes, Amanda
CLOSED:		CLOSED BY:	
TYPE:	Certificate Blocking		
CATEGORY:	16-Boiler Components		
SUBCATEGORY	270. Water Leaks.		
CONDITION:	270. Boiler Components: Water Leaks.		
REQUIREMENT:	270. Repair the water leaks identified on the inspection report. If welding is required, a qualified "R" certificate holder is necessary to perform the repair.		

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC401596 - Boiler - PVI Industries - 2014 - Sparrow N - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: SORRENTINO, SEAN
OPENED: 12/08/2020 **ENTERED BY:** Keyes, Amanda
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 16-Boiler Components
SUBCATEGORY 270. Water Leaks.
CONDITION: 270. Boiler Components: Water Leaks. Tank leaking at unknown location.
REQUIREMENT: 270. Repair the water leaks identified on the inspection report. If welding is required, a qualified "R" certificate holder is necessary to perform the repair.

Location: (DPS-C) Piedmont CI - 3500 **Location #:** 1819170 **Violations:** 4
1245 Camp Rd, , Salisbury, NC 28147-9233, Phone: 704-639-7540
Contact: NC Dept Of Public Safety - 13101, Phone: 919-716-3422

Object: NC183471 - Boiler - Kewanee - 1977 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 02/08/2021 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 25-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 395. Valve leaking.
CONDITION: 395. Operation of PRDs NCAC 13-13.0405: Valve leaking: Both pressure relief devices (PRD) leaking.
REQUIREMENT: 395. Replace both leaking PRD's with ASME/NB stamped PRD's having a set pressure of 150 PSI or less and a total combined relieving capacity of 10000 pounds of steam per hour or more.

Object: NC183472 - Boiler - Kewanee - 1977 - Blr Rm - Active **Violations This Object:** 3

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 02/08/2021 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 17-Baffles and/or Refractory
SUBCATEGORY 293. Out of place.
CONDITION: 293. Baffles and/or Refractory: Refractory damage near burner, material displaced.
REQUIREMENT: 293. Repair/replace the displaced refractory material adjacent to the burner in order to correct his condition.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 02/08/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 25-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 395. Valve leaking.
CONDITION: 395. Operation of PRDs NCAC 13-13.0405: Valve leaking: Both pressure relief devices (PRD's) leaking.
REQUIREMENT: 395. Replace both leaking PRD's with ASME/NB stamped PRD's having a set pressure of 150 PSI or less and a total combined relieving capacity of 10000 pounds of steam per hour or more.

ENTERED BY: Judd, Janie

CLOSED BY:

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 02/08/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 25-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 395. Valve leaking.
CONDITION: 395. Operation of PRDs NCAC 13-13.0405: Valve leaking: Both pressure relief devices (PRD's) leaking.
REQUIREMENT: 395. Replace both leaking PRD's with ASME/NB stamped PRD's having a set pressure of 150 PSI or less and a total combined relieving capacity of 10000 pounds of steam per hour or more.

ENTERED BY: Judd, Janie

CLOSED BY:

Location: (LEE) O T Sloan Park
1420 Bragg St, , Sanford, NC 27330-5435, Phone: 919-775-2107
Contact: Attn Russell Spivey, Lee County Government General Services, Phone: 919-718-4622
Location #: 1815639
Violations: 2
Object: NC419417 - Boiler - Teledyne Laars - 2017 - Outside pool house - Active
Violations This Object: 1

COMPANY: State of North Carolina
INSPECTOR: Gunto III, Andrew
OPENED: 10/20/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations.
At the time of the 10/20/2020 inspection, this boiler was not in operation.
REQUIREMENT: 363. Undefined Boiler Violations.
At follow up inspection the boiler must be firing, and an operational demonstration will be need. This includes the verification of the high-limit temperature controls and its manual reset.

ENTERED BY: Gunto III, Andrew

CLOSED BY:

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC419418 - Boiler - Teledyne Laars - 2017 - Outside pool house - **Violations This Object:** 1
Active

COMPANY:	State of North Carolina	
INSPECTOR:	Gunto III, Andrew	
OPENED:	10/20/2020	ENTERED BY: Gunto III, Andrew
CLOSED:		CLOSED BY:
TYPE:	Certificate Blocking	
CATEGORY:	23-Undefined Boiler Violations	
SUBCATEGORY	363. Undefined Boiler Violations.	
CONDITION:	363. Undefined Boiler Violations. At the time of the 10/20/2020 inspection, this boiler was not in operation.	
REQUIREMENT:	363. Undefined Boiler Violations. At follow up inspection the boiler must be firing, and an operational demonstration will be need. This includes the verification of the high-limit temperature controls and its manual reset.	

Location: (NCCU) Heating Plant **Location #:** 1796457 **Violations:** 1
1801 Fayetteville St, , Durham, NC 27707-3129, Phone: 919-530-6313
Contact: Attn Lori Blake Reid PO #P107428, NC Central University Shephard Station, Phone: 919-530-7244

Object: NC293050 - Boiler - Babcock & Wilcox - 1998 - Blr House Blr 1 - **Violations This Object:** 1
Active

COMPANY:	Hartford Steam Boiler	
INSPECTOR:	SORRENTINO, SEAN	
OPENED:	11/18/2020	ENTERED BY: Keyes, Amanda
CLOSED:		CLOSED BY:
TYPE:	Certificate Blocking	
CATEGORY:	23-Undefined Boiler Violations	
SUBCATEGORY	363. Undefined Boiler Violations.	
CONDITION:	363. The boiler was not operating during this inspection per Sean Sorrentino inspection report.	
REQUIREMENT:	363. You must operate this boiler for external inspection per Sean Sorrentino inspection report.	

Location: (NCDOT) Highway Div 12 Equipment Office **Location #:** 1782980 **Violations:** 2
1710 E Marion St, , Shelby, NC 28152-6259, Phone: 704-480-9020
Contact: Attn Jennifer Savage, Accounting, NC Dept Of Transportation, Phone: 919-835-8002

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC337945 - Boiler - Peerless - 2002 - Blr Rm - Active

Violations This Object: 2

COMPANY: Hartford Steam Boiler

INSPECTOR: Possidente, James

OPENED: 12/15/2020

ENTERED BY: Putek, Terry

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 13-Burners and Fuel Supply Systems

SUBCATEGORY 232. Gas train has improper venting.

CONDITION: 232. Burners and Fuel Supply Systems: Gas train has improper venting.

REQUIREMENT: 232. Vent the gas train to a safe point .

COMPANY: Hartford Steam Boiler

INSPECTOR: Possidente, James

OPENED: 12/15/2020

ENTERED BY: Putek, Terry

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 26-Undefined Pressure Relieving Devices Violations

SUBCATEGORY 399. Undefined Pressure Relieving Devices Violations.

CONDITION: 399. Undefined Pressure Relieving Devices Violations. Pressure relief valve improper installation. Horizontal configuration.

REQUIREMENT: 399. Undefined Pressure Relieving Devices Violations. Reinstall pressure relief valve so the valve stem is in vertical position. The discharge must be piped full size to point of discharge.

Location: (NEW HANOVER) County Landfill

Location #: 1814354

Violations: 1

5210 US Highway 421 N, , Wilmington, NC 28401-2252, Phone: 910-815-3579

Contact: Attn Sam Hawes, New Hanover County Landfill, Phone: 910-815-3579

Object: NC282162 - PV - Buckeye - 1987 - Comp Shed - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 02/23/2021

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 07-Undefined Pressure Vessels Violations

SUBCATEGORY 479. Undefined Pressure Vessels Violations.

CONDITION: 479. Undefined Pressure Vessels Violations: Pressure gage inoperable.

REQUIREMENT: 479. Replace pressure gage. Range on gage must be approximately 2 times the intended operating pressure, however it shall not be less than 1.5 times the intended operating pressure nor more than 4 times the intended operating pressure.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Location: (SMS) Cruikshank Hall **Location #:** 1781296 **Violations:** 1

900 Hillsborough St, , Raleigh, NC 27603-1610, Phone: 919-424-4132

Contact: Attn Eric Poss, Director of Facilities, Saint Marys School, Phone: 919-424-4132

Object: NC384766 - Boiler - A O Smith - 2010 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 01/28/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 16-Boiler Components

SUBCATEGORY 270. Water Leaks.

CONDITION: 270. Boiler Components: Water Leaks.

REQUIREMENT: 270. Determine location of leak and repair. If weld repair is required "R" stamp certificate holder is required to perform repair.

Location: (SMS) Natatorium Pool **Location #:** 1832204 **Violations:** 1

900 Hillsborough St, , Raleigh, NC 27603-1610, Phone: 919-424-4132

Contact: Attn Eric Poss, Director of Facilities, Saint Marys School, Phone: 919-424-4132

Object: NC361042 - Boiler - Teledyne Laars - 2006 - Outside Pool - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 01/28/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 25-Operation of PRDs NCAC 13-13.0405

SUBCATEGORY 393. Valve stem distorted/bent.

CONDITION: 393. Operation of PRDs NCAC 13-13.0405: Pressure Relief Device Valve stem distorted/bent.

REQUIREMENT: 393. Repair or replace relief device. Pressure relief device must be ASME/NB certified with a set pressure of not greater than 160 psig, with a relief capacity of at least 780,000 Btu/hr and have a testing lever.

Location: (UNC-CH) George M Horton Res Hall-136 **Location #:** 1900509 **Violations:** 1

411 Skipper Bowles Dr, , Chapel Hill, NC 27514-3434, Phone: 919-962-1271

Contact: Attn Lawrence Peoples, Manager, UNC Chapel Hill - Giles Horney Bldg 168, Phone: 919-843-8771

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC363063 - PV - Cemline - 2005 - Mech Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: SORRENTINO, SEAN

OPENED: 07/31/2020

ENTERED BY: Keyes, Amanda

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 05-Operation of PRDs NCAC 13-13.0405

SUBCATEGORY 475. Valve leaking.

CONDITION: 475. Operation of PRDs NCAC 13-13.0405: Valve leaking.

REQUIREMENT: 475. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

Location: (UNC-CH) Rams Head Dining Ctr-390

Location #: 1900378

Violations: 1

104 Ridge Rd, , Chapel Hill, NC 27514-4387, Phone: (919)843-8771

Contact: Attn Lawrence Peoples, Manager, UNC Chapel Hill - Giles Horney Bldg 168, Phone: 919-843-8771

Object: NC357411 - PV - Cemline - 2004 - Mech Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: SORRENTINO, SEAN

OPENED: 07/14/2020

ENTERED BY: Keyes, Amanda

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 05-Operation of PRDs NCAC 13-13.0405

SUBCATEGORY 474. Valve inoperative.

CONDITION: 474. Operation of PRDs NCAC 13-13.0405: Valve inoperative.

REQUIREMENT: 474. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

Location: (UNCC) Regional Utility Plt 1

Location #: 1930002

Violations: 1

9201 University City Blvd, , Charlotte, NC 28223-0001, Phone: 704-687-6993

Contact: Attn Kelly Herron, UNC Charlotte, Phone: 704-687-0567

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC328646 - Boiler - Hurst - 2002 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Clay, Steven D.

OPENED: 02/10/2021

ENTERED BY: Putek, Terry

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 16-Boiler Components

SUBCATEGORY 275. Tube/tube ends leak.

CONDITION: 275. Boiler Components: Tube/tube ends leak. Boiler is down for repairs.

REQUIREMENT: 275. Repair the leaking tubes/tube ends. If weld repairs are required, a qualified "R" certificate holder is necessary to perform the work.

Location: (UNCC) Student Activity Center

Location #: 1929965

Violations: 1

9201 University City Blvd, , Charlotte, NC 28223-0001, Phone: 704-687-6993

Contact: Attn Kelly Herron, UNC Charlotte, Phone: 704-687-0567

Object: NC305359 - Boiler - Teledyne Laars - 1995 - 3rd Level - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Clay, Steven D.

OPENED: 02/10/2021

ENTERED BY: Putek, Terry

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409

SUBCATEGORY 003. Required manual reset low water cutoff device not installed.

CONDITION: 003. LWCO and Flow Sensing Devices NCAC 13-13.0409: Required manual reset low water cutoff device not installed.

REQUIREMENT: 003. Install a low-water fuel cutoff device (LWCO) designed for the appropriate service (Steam or Hot Water) that is equipped with a manual reset; or install a manual reset on the existing low water fuel cutoff if appropriate. When the LWCO shuts off the fuel supply to the boiler in the event of a low water condition, the fuel supply must be restarted manually by an operator. Test to ensure proper operation.

Location: (UNCC) Woodward Hall Science & Technology Bldg

Location #: 1827561

Violations: 1

9201 University City Blvd, , Charlotte, NC 28223-0001, Phone: 704-687-6993

Contact: Attn Kelly Herron, UNC Charlotte, Phone: 704-687-0567

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC428980 - Boiler - Chromalox - 2020 - Vivarium Blr Rm - Active **Violations This Object:** 1

COMPANY: State of North Carolina
INSPECTOR: Snuffer, Jimmy
OPENED: 02/02/2021 **ENTERED BY:** Snuffer, Jimmy
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 13-Burners and Fuel Supply Systems
SUBCATEGORY 235. No emergency fuel shut off switch.
CONDITION: 235. Burners and Fuel Supply Systems: No emergency fuel shut off switch.
REQUIREMENT: 235. Install an emergency fuel shut off switch at each egress from the boiler room to shut off all fuel to the boilers.

Location: (UNCW) Education Bldg **Location #:** 1842184 **Violations:** 1
970 Reynolds Dr, , Wilmington, NC 28403-3201, Phone: 910-962-3102
Contact: Attn Ellen Boyd, UNC Wilmington, Phone: 910-962-3102

Object: NC410372 - Boiler - Fulton - 2016 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 01/26/2021 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 12-Casing, Stack Breeching and Flue
SUBCATEGORY 211. Combustion gas leaks.
CONDITION: 211. Casing, Stack Breeching and Flue: Combustion gas leaks.
REQUIREMENT: 211. Repair all combustion gas leaks in the casing, stack breeching, or flue.

Location: (WFU) Biotech Place **Location #:** 3012653 **Violations:** 5
575 Patterson Ave, , Winston Salem, NC 27101-4101, Phone: 336-758-3488
Contact: Attn Jimmy Nifong, Utilities Manager, Wake Forest University, Phone: 336-758-3332, Cell:336-757-6628

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC388001 - PV - Getinge - 2011 - Rm 2E-047 - Active

Violations This Object: 1

COMPANY: State of North Carolina
INSPECTOR: Parker, Richard
OPENED: 02/17/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 05-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 474. Valve inoperative.
CONDITION: 474. Operation of PRDs NCAC 13-13.0405: Valve inoperative.
REQUIREMENT: 474. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

ENTERED BY: Parker, Richard

CLOSED BY:

contact Richard Parker @ 336-202-8341

Object: NC388006 - PV - Getinge - 2011 - Rm 2E-047 - Active

Violations This Object: 1

COMPANY: State of North Carolina
INSPECTOR: Parker, Richard
OPENED: 02/17/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 05-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 474. Valve inoperative.
CONDITION: 474. Operation of PRDs NCAC 13-13.0405: Valve inoperative.
REQUIREMENT: 474. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

ENTERED BY: Parker, Richard

CLOSED BY:

contact Richard Parker @ 336-202-8341

Object: NC388008 - PV - Getinge - 2011 - Rm 2S-051 - Active

Violations This Object: 1

COMPANY: State of North Carolina
INSPECTOR: Parker, Richard
OPENED: 02/17/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 05-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 474. Valve inoperative.
CONDITION: 474. Operation of PRDs NCAC 13-13.0405: Valve inoperative.
REQUIREMENT: 474. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

ENTERED BY: Parker, Richard

CLOSED BY:

contact Richard Parker @ 336-202-8341

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC388009 - PV - Getinge - 2011 - 1N040 - Active

Violations This Object: 1

COMPANY: State of North Carolina
INSPECTOR: Parker, Richard
OPENED: 02/17/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 05-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 474. Valve inoperative.
CONDITION: 474. Operation of PRDs NCAC 13-13.0405: Valve inoperative.
REQUIREMENT: 474. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

ENTERED BY: Parker, Richard
CLOSED BY:

contact Richard Parker @ 336-202-8341

Object: NC388010 - PV - Getinge - 2011 - 1N021 - Active

Violations This Object: 1

COMPANY: State of North Carolina
INSPECTOR: Parker, Richard
OPENED: 02/17/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 05-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 474. Valve inoperative.
CONDITION: 474. Operation of PRDs NCAC 13-13.0405: Valve inoperative.
REQUIREMENT: 474. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

ENTERED BY: Parker, Richard
CLOSED BY:

contact Richard Parker @ 336-202-8341

Location: (WILKES CS) Central Wilkes Middle

Location #: 2910852

Violations: 1

3541 S NC Highway 16, , Moravian Falls, NC 28654-9860, Phone: 336-667-7453

Contact: Attn Bergi Speaks, Maintenance Director, Wilkes County Schools, Phone: 336-651-4009

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC383464 - PV - A O Smith - 2001 - Cafeteria - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Leonard, Shannon D.

OPENED: 12/10/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 05-Operation of PRDs NCAC 13-13.0405

SUBCATEGORY 475. Valve leaking.

CONDITION: 475. Operation of PRDs NCAC 13-13.0405: Valve leaking: Pressure relief valve leaking.

REQUIREMENT: 475. Replace the leaking PRD with an ASME/NB stamped temperature and pressure relieving type PRD having a set pressure of not greater than 150 PSI and a relieving capacity of not less than 189,000 BTU/Hour. The replacement PRD must be equipped with a try-lever and the PRD discharge must be piped to a safe location (I.E. with 6" of the mech room floor).

Location: (WILKES CS) Wilkes Central High

Location #: 1843922

Violations: 1

1179 Moravian Falls Rd, , Wilkesboro, NC 28697-7636, Phone: 336-667-5277

Contact: Attn Bergi Speaks, Maintenance Director, Wilkes County Schools, Phone: 336-651-4009

Object: NC192411 - Boiler - Weil-McLain - 1980 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Leonard, Shannon D.

OPENED: 12/10/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 25-Operation of PRDs NCAC 13-13.0405

SUBCATEGORY 395. Valve leaking.

CONDITION: 395. Operation of PRDs NCAC 13-13.0405: Pressure relief device (PRD) leaking.

REQUIREMENT: 395. Replace the leaking PRD with an ASME/NB stamped PRD having a set pressure of 50 PSI or less and a relieving capacity of 2,040,000 BTU/Hour or more. The replacement PRD must be equipped with a try-lever and the PRD discharge must be piped full size to a safe location (I.E. with 6" of the boiler room floor).

Location: A Cleaner World #196

Location #: 1761482

Violations: 1

1545 Union Cross Rd, , Kernersville, NC 27284-7536, Phone: 336-996-5141

Contact: Chad Tobin, Manager, A Cleaner World #196, Phone: 336-996-5141

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC363950 - Boiler - Parker - 2006 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Leonard, Shannon D.

OPENED: 02/02/2021

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 09-Bottom Blow and Drain Systems NCAC 13-13.0411

SUBCATEGORY 154. Leaking pipe/pipe joints.

CONDITION: 154. Bottom Blow and Drain Systems NCAC 13-13.0411: Leaking pipe/pipe joints: Leaking T connection on boiler blowdown plumbing.

REQUIREMENT: 154. Replace the leaking section of blowdown plumbing with proper schedule 80 black steel pipe in order to correct this condition.

Location: Aviator Brewing Co

Location #: 3208525

Violations: 1

209 Technology Park Ln, , Fuquay Varina, NC 27526-9311, Phone: 919-567-2337

Contact: Mark Doble, Brew Boss, Aviator Brewing Co, Phone: 919-567-2337, Cell:919-601-5497

Object: NC389917 - Boiler - Columbia - 2011 - Front Corner - Active

Violations This Object: 1

COMPANY: State of North Carolina

INSPECTOR: Fish, Emily

OPENED: 08/20/2020

ENTERED BY: Fish, Emily

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409

SUBCATEGORY 005. No provision to test low water cutoff device.

CONDITION: 005. LWCO and Flow Sensing Devices NCAC 13-13.0409: No provision to test low water cutoff device. Manual reset LWCO could not be tested due to inoperative sight glass.

2/24/2021 Manufacturer giving conflicting information. Owner will continue to try and clarify to correct the issue. Emily Fish

REQUIREMENT: 005. Repair sight glass to functioning state so the LWCO can be safely and accurately tested. Contact Emily Fish at (919) 268-0725 when repairs are complete to schedule reinspection.

Location: Boston Cleaners & Laundry

Location #: 1769786

Violations: 1

2182 N Church St, , Burlington, NC 27217-3004, Phone: 336-226-9803

Contact: Attn Bill Robbins, Boston Cleaners & Laundry, Phone: 336-226-9803

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC371303 - Boiler - Parker - 2007 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Leonard, Shannon D.

OPENED: 12/18/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 03-Water Gauge Glass NCAC 13-13.0408

SUBCATEGORY 058. Leaking.

CONDITION: 058. Water Gauge Glass NCAC 13-13.0408: Leaking.

REQUIREMENT: 058. Repair or replace the leaking gauge and test to ensure proper operation.

Location: Capital Ready Mix Concrete

Location #: 3914731

Violations: 1

512 Three Sisters Rd, , Knightdale, NC 27545-8202, Phone: 919-999-0923

Contact: Attn Joe Kisselburg, Plant Manager, Capital Ready Mix Concrete Llc, Phone: 919-999-0923

Object: NC418986 - Boiler - Columbia - 2017 - Red Bldg - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: SORRENTINO, SEAN

OPENED: 12/03/2020

ENTERED BY: Keyes, Amanda

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409

SUBCATEGORY 001. Low water cutoff device not installed.

CONDITION: 001. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device not installed.

REQUIREMENT: 001. Equip the boiler with a low water fuel cutoff device (LWCO) designed for the appropriate service (Steam or Hot Water) that is equipped with a manual reset. When the LWCO shuts off the fuel supply to the boiler in the event of a low water condition, the fuel supply must be restarted manually by an operator. Test to ensure proper operation.

Location: Chandler Concrete Co

Location #: 1775799

Violations: 1

205 W Academy St, , Asheboro, NC 27203-5650, Phone: 336-626-0856

Contact: Attn Tim Ribelin, Maintenance Manager, Chandler Concrete Co Inc (NC), Phone: 336-226-1181

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC285040 - Boiler - Lochinvar - 1997 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Leonard, Shannon D.

OPENED: 02/09/2021

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 02-Pressure Gauges NCAC 13-13.0407

SUBCATEGORY 033. Inoperative.

CONDITION: 033. Pressure Gauges NCAC 13-13.0407: Inoperative: Combination temperature/pressure gauge inoperative.

REQUIREMENT: 033. Install a new combination temperature/pressure gauge. The replacement gauge must have a maximum temperature/pressure measuring range of not less than 1.5 times nor more than 4 times the normal operating temperature and pressure of the boiler (Boiler max operating temp rated at 250 Deg Fahrenheit; max pressure rate at 160 PSI)

Location: Craft Cleaners

Location #: 1780699

Violations: 1

2129 S Main St, , Winston Salem, NC 27127-3052, Phone: 336-777-8109

Contact: There is no contact information available for this location.

Object: NC321519 - PV - Steam Kat - 1960 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Leonard, Shannon D.

OPENED: 01/28/2021

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 05-Operation of PRDs NCAC 13-13.0405

SUBCATEGORY 475. Valve leaking.

CONDITION: 475. Operation of PRDs NCAC 13-13.0405: Valve leaking: Pressure Relief Device (PRD) leaking.

REQUIREMENT: 475. Replace the leaking PRD with an ASME/NB stamped PRD having a set pressure of 125 PSI or less and a relieving capacity of 863,000 BTU/HOUR or more. The replacement PRD must be equipped with a try-lever and the PRD discharge must be piped full size to a safe location (I.E. within 6" of the boiler room floor).

Location: Foothills Brewing Co

Location #: 1790475

Violations: 1

638 W 4th St, , Winston Salem, NC 27101-2730, Phone: 336-777-3348

Contact: Jamie Bartholomaus, Co-Owner, Foothills Brewing Co, Phone: 336-777-3348

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC283771 - Boiler - Hurst - 1996 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Leonard, Shannon D.

OPENED: 02/19/2021

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations: High limit pressure switch manual reset is inoperative and/or broken.

REQUIREMENT: 363. Undefined Boiler Violations. Repair/replace the high limit pressure switch in order to correct this condition. If replacement is required, the replacement high limit pressure switch must be equipped with a functioning manual reset.

Location: Fortnight Brewing Co

Location #: 3453738

Violations: 1

1006 SW Maynard Rd, , Cary, NC 27511-4385, Phone: 919-244-3675

Contact: David Wilkinson, Owner, Fortnight Brewing Co, Phone: 919-244-3675

Object: NC396517 - Boiler - Rite Engineering - 2012 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: SORRENTINO, SEAN

OPENED: 01/27/2021

ENTERED BY: Keyes, Amanda

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 25-Operation of PRDs NCAC 13-13.0405

SUBCATEGORY 395. Valve leaking.

CONDITION: 395. Operation of PRDs NCAC 13-13.0405: Valve leaking.

REQUIREMENT: 395. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

Location: Fox Apparel

Location #: 883450

Violations: 1

100 Industrial Park Ave, , Asheboro, NC 27205-7324, Phone: 336-629-7641

Contact: Attn Elmer Singleton, Fox Apparel Inc, Phone: 336-629-7641

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC344524 - Boiler - Columbia - 2002 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Leonard, Shannon D.

OPENED: 02/10/2021

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 25-Operation of PRDs NCAC 13-13.0405

SUBCATEGORY 395. Valve leaking.

CONDITION: 395. Operation of PRDs NCAC 13-13.0405: Valve leaking: Pressure relief device (PRD) leaking.

REQUIREMENT: 395. Replace the leaking PRD with an ASME/NB stamped PRD having a set pressure of 150 PSI or less and a relieving capacity of 1725 Pounds of steam per hour or more. The replacement PRD must be equipped with a try-lever and the PRD discharge must be piped full size to a safe location (I.E. within 6" of the boiler room floor)

Location: Fulton Family YMCA

Location #: 1844837

Violations: 1

385 W Hanes Mill Rd, , Winston Salem, NC 27105-9626, Phone: 336-661-1093

Contact: There is no contact information available for this location.

Object: NC412588 - Boiler - Steamist - 2016 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Leonard, Shannon D.

OPENED: 10/21/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. Boiler not operating at time of inspection; could not test safety devices to verify proper operation.

REQUIREMENT: 363. Undefined Boiler Violations. Schedule a follow up inspection at a time when the boiler is operating so that the safety devices may be tested to verify proper operation. As an alternative a detailed service report or boiler log that includes documentation of the successful testing of the safety devices is also acceptable.

Location: Harrys On The Hill Llc

Location #: 1795964

Violations: 1

819 Patton Ave, , Asheville, NC 28806-3618, Phone: 828-252-3821

Contact: Jeff Barrett, Collision Repair Manager, Harrys On The Hill Llc, Phone: 828-252-3821

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC344092 - PV - Penway - 2002 - Outside Rear Body Shop - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Possidente, James
OPENED: 12/09/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 07-Undefined Pressure Vessels Violations
SUBCATEGORY 479. Undefined Pressure Vessels Violations.
CONDITION: 479. Undefined Pressure Vessels Violations. Vessel is out of service but has not been disconnected from all sources of potential energy including electricity.
REQUIREMENT: 479. Undefined Pressure Vessels Violations. Disconnect vessel from electricity and compressed air piping.

Location: High Country Tire & Service Station

Location #: 1797182

Violations: 1

8227 US Highway 441 S, , Sylva, NC 28779-7193, Phone: 828-586-0886

Contact: Attn Mickey & Sam McMahan, Owner, High Country Tire & Service Station, Phone: 828-586-0886

Object: NC390660 - PV - Steel Fab - 2010 - Shop - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Possidente, James
OPENED: 12/08/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 07-Undefined Pressure Vessels Violations
SUBCATEGORY 479. Undefined Pressure Vessels Violations.
CONDITION: 479. Undefined Pressure Vessels Violations. Pressure switch cover missing. 230 volt live wires exposed.
REQUIREMENT: 479. Undefined Pressure Vessels Violations. Install a pressure switch cover.

Location: Hillcrest Convalescent Center

Location #: 1797580

Violations: 1

1417 W Pettigrew St, , Durham, NC 27705-4820, Phone: 919-286-7705

Contact: Attn Ted Smith, Administrator, Hillcrest Convalescent Center, Phone: 919-286-7705, Cell:919-219-0426

Object: NC374967 - Boiler - Munchkin - 2007 - Mech Rm 1120 - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: SORRENTINO, SEAN
OPENED: 02/04/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 24-Installation of PRDs NCAC 13-13.0405
SUBCATEGORY 377. Try lever not installed.
CONDITION: 377. Installation of PRDs NCAC 13-13.0405: Try lever not installed.
REQUIREMENT: 377. Replace the relief valve with one with a try lever. The replacement valve must be ASME/NB certified.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Location: Hudson Building **Location #:** 1799097 **Violations:** 1

118 W State St, , Black Mountain, NC 28711-3419, Phone: 828-669-8711

Contact: Attn J Richard Hudson III, Owner, Hudson Building, Phone: 828-669-8711

Object: NC148875 - Boiler - Burnham - 1975 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Possidente, James

OPENED: 12/10/2020

ENTERED BY: Putek, Terry

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 03-Water Gauge Glass NCAC 13-13.0408

SUBCATEGORY 057. Drain inoperative.

CONDITION: 057. Water Gauge Glass NCAC 13-13.0408: Drain inoperative. Sight glass drain inoperative because sight glass is upside down.

REQUIREMENT: 057. Repair or replace the inoperable drain valve on the gauge and test to ensure proper operation.

Location: Kernersville Family YMCA **Location #:** 1845634 **Violations:** 2

1113 W Mountain St, , Kernersville, NC 27284-2125, Phone: 336-996-2231

Contact: There is no contact information available for this location.

Object: NC399650 - Boiler - Stemist - 2013 - Suana - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Leonard, Shannon D.

OPENED: 10/14/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. Boiler not operating at time of inspection; low water cutoff (LWCO) and pressure relief device (PRD) could not be tested to verify proper operation.

REQUIREMENT: 363. Undefined Boiler Violations. Schedule a reinspection at a time when the boiler is operating so that the LWCO and PRD may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the flow switch and PRD is also acceptable.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC418867 - Boiler - Teledyne Laars - 1998 - Hot Tub Wtr Htr - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Leonard, Shannon D.

OPENED: 10/14/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. Boiler not operating at time of inspection; flow switch and pressure relief device (PRD) could not be tested to verify proper operation.

REQUIREMENT: 363. Undefined Boiler Violations. Schedule a reinspection at a time when the boiler is operating so that the flow switch and PRD may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the flow switch and PRD is also acceptable.

Location: Lil Donnie Walkers Car Wash

Location #: 1806163

Violations: 1

1246 S Main St, , Graham, NC 27253-4537, Phone: 336-222-1950

Contact: Attn Pete Walker, Owner, SPG Inc, Phone: 336-222-1950, Cell:336 451 0507

Object: NC294925 - Boiler - Raypak - 1999 - Mech Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Leonard, Shannon D.

OPENED: 11/30/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409

SUBCATEGORY 006. Low water cutoff device inoperative or bypassed.

CONDITION: 006. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device inoperative or bypassed.

REQUIREMENT: 006. Repair or replace the inoperable low water fuel cutoff control and test to ensure proper operation.

Location: Marriott Springhill Suites

Location #: 2443065

Violations: 2

12325 Johnston Rd, , Charlotte, NC 28277-3689, Phone: 704-817-1500

Contact: Sree Ballantyne Llc, Phone: 704-817-1500

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC374594 - Boiler - Munchkin - 2008 - Wtr Htr Rm 1st Flr - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Clay, Steven D.
OPENED: 01/28/2021 **ENTERED BY:** Putek, Terry
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 24-Installation of PRDs NCAC 13-13.0405
SUBCATEGORY 372. Set pressure too high.
CONDITION: 372. Installation of PRDs NCAC 13-13.0405: Set pressure too high. Mawp is 30 psi and SV #1 is 150 psi.
REQUIREMENT: 372. Replace the pressure relieving device with one with a set pressure no higher than the maximum allowable working pressure as determined by the manufacturer.

Object: NC374595 - Boiler - Munchkin - 2008 - Wtr Htr Rm 1st Flr - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Clay, Steven D.
OPENED: 01/28/2021 **ENTERED BY:** Putek, Terry
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 24-Installation of PRDs NCAC 13-13.0405
SUBCATEGORY 372. Set pressure too high.
CONDITION: 372. Installation of PRDs NCAC 13-13.0405: Set pressure too high. Mawp is 30 psi and SV #1 is 125 psi.
REQUIREMENT: 372. Replace the pressure relieving device with one with a set pressure no higher than the maximum allowable working pressure as determined by the manufacturer.

Location: MEE Cleaners **Location #:** 1762243 **Violations:** 1
1226 NW Maynard Rd, , Cary, NC 27513-8719, Phone: 919-380-1713
Contact: Attn Soo Cho, Manager/Owner, MEE Cleaners, Phone: 919-380-1713

Object: NC297120 - Boiler - Hurst - 1999 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: SORRENTINO, SEAN
OPENED: 01/27/2021 **ENTERED BY:** Keyes, Amanda
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 12-Casing, Stack Breeching and Flue
SUBCATEGORY 211. Combustion gas leaks.
CONDITION: 211. Casing, Stack Breeching and Flue: Combustion gas leaks.
REQUIREMENT: 211. Repair all combustion gas leaks in the casing, stack breeching, or flue.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Location: Mt Hope United Church Of Christ **Location #:** 1812482 **Violations:** 2
2400 Mount Hope Church Rd, , Whitsett, NC 27377-9750, Phone: 336-697-1561
Contact: There is no contact information available for this location.

Object: NC399199 - Boiler - Giannoni - 2008 - Bsmt Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 12/01/2020 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations. Boiler not operating at time of inspection; flow switch and pressure relief device (PRD) could not be tested to verify proper operation.

REQUIREMENT: 363. Undefined Boiler Violations. Schedule a reinspection at a time when the boiler is operating so that the flow switch and PRD may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the flow switch and PRD is also acceptable.

Object: NC399200 - Boiler - Giannoni - 2009 - Bsmt Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 12/01/2020 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations. Boiler not operating at time of inspection; flow switch and pressure relief device (PRD) could not be tested to verify proper operation.

REQUIREMENT: 363. Undefined Boiler Violations. Schedule a reinspection at a time when the boiler is operating so that the flow switch and PRD may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the flow switch and PRD is also acceptable.

Location: MVP Group International **Location #:** 868307 **Violations:** 2
430 Gentry Rd, , Elkin, NC 28621-9241, Phone: 336-527-2281
Contact: Attn Don Taylor, Maintenance Manager, MVP Group International, Phone: 336-835-6020 X2235, Cell:336-

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC241785 - Boiler - Kewanee - 1990 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Leonard, Shannon D.

OPENED: 02/01/2021

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409

SUBCATEGORY 012. Flow switch inoperative or bypassed.

CONDITION: 012. LWCO and Flow Sensing Devices NCAC 13-13.0409: Secondary low water cutoff inoperative LWCO switch sticking during testing due to issue with switch internal components or float.

REQUIREMENT: 012. Repair/replace the secondary LWCO switch in order to correct this condition. If replacement is required the replacement LWCO must be equipped with a required manual reset. Once complete, test the LWCO to ensure proper operation.

Object: NC263703 - PV - Steel Fab - 1993 - Rotary Area - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Leonard, Shannon D.

OPENED: 02/01/2021

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 04-Installation of PRDs NCAC 13-13.0405

SUBCATEGORY 453. Inlet pipe too small.

CONDITION: 453. Installation of PRDs NCAC 13-13.0405: Pressure relief device (PRD) inlet connection on one of the two PRD has been reduced and is too small.

REQUIREMENT: 453. Replace the improperly sized PRD Inlet piping between the air tank and the PRD inlet opening. The replacement inlet plumbing must be piped full size and have the same cross sectional area as the PRD inlet opening.

Location: National Guard Armory

Location #: 1813595

Violations: 1

1935 N Church St, , Burlington, NC 27217-2926, Phone: 336-227-7859

Contact: Attn Major Blane Boyd, Director of Facility Maintenance, Joint Forces HQ, Phone: 919-664-6094

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC389334 - Boiler - Lochinvar - 2011 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Leonard, Shannon D.

OPENED: 09/02/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations: Boiler not operating at time of inspection; pressure relief device and flow switch could not be tested to verify proper operation.

REQUIREMENT: 363. SCHEDULE A REINSPECTION AT A TIME WHEN THE BOILER IS OPERATING SO THAT THE PRESSURE RELIEF DEVICE AND FLOW SWITCH MAY BE TESTED TO VERIFY PROPER OPERATION. AS AN ALTERNATIVE, A DETAILED SERVICE REPORT OR BOILER LOG THAT INCLUDES DOCUMENTATION OF THE SUCCESSFUL TESTING OF THESE CONTROLS IS ALSO ACCEPTABLE

Location: National Guard Armory

Location #: 1813513

Violations: 2

292 NC Highway 65, , Reidsville, NC 27320-8897, Phone: 336-349-4428

Contact: Lee Lewis, National Guard Armory, Phone: 984-664-8009

Object: NC425270 - Boiler - Lochinvar - 2018 - Blr Rm - Active

Violations This Object: 1

COMPANY: State of North Carolina

INSPECTOR: Parker, Richard

OPENED: 04/08/2020

ENTERED BY: Parker, Richard

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 25-Operation of PRDs NCAC 13-13.0405

SUBCATEGORY 391. Discharge piping not properly supported.

CONDITION: 391. Operation of PRDs NCAC 13-13.0405: Discharge piping not properly supported.

REQUIREMENT: 391. Support the relief valve discharge piping so it may not impose excessive stress on the relief valve.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC425271 - Boiler - Lochinvar - 2018 - Blr Rm - Active

Violations This Object: 1

COMPANY: State of North Carolina

INSPECTOR: Parker, Richard

OPENED: 04/08/2020

ENTERED BY: Parker, Richard

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 25-Operation of PRDs NCAC 13-13.0405

SUBCATEGORY 391. Discharge piping not properly supported.

CONDITION: 391. Operation of PRDs NCAC 13-13.0405: Discharge piping not properly supported.

REQUIREMENT: 391. Support the relief valve discharge piping so it may not impose excessive stress on the relief valve.

contact Richard Parker @ 336-202-8341

Location: National Guard Armory

Location #: 1813518

Violations: 2

3515 Armory Dr, , High Point, NC 27260-6101, Phone: 336-886-4724

Contact: SFC Michael Oliver, National Guard Armory, Phone: 984-661-1301

Object: NC389824 - Boiler - Lochinvar - 2012 - Blr Rm - Active

Violations This Object: 1

COMPANY: State of North Carolina

INSPECTOR: Johnson, Dean

OPENED: 01/28/2021

ENTERED BY: Johnson, Dean

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 02-Pressure Gauges NCAC 13-13.0407

SUBCATEGORY 031. Out of calibration.

CONDITION: 031. Pressure Gauges NCAC 13-13.0407: Pressure temperature gauge is out of calibration.

REQUIREMENT: 031. Install a pressure temperature gauge having a dial range of at least 1.5 to 4 times the operating pressure and temperature.

Object: NC389825 - Boiler - Lochinvar - 2012 - Blr Rm - Active

Violations This Object: 1

COMPANY: State of North Carolina

INSPECTOR: Johnson, Dean

OPENED: 01/28/2021

ENTERED BY: Johnson, Dean

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 02-Pressure Gauges NCAC 13-13.0407

SUBCATEGORY 031. Out of calibration.

CONDITION: 031. Pressure Gauges NCAC 13-13.0407: Pressure temperature gauge is out of calibration.

REQUIREMENT: 031. Install a pressure temperature gauge having a dial range of at least 1.5 to 4 times the operating pressure and temperature.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Location: Paul J Rizzo Conference Center **Location #:** 1817817 **Violations:** 1
150 Dubose Home Ln, , Chapel Hill, NC 27517-8944, Phone: 919-913-2098

Contact: There is no contact information available for this location.

Object: NC364029 - Boiler - Lochinvar - 2006 - Outside Dubose House - **Violations This Object:** 1
Active

COMPANY:	Hartford Steam Boiler	
INSPECTOR:	Ollison, Jr., James C.	
OPENED:	06/11/2020	ENTERED BY: Keyes, Amanda
CLOSED:		CLOSED BY:
TYPE:	Certificate Blocking	
CATEGORY:	25-Operation of PRDs NCAC 13-13.0405	
SUBCATEGORY	396. Missing nameplate.	
CONDITION:	396. Operation of PRDs NCAC 13-13.0405: Missing nameplate.	
REQUIREMENT:	396. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.	

Location: Professional Rental Services **Location #:** 1821288 **Violations:** 1
220 Frederick St, , Mount Airy, NC 27030-5602, Phone: 336-786-6148

Contact: Attn Mark Wilson, Maintenance, Professional Rental Services, Phone: 336-786-6148, Cell:336-755-7699

Object: NC345478 - Boiler - Hurst - 2002 - Blr Rm - Active **Violations This Object:** 1

COMPANY:	Hartford Steam Boiler	
INSPECTOR:	Leonard, Shannon D.	
OPENED:	01/15/2021	ENTERED BY: Judd, Janie
CLOSED:		CLOSED BY:
TYPE:	Certificate Blocking	
CATEGORY:	23-Undefined Boiler Violations	
SUBCATEGORY	363. Undefined Boiler Violations.	
CONDITION:	363. Undefined Boiler Violations: Boiler not operating at time of inspection; low water cutoff (LWCO) and pressure relief device (PRD) could not be tested to verify proper operation.	
REQUIREMENT:	363. Undefined Boiler Violations: Schedule a inspection of this boiler at a time when it is operating so that the LWCO's and PRD may be tested to verify proper operation. As an alternative, a detailed service report or boiler log that includes documentation of the successful testing of these controls is also acceptable.	

Location: Salem Academy & College **Location #:** 1826678 **Violations:** 1
601 S Church St, , Winston Salem, NC 27101-5318, Phone: 336-345-6769

Contact: There is no contact information available for this location.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC210417 - Boiler - Kewanee - 1983 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Leonard, Shannon D.

OPENED: 02/23/2021

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 10-Feedwater, Condensate/Rtrn Sys NCAC 13-13.0411

SUBCATEGORY 173. Leaking pipe/pipe joints.

CONDITION: 173. Feedwater, Condensate/Rtrn Sys NCAC 13-13.0411: Leaking pipe/pipe joints: Leak at union on feed water plumbing.

REQUIREMENT: 173. Replace the leaking plumbing connections with proper schedule 80 steel pipe in order to correct this condition.

Location: Statesville Family YMCA

Location #: 1845601

Violations: 2

828 Wesley Dr, , Statesville, NC 28677-3355, Phone: 704-873-9622

Contact: Paxton Hix, Facilities Director, Statesville Family YMCA, , Cell:704-880-4915

Object: NC265007 - Boiler - Reimers - 1993 - Mens Steam Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Leonard, Shannon D.

OPENED: 12/16/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. electrical steam generator not operating at time of inspection; safety controls could not be tested to verify proper operation.

REQUIREMENT: 363. Undefined Boiler Violations. Schedule a reinspection at a time when the electric steam generator is operating so that the safety controls may be tested to verify proper operation. As an alternative, a detailed service report or log that includes documentation of the successful testing of these controls is also acceptable.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC380587 - Boiler - Fulton - 2008 - Ladies Steam Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 12/16/2020 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations: electrical steam generator not operating at time of inspection; safety controls could not be tested to verify proper operation.
REQUIREMENT: 363. Undefined Boiler Violations. Schedule a reinspection at a time when the electric steam generator is operating so that the safety controls may be tested to verify proper operation. As an alternative, a detailed service report or log that includes documentation of the successful testing of these controls is also acceptable.

Location: Sterilelink Inc **Location #:** 3810293 **Violations:** 1
3036 Forest Park Dr, , Randleman, NC 27317-7471, Phone: 336-254-2266
Contact: Attn David Wright, Sterilelink Inc, Phone: 336-254-2266

Object: NC413585 - Boiler - Chromalox - 2002 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 01/20/2021 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations. Boiler not operating at time of inspection: Safety devices could not be tested to verify proper operation
REQUIREMENT: 363. Undefined Boiler Violations. Schedule a reinspection at a time when the electric steam generator is operating so that the safety devices may be tested to verify proper operation. As an alternative, a detailed service report or boiler log that includes proper documentation of the successful testing of these controls is also acceptable.

Location: Tailored Chemical Products **Location #:** 332360 **Violations:** 1
1120 Tate Blvd SE, , Hickory, NC 28602-4025, Phone: 828-324-0149
Contact: Tom Stanek, Plant Manager, Tailored Chemical Products Inc, Phone: 828-324-0149, Cell:940-597-7305

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC363847 - Boiler - Cleaver Brooks - 1994 - Blr Area - Active **Violations This Object:** 1

COMPANY: State of North Carolina
INSPECTOR: Smith, Jeremy
OPENED: 09/08/2020 **ENTERED BY:** Smith, Jeremy
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 4/12/2018.
REQUIREMENT: 363. Undefined Boiler Violations. An external Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.

Location: Thomas Tire & Automotive #2 **Location #:** 1836097 **Violations:** 1
829 S Fayetteville St, , Asheboro, NC 27203-6455, Phone: 336-625-2850
Contact: Megan Stevens, Thomas Tire & Automotive, Phone: 336-625-2850

Object: NC406766 - PV - Morganton - 2016 - Comp Shed - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 02/09/2021 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 06-Undefined Pressure Relieving Devices Violations
SUBCATEGORY 478. Undefined Pressure Relieving Devices Violations.
CONDITION: 478. Undefined Pressure Relieving Devices Violations: Pressure gauge inoperative.
REQUIREMENT: 478. Undefined Pressure Relieving Devices Violations: Replace the inoperative pressure gauge. The replacement pressure gauge must have a maximum measuring range of not less than 1.5 times nor more than 4 times the normal operating pressure of the air tank (Max Allowable Pressure of the air tank is at 200 PSI).

Location: Tobacco Rag Processors **Location #:** 1836694 **Violations:** 3
4744 Potato House Ct, , Wilson, NC 27893-8592, Phone: 252-265-0081
Contact: Jimmy Bingle, Manager, Tobacco Rag Processors Inc, Phone: 252- 265-0081/919-738-7659

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC295072 - Boiler - Hurst - 2001 - Blr Rm - Active

Violations This Object: 1

COMPANY: State of North Carolina
INSPECTOR: Harrell, Danny
OPENED: 02/23/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 08-Main Steam System NCAC 13-13.0411
SUBCATEGORY 125. Stop valve(s) stem gland leaking.
CONDITION: 125. Main Steam System NCAC 13-13.0411: Stop valve(s) stem gland leaking.
REQUIREMENT: 125. Repack and/or tighten gland seal on valve. Contact Danny Harrell @ 919-500-3098 when the repair is completed to schedule a re-inspection.

ENTERED BY: Harrell, Danny

CLOSED BY:

Object: NC295073 - Boiler - Hurst - 2001 - Blr Rm - Active

Violations This Object: 2

COMPANY: State of North Carolina
INSPECTOR: Harrell, Danny
OPENED: 02/23/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409
SUBCATEGORY 006. Low water cutoff device inoperative or bypassed.
CONDITION: 006. LWCO and Flow Sensing Devices NCAC 13-13.0409: Secondary manual reset low water cutoff device inoperative or bypassed.
REQUIREMENT: 006. Repair or replace the inoperable manual reset low water fuel cutoff control and test to ensure proper operation.

ENTERED BY: Harrell, Danny

CLOSED BY:

COMPANY: State of North Carolina
INSPECTOR: Harrell, Danny
OPENED: 02/23/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 03-Water Gauge Glass NCAC 13-13.0408
SUBCATEGORY 058. Leaking.
CONDITION: 058. Water Gauge Glass NCAC 13-13.0408: Leaking.
REQUIREMENT: 058. Repair or replace the leaking gauge and test to ensure proper operation. Contact Danny Harrell @ 919-500-3098 when all repairs have been completed.

ENTERED BY: Harrell, Danny

CLOSED BY:

Location: United Metal Finishing

Location #: 1839322

Violations: 2

137 Blue Bell Rd, , Greensboro, NC 27406-5301, Phone: 336-272-8107

Contact: Attn Rick Swink, Manager, United Metal Finishing Inc, Phone: 336-272-8107

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC290007 - Boiler - Weil-McLain - 1985 - Blr Rm - Active

Violations This Object: 2

COMPANY:	Hartford Steam Boiler		
INSPECTOR:	Leonard, Shannon D.		
OPENED:	02/19/2021	ENTERED BY:	Judd, Janie
CLOSED:		CLOSED BY:	
TYPE:	Certificate Blocking		
CATEGORY:	05-Temperature Controls NCAC 13-13.0406		
SUBCATEGORY	093. High limit temperature control inoperative.		
CONDITION:	093. Temperature Controls NCAC 13-13.0406: High limit temperature control inoperative.		
REQUIREMENT:	093. Repair or replace the inoperative high limit temperature control. Test to ensure proper operation.		
COMPANY:	Hartford Steam Boiler		
INSPECTOR:	Leonard, Shannon D.		
OPENED:	02/19/2021	ENTERED BY:	Judd, Janie
CLOSED:		CLOSED BY:	
TYPE:	Certificate Blocking		
CATEGORY:	25-Operation of PRDs NCAC 13-13.0405		
SUBCATEGORY	395. Valve leaking.		
CONDITION:	395. Operation of PRDs NCAC 13-13.0405: Valve leaking. Pressure relied device (PRD) leaking.		
REQUIREMENT:	395. Replace the leaking PRD with an ASME/NB stamped PRD having a set pressure of 50 PSI or less and a relieving capacity of 1,358,000 BTU/Hour or more. The new PRD must have a try lever and the PRD discharge must be piped full size to a safe location (I.E. with 6" of floor).		

Location: West German Garage

Location #: 1842877

Violations: 1

5611 Hillsborough St, , Raleigh, NC 27606-1534, Phone: 919-851-1236

Contact: John Elliason, Manager, West German Garage Inc, Phone: 919-851-1236

Object: NC356708 - PV - Manchester - 1999 - Outside - Active

Violations This Object: 1

COMPANY:	State of North Carolina		
INSPECTOR:	Fish, Emily		
OPENED:	10/15/2020	ENTERED BY:	Fish, Emily
CLOSED:		CLOSED BY:	
TYPE:	Certificate Blocking		
CATEGORY:	09-Pressure Gauges NCAC 13-13.0407		
SUBCATEGORY	032. Incorrect range or insufficient pointer travel.		
CONDITION:	032. Pressure Gauges NCAC 13-13.0407: Incorrect range or insufficient pointer travel.		
REQUIREMENT:	032. Install a pressure gauge on the equipment that is visible to the operator from the floor or work platform. Gauge must be the proper range in accordance with NC Administrative Code, Title 13, Chapter 13, Section .0407. Please call Emily Fish at (919) 268-0725 when ready for reinspection.		

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Location: Williamson Cleaners **Location #:** 1844175 **Violations:** 1

3711 Peppermill Dr N Ste G, , Wilson, NC 27896-7390, Phone: 252-205-6180

Contact: Attn James Min, Owner, Williamson Cleaners, Phone: 252-237-1828, Cell:336-837-7025

Object: NC342375 - Boiler - Columbia - 2002 - Blr Rm - Active **Violations This Object:** 1

COMPANY:	State of North Carolina	
INSPECTOR:	Harrell, Danny	
OPENED:	01/19/2021	ENTERED BY: Harrell, Danny
CLOSED:		CLOSED BY:
TYPE:	Certificate Blocking	
CATEGORY:	03-Water Gauge Glass NCAC 13-13.0408	
SUBCATEGORY	058. Leaking.	
CONDITION:	058. Water Gauge Glass NCAC 13-13.0408: Leaking.	
REQUIREMENT:	058. Repair or replace the leaking gauge and test to ensure proper operation. Contact Danny Harrell @ 919-500-3098 when the repair is completed.	

Location: Windsor Point Retirement Community **Location #:** 1844569 **Violations:** 1

1221 Broad St, , Fuquay Varina, NC 27526-3602, Phone: 919-552-4580

Contact: Jimmy Richardson, Maintenance Supervisor, Windsor Point Retirement Community, Phone: 919-552-4580

Object: NC382669 - PV - LTC - 2010 - Blr Rm - Active **Violations This Object:** 1

COMPANY:	Hartford Steam Boiler	
INSPECTOR:	SORRENTINO, SEAN	
OPENED:	11/13/2020	ENTERED BY: Keyes, Amanda
CLOSED:		CLOSED BY:
TYPE:	Certificate Blocking	
CATEGORY:	01-Installation	
SUBCATEGORY	413. Cracking.	
CONDITION:	413. Installation: Cracking.	
REQUIREMENT:	413. Repair the cracking. If welding is required, a qualified "R" certificate holder is necessary to perform the work.	

Violations This Report: 84

Locations This Report: 57