Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Location: (CABARRUS CS) Beverly Hills Elem Location #: 1768208 Violations: 1

87 Palaside Dr NE, , Concord, NC 28025-3056, Phone: 704-782-0115 **Contact:** Cabarrus County Schools, Phone: 704-262-6239/704-786-6191

Object: NC291622 - Boiler - Weil-McLain - 1998 - Blr Rm - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Clay, Steven D.

OPENED: 02/17/2022 ENTERED BY: Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 25-Operation of PRDs NCAC 13-13.0405

SUBCATEGORY 396. Missing nameplate.

CONDITION: 396. Operation of PRDs NCAC 13-13.0405: PRD nameplate unreadable **REQUIREMENT:** 396. Replace the relief device with one set at a pressure not exceeding the

maximum allowed working pressure determined by the manufacturer. The

replacement valve must be ASME/NB certified.

Location: (CABARRUS CS) Cabarrus County Opportunity School Location #: 1792956 Violations: 1

120 Marsh Ave NW, , Concord, NC 28025-4889, Phone: 704-793-1736 **Contact:** Cabarrus County Schools, Phone: 704-262-6239/704-786-6191

Object: NC291623 - Boiler - Weil-McLain - 1998 - Blr Rm - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Clay, Steven D.

OPENED: 02/17/2022 ENTERED BY: Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 25-Operation of PRDs NCAC 13-13.0405

SUBCATEGORY 394. Valve inoperative.

CONDITION: 394. Operation of PRDs NCAC 13-13.0405: Valve inoperative: PRD was leaking at

base and from weephole

REQUIREMENT: 394. Replace the relief device with one set at a pressure not exceeding the

maximum allowed working pressure determined by the manufacturer. The

replacement valve must be ASME/NB certified.

Location: (CABARRUS CS) Carl A Furr Elem Location #: 2002374 Violations: 1

2725 Clover Rd NW, , Concord, NC 28027-3804, Phone: 704-788-4300 **Contact:** Cabarrus County Schools, Phone: 704-262-6239/704-786-6191

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC364598 - Boiler - Weil-McLain - 2006 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Clay, Steven D.

OPENED: 02/15/2022 ENTERED BY: Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations **SUBCATEGORY** 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. The installer put the wrong ASME nameplate on. **REQUIREMENT:** 363. Undefined Boiler Violations. Customer is to obtain and fill out the needed form

and have the manufacturer send the correct AMSE nameplate for attachment.

Location: (COLUMBUS CS) Acme Delco Elem Location #: 1761932 Violations: 1

16337 Old Lake Rd, , Riegelwood, NC 28456-7077, Phone: 910-655-2957

Contact: Attn Tim Ward, Plant Operations, Columbus County Schools, Phone: 910-642-0161, Cell:910-770-2303

Object: NC252134 - Boiler - Weil-McLain - 1990 - Blr Rm - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 11/04/2021 **ENTERED BY:** Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 12-Casing, Stack Breeching and Flue

SUBCATEGORY 211. Combustion gas leaks.

CONDITION: 211. Casing, Stack Breeching and Flue: Combustion gas leaks.

REQUIREMENT: 211. Repair all combustion gas leaks in the casing, stack breeching, or flue.

Location: (DPS-C) Albemarle CI - 4580 Location #: 1762698 Violations: 2

44150 Airport Rd, , New London, NC 28127-9597, Phone: 704-422-3036

Contact: Ricky Maness, Maintenance Supervisor, Albemarle CI - 4580, Phone: 704-422-2600/702-422-3036

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC296308 - Boiler - Burnham - 1998 - Core Bldg Mech Rm 1244 - Violations This Object: 1

Active

COMPANY: Hartford Steam Boiler **INSPECTOR:** Leonard, Shannon D.

OPENED: 01/06/2022 ENTERED BY: Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 25-Operation of PRDs NCAC 13-13.0405

SUBCATEGORY 397. Try lever inoperative.

CONDITION: 397. Operation of PRDs NCAC 13-13.0405: Try lever inoperative.

REQUIREMENT: 397. Install a new ASME/NB stamped PRD having a set pressure of 60 PSI or less

and a relieving capacity of 2,318,000 BTU/Hour or more. The replacement PRD must be equipped with a functioning try-lever and the PRD discharge must be piped

full size to a safe location (i.e. within 6" of the boiler room floor)

Object: NC414836 - Boiler - Cleveland Range - 2015 - Kitchen - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler **INSPECTOR:** Leonard, Shannon D.

OPENED: 01/06/2022 ENTERED BY: Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 13-Burners and Fuel Supply Systems **SUBCATEGORY** 235. No emergency fuel shut off switch.

CONDITION: 235. Burners and Fuel Supply Systems: No emergency fuel shut off switch.

REQUIREMENT: 235. Install an emergency fuel shut off switch at each egress from the boiler room to

shut off all fuel to the boilers.

Location: (DPS-C) Alexander CI - 4870 Location #: 1762873 Violations: 7

633 Old Landfill Rd, , Taylorsville, NC 28681-8420, Phone: 828-632-1331 **Contact:** NC Dept Of Public Safety - 13101, Phone: 919-716-3422

Object: NC349896 - Boiler - Lochinvar - 2002 - Blr Rm Unit 2 - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler **INSPECTOR:** Leonard, Shannon D.

OPENED: 03/10/2022 ENTERED BY: Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 26-Undefined Pressure Relieving Devices Violations **SUBCATEGORY** 399. Undefined Pressure Relieving Devices Violations.

CONDITION: 399. Undefined Pressure Relieving Devices Violations: Non-temperature and

pressure type pressure relief device (PRD) installed on HLW stamped boiler.

REQUIREMENT: 399. Replace the current PRD with an ASME/NB stamped temperature and

pressure relieving type PRD having a set pressure of 160 PSI or less and a relieving capacity of 990,000 BTU/Hour or more. This PRD must also be designed

to lift and relieve temperature/pressure at 210 degrees Fahrenheit.

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC349897 - Boiler - Lochinvar - 2002 - Blr Rm Unit 1 - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler **INSPECTOR:** Leonard, Shannon D.

OPENED: 03/10/2022 ENTERED BY: Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 26-Undefined Pressure Relieving Devices Violations **SUBCATEGORY** 399. Undefined Pressure Relieving Devices Violations.

CONDITION: 399. Undefined Pressure Relieving Devices Violations: Pressure relief device (PRD)

data plate illegible due to apparent manufacturing defect (Data not properly

stamped on data plate).

REQUIREMENT: 399. Undefined Pressure Relieving Devices Violations: Replace the current PRD

with an ASME/NB stamped temperature and pressure relieving PRD having a set pressure of 160 PSI or less and a relieving capacity of 1,260,000 BTU/Hour. The replacement PRD must also be designed to lift and relieve temperature/pressure at

210 degrees fahrenheit.

Object: NC349899 - PV - LTC - 2002 - Blr Rm Tank 2 - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler **INSPECTOR:** Leonard, Shannon D.

OPENED: 03/10/2022 ENTERED BY: Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 04-Installation of PRDs NCAC 13-13.0405

SUBCATEGORY 452. Set pressure too high.

CONDITION: 452. Installation of PRDs NCAC 13-13.0405: Set pressure too high: Pressure relief

device (PRD) set pressure rating exceeds maximum allowable working pressure

rating of hot water.

REQUIREMENT: 452. Replace the current PRD with an ASME/NB stamped temperature and pressure

relieving PRD having a set pressure of 125 PSI or less and a relieving capacity of 1,980,000 BTU/Hour or more. This PRD must also be designed to lift and relieve

temperature/pressure at 210 degrees Fahrenheit.

Object: NC349900 - Boiler - Lochinvar - 2002 - Outside Bldg Unit 6 - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler **INSPECTOR:** Leonard, Shannon D.

OPENED: 03/10/2022 ENTERED BY: Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 26-Undefined Pressure Relieving Devices Violations **SUBCATEGORY** 399. Undefined Pressure Relieving Devices Violations.

CONDITION: 399. Undefined Pressure Relieving Devices Violations: Pressure Relief Device

(PRD) inlet piping leaking/corroded.

REQUIREMENT: 399. Undefined Pressure Relieving Devices Violations: Replace the PRD inlet

plumbing connection in order to correct this condition the replacement inlet piping

must be piped full size between the boiler and PRD inlet opening.

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC351303 - PV - Lochinvar - 2002 - Rm P17 - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler **INSPECTOR:** Leonard, Shannon D.

OPENED: 03/10/2022 ENTERED BY: Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 04-Installation of PRDs NCAC 13-13.0405

SUBCATEGORY 461. Incorrect pressure relieving device(s) for the application.

CONDITION: 461. Installation of PRDs NCAC 13-13.0405: Incorrect pressure relieving device(s)

for the application: Non-temperature and pressure type pressure relief device (PRD)

installed on HLW stamped boiler.

REQUIREMENT: 461. Replace the current PRD with an ASME/NB stamped temperature and

pressure relieving type PRD having a set pressure of 125 PSI or less and a

relieving capacity of 3,600,000 BTU/Hour or more. This PRD must also be designed

to lift and relieve temperature/pressure at 210 degrees Fahrenheit.

Object: NC414237 - Boiler - Cleveland Range - 2017 - Kitchen - Active Violations This Object: 2

COMPANY: Hartford Steam Boiler **INSPECTOR:** Leonard, Shannon D.

OPENED: 03/10/2022 ENTERED BY: Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 03-Water Gauge Glass NCAC 13-13.0408

SUBCATEGORY 058. Leaking.

CONDITION: 058. Water Gauge Glass NCAC 13-13.0408: Leaking.

REQUIREMENT: 058. Repair or replace the leaking gauge and test to ensure proper operation.

COMPANY: Hartford Steam Boiler **INSPECTOR:** Leonard, Shannon D.

OPENED: 03/10/2022 **ENTERED BY:** Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking
CATEGORY: 16-Boiler Components
SUBCATEGORY 271. Handhole plug leaks.

CONDITION: 271. Boiler Components: Handhole plug leaks.

REQUIREMENT: 271. Replace the leaking gasket. If weld repairs are required, a qualified "R"

certificate holder is necessary to perform the work.

Location: (DPS-C) Lanesboro CI - 4865 Location #: 1805021 Violations: 1

552 Prison Camp Rd, , Polkton, NC 28135-6118, Phone: 704-695-1013 **Contact:** NC Dept Of Public Safety - 13101, Phone: 919-716-3422

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC340797 - Boiler - Cleaver Brooks - 2002 - Blr Rm - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler INSPECTOR: Clay, Steven D.

OPENED: 11/01/2021 ENTERED BY: Putek, Terry

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations **SUBCATEGORY** 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. Boiler can not run due to faulty modulating motor.

Part is on order with C&C Boiler but is currently not available to nation wide parts

shortage. Boiler is not in use and tagged out.

REQUIREMENT: 363. Undefined Boiler Violations. Repair boiler as required. Part needed to repair is

on backorder.

Location: (DPS-C) Lanesboro Minimum CI - 3510 Location #: 1770840 Violations: 1

248 Prison Camp Rd, , Polkton, NC 28135-6115, Phone: 704-694-2622

Contact: Ernie Thomas, Maintenance Supervisor, Brown Creek CI - 3510, Phone: 704-694-2622 X222 X285

Object: NC251882 - Boiler - Lochinvar - 1991 - Blr Rm Unit 5 - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler INSPECTOR: Clay, Steven D.

OPENED: 07/19/2021 **ENTERED BY:** Putek, Terry

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 24-Installation of PRDs NCAC 13-13.0405 **SUBCATEGORY** 378. Discharge opening directed improperly.

CONDITION: 378. Installation of PRDs NCAC 13-13.0405: Discharge opening directed

improperly. Discharge piping not installed on PRD.

REQUIREMENT: 378. Redirect the discharge to a safe point at required in NCAC 13-13.0405.

Location: (DPS-C) NCCIW - 3010 Location #: 1779964 Violations: 2

1034 Bragg St., Raleigh, NC 27610-3846, Phone: 919-733-4340

Contact: Phillip Jones, Maintenance Supervisor, NCCIW - 3010, Phone: 919-508-1690

Object: NC381483 - Boiler - PVI Industries - 2010 - Falcom Blr Rm - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler **INSPECTOR:** SORRENTINO, SEAN

OPENED: 12/08/2020 **ENTERED BY:** Keyes, Amanda

CLOSED: CLOSED BY:

TYPE: Certificate Blocking
CATEGORY: 16-Boiler Components
SUBCATEGORY 270. Water Leaks.

CONDITION: 270. Boiler Components: Water Leaks.

REQUIREMENT: 270. Repair the water leaks identified on the inspection report. If welding is required, a qualified "R" certificate holder is necessary to perform the repair.

3/25/2022 8:18:50 AM **JURISDICTION ONLINE** Page 6 of 34

000.10014 Copyright © 2022 CentralSquare

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC401596 - Boiler - PVI Industries - 2014 - Sparrow N - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler INSPECTOR: SORRENTINO, SEAN

OPENED: 12/08/2020 ENTERED BY: Keyes, Amanda

CLOSED: CLOSED BY:

TYPE: Certificate Blocking
CATEGORY: 16-Boiler Components
SUBCATEGORY 270. Water Leaks.

CONDITION: 270. Boiler Components: Water Leaks. Tank leaking at unknown location. **REQUIREMENT:** 270. Repair the water leaks identified on the inspection report. If welding is

required, a qualified "R" certificate holder is necessary to perform the repair.

Location: (GRAHAM CS) Robbinsville High & Middle Location #: 1824861 Violations: 1

301 Sweetwater Rd, , Robbinsville, NC 28771-9435, Phone: 828-479-3330 HIGH/828-479-8488 MIDDLE **Contact:** Attn Patrick Nicholes, Maintenance Supervisor, Graham County Schools, Phone: 828-479-6636

Object: NC321896 - Boiler - Teledyne Laars - 2000 - Blr Rm - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler **INSPECTOR:** Possidente, James

OPENED: 02/17/2022 ENTERED BY: Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 25-Operation of PRDs NCAC 13-13.0405

SUBCATEGORY 395. Valve leaking.

CONDITION: 395. Operation of PRDs NCAC 13-13.0405: Valve leaking.

REQUIREMENT: 395. Replace the relief device with one set at a pressure not exceeding the

maximum allowed working pressure determined by the manufacturer. The

replacement valve must be ASME/NB certified.

Location: (HAYWOOD CS) Canton Middle Location #: 1772761 Violations: 2

60 Penland St,, Canton, NC 28716-4704, Phone: 828-646-3467

Contact: Joe Buchanan, Maintenance Director, Haywood County Schools, Phone: 828-456-2402 X2302, Cell:828-

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC228431 - Boiler - Weil-McLain - 1987 - Blr Rm - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler **INSPECTOR:** Possidente, James

OPENED: 03/01/2022 ENTERED BY: Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations **SUBCATEGORY** 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. This boiler has been taken out of service however

it has not been properly disconnected from all sources of potential energy.

REQUIREMENT: 363. Undefined Boiler Violations. Disconnect the boiler from all sources of potential

energy including fuel and electricity.

Object: NC352595 - Boiler - Weil-McLain - 2004 - A Bldg - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler **INSPECTOR:** Possidente, James

OPENED: 03/01/2022 ENTERED BY: Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 26-Undefined Pressure Relieving Devices Violations **SUBCATEGORY** 399. Undefined Pressure Relieving Devices Violations.

CONDITION: 399. Undefined Pressure Relieving Devices Violations: The boiler could not be

started for the inspection. The controls could not be tested.

REQUIREMENT: 399. Undefined Pressure Relieving Devices Violations: schedule a follow up

inspection for a day and time when the boiler can be started.

Location: (HAYWOOD CS) Meadowbrook Elem Location #: 1809629 Violations: 1

85 Morning Star Rd, , Canton, NC 28716-9459, Phone: 828-646-3445

Contact: Joe Buchanan, Maintenance Director, Haywood County Schools, Phone: 828-456-2402 X2302, Cell:828-

Object: NC355116 - Boiler - Weil-McLain - 2003 - Blr Rm - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler **INSPECTOR:** Possidente, James

OPENED: 03/01/2022 **ENTERED BY:** Keyes, Amanda

CLOSED: CLOSED BY:

TYPE: Certificate Blocking
CATEGORY: 16-Boiler Components
SUBCATEGORY 273. Shell leaks.

CONDITION: 273. Boiler Components: Shell leaks.

REQUIREMENT: 273. Repair the leaking shell. If weld repairs are required, a qualified "R" certificate

holder is necessary to perform the work.

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Location: (HENDERSON) County Courthouse Location #: 1796551 Violations: 3

200 N Grove St Ste 163, , Hendersonville, NC 28792-5027, Phone: 828-808-9701

Contact: Chris Hill, Maintenance Supervisor, Henderson County Courthouse, Phone: 828 458 4882

Object: NC270732 - Boiler - PVI Industries - 1994 - Court Blr Rm - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler **INSPECTOR:** Possidente, James

OPENED: 01/14/2022 **ENTERED BY:** Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking
CATEGORY: 16-Boiler Components
SUBCATEGORY 273. Shell leaks.

CONDITION: 273. Boiler Components: Shell leaks.

REQUIREMENT: 273. Repair the leaking shell. If weld repairs are required, a qualified "R" certificate

holder is necessary to perform the work.

Object: NC387653 - PV - Niles Steel - 2011 - Court Blr Rm - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler **INSPECTOR:** Possidente, James

OPENED: 01/14/2022 ENTERED BY: Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 04-Installation of PRDs NCAC 13-13.0405

SUBCATEGORY 452. Set pressure too high.

CONDITION: 452. Installation of PRDs NCAC 13-13.0405: Set pressure too high.

REQUIREMENT: 452. Replace the pressure relieving device with one with a set pressure no higher

than the maximum allowable working pressure as determined by the manufacturer.

Object: NC409134 - Boiler - Weil-McLain - 2016 - Blr Rm - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler **INSPECTOR:** Possidente, James

OPENED: 01/14/2022 ENTERED BY: Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 24-Installation of PRDs NCAC 13-13.0405

SUBCATEGORY 372. Set pressure too high.

CONDITION: 372. Installation of PRDs NCAC 13-13.0405: Set pressure too high.

REQUIREMENT: 372. Replace the pressure relieving device with one with a set pressure no higher

than the maximum allowable working pressure as determined by the manufacturer.

Location: (HENDERSON) County Detention Center Location #: 1796552 Violations: 2

200 N Grove St Ste 223, Hendersonville, NC 28792-5027, Phone: 828-808-9701

Contact: Thad Ninnemann, Maintenance Director, Henderson County Detention Center, Phone: 828-808-9701,

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC324687 - Boiler - PVI Industries - 2000 - Courthouse Blr Rm - Violations This Object: 2

Active

COMPANY: Hartford Steam Boiler **INSPECTOR:** Possidente, James

OPENED: 01/14/2022 ENTERED BY: Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking
CATEGORY: 16-Boiler Components
SUBCATEGORY 273. Shell leaks.

CONDITION: 273. Boiler Components: Shell leaks.

REQUIREMENT: 273. Repair the leaking shell. If weld repairs are required, a qualified "R" certificate

holder is necessary to perform the work.

COMPANY: Hartford Steam Boiler **INSPECTOR:** Possidente, James

OPENED: 01/14/2022 ENTERED BY: Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking
CATEGORY: 16-Boiler Components
SUBCATEGORY 273. Shell leaks.

CONDITION: 273. Boiler Components: Shell leaks.

REQUIREMENT: 273. Repair the leaking shell. If weld repairs are required, a qualified "R" certificate

holder is necessary to perform the work.

Location: (HENDERSON) Social Services Location #: 2285281 Violations: 3

1200 Spartanburg Hwy, , Hendersonville, NC 28792-5855, Phone: 828-697-4604

Contact: Henderson County Government, Phone: 828-697-4840

Object: NC369389 - Boiler - Lochinvar - 2006 - Penthouse Blr Rm - Active Violations This Object: 2

COMPANY: Hartford Steam Boiler **INSPECTOR:** Possidente, James

OPENED: 01/14/2022 ENTERED BY: Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 02-Pressure Gauges NCAC 13-13.0407

SUBCATEGORY 035. Leaking.

CONDITION: 035. Pressure Gauges NCAC 13-13.0407: Leaking.

REQUIREMENT: 035. Install a pressure gauge on the equipment that is visible to the operator from

the floor or work platform. Gauge must be the proper range in accordance with NC

Administrative Code, Title 13, Chapter 13, Section .0407.

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

COMPANY: Hartford Steam Boiler **INSPECTOR:** Possidente, James

OPENED: 01/14/2022 ENTERED BY: Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 11-Exp Tanks & Htng Sys Piping NCAC 13-13.0412

SUBCATEGORY 193. Leaking pipe/pipe joints.

CONDITION: 193. Exp Tanks & Htng Sys Piping NCAC 13-13.0412: Leaking pipe/pipe joints.

REQUIREMENT: 193. Repair or replace leaking piping/pipe joints.

Object: NC370806 - Boiler - Lochinvar - 2007 - Penthouse Blr Rm - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler **INSPECTOR:** Possidente, James

OPENED: 01/14/2022 ENTERED BY: Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 11-Exp Tanks & Htng Sys Piping NCAC 13-13.0412

SUBCATEGORY 193. Leaking pipe/pipe joints.

CONDITION: 193. Exp Tanks & Htng Sys Piping NCAC 13-13.0412: Leaking pipe/pipe joints.

REQUIREMENT: 193. Repair or replace leaking piping/pipe joints.

Location: (LENOIR CS) La Grange Elem Location #: 1804602 Violations: 1

402 W Railroad St, , La Grange, NC 28551-1640, Phone: 252-527-1407 **Contact:** Attn R Jones, Lenoir County Public Schools, Phone: 252-527-1407

Object: NC336833 - Boiler - Weil-McLain - 2001 - BLR RM - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 03/07/2022 ENTERED BY: Keyes, Amanda

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409 **SUBCATEGORY** 006. Low water cutoff device inoperative or bypassed.

CONDITION: 006. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device

inoperative or bypassed.

REQUIREMENT: 006. Repair or replace the inoperable low water fuel cutoff control and test to

ensure proper operation.

Location: (LENOIR CS) North Lenoir High Location #: 1815064 Violations: 1

2400 Institute Rd, , La Grange, NC 28551-6716, Phone: 252-527-1407 **Contact:** Attn R Jones, Lenoir County Public Schools, Phone: 252-527-1407

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC287096 - Boiler - Lochinvar - 1997 - Kitchen Blr Rm - Active Violations This Object: 1

> **COMPANY:** Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 03/08/2022 **ENTERED BY:** Keyes, Amanda

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations **SUBCATEGORY** 363. Undefined Boiler Violations.

CONDITION: 363. Boiler not operating.

REQUIREMENT: 363. Reschedule inspection for a time when the boiler is operating so that boiler

safety devices can be verified to operate properly.

Location: (LENOIR CS) Northwest Elem Location #: 1815337 Violations: 1

1701 Old Well Rd, , Kinston, NC 28504-2600, Phone: 252-527-1407

Contact: Attn R Jones, Lenoir County Public Schools, Phone: 252-527-1407

Object: NC041545 - Boiler - NRC - 1957 - Blr Rm - Active Violations This Object: 1

> **COMPANY:** Hartford Steam Boiler

Rudolph, Jay **INSPECTOR:**

OPENED: 03/07/2022 **ENTERED BY:** Keyes, Amanda

CLOSED BY: CLOSED:

TYPE: Certificate Blocking

23-Undefined Boiler Violations **CATEGORY: SUBCATEGORY** 363. Undefined Boiler Violations. **CONDITION:**

363. Boiler Not operating

REQUIREMENT: 363. Reschedule inspection for a time when the boiler is operating so that system

safety devises can be verified to operate properly.

Location: (LENOIR CS) Rochelle Middle **Location #:** 1825083 Violations: 2

301 N Rochelle Blvd, , Kinston, NC 28501-5240, Phone: 252-527-1407 Contact: Attn R Jones, Lenoir County Public Schools, Phone: 252-527-1407

Object: NC065774 - Boiler - Fitzgibbon - 1962 - Blr Rm - Active Violations This Object: 2

> **COMPANY:** Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 03/08/2022 **ENTERED BY:** Keyes, Amanda

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 12-Casing, Stack Breeching and Flue

SUBCATEGORY 211. Combustion gas leaks.

CONDITION: 211. Casing, Stack Breeching and Flue: Combustion gas leaks.

REQUIREMENT: 211. Repair all combustion gas leaks in the casing, stack breeching, or flue.

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 03/08/2022 ENTERED BY: Keyes, Amanda

CLOSED BY:

CLOSED:

TYPE: Certificate Blocking
CATEGORY: 16-Boiler Components
SUBCATEGORY 270. Water Leaks.

CONDITION: 270. Boiler Components: Water Leaks.

REQUIREMENT: 270. Repair the water leaks identified on the inspection report.

Location: (LENOIR CS) Southwood Elem Location #: 1831270 Violations: 1

1245 Hwy 58 S, , Kinston, NC 28504-6909, Phone: 252-527-1407

Contact: Attn R Jones, Lenoir County Public Schools, Phone: 252-527-1407

Object: NC298004 - Boiler - Weil-McLain - 1999 - Gym Blr Rm - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 03/09/2022 ENTERED BY: Keyes, Amanda

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 12-Casing, Stack Breeching and Flue

SUBCATEGORY 211. Combustion gas leaks.

CONDITION: 211. Casing, Stack Breeching and Flue: Combustion gas leaks.

REQUIREMENT: 211. Repair all combustion gas leaks in the casing, stack breeching, or flue.

Location: (LENOIR CS) Woodington Middle Location #: 1845083 Violations: 2

4939 US Highway 258 S, , Kinston, NC 28504-7083, Phone: 252-527-1407 **Contact:** Attn R Jones, Lenoir County Public Schools, Phone: 252-527-1407

Object: NC320551 - Boiler - Weil-McLain - 1999 - Blr Rm - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 03/09/2022 ENTERED BY: Keyes, Amanda

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 24-Installation of PRDs NCAC 13-13.0405

SUBCATEGORY 371. Inadequate relieving capacity.

CONDITION: 371. Installation of PRDs NCAC 13-13.0405: Inadequate relieving capacity.

REQUIREMENT: 371. Replace the pressure relieving device with one with a capacity required by the

boiler manufacturer.

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC398635 - Boiler - Weil-McLain - 2013 - Blr Rm - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 03/09/2022 ENTERED BY: Keyes, Amanda

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 24-Installation of PRDs NCAC 13-13.0405

SUBCATEGORY 371. Inadequate relieving capacity.

CONDITION: 371. Installation of PRDs NCAC 13-13.0405: Inadequate relieving capacity.

REQUIREMENT: 371. Replace the pressure relieving device with one with a capacity required by the

boiler manufacturer.

Location: (LENOIR) County Courthouse Location #: 876965 Violations: 1

130 S Queen St, , Kinston, NC 28501-4941, Phone: 252-559-6452

Contact: Attn Chris Harper, Maintenance, Lenoir County Courthouse, Phone: 252-559-6452

Object: NC388930 - Boiler - Lochinvar - 2011 - Bsmt Rm J003 - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 10/22/2021 **ENTERED BY:** Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 25-Operation of PRDs NCAC 13-13.0405

SUBCATEGORY 395. Valve leaking.

CONDITION: 395. Operation of PRDs NCAC 13-13.0405: Valve leaking: Pressure relief device

leaking.

REQUIREMENT: 395. Replace pressure relief device with a ASME/NB certified pressure relief device

with a set pressure of not

greater than 160 psig, with a relief capacity of not less than 1016 KBH, and with a

testing lever.

Location: (MARTIN CS) Rodgers Elem Location #: 1825274 Violations: 1

2277 Rodgers School Rd, , Williamston, NC 27892-8249, Phone: 252-792-6637

Contact: Martin County Schools, Phone: 252-792-1575

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC303644 - Boiler - Weil-McLain - 1996 - Blr Rm - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 10/19/2021 ENTERED BY: Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 12-Casing, Stack Breeching and Flue

SUBCATEGORY 211. Combustion gas leaks.

CONDITION: 211. Casing, Stack Breeching and Flue: Combustion gas leaks.

REQUIREMENT: 211. Repair all combustion gas leaks in the casing, stack breeching, or flue.

Location: (MH UNIV) Chambers Gym Location #: 1930561 Violations: 1

227 Bailey St,, Mars Hill, NC 28754 , Phone: 828-689-1201

Contact: Attn David May, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:864-653-0230

Object: NC422574 - Boiler - Weil-McLain - 2019 - Blr Rm - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler **INSPECTOR:** Possidente, James

OPENED: 12/08/2021 **ENTERED BY:** Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409

SUBCATEGORY 003. Required manual reset low water cutoff device not installed.

CONDITION: 003. LWCO and Flow Sensing Devices NCAC 13-13.0409: Required manual reset

low water cutoff device not installed: LWCO required manual reset not installed on

secondary

REQUIREMENT: 003. Install a low-water fuel cutoff device (LWCO) designed for the appropriate

service (Steam or Hot Water) that is equipped with a manual reset; or install a manual reset on the existing low water fuel cutoff if appropriate. When the LWCO shuts off the fuel supply to the boiler in the event of a low water condition, the fuel supply must be restarted manually by an operator. Test to ensure proper operation.

Location: (MH UNIV) Laural Hall Location #: 3352814 Violations: 1

143 Womens Hill Dr, , Mars Hill, NC 28754 , Phone: 828-689-1201

Contact: Attn David May, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:864-653-0230

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC393784 - Boiler - A O Smith - 2013 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler INSPECTOR: Possidente, James

OPENED: 12/08/2021 ENTERED BY: Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations **SUBCATEGORY** 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. The boiler is out of service but not properly

disconnected.

REQUIREMENT: 363. Undefined Boiler Violations: Properly disconnect the boiler from all sources of

potential energy including fuel and electricity.

Location: (NC A&T) Band Bldg Location #: 1776866 Violations: 1

1120 E Bessemer Ave, , Greensboro, NC 27405-7106, Phone: 336-334-7025

Contact: NC A & T State University, Phone: 336-334-3806

Object: NC007630 - Boiler - Atlantic - 1948 - Blr Rm 1 - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler **INSPECTOR:** Leonard, Shannon D.

OPENED: 11/01/2021 ENTERED BY: Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking
CATEGORY: 16-Boiler Components
SUBCATEGORY 275. Tube/tube ends leak.

CONDITION: 275. Boiler Components: Tube/tube ends leak: Leak of unknown origin. Possible

tube or tube sheet leakage, but exact source could not be verified.

REQUIREMENT: 275. Repair the leaking tubes/tube ends. If weld repairs are required, a qualified "R"

certificate holder is necessary to perform the work.

Location: (UNCC) Facilities Operations **Location #:** 2550379 **Violations:** 1

9201 University City Blvd, , Charlotte, NC 28223-0001, Phone: 704-687-2199

Contact: Attn Kelly Herron, UNC Charlotte, Phone: 704-687-0567

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC331573 - Boiler - Aerco - 2004 - Blr Rm - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Clay, Steven D.

OPENED: 11/10/2021 **ENTERED BY:** Putek, Terry

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations **SUBCATEGORY** 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. HX cracked. Unit tagged out. Awaiting parts. **REQUIREMENT:** 363. Undefined Boiler Violations. Repair cracking. If welding is required a qualified

'R' certificate holder is necessary to perform the work.

Location: (UNCW) Center For Marine Science Location #: 1868647 Violations: 1

5600 Marvin Moss Ln, , Wilmington, NC 28409-3621, Phone: 910-962-3101

Contact: Jesus Villa, HVAC Maintenance, Center For Marine Science, Phone: 910-962-2414, Cell:910-622-7172

Object: NC415995 - Boiler - Sussman - 2016 - Rm 2341 - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 03/08/2022 **ENTERED BY:** Keyes, Amanda

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 03-Water Gauge Glass NCAC 13-13.0408

SUBCATEGORY 058. Leaking.

CONDITION: 058. Water Gauge Glass NCAC 13-13.0408: Leaking.

REQUIREMENT: 058. Repair or replace the leaking gauge and test to ensure proper operation.

Location: (WU) Bridges Hall Location #: 1880967 Violations: 1

216 Cedar St, , Wingate, NC 28174-5495, Phone: 800-755-5550

Contact: Attn Richard Helms, Manager, Wingate University, Phone: 800-755-5550, Cell:704-507-1962

Object: NC222281 - Boiler - Peerless - 1986 - Mech Rm - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Clay, Steven D.

OPENED: 11/15/2021 **ENTERED BY:** Putek, Terry

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 13-Burners and Fuel Supply Systems **SUBCATEGORY** 231. Leaking automatic gas valve.

CONDITION: 231. Burners and Fuel Supply Systems: Leaking automatic gas valve.

REQUIREMENT: 231. Repair or replace the leaking automatic gas valve.

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Location: (WU) New Stadium Training Bldg **Location #:** 1814520 Violations: 1

660 N Main St, , Wingate, NC 28174-6760, Phone: 704-233-8218

Contact: Attn Richard Helms, Manager, Wingate University, Phone: 800-755-5550, Cell:704-507-1962

Object: NC297025 - Boiler - Eafco - 1998 - Blr Rm - Active Violations This Object: 1

> COMPANY: Hartford Steam Boiler

INSPECTOR: Clay, Steven D.

OPENED: 11/15/2021 ENTERED BY: Putek, Terry

CLOSED: **CLOSED BY:**

TYPE: Certificate Blocking

CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409

SUBCATEGORY 001. Low water cutoff device not installed.

001. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device **CONDITION:**

not installed.

REQUIREMENT: 001. Equip the boiler with a low water fuel cutoff device (LWCO) designed for the

appropriate service (Steam or Hot Water) that is equipped with a manual reset. When the LWCO shuts off the fuel supply to the boiler in the event of a low water condition, the fuel supply must be restarted manually by an operator. Test to ensure

proper operation.

Location: (YANCEY CS) South Toe Elem Violations: 1 **Location #:** 1830380

166 S Toe School Rd, , Burnsville, NC 28714-8551, Phone: 828-675-4321 Contact: Attn Chris Howell, Yancey County Schools, Phone: 828-682-3066

Object: NC326313 - Boiler - Weil-McLain - 2000 - Blr Rm - Active Violations This Object: 1

> **COMPANY:** Hartford Steam Boiler INSPECTOR: Possidente, James

OPENED: 03/10/2022 **ENTERED BY:** Judd, Janie

CLOSED: **CLOSED BY:**

TYPE: Certificate Blocking 16-Boiler Components **CATEGORY: SUBCATEGORY** 273. Shell leaks.

CONDITION: 273. Boiler Components: Shell leaks.

REQUIREMENT: 273. Repair the leaking shell. If weld repairs are required, a qualified "R" certificate

holder is necessary to perform the work.

Location: Broughton Hospital New Hospital Location #: 3904479 Violations: 2

1000 S Sterling St, , Morganton, NC 28655-3938, Phone: 828-433-2329

Contact: Bruce Elder, Maintenance Suppervisor, Broughton Hospital New Hospital, Phone: 828 -608-4503

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC409059 - Boiler - Bryan - 2013 - New Blr Rm - Active Violations This Object: 2

COMPANY: State of North Carolina

INSPECTOR: Sims, Greg

OPENED: 01/12/2022 ENTERED BY: Davis, Greg

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 13-Burners and Fuel Supply Systems

SUBCATEGORY 236. Undefined Boiler Piping and Other Systems Violations.

CONDITION: 236. Burners and Fuel Supply Systems: Undefined Boiler Piping and Other

Systems Violations. Boiler had a fireside incident possibly damaging the burner and

safety interlocks

REQUIREMENT: 236. Undefined Boiler Piping and Other Systems Violations. Test burner and safety

interlocks to assure proper operation.

COMPANY: State of North Carolina

INSPECTOR: Sims, Greg

OPENED: 01/12/2022 ENTERED BY: Davis, Greg

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations **SUBCATEGORY** 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. Boiler had fireside incident damaging outer

casing.

REQUIREMENT: 363. Undefined Boiler Violations. Replace outer casings of the boiler.

Location: Carolina Packers Location #: 1773944 Violations: 1

2999 S Brightleaf Blvd, , Smithfield, NC 27577-5251, Phone: 919-934-2181

Contact: Carolina Packers Inc, Phone: 919-934-2181

Object: NC106918 - Boiler - BE&S - 1971 - Blr Rm - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler INSPECTOR: SORRENTINO, SEAN

OPENED: 02/24/2022 **ENTERED BY:** Keyes, Amanda

CLOSED: CLOSED BY:

TYPE: Certificate Blocking
CATEGORY: 16-Boiler Components
SUBCATEGORY 275. Tube/tube ends leak.

CONDITION: 275. Boiler Components: Tube/tube ends leak.

REQUIREMENT: 275. Repair the leaking tubes/tube ends. If weld repairs are required, a qualified "R"

certificate holder is necessary to perform the work.

Location: Chandler Foods Location #: 1775819 Violations: 1

2727 Immanuel Rd, , Greensboro, NC 27407-2515, Phone: 336-299-1934 **Contact:** Attn Mike McMasters, Chandler Foods Inc, Phone: 336-299-1934

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC244966 - Boiler - Ajax - 1989 - Blr Rm - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler **INSPECTOR:** Leonard, Shannon D.

OPENED: 03/09/2022 ENTERED BY: Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking
CATEGORY: 16-Boiler Components

SUBCATEGORY 277. Other component leaking.

CONDITION: 277. Boiler Components: Other component leaking: Leaking gaskets front and rear

access covers.

REQUIREMENT: 277. Repair the leaking component. If weld repairs are required, a qualified "R"

certificate holder is necessary to perform the work.

Location: Clean Laundry Services Location #: 1879873 Violations: 1

2103 Sullivan St, , Greensboro, NC 27405-7331, Phone: 336-897-0008 **Contact:** Andrew Trauschke, Clean Laundry Services, Phone: 336-210-1255

Object: NC351212 - Boiler - Superior Boiler Works - 2003 - Blr Rm - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler **INSPECTOR:** Leonard, Shannon D.

OPENED: 11/01/2021 ENTERED BY: Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 25-Operation of PRDs NCAC 13-13.0405

SUBCATEGORY 395. Valve leaking.

CONDITION: 395. Operation of PRDs NCAC 13-13.0405: Valve leaking: Both pressure relief

devices (PRD) leaking.

REQUIREMENT: 395. Replace the two leaking PRD's with ASME/NB stamped PRD's. The set

pressure of each PRD must be rated at 150 PSI or less and the combined relieving capacities of the two replacement PRD's must be greater than or equal to 10,136

pounds of steam per hour.

Location: Dale Earnhardt Inc Location #: 1781942 Violations: 1

1675 Dale Earnhardt Hwy Ste 3, , Mooresville, NC 28115-8330, Phone: 704-662-8000 X3311

Contact: Attn Bob Bauer, Shop Manager, Dale Earnhardt Inc, Phone: 704-662-8000 X3311, Cell:336-972-0393

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC282929 - Boiler - Raypak - 1997 - Blr Rm WC 1 - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler **INSPECTOR:** Leonard, Shannon D.

OPENED: 01/11/2022 ENTERED BY: Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations **SUBCATEGORY** 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations: Boiler not operating at time of inspection; flow

switch and pressure relief device (PRD) could not be tested to verify proper

operation.

REQUIREMENT: 363. Undefined Boiler Violations: Schedule a reinspection at a time when the boiler

is operating so that the flow switch and PRD may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the controls is also acceptable

Location: Elevate Textile Location #: 1771590 Violations: 11

1001 Turnpike Rd, , Raeford, NC 28376-8566, Phone: 910-875-3731

Contact: Attn David Limbacher, Maintenance Manager, Elevate Textile INC, Phone: 910-875-3731 X472, Cell:910-

Object: NC197933 - PV - Gcdmc - 1964 - Dye Kier #3 - Active Violations This Object: 2

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 01/19/2022 ENTERED BY: Keyes, Amanda

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 04-Installation of PRDs NCAC 13-13.0405

SUBCATEGORY 457. Try lever not installed.

CONDITION: 457. Installation of PRDs NCAC 13-13.0405: Try lever not installed.

REQUIREMENT: 457. Replace the relief valve with one with a try lever. The replacement relief valve

must be ASME/NB certified.

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 01/19/2022 ENTERED BY: Keyes, Amanda

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 05-Operation of PRDs NCAC 13-13.0405

SUBCATEGORY 475. Valve leaking.

CONDITION: 475. Operation of PRDs NCAC 13-13.0405: Valve leaking.

REQUIREMENT: 475. Replace the relief device with one set at a pressure not exceeding the

maximum allowed working pressure determined by the manufacturer. The

replacement valve must be ASME/NB certified.

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC197936 - PV - Gcdmc - 1964 - Dye Kier #6 Expansion Tank - Violations This Object: 1

Active

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay **OPENED:** 01/19/2022

OPENED: 01/19/2022 ENTERED BY: Keyes, Amanda

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 05-Operation of PRDs NCAC 13-13.0405

SUBCATEGORY 475. Valve leaking.

CONDITION: 475. Operation of PRDs NCAC 13-13.0405: Valve leaking.

REQUIREMENT: 475. Replace the relief device with one set at a pressure not exceeding the

maximum allowed working pressure determined by the manufacturer. The

replacement valve must be ASME/NB certified.

Object: NC197938 - PV - Gcdmc - 1964 - Dye Kier #5 Expansion Tank - Violations This Object: 2

Active

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay **OPENED:** 01/19/2022

OPENED: 01/19/2022 ENTERED BY: Keyes, Amanda

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 04-Installation of PRDs NCAC 13-13.0405

SUBCATEGORY 457. Try lever not installed.

CONDITION: 457. Installation of PRDs NCAC 13-13.0405: Try lever not installed.

REQUIREMENT: 457. Replace the relief valve with one with a try lever. The replacement relief valve

must be ASME/NB certified.

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 01/19/2022 **ENTERED BY:** Keyes, Amanda

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 05-Operation of PRDs NCAC 13-13.0405

SUBCATEGORY 475. Valve leaking.

CONDITION: 475. Operation of PRDs NCAC 13-13.0405: Valve leaking.

REQUIREMENT: 475. Replace the relief device with one set at a pressure not exceeding the

maximum allowed working pressure determined by the manufacturer. The

replacement valve must be ASME/NB certified.

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC197940 - PV - Gcdmc - 1964 - Dye Kier #3 Expansion Tank - Violations This Object: 1

Active

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay **OPENED:** 01/19/2022

OPENED: 01/19/2022 ENTERED BY: Keyes, Amanda

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 05-Operation of PRDs NCAC 13-13.0405

SUBCATEGORY 475. Valve leaking.

CONDITION: 475. Operation of PRDs NCAC 13-13.0405: Valve leaking.

REQUIREMENT: 475. Replace the relief device with one set at a pressure not exceeding the

maximum allowed working pressure determined by the manufacturer. The

replacement valve must be ASME/NB certified.

Object: NC197942 - PV - Gcdmc - 1964 - Dye Kier #2 Expansion Tank - Violations This Object: 1

Active

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 01/19/2022 **ENTERED BY:** Keyes, Amanda

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 04-Installation of PRDs NCAC 13-13.0405

SUBCATEGORY 457. Try lever not installed.

CONDITION: 457. Installation of PRDs NCAC 13-13.0405: Try lever not installed.

REQUIREMENT: 457. Replace the relief valve with one with a try lever. The replacement relief valve

must be ASME/NB certified.

Object: NC197943 - PV - Gcdmc - 1964 - Dye Kier #2 - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 01/19/2022 ENTERED BY: Keyes, Amanda

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 04-Installation of PRDs NCAC 13-13.0405

SUBCATEGORY 457. Try lever not installed.

CONDITION: 457. Installation of PRDs NCAC 13-13.0405: Try lever not installed.

REQUIREMENT: 457. Replace the relief valve with one with a try lever. The replacement relief valve

must be ASME/NB certified.

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC197944 - PV - Gcdmc - 1964 - Dye Kier #1 Expansion Tank - Violations This Object: 1

Active

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 01/19/2022 ENTERED BY: Keyes, Amanda

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 04-Installation of PRDs NCAC 13-13.0405

SUBCATEGORY 457. Try lever not installed.

CONDITION: 457. Installation of PRDs NCAC 13-13.0405: Try lever not installed.

REQUIREMENT: 457. Replace the relief valve with one with a try lever. The replacement relief valve

must be ASME/NB certified.

Object: NC197946 - PV - Perry Products - 1970 - Dye Kier #4 Expansion Violations This Object: 1

Tank - Active

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 01/19/2022 **ENTERED BY:** Keyes, Amanda

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 04-Installation of PRDs NCAC 13-13.0405

SUBCATEGORY 457. Try lever not installed.

CONDITION: 457. Installation of PRDs NCAC 13-13.0405: Try lever not installed.

REQUIREMENT: 457. Replace the relief valve with one with a try lever. The replacement relief valve

must be ASME/NB certified.

Object: NC366617 - PV - Gcdmc - 1995 - Jet #20 - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 01/20/2022 ENTERED BY: Keyes, Amanda

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 02-Manufacturer's Data Report & Nameplate

SUBCATEGORY 431. Nameplate stamping is incorrect, missing, or illegible.

CONDITION: 431. Manufacturer's Data Report & Nameplate: Nameplate stamping is incorrect,

missing, or illegible.

REQUIREMENT: 431. Obtain a replacement nameplate from the manufacturer or a replacement in

accordance with the National Board Inspection Code.

Location: First Moravian Church **Location #:** 1789142 **Violations:** 1

304 S Elam Ave, , Greensboro, NC 27403-1407, Phone: 336-272-2196 **Contact:** Attn Tony Hayworth, First Moravian Church, Phone: 336-272-2196

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC351414 - Boiler - H B Smith - 2003 - Education Bldg Blr Rm - Violations This Object: 1

Active

COMPANY: Hartford Steam Boiler **INSPECTOR:** Leonard, Shannon D.

OPENED: 03/04/2022 ENTERED BY: Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409 **SUBCATEGORY** 006. Low water cutoff device inoperative or bypassed.

CONDITION: 006. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device

inoperative or bypassed.

REQUIREMENT: 006. Repair or replace the probe type LWCO in order to correct this condition. If

replacement of the LWCO is required, the replacement LWCO must be equipped with a manual reset switch. Once complete test the LWCO for proper operation.

Location: Four Seasons Dry Cleaners & Laundry **Location #:** 1790815 **Violations:** 1

7015 Market St, , Wilmington, NC 28411-9729, Phone: 910-297-0362

Contact: Attn Alvaro Cervants, Owner, Four Seasons Dry Cleaners & Laundry, Phone: 910-297-0362

Object: NC263815 - Boiler - Fulton - 1995 - Blr Rm - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 01/25/2022 **ENTERED BY:** Keyes, Amanda

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 03-Water Gauge Glass NCAC 13-13.0408

SUBCATEGORY 058. Leaking.

CONDITION: 058. Water Gauge Glass NCAC 13-13.0408: Leaking.

REQUIREMENT: 058. Repair or replace the leaking gauge and test to ensure proper operation.

Location: Groometown United Methodist Church **Location #:** 1794479 **Violations:** 1

5005 Groometown Rd, , Greensboro, NC 27407-9607, Phone: 336-294-0341

Contact: There is no contact information available for this location.

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC404481 - Boiler - Sermeta - 2015 - Blr Rm - Active Violations This Object: 1

COMPANY: State of North Carolina

INSPECTOR: Johnson, Dean

OPENED: 03/15/2022 **ENTERED BY:** Johnson, Dean

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409

SUBCATEGORY 012. Flow switch inoperative or bypassed.

CONDITION: 012. LWCO and Flow Sensing Devices NCAC 13-13.0409: Flow switch is leaking

water through the control.

REQUIREMENT: 012. Install a flow switch that will shut off the burner in case of stoppage of water

flow and test to ensure proper operation.

Location: Harris Regional Hospital Location #: 1795916 Violations: 1

68 Hospital Rd, , Sylva, NC 28779-2722, Phone: 828-586-7000

Contact: Attn Mark Huston, Maintenance Supervisor, Harris Regional Hospital, , Cell:828-768-2837

Object: NC046098 - Boiler - Kewanee - 1958 - West Blr Rm - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler **INSPECTOR:** Possidente. James

OPENED: 09/16/2021 **ENTERED BY:** Putek, Terry

CLOSED: CLOSED BY:

TYPE: Certificate Blocking
CATEGORY: 16-Boiler Components
SUBCATEGORY 275. Tube/tube ends leak.

CONDITION: 275. Boiler Components: Tube/tube ends leak.

REQUIREMENT: 275. Repair the leaking tubes/tube ends. If weld repairs are required, a qualified "R"

certificate holder is necessary to perform the work.

Location: Hill Hosiery Mill Location #: 1797557 Violations: 1

602 Davidson St, , Thomasville, NC 27360-3628, Phone: 336-472-7508

Contact: Hill Hosiery Mill Inc, Phone: 336-472-7508

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC055056 - Boiler - Titusville - 1960 - Blr Rm - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler **INSPECTOR:** Leonard, Shannon D.

OPENED: 03/17/2022 ENTERED BY: Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409 **SUBCATEGORY** 006. Low water cutoff device inoperative or bypassed.

CONDITION: 006. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device

inoperative or bypassed.

REQUIREMENT: 006. Repair or replace the inoperable low water fuel cutoff control and test to

ensure proper operation.

Location: John Umstead Hospital Location #: 1802165 Violations: 1

1003 12th St,, Butner, NC 27509-1626, Phone: 919-575-7536

Contact: Attn Edd Lovette, John Umstead Hospital, Phone: 919-575-7971

Object: NC401217 - Boiler - Cleaver Brooks - 2014 - New Blr Rm - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler **INSPECTOR:** SORRENTINO, SEAN

OPENED: 02/14/2022 ENTERED BY: Keyes, Amanda

CLOSED: CLOSED BY:

TYPE: Certificate Blocking
CATEGORY: 16-Boiler Components
SUBCATEGORY 275. Tube/tube ends leak.

CONDITION: 275. Boiler Components: Tube/tube ends leak.

REQUIREMENT: 275. Repair the leaking tubes/tube ends. If weld repairs are required, a qualified "R"

certificate holder is necessary to perform the work.

Location: La Quinta Inn & Suites Charlotte Airport South Location #: 1804616 Violations: 1

4900 S Tryon St,, Charlotte, NC 28217-2404, Phone: 704-523-5599

Contact: Calvin Williams, Maintenance, La Quinta Inn & Suites Charlotte Airport South, Phone: 704-523-5599

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC283314 - Boiler - Weben Jarco - 1998 - 2nd Flr Equip Rm - Violations This Object: 1

Active

COMPANY: Hartford Steam Boiler INSPECTOR: Clav. Steven D.

OPENED: 11/05/2021 **ENTERED BY:** Putek, Terry

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409

SUBCATEGORY 009. Water level control inoperative or bypassed.

CONDITION: 009. LWCO and Flow Sensing Devices NCAC 13-13.0409: Water level control

inoperative or bypassed. LWCO has a leak.

REQUIREMENT: 009. Repair or replace the inoperable water level control and test to ensure proper

operation.

Location: Lake Jeanette Cleaners Location #: 442517 Violations: 1

417 Pisgah Church Rd, , Greensboro, NC 27455-2590, Phone: 336-288-1250 **Contact:** Chun Yi, Owner, Lake Jeanette Cleaners, Phone: 336-288-1250

Object: NC279241 - Boiler - Fulton - 1996 - Blr Rm - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler **INSPECTOR:** Leonard, Shannon D.

OPENED: 01/15/2022 ENTERED BY: Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations **SUBCATEGORY** 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations: Boiler overdue for required external operating

inspection.

REQUIREMENT: 363. Undefined Boiler Violations: An external operating inspection of this boiler must

be completed as soon as possible in order to address this condition.

Location: Mars Hill Baptist Church Location #: 1808332 Violations: 1

67 N Main St., Mars Hill, NC 28754-9503, Phone: 828-689-2911

Contact: Sharon Welsch, Secretary, Mars Hill Baptist Church, Phone: 828-689-2911

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC262845 - Boiler - Burnham - 1993 - Bsmt Blr Rm - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler **INSPECTOR:** Possidente, James

OPENED: 09/15/2021 **ENTERED BY:** Putek, Terry

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409 **SUBCATEGORY** 002. Only one of two low water cutoff devices required installed.

CONDITION: 002. LWCO and Flow Sensing Devices NCAC 13-13.0409: Only one of two low

water cutoff devices required installed.

REQUIREMENT: 002. Install a second low-water fuel cutoff device (LWCO) designed for the

appropriate service (Steam or Hot Water) that is equipped with a manual reset. When the LWCO shuts off the fuel supply to the boiler in the event of a low water condition, the fuel supply must be restarted manually by an operator. Test to ensure

proper operation.

Location: Medicago USA Location #: 3005097 Violations: 1

7 Triangle Dr, , Durham, NC 27709-0005, Phone: 919-313-9670

Contact: Attn Tatyana Blankenship, Director, Medicago USA Inc, Phone: 919-313-9670

Object: NC387341 - Boiler - Raypak - 2011 - Roof Terrace - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler **INSPECTOR:** Richey, Paul D.

OPENED: 02/08/2022 ENTERED BY: Keyes, Amanda

CLOSED: CLOSED BY:

TYPE: Certificate Blocking
CATEGORY: 16-Boiler Components
SUBCATEGORY 270. Water Leaks.

CONDITION: 270. Boiler Components: Water Leaks.

REQUIREMENT: 270. Repair the water leaks identified on the inspection report.

Location: Murdoch Center **Location #:** 1812698 **Violations:** 1

1600 E C St, , Butner, NC 27509-2530, Phone: 919-575-1181

Contact: Attn Gwynn Long, Supervisor, DHHS Murdoch Center, Phone: 919-575-1181

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC149064 - PV - Legion Industries - 1956 - Main Kitchen - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Richey, Paul D.

OPENED: 02/09/2022 ENTERED BY: Keyes, Amanda

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 06-Undefined Pressure Relieving Devices Violations **SUBCATEGORY** 478. Undefined Pressure Relieving Devices Violations.

CONDITION: 478. No steam to this object which makes it impossible to test PRD

REQUIREMENT: 478. Restore steam to this kettle and test PRD or properly disconnect this object.

Location: National Guard Armory Location #: 1813514 Violations: 1

700 Charles St, , Monroe, NC 28112-5725, Phone: 704-283-5512

Contact: National Guard Armory, Phone: 704-2835512

Object: NC374095 - Boiler - Weil-McLain - 2008 - Blr Rm - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Clay, Steven D.

OPENED: 09/13/2021 **ENTERED BY:** Putek, Terry

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 05-Temperature Controls NCAC 13-13.0406 **SUBCATEGORY** 093. High limit temperature control inoperative.

CONDITION: 093. Temperature Controls NCAC 13-13.0406: High limit temperature control

inoperative.

REQUIREMENT: 093. Repair or replace the inoperative high limit temperature control. Test to ensure

proper operation.

Location: National Guard Armory Location #: 1813555 Violations: 1

890 Withrow Rd, , Forest City, NC 28043-9697, Phone: 828-287-0669

Contact: Attn Blane Boyd, Director of Facility Maintenance, NGA Facilities Maintenance, Phone: 984-664-6094

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC279743 - Boiler - Weil-McLain - 1996 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler **INSPECTOR:** Possidente, James

OPENED: 01/11/2022 ENTERED BY: Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 25-Operation of PRDs NCAC 13-13.0405

SUBCATEGORY 395. Valve leaking.

CONDITION: 395. Operation of PRDs NCAC 13-13.0405: Valve leaking.

REQUIREMENT: 395. Replace the relief device with one set at a pressure not exceeding the

maximum allowed working pressure determined by the manufacturer. The

replacement valve must be ASME/NB certified.

Location: NC School Of Science & Mathematics Location #: 1813129 Violations: 1

1219 Broad St, , Durham, NC 27705-3577, Phone: 919-416-2672 **Contact:** NC School Of Science & Mathematics, Phone: 919-416-2793

Object: NC212851 - Boiler - Kewanee - 1984 - Main Blr Rm - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler **INSPECTOR:** SORRENTINO, SEAN

OPENED: 02/09/2022 ENTERED BY: Keyes, Amanda

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 25-Operation of PRDs NCAC 13-13.0405

SUBCATEGORY 395. Valve leaking.

CONDITION: 395. Operation of PRDs NCAC 13-13.0405: Valve leaking.

REQUIREMENT: 395. Replace the relief device with one set at a pressure not exceeding the

maximum allowed working pressure determined by the manufacturer. The

replacement valve must be ASME/NB certified.

Location: NC Wesleyan College Location #: 1813234 Violations: 1

3400 N Wesleyan Blvd, , Rocky Mount, NC 27804-8699, Phone: 252-985-5222

Contact: Renee Bradley, Facility Administrator, NC Wesleyan College, Phone: 252-985-5574

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC206070 - Boiler - Weil-McLain - 1982 - Nash Hall Blr Rm - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler INSPECTOR: SORRENTINO, SEAN

OPENED: 02/03/2022 ENTERED BY: Keyes, Amanda

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 24-Installation of PRDs NCAC 13-13.0405

SUBCATEGORY 377. Try lever not installed.

CONDITION: 377. Installation of PRDs NCAC 13-13.0405: Try lever not installed.

REQUIREMENT: 377. Replace the relief valve with one with a try lever. The replacement valve must

be ASME/NB certified.

Location: Quality Used Parts & Sales & Service Location #: 1807281 Violations: 1

5707 US Highway 264 W, , Washington, NC 27889-7692, Phone: 252-946-6495

Contact: There is no contact information available for this location.

Object: NC294692 - PV - Manchester - 1998 - Comp Rm - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 02/08/2022 **ENTERED BY:** Keyes, Amanda

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 09-Pressure Gauges NCAC 13-13.0407 **SUBCATEGORY** 030. Pressure gauge not installed.

CONDITION: 030. Pressure Gauges NCAC 13-13.0407: Pressure gauge not installed.

REQUIREMENT: 030. Install a pressure gauge on the equipment that is visible to the operator from

the floor or work platform. Gauge must be the proper range in accordance with NC

Administrative Code, Title 13, Chapter 13, Section .0407.

Location: River Landing At Sandy Ridge Location #: 1824609 Violations: 3

1575 John Knox Dr, , Colfax, NC 27235-9662, Phone: 336-668-4900

Contact: Eddie Hedrick, Manager, River Landing At Sandy Ridge, Phone: 336-668-4900

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC311181 - Boiler - PVI Industries - 2001 - Main Mech Rm M26 - Violations This Object: 1

Active

COMPANY: Hartford Steam Boiler **INSPECTOR:** Leonard, Shannon D.

OPENED: 02/14/2022 ENTERED BY: Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking
CATEGORY: 16-Boiler Components
SUBCATEGORY 275. Tube/tube ends leak.

CONDITION: 275. Boiler Components: Tube/tube ends leak: Possible tube leak front tube sheet

of boiler.

REQUIREMENT: 275. Repair the leaking tubes/tube ends. If weld repairs are required, a qualified "R"

certificate holder is necessary to perform the work.

Object: NC367358 - Boiler - Lochinvar - 2007 - Mech Rm A 309 - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler **INSPECTOR:** Leonard, Shannon D.

OPENED: 02/14/2022 ENTERED BY: Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409

SUBCATEGORY 020. Leaking gasket or joints.

CONDITION: 020. LWCO and Flow Sensing Devices NCAC 13-13.0409: Leaking gasket or joints:

Flow switch leaking.

REQUIREMENT: 020. Replace the leaking flow switch in order to correct this issue.

Object: NC367359 - Boiler - Lochinvar - 2007 - Mech Rm A 309 - Active Violations This Object: 1

COMPANY: Hartford Steam Boiler **INSPECTOR:** Leonard, Shannon D.

OPENED: 02/14/2022 ENTERED BY: Judd, Janie

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409

SUBCATEGORY 020. Leaking gasket or joints.

CONDITION: 020. LWCO and Flow Sensing Devices NCAC 13-13.0409: Leaking gasket or joints:

Flow switch leaking

REQUIREMENT: 020. Replace the leaking flow switch in order to correct this issue.

Location: Sunny Cleaners Location #: 2225593 Violations: 1

2871 Jones Franklin Rd, , Raleigh, NC 27606-4007, Phone: 919-233-9495 **Contact:** Attn Sun Chul Hwang, Owner, Sunny Cleaners, Phone: 919-233-9495

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC368059 - Boiler - Columbia - 2006 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler **INSPECTOR:** SORRENTINO, SEAN

OPENED: 03/07/2022 ENTERED BY: Keyes, Amanda

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 12-Casing, Stack Breeching and Flue

SUBCATEGORY 211. Combustion gas leaks.

CONDITION: 211. Casing, Stack Breeching and Flue: Combustion gas leaks.

REQUIREMENT: 211. Repair all combustion gas leaks in the casing, stack breeching, or flue.

Location: UFP Salisbury LLC Location #: 2158141 Violations: 1

2815 Woodtech Dr, , Newton, NC 28658-8967, Phone: 704-855-1600

Contact: UFPI Regulatory Compliance, Phone: 616-365-1526

Object: NC367821 - PV - Silvan - 2007 - SE Corner Bldg 3 - Active Violations This Object: 1

COMPANY: State of North Carolina

INSPECTOR: Hutchens, Mark

OPENED: 02/23/2022 **ENTERED BY:** Hutchens, Mark

CLOSED: CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 04-Installation of PRDs NCAC 13-13.0405 **SUBCATEGORY** 450. Pressure relieving devices not installed.

CONDITION: 450. Installation of PRDs NCAC 13-13.0405: Pressure relieving devices not

installed.

REQUIREMENT: 450. Install a pressure relieving device in accordance with NCAC 13-13.0405.

Violations This Report: 85
Locations This Report: 56