Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

(ASV CS) Central C			_ocation #:	1775429	Violations: 2
		8801-3854, Phone: 828-350-		7000/11	
Contact: Tim Hold	ombe, Manage	r, Asheville City Schools, Pho	one: 828-350	)-7000/Main	1 828-350-6196
Object: NC205160	) - Boiler - Weil	-McLain - 1982 - Blr Rm - Acti	ive	Violatior	ns This Object: 2
CO	MPANY:	State of North Carolina			
INS	SPECTOR:	(By Request), the Owner/Use	er		
OP	ENED:	01/13/2021	ENTE	RED BY:	Putek, Terry
CL	OSED:		CLOS	SED BY:	
TY	PE:	Certificate Blocking			
CA	TEGORY:	01-LWCO and Flow Sensing	Devices NC	AC 13-13.0	409
SU	BCATEGORY	005. No provision to test low	water cutoff	device.	
CO		005. LWCO and Flow Sensin water cutoff device.	g Devices N	CAC 13-13.	.0409: No provision to test low
RE		: 005. Equip the low water fuel cutoff device on the boiler with a vertical drain and blow-off valve assembly of not less than 3/4-inch nominal pipe size to allow for flushing and testing of the low water cutoff while the boiler is in operation.			
со	MPANY:	State of North Carolina			
INS	SPECTOR:	(By Request), the Owner/Use	er		
OP	PENED:	01/13/2021	ENTE	RED BY:	Putek, Terry
CL	OSED:		CLOS	SED BY:	-
TY	PE:	Certificate Blocking			
CA	TEGORY:	24-Installation of PRDs NCAG	C 13-13.040	5	
SU	BCATEGORY	372. Set pressure too high.			
CO		372. Installation of PRDs NC/ and SV #1 is 75 psi.	AC 13-13.04	05: Set pre	ssure too high. Mawp is 50 psi
RE		372. Replace the pressure re than the maximum allowable	•		with a set pressure no higher termined by the manufacturer.

Location: (ASV CS) Claxton Elem 241 Merrimon Ave, , Asheville, NC 28801-1217, Phone: 828-350-6500 Contact: Tim Holcombe, Manager, Asheville City Schools, Phone: 828-350-7000/Maint 828-350-6196

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC26	2601 - Boiler - Wei	-McLain - 1993 - Bsmt - Active	Violations This Object: 1
	COMPANY:	Hartford Steam Boiler	
	INSPECTOR:	Possidente, James	
	OPENED:	01/13/2021	ENTERED BY: Putek, Terry
	CLOSED:		CLOSED BY:
	TYPE:	Certificate Blocking	
	CATEGORY:	01-LWCO and Flow Sensing Devic	es NCAC 13-13.0409
	SUBCATEGORY	005. No provision to test low water	cutoff device.
	CONDITION:	005. LWCO and Flow Sensing Dev water cutoff device.	rices NCAC 13-13.0409: No provision to test lo
	REQUIREMENT:	blow-off valve assembly of not less	f device on the boiler with a vertical drain and than 3/4-inch nominal pipe size to allow for er cutoff while the boiler is in operation.
bject: NC26	2602 - Boiler - Weil	I-McLain - 1993 - Blr Rm - Active	Violations This Object: 1
	COMPANY:	Hartford Steam Boiler	
	INSPECTOR:	Possidente, James	
	OPENED:	01/13/2021	ENTERED BY: Putek, Terry
	CLOSED:		CLOSED BY:
	TYPE:	Certificate Blocking	
	CATEGORY:	01-LWCO and Flow Sensing Devic	es NCAC 13-13.0409
	SUBCATEGORY	005. No provision to test low water	cutoff device.
	CONDITION:	005. LWCO and Flow Sensing Dev water cutoff device.	rices NCAC 13-13.0409: No provision to test lo
	REQUIREMENT:	blow-off valve assembly of not less	f device on the boiler with a vertical drain and than 3/4-inch nominal pipe size to allow for er cutoff while the boiler is in operation.
bject: NC38	8477 - PV - Lochin	var - 2006 - Cafeteria Blr Rm - Activ	e Violations This Object: 1
	COMPANY:	Hartford Steam Boiler	
	INSPECTOR:	Possidente, James	
	OPENED:	01/13/2021	ENTERED BY: Putek, Terry
	CLOSED:		CLOSED BY:
	TYPE:	Certificate Blocking	
	CATEGORY:	04-Installation of PRDs NCAC 13-1	3.0405
	SUBCATEGORY	461. Incorrect pressure relieving de	evice(s) for the application.
	CONDITION:	461. Installation of PRDs NCAC 13	-13.0405: Incorrect pressure relieving device(s ve is pressure only mounted horizontal.
			one set at a pressure not exceeding the

Location: (ASV CS) Ira B Jones Elem Location #: 1800336 Violations: 1 544 Kimberly Ave, , Asheville, NC 28804-2560, Phone: 828-350-6700 Contact: Tim Holcombe, Manager, Asheville City Schools, Phone: 828-350-7000/Maint 828-350-6196

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object:	NC288783 - Boiler - Wei	I-McLain - 1996 - New Blr Rm - Active	Violations This Object: 1	
	COMPANY:	Hartford Steam Boiler		
	INSPECTOR:	Possidente, James		
	OPENED:	01/12/2021 EN	ITERED BY: Putek, Terry	
	CLOSED:	CL	OSED BY:	
	TYPE:	Certificate Blocking		
CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409			NCAC 13-13.0409	
	SUBCATEGORY	005. No provision to test low water cuto	off device.	
	CONDITION:	005. LWCO and Flow Sensing Devices water cutoff device.	NCAC 13-13.0409: No provision to test low	
	REQUIREMENT:	<b>UIREMENT:</b> 005. Equip the low water fuel cutoff device on the boiler with a vertical d blow-off valve assembly of not less than 3/4-inch nominal pipe size to al flushing and testing of the low water cutoff while the boiler is in operation Recommend installing probe type LWCO with test and reset button to al the device.		

Location: (ASV CS) Vance Elem 98 Sulphur Springs Rd, , Asheville, NC 28806-2646, Phone: 828-250-6600 Contact: Tim Holcombe, Manager, Asheville City Schools, Phone: 828-350-7000/Maint 828-350-6196

COMPANY:	Hartford Steam Boiler			
INSPECTOR:	Possidente, James			
OPENED:	01/13/2021	ENTERED BY:	Putek, Terry	
CLOSED:		CLOSED BY:		
TYPE:	Certificate Blocking			
CATEGORY:	01-LWCO and Flow Sensing	O and Flow Sensing Devices NCAC 13-13.0409		
SUBCATEGORY	005. No provision to test low v	water cutoff device.	ater cutoff device.	
	005. LWCO and Flow Sensing water cutoff device.	g Devices NCAC 13-13	8.0409: No provision to test lov	
	005. Equip the low water fuel blow-off valve assembly of no flushing and testing of the low	t less than 3/4-inch nor	minal pipe size to allow for	

Location: (DPS-C) Columbus CI - 4355 1255 Prison Camp Rd, , Whiteville, NC 28472-4887, Phone: 910-642-3285 Contact: NC Dept Of Public Safety - 13101, Phone: 919-716-3422 Violations: 5

Object: NC361313 - Boiler - Rbi	- 2005 - Elm Dorm - Active	Violations This Object: 1
COMPANY:	Hartford Steam Boiler	
INSPECTOR:	Rudolph, Jay	
OPENED:	11/24/2020	ENTERED BY: Judd, Janie
CLOSED:		CLOSED BY:
TYPE:	Certificate Blocking	
CATEGORY:	25-Operation of PRDs NCAC 13-13	3.0405
SUBCATEGORY	395. Valve leaking.	
CONDITION:	395. Operation of PRDs NCAC 13- leaking.	13.0405: Valve leaking: Pressure relief device
		ified pressure relief device with a set pressure of lief capacity of not less than 638 KBH, and with a
Dbject: NC362565 - Boiler - Rbi	- 2006 - Fier Dorm - Active	Violations This Object: 2
COMPANY:	Hartford Steam Boiler	
INSPECTOR:	Rudolph, Jay	
OPENED:	11/24/2020	ENTERED BY: Judd, Janie
CLOSED:		CLOSED BY:
TYPE:	Certificate Blocking	
CATEGORY:	07-Undefined Controls Violations	
SUBCATEGORY	112. Undefined Controls Violations	
CONDITION:	112. Undefined Controls Violations	. Flow switch leaking.
REQUIREMENT:	112. Undefined Controls Violations operation.	: Replace flow switch. Test to verify proper
COMPANY:	Hartford Steam Boiler	
INSPECTOR:	Rudolph, Jay	
OPENED:	11/24/2020	ENTERED BY: Judd, Janie
CLOSED:		CLOSED BY:
TYPE:	Certificate Blocking	
CATEGORY:	25-Operation of PRDs NCAC 13-13	3.0405
SUBCATEGORY	395. Valve leaking.	
CONDITION:	-	13.0405: Valve leaking: Pressure relief device
	395. Replace with a ASME/NB cert	ified pressure relief device with a set pressure of lief capacity of not less than 638 KBH, and with a

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC382455 - Boiler - Clev Active	veland Range - 2010 - Food Service	- Violations This Object: 2	
COMPANY:	Hartford Steam Boiler		
INSPECTOR:	Rudolph, Jay		
OPENED:	11/24/2020	ENTERED BY: Judd, Janie	
CLOSED:		CLOSED BY:	
TYPE:	Certificate Blocking		
CATEGORY:	03-Water Gauge Glass NCAC 13-1	13.0408	
SUBCATEGORY	058. Leaking.		
CONDITION:	CONDITION: 058. Water Gauge Glass NCAC 13-13.0408: Leaking.		
REQUIREMENT:	058. Repair or replace the leaking	gauge and test to ensure proper operation.	
COMPANY:	Hartford Steam Boiler		
INSPECTOR:	Rudolph, Jay		
OPENED:	11/24/2020	ENTERED BY: Judd, Janie	
CLOSED:		CLOSED BY:	
TYPE:	Certificate Blocking		
CATEGORY:	25-Operation of PRDs NCAC 13-13	3.0405	
SUBCATEGORY	395. Valve leaking.		
CONDITION:	395. Operation of PRDs NCAC 13- leaking.	13.0405: Valve leaking: Pressure relief device	
REQUIREMENT:		tified pressure relief device with a set pressure of ef capacity of not less than 266 PPH, and with a	

Location: (DPS-C) Enterprise Laundry Chase - 8255 Location #: 1786752 Violations: 1 201 Stevens Mill Rd, , Goldsboro, NC 27530-1056, Phone: 919-581-1037 Contact: NC Dept Of Public Safety - 71002, Phone: 919-716-3422

Dbject: NC393522 - Boiler - Miur	a - 2011 - Blr Rm - Active	Violations This Object: 1		
COMPANY:	State of North Carolina			
INSPECTOR:	Smith, Jeremy			
OPENED:	11/06/2020	ENTERED BY:	Smith, Jeremy	
CLOSED:		CLOSED BY:		
TYPE:	Certificate Blocking			
CATEGORY:	23-Undefined Boiler Violations			
SUBCATEGORY	363. Undefined Boiler Violations.			
CONDITION:	inspection every year. Contrary to	oiler Violations. All high-pressure boilers require an external year. Contrary to 13 NCAC 13.0211(b), an external inspection has ed on an annual basis. The last external inspection completed wa		
REQUIREMENT:	363. Undefined Boiler Violations. completed. Contact your inspecto schedule an external inspection.		•	

Location:	: (DPS-C) NCCIW - 3010 1034 Bragg St, , Raleigh, NC 276 Contact: Phillip Jones, Maintenar		Location #: 1779964 Violations: 2 610-3846, Phone: 919-733-4340 nce Supervisor, NCCIW - 3010, Phone: 919-508-1690				
	Object:	NC381483 - Boiler - PVI	Industries - 2010 - Falcom Blr Rm - Act	ive Violation	s This Object: 1		
		COMPANY: INSPECTOR: OPENED:	Hartford Steam Boiler SORRENTINO, SEAN 12/08/2020 EN	ITERED BY:	Keyes, Amanda		
		CLOSED:		OSED BY:			
		TYPE:	Certificate Blocking				
		CATEGORY:	16-Boiler Components				
		SUBCATEGORY	270. Water Leaks.				
		CONDITION:	270. Boiler Components: Water Leaks				
		REQUIREMENT:	T: 270. Repair the water leaks identified on the inspection report. If welding is required, a qualified "R" certificate holder is necessary to perform the repair.				
	Object:	NC401596 - Boiler - PVI	Industries - 2014 - Sparrow N - Active	Violation	s This Object: 1		
		COMPANY: INSPECTOR: OPENED:	Hartford Steam Boiler SORRENTINO, SEAN 12/08/2020 EN	ITERED BY:	Keyes, Amanda		
		CLOSED:		OSED BY:			
		TYPE:	Certificate Blocking				
		CATEGORY:	16-Boiler Components				
		SUBCATEGORY	270. Water Leaks.				
		CONDITION:	270. Boiler Components: Water Leaks	. Tank leaking	at unknown location.		
		REQUIREMENT:	270. Repair the water leaks identified or required, a qualified "R" certificate hold	on the inspection	on report. If welding is		
Location:	701 Stev		<b>Location</b> NC 27530-9712, Phone: 919-731-202 ty - 13101, Phone: 919-716-3422	<b>#:</b> 1814142 23	Violations: 6		
	Object:	NC266530 - Boiler - Tele	dyne Laars - 1993 - Admin Bldg - Activ	e Violation	s This Object: 1		
		CONDITION:	CL Certificate Blocking 06-Thermometer NCAC 13-13.0410 111. Thermometer inoperative. 111. Thermometer NCAC 13-13.0410:				
		KEQUIKEMENT:	111. Replace inoperative thermometer temperature in degrees Fahrenheit of t range of approximately 2 times the inter than 1 1/2 times the intended operating intended operating temperature.	he water. The ended operating	thermometer shall have a g temperature but not less		

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC266537 - Boiler - Rhe	em/Ruud - 1993 - Dorm D1 - Active	Violations This Object: 1		
COMPANY:	Hartford Steam Boiler			
INSPECTOR:	Rudolph, Jay			
OPENED:	12/16/2020	ENTERED BY: Judd, Janie		
CLOSED:		CLOSED BY:		
TYPE:	Certificate Blocking			
CATEGORY:	06-Thermometer NCAC 13-13.0410			
SUBCATEGORY	111. Thermometer inoperative.			
CONDITION:	111. Thermometer NCAC 13-13.04	10: Thermometer inoperative.		
REQUIREMENT:	111. Replace inoperative thermometer at/in the boiler outlet to measure the temperature in degrees Fahrenheit of the water. The thermometer shall have a range of approximately 2 times the intended operating temperature but not less than 1 1/2 times the intended operating temperature, nor more than 4 times the intended operating temperature.			

Object: NC266542 - Boiler - Rheem/Ruud - 1993 - Dorm C4 - Active Violations This Object: 1

			-
COMPANY:	Hartford Steam Boiler		
INSPECTOR:	Rudolph, Jay		
OPENED:	12/17/2020	ENTERED BY:	Judd, Janie
CLOSED:		CLOSED BY:	
TYPE:	Certificate Blocking		
CATEGORY:	06-Thermometer NCAC 13-13.04	410	
SUBCATEGORY	111. Thermometer inoperative.		
CONDITION:	111. Thermometer NCAC 13-13.	0410: Thermometer	<sup>·</sup> inoperative.
REQUIREMENT:	111. Replace inoperative thermo temperature in degrees Fahrenho range of approximately 2 times th than 1 1/2 times the intended oper intended operating temperature.	eit of the water. The ne intended operatir	thermometer shall have a thermometer shall have a temperature but not less

COMPANY:	Hartford Steam Boiler			
INSPECTOR:	Rudolph, Jay			
OPENED:	12/17/2020	ENTERED BY:	Judd, Janie	
CLOSED:		CLOSED BY:		
TYPE:	Certificate Blocking			
CATEGORY:	23-Undefined Boiler Violations			
SUBCATEGORY	363. Undefined Boiler Violations.			
CONDITION:	363. Undefined Boiler Violations. E	oiler not operating	]	
		Violations. Reschedule inspection for a time when the boiler ety devices can be verified to function properly or disconnec water and electrical sources.		

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC320439 - Boiler - Rhe	em/Ruud - 1999 - Dorm C1 - Active	Violations This Object: 1	
COMPANY:	Hartford Steam Boiler		
INSPECTOR:	Rudolph, Jay		
OPENED:	12/17/2020	ENTERED BY: Judd, Janie	
CLOSED:		CLOSED BY:	
TYPE:	Certificate Blocking		
CATEGORY:	RY: 06-Thermometer NCAC 13-13.0410		
SUBCATEGORY	111. Thermometer inoperative.		
CONDITION:	111. Thermometer NCAC 13-13.04	10: Thermometer inoperative.	
REQUIREMENT:	<b>T:</b> 111. Replace inoperative thermometer at/in the boiler outlet to measure the temperature in degrees Fahrenheit of the water. The thermometer shall have a range of approximately 2 times the intended operating temperature but not less than 1 1/2 times the intended operating temperature, nor more than 4 times the intended operating temperature.		

Object: NC381334 - Boiler - Lochinvar - 2008 - Kitchen Mech Rm - Active Violations This Object: 1

COMPANY:	Hartford Steam Boiler		
INSPECTOR:	Rudolph, Jay		
OPENED:	12/16/2020	ENTERED BY:	Judd, Janie
CLOSED:		CLOSED BY:	
TYPE:	Certificate Blocking		
CATEGORY:	06-Thermometer NCAC 13-13.041	0	
SUBCATEGORY	111. Thermometer inoperative.		
CONDITION:	111. Thermometer NCAC 13-13.04	10: Thermometer	inoperative.
REQUIREMENT:	111. Replace inoperative thermometemperature in degrees Fahrenheit range of approximately 2 times the than 1 1/2 times the intended operating temperature.	of the water. The intended operatin	thermometer shall have a g temperature but not less

Location:(LEE) O T Sloan ParkLocation #: 1815639Violations: 41420 Bragg St, , Sanford, NC27330-5435, Phone: 919-775-2107Contact:Attn Russell Spivey, Lee County Government General Services, Phone: 919-718-4622

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

 Active COMPANY:	State of North Carolina		
••••••			
INSPECTOR:	Gunto III, Andrew		
OPENED: CLOSED:	10/20/2020	ENTERED BY: CLOSED BY:	Gunto III, Andrew
TYPE:	Certificate Blocking	CLUSED B1.	
CATEGORY:	23-Undefined Boiler Violations		
	363. Undefined Boiler Violations.		
CONDITION:	363. Undefined Boiler Violations.		
CONDITION:	At the time of the 10/20/2020 insp	pection, this boiler	was not in operation.
REQUIREMENT:	363. Undefined Boiler Violations. At follow up inspection the boiler will be need. This includes the ve its manual reset.		d an operational demonstration gh-limit temperature controls and
COMPANY:	State of North Carolina		
INSPECTOR:	Gunto III, Andrew		
OPENED:	10/20/2020	ENTERED BY:	Gunto III, Andrew
CLOSED:		CLOSED BY:	
TYPE:	Certificate Blocking		
CATEGORY:	24-Installation of PRDs NCAC 13	3-13.0405	
SUBCATEGORY	378. Discharge opening directed	improperly.	
CONDITION:	378. Installation of PRDs NCAC The safety valve on this boiler is		e location.
REQUIREMENT:	378. Redirect the discharge to a s Pipe the safety valve vent so that repairs must satisfy the requirem of North Carolina.	refrigerant is vent	ted outside to a safe location. All

**Object:** NC419418 - Boiler - Teledyne Laars - 2017 - Outside pool house - **Violations This Object:** 2 Active

COMPANY:	State of North Carolina		
INSPECTOR:	Gunto III, Andrew		
OPENED:	10/20/2020	ENTERED BY:	Gunto III, Andrew
CLOSED:		CLOSED BY:	
TYPE:	Certificate Blocking		
CATEGORY:	23-Undefined Boiler Violations		
SUBCATEGORY	363. Undefined Boiler Violations.		
••••••	363. Undefined Boiler Violations. At the time of the 10/20/2020 inspe	ction, this boiler w	as not in operation.
	363. Undefined Boiler Violations. At follow up inspection the boiler m will be need. This includes the veri its manual reset.		

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

	COMPANY:	State of North Carolina		
	INSPECTOR:	Gunto III, Andrew		
	OPENED:	10/20/2020	ENTERED BY:	Gunto III, Andrew
	CLOSED:		CLOSED BY:	
	TYPE:	Certificate Blocking		
	CATEGORY:	24-Installation of PRDs NC		
	SUBCATEGOR	Y 378. Discharge opening dire	ected improperly.	
	CONDITION:	378. Installation of PRDs N The safety valve on this boi		e location.
			o that refrigerant is vente	ed outside to a safe location. A Boiler and Pressure Vessel Ac
1801 Fa	•	NC 27707-3129, Phone: 919 O #P107428 NC Central Univ		Violations: 1 Phone: 919-530-7244
1801 Fa	yetteville St, , Durham, N t: Attn Lori Blake Reid Po	NC 27707-3129, Phone: 919 O #P107428, NC Central Univ bcock & Wilcox - 1998 - Blr H	530-6313 versity Shephard Station,	
1801 Fa	yetteville St, , Durham, N t: Attn Lori Blake Reid Po NC293050 - Boiler - Ba	O #P107428, NC Central Univ	530-6313 versity Shephard Station,	Phone: 919-530-7244
1801 Fa	yetteville St, , Durham, N t: Attn Lori Blake Reid Po NC293050 - Boiler - Ba Active	O #P107428, NC Central Univ bcock & Wilcox - 1998 - Blr H	530-6313 versity Shephard Station,	Phone: 919-530-7244
1801 Fa	yetteville St, , Durham, N t: Attn Lori Blake Reid Po NC293050 - Boiler - Ba Active COMPANY:	O #P107428, NC Central Univ bcock & Wilcox - 1998 - Blr H Hartford Steam Boiler	530-6313 versity Shephard Station,	Phone: 919-530-7244
1801 Fa	yetteville St, , Durham, N t: Attn Lori Blake Reid Po NC293050 - Boiler - Ba Active COMPANY: INSPECTOR:	O #P107428, NC Central Univ bcock & Wilcox - 1998 - Blr H Hartford Steam Boiler SORRENTINO, SEAN	530-6313 versity Shephard Station, ouse Blr 1 - <b>Violatio</b>	Phone: 919-530-7244 ns This Object: 1
1801 Fa	yetteville St, , Durham, N t: Attn Lori Blake Reid Po NC293050 - Boiler - Ba Active COMPANY: INSPECTOR: OPENED:	O #P107428, NC Central Univ bcock & Wilcox - 1998 - Blr H Hartford Steam Boiler SORRENTINO, SEAN	530-6313 versity Shephard Station, ouse Blr 1 - Violation	Phone: 919-530-7244 ns This Object: 1
1801 Fa	yetteville St, , Durham, N t: Attn Lori Blake Reid Po NC293050 - Boiler - Ba Active COMPANY: INSPECTOR: OPENED: CLOSED:	O #P107428, NC Central Univ bcock & Wilcox - 1998 - Blr H Hartford Steam Boiler SORRENTINO, SEAN 11/18/2020	ENTERED BY: CLOSED BY:	Phone: 919-530-7244 ns This Object: 1
1801 Fa	yetteville St, , Durham, N t: Attn Lori Blake Reid Po NC293050 - Boiler - Bal Active COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	O #P107428, NC Central Univ bcock & Wilcox - 1998 - Blr H Hartford Steam Boiler SORRENTINO, SEAN 11/18/2020 Certificate Blocking	ENTERED BY: CLOSED BY:	Phone: 919-530-7244 ns This Object: 1
1801 Fa	yetteville St, , Durham, N t: Attn Lori Blake Reid Po NC293050 - Boiler - Bal Active COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	O #P107428, NC Central Univ bcock & Wilcox - 1998 - Blr H Hartford Steam Boiler SORRENTINO, SEAN 11/18/2020 Certificate Blocking 23-Undefined Boiler Violatio	ENTERED BY: CLOSED BY: CLOSED BY:	Phone: 919-530-7244 ns This Object: 1 Keyes, Amanda

Location: (NCDOT) Highway Div 12 Equipment Office Location #: 1782980 Violations: 2 1710 E Marion St, , Shelby, NC 28152-6259, Phone: 704-480-9020 Contact: Attn Jennifer Savage, Accounting, NC Dept Of Transportation, Phone: 919-835-8002

Object: NC337945 - Boiler - Pee	rless - 2002 - Blr Rm - Active	Violation	is This Object: 2
COMPANY:	Hartford Steam Boiler		
INSPECTOR:	Possidente, James		
OPENED:	12/15/2020	ENTERED BY:	Putek, Terry
CLOSED:		CLOSED BY:	
TYPE:	Certificate Blocking		
CATEGORY:	13-Burners and Fuel Supply System	ms	
SUBCATEGORY	232. Gas train has improper ventin	g.	
CONDITION:	232. Burners and Fuel Supply Syst	tems: Gas train ha	s improper venting.
REQUIREMENT:	232. Vent the gas train to a safe po	pint.	
COMPANY:	Hartford Steam Boiler		
INSPECTOR:	Possidente, James		
OPENED:	12/15/2020	ENTERED BY:	Putek, Terry
CLOSED:		CLOSED BY:	
TYPE:	Certificate Blocking		
CATEGORY:	26-Undefined Pressure Relieving	Devices Violations	
SUBCATEGORY	399. Undefined Pressure Relieving	Devices Violation	S.
CONDITION:	399. Undefined Pressure Relieving improper installation. Horizontal co		s. Pressure relief valve
REQUIREMENT:	399. Undefined Pressure Relieving valve so the valve stem is in vertica to point of discharge.		

Location: (NEW HANOVER) Cape Fear Museum	Location #: 1814368	Violations: 1
814 Market St,, Wilmington, NC 28401-4731, Phone:	910-341-4350	
Contact: New Hanover County Government, Phone:	910-798-4330	
Object: NC/10285 - Boiler - Sermeta - 2018 - Bir Pm	- Activo Violation	s This Object: 1

ject: NC419285 - Boiler - Serr	neta - 2018 - Blr Rm - Active	Violations This Object: 1
COMPANY:	Hartford Steam Boiler	
INSPECTOR:	Rudolph, Jay	
OPENED:	11/24/2020	ENTERED BY: Judd, Janie
CLOSED:		CLOSED BY:
TYPE:	Certificate Blocking	
CATEGORY:	25-Operation of PRDs NCAC	13-13.0405
SUBCATEGORY	395. Valve leaking.	
CONDITION:	395. Operation of PRDs NCA leaking.	C 13-13.0405: Valve leaking: Pressure relief device
REQUIREMENT:	•	B certified pressure relief device with a set pressure of a relief capacity of not less than 994 KBH and with a

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

	Object: NC384766 - Boiler - A C	Smith - 2010 - Blr Rm - Active     Violations This Ob	ject: 1
	COMPANY:	Hartford Steam Boiler	
	INSPECTOR:	Rudolph, Jay	
	OPENED:	01/28/2020 ENTERED BY: Judd, Jan	nie
	CLOSED:	CLOSED BY:	
	TYPE:	Certificate Blocking	
	CATEGORY:	16-Boiler Components	
	SUBCATEGORY	f 270. Water Leaks.	
	CONDITION:	270. Boiler Components: Water Leaks.	
	REQUIREMENT	: 270. Determine location of leak and repair. If weld repair is requ certificate holder is required to perform repair.	iired "R" stamp
ation:	Contact: Attn Eric Poss, Director		ions: 1 vject: 1
cation:	900 Hillsborough St, , Raleigh, NG Contact: Attn Eric Poss, Director	<b>Location #:</b> 1832204 <b>Violat</b> C 27603-1610, Phone: 919-424-4132 r of Facilities, Saint Marys School, Phone: 919-424-4132	
cation:	900 Hillsborough St, , Raleigh, NG Contact: Attn Eric Poss, Director Object: NC361042 - Boiler - Tele COMPANY:	Location #: 1832204 Violati C 27603-1610, Phone: 919-424-4132 r of Facilities, Saint Marys School, Phone: 919-424-4132 edyne Laars - 2006 - Outside Pool - Active Violations This Ob Hartford Steam Boiler	
ation:	900 Hillsborough St, , Raleigh, NG Contact: Attn Eric Poss, Director Object: NC361042 - Boiler - Tele COMPANY: INSPECTOR:	Location #: 1832204 Violati C 27603-1610, Phone: 919-424-4132 r of Facilities, Saint Marys School, Phone: 919-424-4132 edyne Laars - 2006 - Outside Pool - Active Violations This Ob Hartford Steam Boiler Rudolph, Jay	ject: 1
ation:	900 Hillsborough St, , Raleigh, NG Contact: Attn Eric Poss, Director Object: NC361042 - Boiler - Tele COMPANY:	Location #: 1832204 Violati C 27603-1610, Phone: 919-424-4132 r of Facilities, Saint Marys School, Phone: 919-424-4132 edyne Laars - 2006 - Outside Pool - Active Violations This Ob Hartford Steam Boiler Rudolph, Jay	ject: 1
ation:	900 Hillsborough St, , Raleigh, NG Contact: Attn Eric Poss, Director Object: NC361042 - Boiler - Tele COMPANY: INSPECTOR: OPENED:	Location #: 1832204 Violati C 27603-1610, Phone: 919-424-4132 r of Facilities, Saint Marys School, Phone: 919-424-4132 edyne Laars - 2006 - Outside Pool - Active Violations This Ob Hartford Steam Boiler Rudolph, Jay 01/28/2020 ENTERED BY: Judd, Jar	ject: 1
ation:	900 Hillsborough St, , Raleigh, NG Contact: Attn Eric Poss, Director Object: NC361042 - Boiler - Tele COMPANY: INSPECTOR: OPENED: CLOSED:	Location #: 1832204 Violati C 27603-1610, Phone: 919-424-4132 r of Facilities, Saint Marys School, Phone: 919-424-4132 edyne Laars - 2006 - Outside Pool - Active Violations This Ob Hartford Steam Boiler Rudolph, Jay 01/28/2020 ENTERED BY: Judd, Jan CLOSED BY:	ject: 1
ation:	900 Hillsborough St, , Raleigh, NG Contact: Attn Eric Poss, Director Object: NC361042 - Boiler - Tele COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	Location #: 1832204 Violati C 27603-1610, Phone: 919-424-4132 r of Facilities, Saint Marys School, Phone: 919-424-4132 edyne Laars - 2006 - Outside Pool - Active Violations This Ob Hartford Steam Boiler Rudolph, Jay 01/28/2020 ENTERED BY: Judd, Jan CLOSED BY: Certificate Blocking	ject: 1
ation:	900 Hillsborough St, , Raleigh, NG Contact: Attn Eric Poss, Director Object: NC361042 - Boiler - Tele COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	Location #: 1832204 Violati C 27603-1610, Phone: 919-424-4132 r of Facilities, Saint Marys School, Phone: 919-424-4132 edyne Laars - 2006 - Outside Pool - Active Violations This Ob Hartford Steam Boiler Rudolph, Jay 01/28/2020 ENTERED BY: Judd, Jan CLOSED BY: Certificate Blocking 25-Operation of PRDs NCAC 13-13.0405	n <b>ject:</b> 1

Location: (UNC-CH) George M Horton Res Hall-136 411 Skipper Bowles Dr, , Chapel Hill, NC 27514-3434, Phone: 919-962-1271 Contact: Attn Lawrence Peoples, Manager, UNC Chapel Hill - Giles Horney Bldg 168, Phone: 919-843-8771

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object:	NC363063 - PV - Cemli	ne - 2005 - Mech Rm - Active	Violatio	ns This Object: 1
	COMPANY:	Hartford Steam Boiler		
	INSPECTOR:	SORRENTINO, SEAN		
	OPENED:	07/31/2020	ENTERED BY:	Keyes, Amanda
	CLOSED:		CLOSED BY:	
	TYPE:	Certificate Blocking		
	CATEGORY:	05-Operation of PRDs NCAC 1	3-13.0405	
	SUBCATEGOR	<b>Y</b> 475. Valve leaking.		
	CONDITION:	475. Operation of PRDs NCAC	: 13-13.0405: Valve le	aking.
		maximum allowed working pres replacement valve must be AS		he manufacturer. The
104 Ridg		tr-390 <b>Lo</b> 27514-4387, Phone: (919)843-8 s, Manager, UNC Chapel Hill - Gi		<b>Violations:</b> 1 Phone: 919-843-877
104 Ridg Contact	ge Rd, , Chapel Hill, NC : Attn Lawrence People	27514-4387, Phone: (919)843-8	3771 iles Horney Bldg 168,	
104 Ridg Contact	ge Rd, , Chapel Hill, NC : Attn Lawrence People	27514-4387, Phone: (919)843-8 s, Manager, UNC Chapel Hill - Gi	3771 iles Horney Bldg 168,	Phone: 919-843-877
104 Ridg Contact	ge Rd, , Chapel Hill, NC : Attn Lawrence Peoples NC357411 - PV - Cemli	27514-4387, Phone: (919)843-8 s, Manager, UNC Chapel Hill - Gi ne - 2004 - Mech Rm - Active	3771 iles Horney Bldg 168,	Phone: 919-843-877
104 Ridg Contact	ge Rd, , Chapel Hill, NC : Attn Lawrence People NC357411 - PV - Cemli COMPANY:	27514-4387, Phone: (919)843-8 s, Manager, UNC Chapel Hill - Gi ne - 2004 - Mech Rm - Active Hartford Steam Boiler	3771 iles Horney Bldg 168,	Phone: 919-843-877
104 Ridg Contact	ye Rd, , Chapel Hill, NC : Attn Lawrence Peoples NC357411 - PV - Cemli COMPANY: INSPECTOR:	27514-4387, Phone: (919)843-8 s, Manager, UNC Chapel Hill - Gi ne - 2004 - Mech Rm - Active Hartford Steam Boiler SORRENTINO, SEAN	3771 iles Horney Bldg 168, <b>Violatio</b>	Phone: 919-843-877 <sup>,</sup> ns This Object: 1
104 Ridg Contact	ge Rd, , Chapel Hill, NC : Attn Lawrence Peoples NC357411 - PV - Cemli COMPANY: INSPECTOR: OPENED:	27514-4387, Phone: (919)843-8 s, Manager, UNC Chapel Hill - Gi ne - 2004 - Mech Rm - Active Hartford Steam Boiler SORRENTINO, SEAN	3771 iles Horney Bldg 168, Violation ENTERED BY:	Phone: 919-843-877 <sup>,</sup> ns This Object: 1
104 Ridg Contact	ge Rd, , Chapel Hill, NC : Attn Lawrence Peoples NC357411 - PV - Cemli COMPANY: INSPECTOR: OPENED: CLOSED:	27514-4387, Phone: (919)843-8 s, Manager, UNC Chapel Hill - Gi ne - 2004 - Mech Rm - Active Hartford Steam Boiler SORRENTINO, SEAN 07/14/2020	3771 iles Horney Bldg 168, Violation ENTERED BY: CLOSED BY:	Phone: 919-843-877 <sup>,</sup> ns This Object: 1
104 Ridg Contact	ye Rd, , Chapel Hill, NC : Attn Lawrence Peoples NC357411 - PV - Cemli COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	27514-4387, Phone: (919)843-8 s, Manager, UNC Chapel Hill - Gi ne - 2004 - Mech Rm - Active Hartford Steam Boiler SORRENTINO, SEAN 07/14/2020 Certificate Blocking	3771 iles Horney Bldg 168, Violation ENTERED BY: CLOSED BY:	Phone: 919-843-877 <sup>,</sup> ns This Object: 1
104 Ridg Contact	ye Rd, , Chapel Hill, NC : Attn Lawrence Peoples NC357411 - PV - Cemli COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	27514-4387, Phone: (919)843-8 s, Manager, UNC Chapel Hill - Gi ne - 2004 - Mech Rm - Active Hartford Steam Boiler SORRENTINO, SEAN 07/14/2020 Certificate Blocking 05-Operation of PRDs NCAC 1	3771 iles Horney Bldg 168, Violation ENTERED BY: CLOSED BY: 13-13.0405	Phone: 919-843-877 <sup>4</sup> n <b>s This Object:</b> 1 Keyes, Amanda

Location:(WILKES CS) C B Eller ElemLocation #: 1771961Violations: 11288 Cb Eller School Rd, , Elkin, NC28621-8884, Phone: 336-835-5640Contact: Attn Bergi Speaks, Maintenance Director, Wilkes County Schools, Phone: 336-651-4009

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC086235 - Boiler - Kew	anee - 1965 - Blr Rm - Active	Violations This Object: 1
COMPANY:	Hartford Steam Boiler	
INSPECTOR:	Leonard, Shannon D.	
OPENED:	12/10/2020	ENTERED BY: Judd, Janie
CLOSED:		CLOSED BY:
TYPE:	Certificate Blocking	
CATEGORY:	25-Operation of PRDs NCAC 13	3-13.0405
SUBCATEGORY	395. Valve leaking.	
CONDITION:	395. Operation of PRDs NCAC (PRD) leaking.	13-13.0405: Valve leaking: Pressure relief device
REQUIREMENT:	pressure of 30 PSI or less and a The replacement PRD must be	vith an ASME/NB stamped PRD having a set a relieving capacity of 2,625,000 BTU/Hour or more equipped with a try lever and the PRD discharge location (I.E. within 6" of the boiler room floor).

Location:(WILKES CS) Central Wilkes MiddleLocation #: 2910852Violations: 13541 S NC Highway 16, , Moravian Falls, NC28654-9860, Phone: 336-667-7453Contact: Attn Bergi Speaks, Maintenance Director, Wilkes County Schools, Phone: 336-651-4009

Object: NC383464 - PV - A O Sn	nith - 2001 - Cafeteria - Active	Violatio	ns This Object: 1
COMPANY:	Hartford Steam Boiler		
INSPECTOR:	Leonard, Shannon D.		
OPENED:	12/10/2020	ENTERED BY:	Judd, Janie
CLOSED:		CLOSED BY:	
TYPE:	Certificate Blocking		
CATEGORY:	05-Operation of PRDs NCAC 13	-13.0405	
SUBCATEGORY	475. Valve leaking.		
CONDITION:	475. Operation of PRDs NCAC 1 leaking.	3-13.0405: Valve le	aking: Pressure relief valve
REQUIREMENT:	475. Replace the leaking PRD w pressure relieving type PRD hav a relieving capacity of not lest that be equipped with a try-lever and location (I.E. with 6" of the mech	ing a set pressure c an 189,000 BTU/Ho the PRD discharge	of not greater than 150 PSI and our. The replacement PRD must

Location: (WILKES CS) Wilkes Central High 1179 Moravian Falls Rd, , Wilkesboro, NC 28697-7636, Phone: 336-667-5277 Contact: Attn Bergi Speaks, Maintenance Director, Wilkes County Schools, Phone: 336-651-4009

	Object: NC19	92411 - Boiler - Wei	I-McLain - 1980 - Blr Rm - Active	Violation	ns This Object: 1
		COMPANY:	Hartford Steam Boiler		
		INSPECTOR:	Leonard, Shannon D.		
		OPENED:	12/10/2020	ENTERED BY:	Judd, Janie
		CLOSED:		CLOSED BY:	
		TYPE:	Certificate Blocking		
		CATEGORY:	25-Operation of PRDs NCAC 13-1	3.0405	
		SUBCATEGORY	' 395. Valve leaking.		
		CONDITION:	395. Operation of PRDs NCAC 13	-13.0405: Pressure	e relief device (PRD) leaking.
		REQUIREMENT:	395.Replace the leaking PRD with pressure of 50 PSI or less and a re The replacement PRD must be eq must be piped full size to a safe lo	elieving capacity of uipped with a try-le	<sup>f</sup> 2,040,000 BTU/Hour or more ever and the PRD discharge
cation:		gy Park Ln, , Fuqua	<b>Loca</b> y Varina, NC 27526-9311, Phone: , Aviator Brewing Co, Phone: 919-		<b>Violations:</b> 3 9-601-5497
	Object: NC38	39917 - Boiler - Colu	umbia - 2011 - Front Corner - Active	e Violation	ns This Object: 3
		COMPANY:	State of North Carolina		
		INSPECTOR:			
			Fish, Emily 08/20/2020	ENTERED BY:	Fish, Emily
		INSPECTOR:	Fish, Emily	ENTERED BY: CLOSED BY:	Fish, Emily
		INSPECTOR: OPENED:	Fish, Emily 08/20/2020		Fish, Emily
		INSPECTOR: OPENED: CLOSED:	Fish, Emily 08/20/2020 Certificate Blocking	CLOSED BY:	
		INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	Fish, Emily 08/20/2020 Certificate Blocking 01-LWCO and Flow Sensing Devi	CLOSED BY: ces NCAC 13-13.0	
		INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	Fish, Emily 08/20/2020 Certificate Blocking	CLOSED BY: ces NCAC 13-13.0 r cutoff device. vices NCAC 13-13	.0409: No provision to test lo
		INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY: SUBCATEGORY CONDITION:	Fish, Emily 08/20/2020 Certificate Blocking 01-LWCO and Flow Sensing Devic 005. No provision to test low wate 005. LWCO and Flow Sensing De water cutoff device. Manual reset	CLOSED BY: ces NCAC 13-13.0 r cutoff device. vices NCAC 13-13 LWCO could not be ing state so the LW	409 .0409: No provision to test lo e tested due to inoperative VCO can be safely and
		INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY: SUBCATEGORY CONDITION:	Fish, Emily 08/20/2020 Certificate Blocking 01-LWCO and Flow Sensing Devi 005. No provision to test low wate 005. LWCO and Flow Sensing De water cutoff device. Manual reset sight glass. 005. Repair sight glass to function accurately tested. Contact Emily F	CLOSED BY: ces NCAC 13-13.0 r cutoff device. vices NCAC 13-13 LWCO could not be ing state so the LW	409 .0409: No provision to test lov e tested due to inoperative VCO can be safely and
		INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY: SUBCATEGORY CONDITION: REQUIREMENT:	Fish, Emily 08/20/2020 Certificate Blocking 01-LWCO and Flow Sensing Devia 005. No provision to test low wate 005. LWCO and Flow Sensing De water cutoff device. Manual reset sight glass. 005. Repair sight glass to function accurately tested. Contact Emily F to schedule reinspection.	CLOSED BY: ces NCAC 13-13.0 r cutoff device. vices NCAC 13-13 LWCO could not be ing state so the LW	409 .0409: No provision to test lo e tested due to inoperative VCO can be safely and
		INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY: SUBCATEGORY CONDITION: REQUIREMENT:	Fish, Emily 08/20/2020 Certificate Blocking 01-LWCO and Flow Sensing Devia 005. No provision to test low wate 005. LWCO and Flow Sensing De water cutoff device. Manual reset sight glass. 005. Repair sight glass to function accurately tested. Contact Emily F to schedule reinspection. State of North Carolina	CLOSED BY: ces NCAC 13-13.0 r cutoff device. vices NCAC 13-13 LWCO could not be ing state so the LW	409 .0409: No provision to test lov e tested due to inoperative VCO can be safely and
		INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY: SUBCATEGORY CONDITION: REQUIREMENT: COMPANY: INSPECTOR:	Fish, Emily 08/20/2020 Certificate Blocking 01-LWCO and Flow Sensing Devia 005. No provision to test low water 005. LWCO and Flow Sensing De water cutoff device. Manual reset sight glass. 005. Repair sight glass to function accurately tested. Contact Emily F to schedule reinspection. State of North Carolina Fish, Emily	CLOSED BY: ces NCAC 13-13.0 r cutoff device. vices NCAC 13-13 LWCO could not be ing state so the LV ish at (919) 268-07	409 .0409: No provision to test lov e tested due to inoperative VCO can be safely and 725 when repairs are complet
		INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY: SUBCATEGORY CONDITION: REQUIREMENT: COMPANY: INSPECTOR: OPENED:	Fish, Emily 08/20/2020 Certificate Blocking 01-LWCO and Flow Sensing Devia 005. No provision to test low water 005. LWCO and Flow Sensing De water cutoff device. Manual reset sight glass. 005. Repair sight glass to function accurately tested. Contact Emily F to schedule reinspection. State of North Carolina Fish, Emily	CLOSED BY: ces NCAC 13-13.0 r cutoff device. vices NCAC 13-13 LWCO could not be ing state so the LW ish at (919) 268-07	409 .0409: No provision to test lov e tested due to inoperative VCO can be safely and 725 when repairs are complet
		INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY: SUBCATEGORY CONDITION: REQUIREMENT: COMPANY: INSPECTOR: OPENED: CLOSED:	Fish, Emily 08/20/2020 Certificate Blocking 01-LWCO and Flow Sensing Devia 005. No provision to test low wate 005. LWCO and Flow Sensing De water cutoff device. Manual reset sight glass. 005. Repair sight glass to function accurately tested. Contact Emily F to schedule reinspection. State of North Carolina Fish, Emily 11/09/2020	CLOSED BY: ces NCAC 13-13.0 r cutoff device. vices NCAC 13-13 LWCO could not be ing state so the LV ish at (919) 268-07 ENTERED BY: CLOSED BY:	409 .0409: No provision to test lov e tested due to inoperative VCO can be safely and 725 when repairs are complet
		INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY: SUBCATEGORY CONDITION: REQUIREMENT: NSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	Fish, Emily 08/20/2020 Certificate Blocking 01-LWCO and Flow Sensing Devi 005. No provision to test low wate 005. LWCO and Flow Sensing De water cutoff device. Manual reset sight glass. 005. Repair sight glass to function accurately tested. Contact Emily F to schedule reinspection. State of North Carolina Fish, Emily 11/09/2020 Certificate Blocking	CLOSED BY: ces NCAC 13-13.0 r cutoff device. vices NCAC 13-13 LWCO could not be ing state so the LW ish at (919) 268-07 ENTERED BY: CLOSED BY: 3.0405	409 .0409: No provision to test loo e tested due to inoperative VCO can be safely and 725 when repairs are complet
		INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY: SUBCATEGORY CONDITION: REQUIREMENT: NSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	Fish, Emily 08/20/2020 Certificate Blocking 01-LWCO and Flow Sensing Devi 005. No provision to test low wate 005. LWCO and Flow Sensing De water cutoff device. Manual reset sight glass. 005. Repair sight glass to function accurately tested. Contact Emily F to schedule reinspection. State of North Carolina Fish, Emily 11/09/2020 Certificate Blocking 25-Operation of PRDs NCAC 13-1	CLOSED BY: ces NCAC 13-13.0 r cutoff device. vices NCAC 13-13 LWCO could not be ing state so the LW ish at (919) 268-07 ENTERED BY: CLOSED BY: 3.0405 r supported.	409 .0409: No provision to test lor e tested due to inoperative VCO can be safely and 725 when repairs are complet

	COMPANY:	State of North Carolina
	INSPECTOR:	Fish, Emily
	OPENED:	11/09/2020 ENTERED BY: Fish, Emily
	CLOSED:	CLOSED BY:
	TYPE:	Certificate Blocking
	CATEGORY:	25-Operation of PRDs NCAC 13-13.0405
	SUBCATEGORY	1 395. Valve leaking.
	CONDITION:	395. Operation of PRDs NCAC 13-13.0405: Valve leaking.
	REQUIREMENT:	: 395. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.
25		Location #: 1770426 Violations: 2 NC 28306-3024, Phone: 910-484-4144 formation available for this location.
0	bject: NC400995 - PV - Morga	Inton - 2013 - Bldg Rear - Active Violations This Object: 1
	COMPANY:	Hartford Steam Boiler
	INSPECTOR:	Rudolph, Jay
	OPENED:	01/08/2021 ENTERED BY: Judd, Janie
	CLOSED:	CLOSED BY:
	TYPE:	Certificate Blocking
	CATEGORY:	07-Undefined Pressure Vessels Violations
		479. Undefined Pressure Vessels Violations.
		170 Undefined Dressure Vessels Vieletiens, Dressure gage inconcrebie
	CONDITION:	479. Undefined Pressure Vessels Violations: Pressure gage inoperable.
		: 479. Undefined Pressure Vessels Violations.Replace pressure gage. Range on gage shall be approximately 2 times the intended operating pressure, however it
ο		: 479. Undefined Pressure Vessels Violations.Replace pressure gage. Range on gage shall be approximately 2 times the intended operating pressure, however it shall not be less than 1.5 times the intended operating pressure nor more than 4 times the intended operating pressure.
<u>o</u>	REQUIREMENT: Dbject: NC411119 - PV - Morgan	: 479. Undefined Pressure Vessels Violations.Replace pressure gage. Range on gage shall be approximately 2 times the intended operating pressure, however it shall not be less than 1.5 times the intended operating pressure nor more than 4 times the intended operating pressure.
<u>o</u>	REQUIREMENT: Dbject: NC411119 - PV - Morgan	<ul> <li>479. Undefined Pressure Vessels Violations.Replace pressure gage. Range on gage shall be approximately 2 times the intended operating pressure, however it shall not be less than 1.5 times the intended operating pressure nor more than 4 times the intended operating pressure.</li> <li>anton - 2014 - Bldg Rear - Active Violations This Object: 1</li> </ul>
<u>0</u>	REQUIREMENT: Dbject: NC411119 - PV - Morgan COMPANY:	<ul> <li>479. Undefined Pressure Vessels Violations.Replace pressure gage. Range on gage shall be approximately 2 times the intended operating pressure, however it shall not be less than 1.5 times the intended operating pressure nor more than 4 times the intended operating pressure.</li> <li>anton - 2014 - Bldg Rear - Active Violations This Object: 1</li> <li>Hartford Steam Boiler</li> </ul>
<u>o</u>	REQUIREMENT: Dibject: NC411119 - PV - Morgan COMPANY: INSPECTOR:	<ul> <li>479. Undefined Pressure Vessels Violations.Replace pressure gage. Range on gage shall be approximately 2 times the intended operating pressure, however it shall not be less than 1.5 times the intended operating pressure nor more than 4 times the intended operating pressure.</li> <li>anton - 2014 - Bldg Rear - Active Violations This Object: 1</li> <li>Hartford Steam Boiler Rudolph, Jay</li> </ul>
<u>o</u>	REQUIREMENT: bject: NC411119 - PV - Morgan COMPANY: INSPECTOR: OPENED: CLOSED: TYPE:	: 479. Undefined Pressure Vessels Violations.Replace pressure gage. Range on gage shall be approximately 2 times the intended operating pressure, however it shall not be less than 1.5 times the intended operating pressure nor more than 4 times the intended operating pressure. Inton - 2014 - Bldg Rear - Active Violations This Object: 1 Hartford Steam Boiler Rudolph, Jay 01/08/2021 ENTERED BY: Judd, Janie CLOSED BY: Certificate Blocking
<u>0</u>	REQUIREMENT: bject: NC411119 - PV - Morgan COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	: 479. Undefined Pressure Vessels Violations.Replace pressure gage. Range on gage shall be approximately 2 times the intended operating pressure, however it shall not be less than 1.5 times the intended operating pressure nor more than 4 times the intended operating pressure. Inton - 2014 - Bldg Rear - Active Violations This Object: 1 Hartford Steam Boiler Rudolph, Jay 01/08/2021 ENTERED BY: Judd, Janie CLOSED BY: Certificate Blocking 07-Undefined Pressure Vessels Violations
<u>o</u>	REQUIREMENT: bject: NC411119 - PV - Morgan COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	: 479. Undefined Pressure Vessels Violations.Replace pressure gage. Range on gage shall be approximately 2 times the intended operating pressure, however it shall not be less than 1.5 times the intended operating pressure nor more than 4 times the intended operating pressure. Inton - 2014 - Bldg Rear - Active Violations This Object: 1 Hartford Steam Boiler Rudolph, Jay 01/08/2021 ENTERED BY: Judd, Janie CLOSED BY: Certificate Blocking
<u>o</u>	REQUIREMENT: bject: NC411119 - PV - Morgan COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	: 479. Undefined Pressure Vessels Violations.Replace pressure gage. Range on gage shall be approximately 2 times the intended operating pressure, however it shall not be less than 1.5 times the intended operating pressure nor more than 4 times the intended operating pressure. Inton - 2014 - Bldg Rear - Active Violations This Object: 1 Hartford Steam Boiler Rudolph, Jay 01/08/2021 ENTERED BY: Judd, Janie CLOSED BY: Certificate Blocking 07-Undefined Pressure Vessels Violations

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Location:	-	Location #: 1769786 Violations: 1 C 27217-3004, Phone: 336-226-9803 n Cleaners & Laundry, Phone: 336-226-9803
	Object: NC371303 - Boiler - Parl	ker - 2007 - Blr Rm - Active Violations This Object: 1
	COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY: SUBCATEGORY	Hartford Steam Boiler Leonard, Shannon D. 12/18/2020 ENTERED BY: Judd, Janie CLOSED BY: Certificate Blocking 03-Water Gauge Glass NCAC 13-13.0408 058. Leaking.
	CONDITION:	058. Water Gauge Glass NCAC 13-13.0408: Leaking. 058. Repair or replace the leaking gauge and test to ensure proper operation.
Location:	•	Location #: 3914731 Violations: 1 e, NC 27545-8202, Phone: 919-999-0923 ant Manager, Capital Ready Mix Concrete Llc, Phone: 919-999-0923
	Object: NC418986 - Boiler - Colu	Umbia - 2017 - Red Bldg - Active     Violations This Object: 1
	COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY: SUBCATEGORY CONDITION:	Hartford Steam Boiler SORRENTINO, SEAN 12/03/2020 ENTERED BY: Keyes, Amanda CLOSED BY: Certificate Blocking 01-LWCO and Flow Sensing Devices NCAC 13-13.0409 001. Low water cutoff device not installed. 001. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device not installed.

Location: Carmel Country Club Location #: 1773228 4735 Carmel Rd, , Charlotte, NC 28226-7844, Phone: 704-945-9630 Contact: Winfred Sanders, Maintenance, Carmel Country Club, Phone: 704-506-1619

Violations: 1

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

	Object:	NC428969 - Boiler - Bu	urnham - 2020 - Blr Rm - Active	Violatio	ns This Object: 1
		COMPANY:	State of North Carolina		
		INSPECTOR:	Snuffer, Jimmy		
		OPENED:	01/25/2021	ENTERED BY:	Snuffer, Jimmy
		CLOSED:		CLOSED BY:	
		TYPE:	Certificate Blocking		
		CATEGORY:	13-Burners and Fuel Supply S	ystems	
		SUBCATEGOR	RY 235. No emergency fuel shut o	ff switch.	
		CONDITION:	235. Burners and Fuel Supply	Systems: No emerger	ncy fuel shut off switch.
		REQUIREMEN	T: 235. Install an emergency fuel shut off all fuel to the boilers.	shut off switch at eacl	h egress from the boiler room to
ocation:	Cintas C	orp	Le	ocation #: 1791576	Violations: 1
ocation:		•		ocation #: 1791576	Violations: 1
ocation:	610 Woo	dy Dr, , Graham, NC	27253-3814, Phone: 336-228-053	31	
ocation:	610 Woo	dy Dr, , Graham, NC		31	
ocation:	610 Woo Contact	ody Dr, , Graham, NC 2 Attn Jesus Sepulveda	27253-3814, Phone: 336-228-053	1 6 Corp, Phone: 336-22	
ocation:	610 Woo Contact	ody Dr, , Graham, NC 2 Attn Jesus Sepulveda	27253-3814, Phone: 336-228-053 a, Maintenance Supervisor, Cintas	1 6 Corp, Phone: 336-22	28-0531 X7222, Cell:787-438-
ocation:	610 Woo Contact	dy Dr, , Graham, NC 2 Attn Jesus Sepulveda NC408261 - Boiler - Cl	27253-3814, Phone: 336-228-053 a, Maintenance Supervisor, Cintas leaver Brooks - 2016 - Blr Rm - A	1 6 Corp, Phone: 336-22	28-0531 X7222, Cell:787-438-
ocation:	610 Woo Contact	ody Dr, , Graham, NC Attn Jesus Sepulveda NC408261 - Boiler - Cl COMPANY:	27253-3814, Phone: 336-228-053 a, Maintenance Supervisor, Cintas leaver Brooks - 2016 - Blr Rm - A State of North Carolina	1 6 Corp, Phone: 336-22	28-0531 X7222, Cell:787-438-
ocation:	610 Woo Contact	ody Dr, , Graham, NC Attn Jesus Sepulveda NC408261 - Boiler - Cl COMPANY: INSPECTOR:	27253-3814, Phone: 336-228-053 a, Maintenance Supervisor, Cintas leaver Brooks - 2016 - Blr Rm - A State of North Carolina Smith, Jeremy	31 Corp, Phone: 336-22 ctive <b>Violatio</b>	28-0531 X7222, Cell:787-438- ns This Object: 1
ocation:	610 Woo Contact	ody Dr, , Graham, NC Attn Jesus Sepulveda NC408261 - Boiler - Cl COMPANY: INSPECTOR: OPENED:	27253-3814, Phone: 336-228-053 a, Maintenance Supervisor, Cintas leaver Brooks - 2016 - Blr Rm - A State of North Carolina Smith, Jeremy	Corp, Phone: 336-22 tive Violation	28-0531 X7222, Cell:787-438- ns This Object: 1
ocation:	610 Woo Contact	Attn Jesus Sepulveda NC408261 - Boiler - Cl COMPANY: INSPECTOR: OPENED: CLOSED:	27253-3814, Phone: 336-228-053 a, Maintenance Supervisor, Cintas leaver Brooks - 2016 - Blr Rm - A State of North Carolina Smith, Jeremy 11/06/2020	Corp, Phone: 336-22 tive Violation	28-0531 X7222, Cell:787-438- ns This Object: 1
ocation:	610 Woo Contact	ody Dr, , Graham, NC 2 Attn Jesus Sepulveda NC408261 - Boiler - Cl COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	27253-3814, Phone: 336-228-053 a, Maintenance Supervisor, Cintas leaver Brooks - 2016 - Blr Rm - A State of North Carolina Smith, Jeremy 11/06/2020 Certificate Blocking	Corp, Phone: 336-22 tive Violation ENTERED BY: CLOSED BY:	28-0531 X7222, Cell:787-438- <b>ns This Object:</b> 1
ocation:	610 Woo Contact	ody Dr, , Graham, NC 2 Attn Jesus Sepulveda NC408261 - Boiler - Cl COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	27253-3814, Phone: 336-228-053 a, Maintenance Supervisor, Cintas leaver Brooks - 2016 - Blr Rm - A State of North Carolina Smith, Jeremy 11/06/2020 Certificate Blocking 23-Undefined Boiler Violations <b>XY</b> 363. Undefined Boiler Violation 363. Undefined Boiler Violation inspection every year. Contrar	ENTERED BY: CLOSED BY: NS. All high-pressure b y to 13 NCAC 13.0211	28-0531 X7222, Cell:787-438- <b>ns This Object:</b> 1 Smith, Jeremy

Location: Cleaners Express

Location #: 1761026

Violations: 1

108 N Arlington St, , Salisbury, NC 28144-4615, Phone: 704-638-2344 **Contact:** Attn Yong Aee, Owner, Cleaners Express, Phone: 704-638-2344

	Object: 1	10004000 - Dollei - I lu	rst - 2006 - Blr Rm - Active	Tolation	ns This Object: 1
		COMPANY:	State of North Carolina		
		INSPECTOR:	Smith, Jeremy		
		OPENED:	11/06/2020	ENTERED BY:	Smith, Jeremy
		CLOSED:		CLOSED BY:	
		TYPE:	Certificate Blocking		
		CATEGORY:	23-Undefined Boiler Violat	ions	
		SUBCATEGOR	Y 363. Undefined Boiler Viol	ations.	
		CONDITION:		trary to 13 NCAC 13.0211	oilers require an external (b), an external inspection ha ernal inspection completed w
		REQUIREMENT	363. Undefined Boiler Viola completed. Contact your in schedule an external inspe-	spector or the Boiler Safe	ertificate inspection shall be ty Bureau at 919-707-7918 to
cation:	Compare	Foods #1		Location #: 2881380	Violations: 2
	3600 N Sł	haron Amity Rd, , Charl	lotte, NC 28205-5932, Phor	ne: 704-536-3176	
	Contact:	There is no contact info	ormation available for this loo	cation.	
	Object:	NC382552 - PV - Stand	lard - 1999 - Outside Motor F	Rm - Active Violatio	ns This Object: 1
	Object: N	NC382552 - PV - Stand COMPANY:	lard - 1999 - Outside Motor F Hartford Steam Boiler	Rm - Active Violation	ns This Object: 1
	Object: N		Hartford Steam Boiler	Rm - Active Violation	ns This Object: 1
	Object: N	COMPANY:		Rm - Active Violation	ns This Object: 1 Putek, Terry
	Object: N	COMPANY: INSPECTOR:	Hartford Steam Boiler Clay, Steven D.		
	Object: N	COMPANY: INSPECTOR: OPENED:	Hartford Steam Boiler Clay, Steven D. 08/17/2020	ENTERED BY:	
	Object: N	COMPANY: INSPECTOR: OPENED: CLOSED:	Hartford Steam Boiler Clay, Steven D.	ENTERED BY: CLOSED BY:	
	Object: N	COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	Hartford Steam Boiler Clay, Steven D. 08/17/2020 Certificate Blocking 04-Installation of PRDs NC	ENTERED BY: CLOSED BY: CAC 13-13.0405	Putek, Terry
	Object: N	COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	Hartford Steam Boiler Clay, Steven D. 08/17/2020 Certificate Blocking 04-Installation of PRDs NC Y 461. Incorrect pressure rel	ENTERED BY: CLOSED BY: CAC 13-13.0405 ieving device(s) for the ap NCAC 13-13.0405: Incorre	Putek, Terry
	Object: N	COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY: SUBCATEGORY CONDITION:	Hartford Steam Boiler Clay, Steven D. 08/17/2020 Certificate Blocking 04-Installation of PRDs NC Y 461. Incorrect pressure rel 461. Installation of PRDs N	ENTERED BY: CLOSED BY: CAC 13-13.0405 ieving device(s) for the ap NCAC 13-13.0405: Incorre lock wire. vice with one set at a press pressure determined by t	Putek, Terry plication. ct pressure relieving device(s sure not exceeding the
		COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY: SUBCATEGORY CONDITION: REQUIREMENT	Hartford Steam Boiler Clay, Steven D. 08/17/2020 Certificate Blocking 04-Installation of PRDs NC Y 461. Incorrect pressure rel 461. Installation of PRDs N for the application. Broken C: 461. Replace the relief dev maximum allowed working	ENTERED BY: CLOSED BY: CAC 13-13.0405 ieving device(s) for the ap NCAC 13-13.0405: Incorre lock wire. vice with one set at a press pressure determined by the ASME/NB certified.	Putek, Terry plication. ct pressure relieving device(s sure not exceeding the
		COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY: SUBCATEGORY CONDITION: REQUIREMENT	Hartford Steam Boiler Clay, Steven D. 08/17/2020 Certificate Blocking 04-Installation of PRDs NO Y 461. Incorrect pressure rel 461. Installation of PRDs N for the application. Broken T: 461. Replace the relief dev maximum allowed working replacement valve must be	ENTERED BY: CLOSED BY: CAC 13-13.0405 ieving device(s) for the ap NCAC 13-13.0405: Incorre lock wire. vice with one set at a press pressure determined by the ASME/NB certified.	Putek, Terry plication. ct pressure relieving device(s sure not exceeding the he manufacturer. The
		COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY: SUBCATEGORY CONDITION: REQUIREMENT	Hartford Steam Boiler Clay, Steven D. 08/17/2020 Certificate Blocking 04-Installation of PRDs NO Y 461. Incorrect pressure rel 461. Installation of PRDs N for the application. Broken T: 461. Replace the relief dev maximum allowed working replacement valve must be lard - 1999 - Outside Motor F Hartford Steam Boiler Clay, Steven D.	ENTERED BY: CLOSED BY: CAC 13-13.0405 ieving device(s) for the ap NCAC 13-13.0405: Incorre lock wire. vice with one set at a press pressure determined by the ASME/NB certified.	Putek, Terry plication. ct pressure relieving device(s sure not exceeding the he manufacturer. The
		COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY: SUBCATEGORY CONDITION: REQUIREMENT	Hartford Steam Boiler Clay, Steven D. 08/17/2020 Certificate Blocking 04-Installation of PRDs NC Y 461. Incorrect pressure rel 461. Installation of PRDs N for the application. Broken F: 461. Replace the relief dev maximum allowed working replacement valve must be dard - 1999 - Outside Motor F Hartford Steam Boiler	ENTERED BY: CLOSED BY: CAC 13-13.0405 ieving device(s) for the ap NCAC 13-13.0405: Incorre lock wire. vice with one set at a press pressure determined by the ASME/NB certified.	Putek, Terry plication. ct pressure relieving device(s sure not exceeding the he manufacturer. The
		COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY: SUBCATEGOR' CONDITION: REQUIREMENT NC382553 - PV - Stand COMPANY: INSPECTOR:	Hartford Steam Boiler Clay, Steven D. 08/17/2020 Certificate Blocking 04-Installation of PRDs NO Y 461. Incorrect pressure rel 461. Installation of PRDs N for the application. Broken T: 461. Replace the relief dev maximum allowed working replacement valve must be lard - 1999 - Outside Motor F Hartford Steam Boiler Clay, Steven D.	ENTERED BY: CLOSED BY: CAC 13-13.0405 ieving device(s) for the ap NCAC 13-13.0405: Incorre lock wire. vice with one set at a press pressure determined by the ASME/NB certified. Rm - Active Violation	Putek, Terry plication. ct pressure relieving device(s sure not exceeding the he manufacturer. The
		COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY: SUBCATEGORY CONDITION: REQUIREMENT NC382553 - PV - Stand COMPANY: INSPECTOR: OPENED:	Hartford Steam Boiler Clay, Steven D. 08/17/2020 Certificate Blocking 04-Installation of PRDs NO Y 461. Incorrect pressure rel 461. Installation of PRDs N for the application. Broken T: 461. Replace the relief dev maximum allowed working replacement valve must be lard - 1999 - Outside Motor F Hartford Steam Boiler Clay, Steven D.	ENTERED BY: CLOSED BY: CAC 13-13.0405 ieving device(s) for the ap VCAC 13-13.0405: Incorre lock wire. vice with one set at a press pressure determined by the ASME/NB certified. Rm - Active Violation ENTERED BY:	Putek, Terry plication. ct pressure relieving device(s sure not exceeding the he manufacturer. The
		COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY: SUBCATEGORY CONDITION: REQUIREMENT NC382553 - PV - Stand COMPANY: INSPECTOR: OPENED: CLOSED:	Hartford Steam Boiler Clay, Steven D. 08/17/2020 Certificate Blocking 04-Installation of PRDs NC Y 461. Incorrect pressure rel 461. Installation of PRDs N for the application. Broken F: 461. Replace the relief dev maximum allowed working replacement valve must be lard - 1999 - Outside Motor F Hartford Steam Boiler Clay, Steven D. 08/17/2020	ENTERED BY: CLOSED BY: CAC 13-13.0405 ieving device(s) for the ap NCAC 13-13.0405: Incorre lock wire. vice with one set at a press pressure determined by the ASME/NB certified. Rm - Active Violation ENTERED BY: CLOSED BY:	Putek, Terry plication. ct pressure relieving device(s sure not exceeding the he manufacturer. The
		COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY: SUBCATEGORY CONDITION: REQUIREMENT NC382553 - PV - Stand COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	Hartford Steam Boiler Clay, Steven D. 08/17/2020 Certificate Blocking 04-Installation of PRDs NC Y 461. Incorrect pressure rel 461. Installation of PRDs N for the application. Broken T: 461. Replace the relief dev maximum allowed working replacement valve must be dard - 1999 - Outside Motor F Hartford Steam Boiler Clay, Steven D. 08/17/2020 Certificate Blocking	ENTERED BY: CLOSED BY: CAC 13-13.0405 ieving device(s) for the ap VCAC 13-13.0405: Incorre lock wire. vice with one set at a press pressure determined by the ASME/NB certified. Rm - Active Violation ENTERED BY: CLOSED BY: CAC 13-13.0405	Putek, Terry plication. ct pressure relieving device(s sure not exceeding the he manufacturer. The
		COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY: SUBCATEGORY CONDITION: REQUIREMENT NC382553 - PV - Stand COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	Hartford Steam Boiler Clay, Steven D. 08/17/2020 Certificate Blocking 04-Installation of PRDs NC Y 461. Incorrect pressure rel 461. Installation of PRDs N for the application. Broken F: 461. Replace the relief dev maximum allowed working replacement valve must be dard - 1999 - Outside Motor F Hartford Steam Boiler Clay, Steven D. 08/17/2020 Certificate Blocking 04-Installation of PRDs NC Y 459. Discharge piping too	ENTERED BY: CLOSED BY: CAC 13-13.0405 ieving device(s) for the ap NCAC 13-13.0405: Incorre lock wire. vice with one set at a press pressure determined by the ASME/NB certified. Rm - Active Violation ENTERED BY: CLOSED BY: CAC 13-13.0405 small. NCAC 13-13.0405: Dischard	Putek, Terry plication. ct pressure relieving device(s sure not exceeding the he manufacturer. The

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

	n: Craig Davis Properties Bldg 400       Location #: 1780746       Violations: 1         800 Park Offices Dr, , Research Triangle Park, NC       27709-0100, Phone: 919-485-0507       Violations: 1         Contact:       Davis 54 Llc, Phone: 919-485-0507, Cell:919-678-4301       Violations: 1				
	Object: NC429276 - PV - Steel	Fab - 2018 - 400 Comp Rm - Active   Violations This Object: 1			
	COMPANY: INSPECTOR:	State of North Carolina Gunto III, Andrew			
	OPENED:	01/21/2021 ENTERED BY: Gunto III, Andrew			
	CLOSED:	CLOSED BY:			
	TYPE:	Certificate Blocking			
	CATEGORY:	04-Installation of PRDs NCAC 13-13.0405			
		Y 452. Set pressure too high.			
	CONDITION:	452. Installation of PRDs NCAC 13-13.0405: Set pressure too high. This vessel has an MAWP of 200 psi. The newly installed safety valves are set to release at 275 psi.			
	REQUIREMENT	<b>T:</b> 452. Replace the pressure relieving device with one with a set pressure no higher than the maximum allowable working pressure as determined by the manufacturer. All repairs must satisfy the requirements of the Uniform Boiler and Pressure Vessel Act of North Carolina.			
Location:	530 Motor Rd, , Winston Salem,	Location #: 1780999 Violations: 1 NC 27105-2245, Phone: 336-767-0096			
		tor, Crestwood Baptist Church, Phone: 336-767-0096			
	Object: NC278720 - Boiler - Cro	tor, Crestwood Baptist Church, Phone: 336-767-0096 own - 1996 - Blr Rm - Active Violations This Object: 1			
	Object: NC278720 - Boiler - Cro COMPANY:	tor, Crestwood Baptist Church, Phone: 336-767-0096 own - 1996 - Blr Rm - Active Violations This Object: 1 Hartford Steam Boiler			
	Object: NC278720 - Boiler - Cro COMPANY: INSPECTOR: OPENED:	tor, Crestwood Baptist Church, Phone: 336-767-0096 own - 1996 - Blr Rm - Active Violations This Object: 1 Hartford Steam Boiler Leonard, Shannon D. 12/01/2020 ENTERED BY: Judd, Janie			
	Object: NC278720 - Boiler - Cro COMPANY: INSPECTOR:	tor, Crestwood Baptist Church, Phone: 336-767-0096 own - 1996 - Blr Rm - Active Violations This Object: 1 Hartford Steam Boiler Leonard, Shannon D. 12/01/2020 ENTERED BY: Judd, Janie CLOSED BY:			
	Object: NC278720 - Boiler - Cro COMPANY: INSPECTOR: OPENED: CLOSED:	tor, Crestwood Baptist Church, Phone: 336-767-0096 own - 1996 - Blr Rm - Active Violations This Object: 1 Hartford Steam Boiler Leonard, Shannon D. 12/01/2020 ENTERED BY: Judd, Janie CLOSED BY: Certificate Blocking			
	Object: NC278720 - Boiler - Cro COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	tor, Crestwood Baptist Church, Phone: 336-767-0096 own - 1996 - Blr Rm - Active Violations This Object: 1 Hartford Steam Boiler Leonard, Shannon D. 12/01/2020 ENTERED BY: Judd, Janie CLOSED BY:			
	Object: NC278720 - Boiler - Cro COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	tor, Crestwood Baptist Church, Phone: 336-767-0096 own - 1996 - Blr Rm - Active Violations This Object: 1 Hartford Steam Boiler Leonard, Shannon D. 12/01/2020 ENTERED BY: Judd, Janie CLOSED BY: Certificate Blocking 25-Operation of PRDs NCAC 13-13.0405			
	Object: NC278720 - Boiler - Cro COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY: SUBCATEGOR CONDITION:	tor, Crestwood Baptist Church, Phone: 336-767-0096 own - 1996 - Blr Rm - Active Violations This Object: 1 Hartford Steam Boiler Leonard, Shannon D. 12/01/2020 ENTERED BY: Judd, Janie CLOSED BY: Certificate Blocking 25-Operation of PRDs NCAC 13-13.0405 Y 395. Valve leaking. 395. Operation of PRDs NCAC 13-13.0405: Valve leaking: Pressure relief device			

Contact: William Efrid, Fire Chief, East Side Volunteer Fire Dept Station 2, Phone: 704-982-3698

	-	anton - 2011 - Rear Cooking Area - Active Violations This Object: 1
	COMPANY:	State of North Carolina
	INSPECTOR:	Coley, Oscar
	OPENED:	11/30/2020ENTERED BY:Coley, Oscar
	CLOSED:	CLOSED BY:
	TYPE:	Certificate Blocking
	CATEGORY:	07-Undefined Pressure Vessels Violations
		Y 479. Undefined Pressure Vessels Violations.
	CONDITION:	479. Undefined Pressure Vessels Violations. Operating with an expired certificate inspection.
	REQUIREMENT:	: 479. Undefined Pressure Vessels Violations. NC law requires current certificate c inspection. Please contact your insurance inspector or Junior Coley (state inspector) (My phone 704-261-6873) to schedule an inspection ASAP!
ation: Ergon Asphal 2520 Wilco Bl		Location #: 3316456 Violations: 2 27893-9020, Phone: 252-991-4692
Contact: Attr	n Sean Randall, Man	nager, Ergon Asphalt & Emulsions Inc, Phone: 580-583-6618
Object: NC3	93068 - Boiler - York	rk Shipley - 2011 - Blr Rm - Active Violations This Object: 2
	COMPANY:	State of North Carolina
	INSPECTOR:	Harrell, Danny
	OPENED:	12/07/2020 ENTERED BY: Harrell, Danny
	OPENED: CLOSED:	12/07/2020 ENTERED BY: Harrell, Danny CLOSED BY:
	CLOSED:	CLOSED BY:
	CLOSED: TYPE: CATEGORY:	CLOSED BY: Certificate Blocking
	CLOSED: TYPE: CATEGORY:	CLOSED BY: Certificate Blocking 13-Burners and Fuel Supply Systems
	CLOSED: TYPE: CATEGORY: SUBCATEGORY CONDITION:	CLOSED BY: Certificate Blocking 13-Burners and Fuel Supply Systems Y 234. Combustion air supply inadequate. 234. Burners and Fuel Supply Systems: Combustion air supply louver linkage ha been disconnected and interlock bypassed. Rollup door being used to supply combustion makeup air. : 234. Increase the combustion air supply to at least the minimums specified in
	CLOSED: TYPE: CATEGORY: SUBCATEGORY CONDITION:	CLOSED BY: Certificate Blocking 13-Burners and Fuel Supply Systems Y 234. Combustion air supply inadequate. 234. Burners and Fuel Supply Systems: Combustion air supply louver linkage has been disconnected and interlock bypassed. Rollup door being used to supply combustion makeup air. 234. Increase the combustion air supply to at least the minimums specified in NCAC 13-13.0419. Reconnect the motorized louver and insure that the interlock
	CLOSED: TYPE: CATEGORY: SUBCATEGORY CONDITION: REQUIREMENT:	CLOSED BY: Certificate Blocking 13-Burners and Fuel Supply Systems Y 234. Combustion air supply inadequate. 234. Burners and Fuel Supply Systems: Combustion air supply louver linkage ha been disconnected and interlock bypassed. Rollup door being used to supply combustion makeup air. 234. Increase the combustion air supply to at least the minimums specified in NCAC 13-13.0419. Reconnect the motorized louver and insure that the interlock the boiler is working properly.
	CLOSED: TYPE: CATEGORY: SUBCATEGORY CONDITION: REQUIREMENT: COMPANY:	CLOSED BY: Certificate Blocking 13-Burners and Fuel Supply Systems Y 234. Combustion air supply inadequate. 234. Burners and Fuel Supply Systems: Combustion air supply louver linkage has been disconnected and interlock bypassed. Rollup door being used to supply combustion makeup air. 234. Increase the combustion air supply to at least the minimums specified in NCAC 13-13.0419. Reconnect the motorized louver and insure that the interlock the boiler is working properly. State of North Carolina
	CLOSED: TYPE: CATEGORY: SUBCATEGORY CONDITION: REQUIREMENT: COMPANY: INSPECTOR:	CLOSED BY: Certificate Blocking 13-Burners and Fuel Supply Systems Y 234. Combustion air supply inadequate. 234. Burners and Fuel Supply Systems: Combustion air supply louver linkage has been disconnected and interlock bypassed. Rollup door being used to supply combustion makeup air. 234. Increase the combustion air supply to at least the minimums specified in NCAC 13-13.0419. Reconnect the motorized louver and insure that the interlock the boiler is working properly. State of North Carolina Harrell, Danny
	CLOSED: TYPE: CATEGORY: SUBCATEGORY CONDITION: REQUIREMENT: REQUIREMENT: NSPECTOR: OPENED:	CLOSED BY: Certificate Blocking 13-Burners and Fuel Supply Systems Y 234. Combustion air supply inadequate. 234. Burners and Fuel Supply Systems: Combustion air supply louver linkage has been disconnected and interlock bypassed. Rollup door being used to supply combustion makeup air. 234. Increase the combustion air supply to at least the minimums specified in NCAC 13-13.0419. Reconnect the motorized louver and insure that the interlock the boiler is working properly. State of North Carolina Harrell, Danny 12/07/2020 ENTERED BY: Harrell, Danny
	CLOSED: TYPE: CATEGORY: SUBCATEGORY CONDITION: REQUIREMENT: REQUIREMENT: NSPECTOR: OPENED: CLOSED:	CLOSED BY: Certificate Blocking 13-Burners and Fuel Supply Systems Y 234. Combustion air supply inadequate. 234. Burners and Fuel Supply Systems: Combustion air supply louver linkage has been disconnected and interlock bypassed. Rollup door being used to supply combustion makeup air. 234. Increase the combustion air supply to at least the minimums specified in NCAC 13-13.0419. Reconnect the motorized louver and insure that the interlock the boiler is working properly. State of North Carolina Harrell, Danny 12/07/2020 ENTERED BY: Harrell, Danny CLOSED BY:
	CLOSED: TYPE: CATEGORY: SUBCATEGORY CONDITION: REQUIREMENT: REQUIREMENT: NSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	CLOSED BY: Certificate Blocking 13-Burners and Fuel Supply Systems Y 234. Combustion air supply inadequate. 234. Burners and Fuel Supply Systems: Combustion air supply louver linkage has been disconnected and interlock bypassed. Rollup door being used to supply combustion makeup air. 2 234. Increase the combustion air supply to at least the minimums specified in NCAC 13-13.0419. Reconnect the motorized louver and insure that the interlock the boiler is working properly. State of North Carolina Harrell, Danny 12/07/2020 ENTERED BY: Harrell, Danny CLOSED BY: Certificate Blocking 13-Burners and Fuel Supply Systems
	CLOSED: TYPE: CATEGORY: SUBCATEGORY CONDITION: REQUIREMENT: REQUIREMENT: NSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	CLOSED BY: Certificate Blocking 13-Burners and Fuel Supply Systems Y 234. Combustion air supply inadequate. 234. Burners and Fuel Supply Systems: Combustion air supply louver linkage has been disconnected and interlock bypassed. Rollup door being used to supply combustion makeup air. 2 234. Increase the combustion air supply to at least the minimums specified in NCAC 13-13.0419. Reconnect the motorized louver and insure that the interlock the boiler is working properly. State of North Carolina Harrell, Danny 12/07/2020 ENTERED BY: Harrell, Danny CLOSED BY: Certificate Blocking

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Obiect: NC2	63815 - Boiler - Fu	ton - 1995 - Blr Rm - Active	Violatio	ns This Object: 1
	COMPANY:	Hartford Steam Boiler		
	INSPECTOR:	Rudolph, Jay		
	OPENED:	01/09/2021	ENTERED BY:	Judd, Janie
	CLOSED:		CLOSED BY:	
	TYPE:	Certificate Blocking		
	CATEGORY:	23-Undefined Boiler Violations		
	SUBCATEGOR	<b>Y</b> 363. Undefined Boiler Violations.		
	CONDITION:	363. Undefined Boiler Violations: I	-ireside inspection	not accessible.
	REQUIREMENT	: 363. Undefined Boiler Violations: \$	•	
		the boiler is accessible.		
Contact: The	Mill Rd, , Winston re is no contact inf	Salem, NC 27105-9626, Phone: 33 prmation available for this location.		Violations: 1
385 W Hanes Contact: The	Mill Rd, , Winston re is no contact inf 12588 - Boiler - Ste	Salem, NC 27105-9626, Phone: 33 ormation available for this location. eamist - 2016 - Blr Rm - Active	86-661-1093	Violations: 1 ns This Object: 1
385 W Hanes Contact: The	Mill Rd, , Winston re is no contact inf 12588 - Boiler - Ste <b>COMPANY:</b>	Salem, NC 27105-9626, Phone: 33 prmation available for this location. eamist - 2016 - Blr Rm - Active Hartford Steam Boiler	86-661-1093	
385 W Hanes Contact: The	Mill Rd, , Winston re is no contact inf 12588 - Boiler - Ste COMPANY: INSPECTOR:	Salem, NC 27105-9626, Phone: 33 ormation available for this location. eamist - 2016 - Blr Rm - Active Hartford Steam Boiler Leonard, Shannon D.	36-661-1093 Violatio	ns This Object: 1
385 W Hanes Contact: The	Mill Rd, , Winston re is no contact inf 12588 - Boiler - Ste COMPANY: INSPECTOR: OPENED:	Salem, NC 27105-9626, Phone: 33 prmation available for this location. eamist - 2016 - Blr Rm - Active Hartford Steam Boiler	Violatio	
385 W Hanes Contact: The	Mill Rd, , Winston re is no contact inf 12588 - Boiler - Ste COMPANY: INSPECTOR: OPENED: CLOSED:	Salem, NC 27105-9626, Phone: 33 ormation available for this location. eamist - 2016 - Blr Rm - Active Hartford Steam Boiler Leonard, Shannon D. 10/21/2020	36-661-1093 Violatio	ns This Object: 1
385 W Hanes Contact: The	Mill Rd, , Winston re is no contact inf 12588 - Boiler - Ste COMPANY: INSPECTOR: OPENED: CLOSED: TYPE:	Salem, NC 27105-9626, Phone: 33 ormation available for this location. eamist - 2016 - Blr Rm - Active Hartford Steam Boiler Leonard, Shannon D. 10/21/2020 Certificate Blocking	Violatio	ns This Object: 1
385 W Hanes Contact: The	Mill Rd, , Winston re is no contact inf 12588 - Boiler - Ste COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	Salem, NC 27105-9626, Phone: 33 ormation available for this location. eamist - 2016 - Blr Rm - Active Hartford Steam Boiler Leonard, Shannon D. 10/21/2020 Certificate Blocking 23-Undefined Boiler Violations	Violatio	ns This Object: 1
385 W Hanes Contact: The	Mill Rd, , Winston re is no contact inf 12588 - Boiler - Ste COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY: SUBCATEGOR	Salem, NC 27105-9626, Phone: 33 ormation available for this location. eamist - 2016 - Blr Rm - Active Hartford Steam Boiler Leonard, Shannon D. 10/21/2020 Certificate Blocking 23-Undefined Boiler Violations Y 363. Undefined Boiler Violations.	Violatio ENTERED BY: CLOSED BY:	<b>ns This Object:</b> 1 Judd, Janie
385 W Hanes Contact: The	Mill Rd, , Winston re is no contact inf 12588 - Boiler - Ste COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	Salem, NC 27105-9626, Phone: 33 ormation available for this location. eamist - 2016 - Blr Rm - Active Hartford Steam Boiler Leonard, Shannon D. 10/21/2020 Certificate Blocking 23-Undefined Boiler Violations	Violatio ENTERED BY: CLOSED BY: Boiler not operating	<b>ns This Object:</b> 1 Judd, Janie

Location:GE Global Nuclear Fuels America (Hartford)Location #: 176064Violations: 13901 Castle Hayne Rd, , Wilmington, NC28402-1810, Phone: 910-675-5445Contact: Attn Jeffrey Starling M/C G50, Site Maintenance Coordinator, GE Global Nuclear Fuels, Phone: 910-819-

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

	Object:	NC135849 - PV - Delta	- 1973 - Outside FMO Comp Rm - Active Violations This Object: 1
		COMPANY:	Hartford Steam Boiler
		INSPECTOR:	Rudolph, Jay
		OPENED:	07/01/2020 ENTERED BY: Judd, Janie
		CLOSED:	CLOSED BY:
		TYPE:	Certificate Blocking
		CATEGORY:	04-Installation of PRDs NCAC 13-13.0405
		SUBCATEGOR	Y 460. Seals broken/ missing.
		CONDITION:	460. Installation of PRDs NCAC 13-13.0405: Pressure relief device tamper seal broken.
		REQUIREMENT	F: 460. Replace with a new ASME/NB certified pressure relief device with a set pressure of not greater than 125
			psig, with sufficient relief capacity and a testing lever.
cation:	819 Patt		<b>Location #:</b> 1795964 <b>Violations:</b> 1 28806-3618, Phone: 828-252-3821 Repair Manager, Harrys On The Hill Llc, Phone: 828-252-3821
cation:	819 Patt Contact	on Ave, , Asheville, NC : Jeff Barrett, Collision F	28806-3618, Phone: 828-252-3821
cation:	819 Patt Contact	on Ave, , Asheville, NC : Jeff Barrett, Collision F NC344092 - PV - Penw	28806-3618, Phone: 828-252-3821 Repair Manager, Harrys On The Hill Llc, Phone: 828-252-3821
cation:	819 Patt Contact	on Ave, , Asheville, NC : Jeff Barrett, Collision F NC344092 - PV - Penw Active	28806-3618, Phone: 828-252-3821 Repair Manager, Harrys On The Hill Llc, Phone: 828-252-3821 /ay - 2002 - Outside Rear Body Shop - Violations This Object: 1
cation:	819 Patt Contact	on Ave, , Asheville, NC : Jeff Barrett, Collision F NC344092 - PV - Penw Active COMPANY:	28806-3618, Phone: 828-252-3821 Repair Manager, Harrys On The Hill Llc, Phone: 828-252-3821 vay - 2002 - Outside Rear Body Shop - Violations This Object: 1 Hartford Steam Boiler
cation:	819 Patt Contact	on Ave, , Asheville, NC : Jeff Barrett, Collision F NC344092 - PV - Penw Active COMPANY: INSPECTOR:	28806-3618, Phone: 828-252-3821 Repair Manager, Harrys On The Hill Llc, Phone: 828-252-3821 /ay - 2002 - Outside Rear Body Shop - Violations This Object: 1 Hartford Steam Boiler Possidente, James
cation:	819 Patt Contact	on Ave, , Asheville, NC : Jeff Barrett, Collision F NC344092 - PV - Penw Active COMPANY: INSPECTOR: OPENED:	28806-3618, Phone: 828-252-3821 Repair Manager, Harrys On The Hill Llc, Phone: 828-252-3821 /ay - 2002 - Outside Rear Body Shop - Violations This Object: 1 Hartford Steam Boiler Possidente, James 12/09/2020 ENTERED BY: Putek, Terry
cation:	819 Patt Contact	on Ave, , Asheville, NC : Jeff Barrett, Collision F NC344092 - PV - Penw Active COMPANY: INSPECTOR: OPENED: CLOSED:	28806-3618, Phone: 828-252-3821 Repair Manager, Harrys On The Hill Llc, Phone: 828-252-3821 vay - 2002 - Outside Rear Body Shop - Violations This Object: 1 Hartford Steam Boiler Possidente, James 12/09/2020 ENTERED BY: Putek, Terry CLOSED BY:
ocation:	819 Patt Contact	on Ave, , Asheville, NC : Jeff Barrett, Collision F NC344092 - PV - Penw Active COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	28806-3618, Phone: 828-252-3821 Repair Manager, Harrys On The Hill Llc, Phone: 828-252-3821 /ay - 2002 - Outside Rear Body Shop - Violations This Object: 1 Hartford Steam Boiler Possidente, James 12/09/2020 ENTERED BY: Putek, Terry CLOSED BY: Certificate Blocking
cation:	819 Patt Contact	on Ave, , Asheville, NC : Jeff Barrett, Collision F NC344092 - PV - Penw Active COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	28806-3618, Phone: 828-252-3821 Repair Manager, Harrys On The Hill Llc, Phone: 828-252-3821 yay - 2002 - Outside Rear Body Shop - Violations This Object: 1 Hartford Steam Boiler Possidente, James 12/09/2020 ENTERED BY: Putek, Terry CLOSED BY: Certificate Blocking 07-Undefined Pressure Vessels Violations

Location:High Country Tire & Service StationLocation #: 1797182Violations: 18227 US Highway 441 S, , Sylva, NC28779-7193, Phone: 828-586-0886Contact: Attn Mickey & Sam McMahan, Owner, High Country Tire & Service Station, Phone: 828-586-0886

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object	: NC390660 - PV - Steel	Fab - 2010 - Shop - Active	Violatio	ns This Object: 1
	COMPANY:	Hartford Steam Boiler		
	INSPECTOR:	Possidente, James		
	OPENED:	12/08/2020	ENTERED BY:	Putek, Terry
	CLOSED:		CLOSED BY:	
	TYPE:	Certificate Blocking		
	CATEGORY:	07-Undefined Pressure Vesse	Is Violations	
	SUBCATEGOR	Y 479. Undefined Pressure Vess	sels Violations.	
	CONDITION:	479. Undefined Pressure Vess volt live wires exposed.	sels Violations. Pressu	re switch cover missing. 230
	REQUIREMENT	<b>F:</b> 479. Undefined Pressure Vess	sels Violations. Install	a pressure switch cover.
cation: Hudsor	0	_	ocation #: 1799097	Violations: 1
118 W <b>Contac</b>	State St, , Black Mountair ct: Attn J Richard Hudsor	n, NC 28711-3419, Phone: 828 n III, Owner, Hudson Building, P	-669-8711 hone: 828-669-8711	
118 W <b>Contac</b>	State St, , Black Mountair ct: Attn J Richard Hudson : NC148875 - Boiler - Bu	n, NC 28711-3419, Phone: 828 n III, Owner, Hudson Building, P urnham - 1975 - Blr Rm - Active	-669-8711 hone: 828-669-8711	Violations: 1 ns This Object: 1
118 W <b>Contac</b>	State St, , Black Mountair ct: Attn J Richard Hudson : NC148875 - Boiler - Bu COMPANY:	n, NC 28711-3419, Phone: 828 n III, Owner, Hudson Building, P urnham - 1975 - Blr Rm - Active Hartford Steam Boiler	-669-8711 hone: 828-669-8711	
118 W <b>Contac</b>	State St, , Black Mountair ct: Attn J Richard Hudson : NC148875 - Boiler - Bu COMPANY: INSPECTOR:	n, NC 28711-3419, Phone: 828 n III, Owner, Hudson Building, P urnham - 1975 - Blr Rm - Active Hartford Steam Boiler Possidente, James	-669-8711 hone: 828-669-8711 <b>Violatio</b>	ns This Object: 1
118 W <b>Contac</b>	State St, , Black Mountair ct: Attn J Richard Hudson : NC148875 - Boiler - Bu COMPANY: INSPECTOR: OPENED:	n, NC 28711-3419, Phone: 828 n III, Owner, Hudson Building, P urnham - 1975 - Blr Rm - Active Hartford Steam Boiler	-669-8711 hone: 828-669-8711 Violatio ENTERED BY:	
118 W <b>Contac</b>	State St, , Black Mountair ct: Attn J Richard Hudson : NC148875 - Boiler - Bu COMPANY: INSPECTOR: OPENED: CLOSED:	n, NC 28711-3419, Phone: 828 n III, Owner, Hudson Building, P urnham - 1975 - Blr Rm - Active Hartford Steam Boiler Possidente, James 12/10/2020	-669-8711 hone: 828-669-8711 <b>Violatio</b>	ns This Object: 1
118 W <b>Contac</b>	State St, , Black Mountair ct: Attn J Richard Hudson : NC148875 - Boiler - Bu COMPANY: INSPECTOR: OPENED: CLOSED: TYPE:	n, NC 28711-3419, Phone: 828 n III, Owner, Hudson Building, Pl urnham - 1975 - Blr Rm - Active Hartford Steam Boiler Possidente, James 12/10/2020 Certificate Blocking	-669-8711 hone: 828-669-8711 Violatio ENTERED BY: CLOSED BY:	ns This Object: 1
118 W <b>Contac</b>	State St, , Black Mountair ct: Attn J Richard Hudson : NC148875 - Boiler - Bu COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	n, NC 28711-3419, Phone: 828 n III, Owner, Hudson Building, P urnham - 1975 - Blr Rm - Active Hartford Steam Boiler Possidente, James 12/10/2020 Certificate Blocking 03-Water Gauge Glass NCAC	-669-8711 hone: 828-669-8711 Violatio ENTERED BY: CLOSED BY:	ns This Object: 1
118 W <b>Contac</b>	State St, , Black Mountair ct: Attn J Richard Hudson : NC148875 - Boiler - Bu COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	n, NC 28711-3419, Phone: 828 n III, Owner, Hudson Building, Phone: 828 n Hartford Steam Boiler Possidente, James 12/10/2020 Certificate Blocking 03-Water Gauge Glass NCAC	-669-8711 hone: 828-669-8711 <b>Violatio</b> ENTERED BY: CLOSED BY: 13-13.0408	<b>ns This Object:</b> 1 Putek, Terry
118 W <b>Contac</b>	State St, , Black Mountair ct: Attn J Richard Hudson : NC148875 - Boiler - Bu COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	n, NC 28711-3419, Phone: 828 n III, Owner, Hudson Building, P urnham - 1975 - Blr Rm - Active Hartford Steam Boiler Possidente, James 12/10/2020 Certificate Blocking 03-Water Gauge Glass NCAC	-669-8711 hone: 828-669-8711 <b>Violatio</b> <b>ENTERED BY:</b> <b>CLOSED BY:</b> 13-13.0408 C 13-13.0408: Drain i	<b>ns This Object:</b> 1 Putek, Terry

 Location: J Iverson Riddle Developmental Center
 Location #: 1843125
 Violations: 1

 300 Enola Rd, , Morganton, NC
 28655-4608, Phone: 828-433-2771
 Violations: 1

 Contact: Attn Todd Aderholt, Special Executive To Director, J Iverson Riddle Developmental Center, Phone: 828-433 

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC412660 - PV - Reco - 2019 - Maple Bldg Mech Rm Bsmt - Active Violations This Object: 1

		ckeye - 1986 - Store Rm - Active	Violatio	ns This Object: 1
	Contact: Attn Rob Womack	Manager, Carolina Lubes Inc #452	Phone: 919-828-951	1 X294, Cell:919-828-9425
	5501 University Pkwy, , Winst	on Salem, NC 27105-1370, Phon	e: 336-767-0288	
ocation	: Jiffy Lube #452	L	ocation #: 1801802	Violations: 1
		than the maximum allowable v	0	
	REQUIREME	NT: 452. Replace the pressure rel	eving device with one	with a set pressure no higher
	CONDITION:	452. Installation of PRDs NCA 125 psi & SV #1 is 150 psi.	C 13-13.0405: Set pre	ssure too high. Mawp is set a
	SUBCATEGO	<b>DRY</b> 452. Set pressure too high.		
	CATEGORY:	04-Installation of PRDs NCAC	13-13.0405	
	TYPE:	Certificate Blocking		
	CLOSED:		CLOSED BY:	
	OPENED:	09/24/2020	ENTERED BY:	Putek, Terry
	INSPECTOR:	: Richey, Paul D.		

OPENED:	12/29/2020	ENTERED BY:	Parker, Richard
CLOSED:		CLOSED BY:	
TYPE:	Certificate Blocking		
CATEGORY:	09-Pressure Gauges NCAC 13-13.	0407	
SUBCATEGORY	032. Incorrect range or insufficient	pointer travel.	
CONDITION:	032. Pressure Gauges NCAC 13-1 travel.	3.0407: Incorrect r	ange or insufficient pointer
REQUIREMENT:	032. Install a pressure gauge on the the floor or work platform. Gauge r Administrative Code, Title 13, Chap	nust be the proper	range in accordance with NC
	contact Richard Parker @ 336-202	-8341	

Location: Kernersville Family YMCA

Location #: 1845634

1113 W Mountain St, , Kernersville, NC 27284-2125, Phone: 336-996-2231 **Contact:** There is no contact information available for this location.

Violations: 2

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Objec	t: NC399650 - Boiler - Ster	nist - 2013 - Suana - Active	Violations This Object: 1
	COMPANY:	Hartford Steam Boiler	
	INSPECTOR:	Leonard, Shannon D.	
	OPENED:	10/14/2020	ENTERED BY: Judd, Janie
	CLOSED:		CLOSED BY:
	TYPE:	Certificate Blocking	
	CATEGORY:	23-Undefined Boiler Violation	S
	SUBCATEGORY	363. Undefined Boiler Violation	ons.
	CONDITION:		ons. Boiler not operating at time of inspection; low ssure relief device (PRD) could not be tested to verify
	REQUIREMENT:	is operating so that the LWCC As an alternative, a detailed b	ons. Schedule a reinspection at a time when the boiler O and PRD may be tested to verify proper operation. poiler log or service report that includes documentation e flow switch and PRD is also acceptable.
Objec	Active	edyne Laars - 1998 - Hot Tub \	Vtr Htr - Violations This Object: 1
	COMPANY:	Hartford Steam Boiler	
	INSPECTOR:	Leonard, Shannon D.	
	OPENED:	10/14/2020	ENTERED BY: Judd, Janie
	CLOSED: TYPE:	Contificate Displains	CLOSED BY:
	CATEGORY:	Certificate Blocking 23-Undefined Boiler Violation	
		363. Undefined Boiler Violation	
	CONDITION:		
	CONDITION:		ons. Boiler not operating at time of inspection; flow vice (PRD) could not be tested to verify proper
	REQUIREMENT:	is operating so that the flow soperation. As an alternative, a	ons. Schedule a reinspection at a time when the boiler witch and PRD may be tested to verify proper a detailed boiler log or service report that includes sful testing of the flow switch and PRD is also

 Location:
 Lil Donnie Walkers Car Wash
 Location #: 1806163
 Violations: 1

 1246 S Main St, , Graham, NC
 27253-4537, Phone: 336-222-1950
 Violations: 1

 Contact:
 Attn Pete Walker, Owner, SPG Inc, Phone: 336-222-1950, Cell:336 451 0507
 Violations: 1

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

	Object: NC294925 - Boil	er - Raypak - 1999 - Mech Rm - Acti	ve Violatio	ns This Object: 1
	COMPAN	Y: Hartford Steam Boiler		
	INSPECT	OR: Leonard, Shannon D.		
	OPENED	: 11/30/2020	ENTERED BY:	Judd, Janie
	CLOSED	:	CLOSED BY:	
	TYPE:	Certificate Blocking		
	CATEGO	RY: 01-LWCO and Flow Sensin	g Devices NCAC 13-13.0	)409
	SUBCAT	EGORY 006. Low water cutoff devic	e inoperative or bypasse	d.
	CONDITI	ON: 006. LWCO and Flow Sens inoperative or bypassed.	ng Devices NCAC 13-13	3.0409: Low water cutoff devic
	REQUIRE	EMENT: 006. Repair or replace the i ensure proper operation.	noperable low water fuel	cutoff control and test to
ation:	Milkco Inc 220 Deaverview Rd Ast	neville NC 28806-1710 Phone: 828	Location #: 482567	Violations: 1
ation:	220 Deaverview Rd, , Ash	neville, NC 28806-1710, Phone: 828 aintenance, Milkco Inc, Phone: 828-/	-254-6851	Violations: 1
ation:	220 Deaverview Rd, , Ash Contact: Scott Willett, Ma		3-254-6851 400-0161	Violations: 1 ns This Object: 1
ation:	220 Deaverview Rd, , Ash Contact: Scott Willett, Ma	aintenance, Milkco Inc, Phone: 828- - Eisenbeck - 2005 - Maint Shop Blr	3-254-6851 400-0161	
ation:	220 Deaverview Rd, , Ash Contact: Scott Willett, Ma Object: NC365428 - PV	aintenance, Milkco Inc, Phone: 828- - Eisenbeck - 2005 - Maint Shop Blr IY: Hartford Steam Boiler	3-254-6851 400-0161	
ation:	220 Deaverview Rd, , Ash Contact: Scott Willett, Ma Object: NC365428 - PV COMPAN	aintenance, Milkco Inc, Phone: 828- - Eisenbeck - 2005 - Maint Shop Blr IY: Hartford Steam Boiler FOR: Possidente, James	3-254-6851 400-0161	
ation:	220 Deaverview Rd, , Ash Contact: Scott Willett, Ma Object: NC365428 - PV COMPAN INSPECT	<ul> <li>aintenance, Milkco Inc, Phone: 828-</li> <li>Eisenbeck - 2005 - Maint Shop Blr</li> <li>IY: Hartford Steam Boiler</li> <li>OR: Possidente, James</li> <li>10/14/2020</li> </ul>	8-254-6851 400-0161 Rm - Active <b>Violatio</b>	ns This Object: 1
ation:	220 Deaverview Rd, , Ash Contact: Scott Willett, Ma Object: NC365428 - PV COMPAN INSPECT OPENED	<ul> <li>aintenance, Milkco Inc, Phone: 828-</li> <li>Eisenbeck - 2005 - Maint Shop Blr</li> <li>IY: Hartford Steam Boiler</li> <li>OR: Possidente, James</li> <li>10/14/2020</li> </ul>	ENTERED BY:	ns This Object: 1
ation:	220 Deaverview Rd, , Ash Contact: Scott Willett, Ma Object: NC365428 - PV COMPAN INSPECT OPENED CLOSED	<ul> <li>aintenance, Milkco Inc, Phone: 828-</li> <li>Eisenbeck - 2005 - Maint Shop Blr</li> <li>IY: Hartford Steam Boiler</li> <li>TOR: Possidente, James</li> <li>10/14/2020</li> <li>Certificate Blocking</li> </ul>	ENTERED BY: CLOSED BY:	<b>ns This Object:</b> 1 Putek, Terry
ation:	220 Deaverview Rd, , Ash Contact: Scott Willett, Ma Object: NC365428 - PV COMPAN INSPECT OPENED CLOSED TYPE: CATEGO	<ul> <li>aintenance, Milkco Inc, Phone: 828-</li> <li>Eisenbeck - 2005 - Maint Shop Blr</li> <li>IY: Hartford Steam Boiler</li> <li>TOR: Possidente, James</li> <li>10/14/2020</li> <li>Certificate Blocking</li> </ul>	ENTERED BY: CLOSED BY:	<b>ns This Object:</b> 1 Putek, Terry
ation:	220 Deaverview Rd, , Ash Contact: Scott Willett, Ma Object: NC365428 - PV COMPAN INSPECT OPENED CLOSED TYPE: CATEGO	<ul> <li>aintenance, Milkco Inc, Phone: 828-</li> <li>Eisenbeck - 2005 - Maint Shop Blr</li> <li>IY: Hartford Steam Boiler</li> <li>TOR: Possidente, James</li> <li>certificate Blocking</li> <li>ORY: 08-Unqual Orgs: Repair/Alte</li> <li>TEGORY 491. Unauthorized Repair.</li> </ul>	ENTERED BY: CLOSED BY:	<b>ns This Object:</b> 1 Putek, Terry

Location: Monsoon Car Wash Location #: 2001664 2558 Lewisville Clemmons Rd, , Clemmons, NC 27012-8711, Phone: 336-500-1937 Contact: There is no contact information available for this location. Violations: 1

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC	374671 - PV - Manc	chester - 1996 - Equip Rm - Active	Violatio	ns This Object: 1
	COMPANY:	State of North Carolina		
	INSPECTOR:	Parker, Richard		
	OPENED:	02/24/2020	ENTERED BY:	Parker, Richard
	CLOSED:		CLOSED BY:	
	TYPE:	Certificate Blocking		
	CATEGORY:	07-Undefined Pressure Vessels		
	SUBCATEGOR	Y 479. Undefined Pressure Vessels	s Violations.	
	CONDITION:	479. No one at location.		
	REQUIREMENT	<b>I:</b> 479. Contact inspector and sche	dule inspection.	
		contact Richard Parker @ 336-20	02-8341	
5122 N Cau	•		ation #: 4048752 336-408-1546	Violations: 1
5122 N Cau <b>Contact:</b> R	seway Rd, , Winston oger Morris, Morris H	g Inc Loc n Salem, NC 27106-9695, Phone:	ation #: 4048752 336-408-1546 ne: 336-408-1546	Violations: 1 ns This Object: 1
5122 N Cau <b>Contact:</b> R	seway Rd, , Winston oger Morris, Morris H	g Inc <b>Loc</b> Salem, NC 27106-9695, Phone: Heating & Air Conditioning Inc, Pho	ation #: 4048752 336-408-1546 ne: 336-408-1546	
5122 N Cau <b>Contact:</b> R	seway Rd, , Winston oger Morris, Morris H 2426511 - PV - Brunr	g Inc <b>Loc</b> n Salem, NC 27106-9695, Phone: Heating & Air Conditioning Inc, Pho ner - 1985 - Outside Shed - Active	ation #: 4048752 336-408-1546 ne: 336-408-1546	
5122 N Cau <b>Contact:</b> R	seway Rd, , Winston oger Morris, Morris H 2426511 - PV - Brunr COMPANY: INSPECTOR: OPENED:	g Inc Loca n Salem, NC 27106-9695, Phone: Heating & Air Conditioning Inc, Pho ner - 1985 - Outside Shed - Active State of North Carolina	ation #: 4048752 336-408-1546 ne: 336-408-1546 Violation ENTERED BY:	
5122 N Cau <b>Contact:</b> R	Seway Rd, , Winston oger Morris, Morris H 2426511 - PV - Brunr COMPANY: INSPECTOR: OPENED: CLOSED:	g Inc Loca a Salem, NC 27106-9695, Phone: Heating & Air Conditioning Inc, Pho her - 1985 - Outside Shed - Active State of North Carolina Parker, Richard 12/09/2020	ation #: 4048752 336-408-1546 ne: 336-408-1546 Violatio	ns This Object: 1
5122 N Cau <b>Contact:</b> R	Seway Rd, , Winston oger Morris, Morris H 2426511 - PV - Brunr COMPANY: INSPECTOR: OPENED: CLOSED: TYPE:	g Inc Loca Salem, NC 27106-9695, Phone: Heating & Air Conditioning Inc, Phone: Heating & Air Con	ation #: 4048752 336-408-1546 ne: 336-408-1546 Violation ENTERED BY: CLOSED BY:	ns This Object: 1
5122 N Cau <b>Contact:</b> R	Seway Rd, , Winston oger Morris, Morris H 2426511 - PV - Brunn COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	g Inc Loca Salem, NC 27106-9695, Phone: Heating & Air Conditioning Inc, Pho ner - 1985 - Outside Shed - Active State of North Carolina Parker, Richard 12/09/2020 Certificate Blocking 07-Undefined Pressure Vessels	ation #: 4048752 336-408-1546 ne: 336-408-1546 Violation ENTERED BY: CLOSED BY:	ns This Object: 1
5122 N Cau <b>Contact:</b> R	Seway Rd, , Winston oger Morris, Morris H 2426511 - PV - Brunr COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY: SUBCATEGOR	g Inc Loca Salem, NC 27106-9695, Phone: Heating & Air Conditioning Inc, Phone Heating & Air Conditioning Inc, Phone Mer - 1985 - Outside Shed - Active State of North Carolina Parker, Richard 12/09/2020 Certificate Blocking 07-Undefined Pressure Vessels Y 479. Undefined Pressure Vessels	ation #: 4048752 336-408-1546 ne: 336-408-1546 Violation ENTERED BY: CLOSED BY: Violations s Violations.	ns This Object: 1
5122 N Cau <b>Contact:</b> R	Seway Rd, , Winston oger Morris, Morris H 2426511 - PV - Brunn COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	g Inc Loca Salem, NC 27106-9695, Phone: Heating & Air Conditioning Inc, Pho ner - 1985 - Outside Shed - Active State of North Carolina Parker, Richard 12/09/2020 Certificate Blocking 07-Undefined Pressure Vessels	ation #: 4048752 336-408-1546 ne: 336-408-1546 Violation ENTERED BY: CLOSED BY: Violations s Violations.	ns This Object: 1
5122 N Cau <b>Contact:</b> R	Seway Rd, , Winston oger Morris, Morris H 2426511 - PV - Brunr COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY: SUBCATEGOR CONDITION:	g Inc Loca Salem, NC 27106-9695, Phone: Heating & Air Conditioning Inc, Phone Heating & Air Conditioning Inc, Phone Mer - 1985 - Outside Shed - Active State of North Carolina Parker, Richard 12/09/2020 Certificate Blocking 07-Undefined Pressure Vessels Y 479. Undefined Pressure Vessels	ation #: 4048752 336-408-1546 ne: 336-408-1546 Violation ENTERED BY: CLOSED BY: Violations s Violations. ure vessel.	ns This Object: 1

Location:Mt Hope United Church Of ChristLocation #: 1812482Violations: 22400 Mount Hope Church Rd, , Whitsett, NC27377-9750, Phone: 336-697-1561Contact: There is no contact information available for this location.Violations: 2

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

bject.	NC399199 - Boiler - Giar	nnoni - 2008 - Bsmt Blr Rm - Active	Violations This Object: 1
	COMPANY:	Hartford Steam Boiler	
	INSPECTOR:	Leonard, Shannon D.	
	OPENED:	12/01/2020	ENTERED BY: Judd, Janie
	CLOSED:		CLOSED BY:
	TYPE:	Certificate Blocking	
	CATEGORY:	23-Undefined Boiler Violations	
	SUBCATEGORY	363. Undefined Boiler Violations.	
	CONDITION:		Boiler not operating at time of inspection; flow PRD) could not be tested to verify proper
	REQUIREMENT:	is operating so that the flow switch operation. As an alternative, a deta	Schedule a reinspection at a time when the boile and PRD may be tested to verify proper ailed boiler log or service report that includes esting of the flow switch and PRD is also
bject:	COMPANY:	nnoni - 2009 - Bsmt Blr Rm - Active Hartford Steam Boiler	Violations This Object: 1
bject:	COMPANY: INSPECTOR:	nnoni - 2009 - Bsmt Blr Rm - Active Hartford Steam Boiler Leonard, Shannon D.	
bject:	COMPANY: INSPECTOR: OPENED:	nnoni - 2009 - Bsmt Blr Rm - Active Hartford Steam Boiler	ENTERED BY: Judd, Janie
bject:	COMPANY: INSPECTOR: OPENED: CLOSED:	nnoni - 2009 - Bsmt Blr Rm - Active Hartford Steam Boiler Leonard, Shannon D. 12/01/2020	
bject:	COMPANY: INSPECTOR: OPENED: CLOSED: TYPE:	nnoni - 2009 - Bsmt Blr Rm - Active Hartford Steam Boiler Leonard, Shannon D. 12/01/2020 Certificate Blocking	ENTERED BY: Judd, Janie
bject:	COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	Anoni - 2009 - Bsmt Blr Rm - Active Hartford Steam Boiler Leonard, Shannon D. 12/01/2020 Certificate Blocking 23-Undefined Boiler Violations	ENTERED BY: Judd, Janie
)bject:	COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY: SUBCATEGORY	Anoni - 2009 - Bsmt Blr Rm - Active Hartford Steam Boiler Leonard, Shannon D. 12/01/2020 Certificate Blocking 23-Undefined Boiler Violations 363. Undefined Boiler Violations.	ENTERED BY: Judd, Janie CLOSED BY:
)bject:	COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	Hartford Steam Boiler Leonard, Shannon D. 12/01/2020 Certificate Blocking 23-Undefined Boiler Violations 363. Undefined Boiler Violations. 363. Undefined Boiler Violations.	ENTERED BY: Judd, Janie

Location:National Guard ArmoryLocation #: 1813595Violations: 11935 N Church St, , Burlington, NC27217-2926, Phone: 336-227-7859Contact: Attn Major Blane Boyd, Director of Facility Maintenance, Joint Forces HQ, Phone: 919-664-6094

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC389334 - Boiler - Loch	ninvar - 2011 - Blr Rm - Active	Violations This Object: 1
COMPANY:	Hartford Steam Boiler	
INSPECTOR:	Leonard, Shannon D.	
OPENED:	09/02/2020	ENTERED BY: Judd, Janie
CLOSED:		CLOSED BY:
TYPE:	Certificate Blocking	
CATEGORY:	23-Undefined Boiler Violations	
SUBCATEGORY	363. Undefined Boiler Violations.	
		Boiler not operating at time of inspection; pressure not be tested to verify proper operation.
	OPERATING SO THAT THE PRE MAY BE TESTED TO VERIFY PR DETAILED SERVICE REPORT O	ON AT A TIME WHEN THE BOILER IS SSURE RELIEF DEVICE AND FLOW SWITCH OPER OPERATION. AS AN ALTERNATIVE, A R BOILER LOG THAT INCLUDES CESSFUL TESTING OF THESE CONTROLS IS

Location: National Guard Armory

Location #: 1813513 Violations: 2

292 NC Highway 65, , Reidsville, NC 27320-8897, Phone: 336-349-4428 **Contact:** Lee Lewis, National Guard Armory, Phone: 984-664-8009

bject: NC425270 - Boiler - Lochinvar - 2018 - Blr Rm - Active		Violations This Object: 1	
COMPANY:	State of North Carolina		
INSPECTOR:	Parker, Richard		
OPENED:	04/08/2020	ENTERED BY:	Parker, Richard
CLOSED:		CLOSED BY:	
TYPE:	Certificate Blocking		
CATEGORY:	25-Operation of PRDs NCAC 1	3-13.0405	
SUBCATEGORY	391. Discharge piping not prope	erly supported.	
CONDITION:	391. Operation of PRDs NCAC supported.	13-13.0405: Dischar	ge piping not properly
REQUIREMENT:	391. Support the relief valve dis on the relief valve.	scharge piping so it m	ay not impose excessive stress

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC42	25271 - Boiler - Loc	hinvar - 2018 - Blr Rm - Active	Violations This Object: 1
	COMPANY:	State of North Carolina	
	INSPECTOR:	Parker, Richard	
	OPENED:	04/08/2020	ENTERED BY: Parker, Richard
	CLOSED:		CLOSED BY:
	TYPE:	Certificate Blocking	
	CATEGORY:	25-Operation of PRDs NCAC 13-	13.0405
	SUBCATEGORY	' 391. Discharge piping not proper	y supported.
	CONDITION:	391. Operation of PRDs NCAC 13 supported.	3-13.0405: Discharge piping not properly
	REQUIREMENT:	: 391. Support the relief valve discl on the relief valve.	harge piping so it may not impose excessive stre
		contact Richard Parker @ 336-20	02-8341
	Way, , Kannapolis,	NC 28081-3379, Phone: 704-250	
500 Laureate <b>Contact:</b> Cha	Way, , Kannapolis, rles Kraus, Facilitie	NC 28081-3379, Phone: 704-250	
500 Laureate V Contact: Cha	Way, , Kannapolis, rles Kraus, Facilitie	NC 28081-3379, Phone: 704-250 s Operations/Zone 7 Supervisor, L	-5017 INC Charlotte, Phone: 704-250-5017, Cell:980-
500 Laureate <b>Contact:</b> Cha	Way, , Kannapolis, rles Kraus, Facilitie 71947 - Boiler - Brya	NC 28081-3379, Phone: 704-250 s Operations/Zone 7 Supervisor, L an - 2007 - Penthouse - Active	-5017 INC Charlotte, Phone: 704-250-5017, Cell:980-
500 Laureate V Contact: Cha	Way, , Kannapolis, rles Kraus, Facilitie 71947 - Boiler - Brya COMPANY: INSPECTOR: OPENED:	NC 28081-3379, Phone: 704-250 s Operations/Zone 7 Supervisor, L an - 2007 - Penthouse - Active State of North Carolina	-5017 INC Charlotte, Phone: 704-250-5017, Cell:980- Violations This Object: 1 ENTERED BY: Smith, Jeremy
500 Laureate <b>Contact:</b> Cha	Way, , Kannapolis, rles Kraus, Facilitie 71947 - Boiler - Brya COMPANY: INSPECTOR: OPENED: CLOSED:	NC 28081-3379, Phone: 704-250 s Operations/Zone 7 Supervisor, L an - 2007 - Penthouse - Active State of North Carolina Smith, Jeremy	-5017 INC Charlotte, Phone: 704-250-5017, Cell:980- Violations This Object: 1
500 Laureate V Contact: Cha	Way, , Kannapolis, rles Kraus, Facilitie 71947 - Boiler - Brya COMPANY: INSPECTOR: OPENED:	NC 28081-3379, Phone: 704-250 s Operations/Zone 7 Supervisor, L an - 2007 - Penthouse - Active State of North Carolina Smith, Jeremy 11/06/2020 Certificate Blocking	-5017 INC Charlotte, Phone: 704-250-5017, Cell:980- Violations This Object: 1 ENTERED BY: Smith, Jeremy
500 Laureate <b>Contact:</b> Cha	Way, , Kannapolis, rles Kraus, Facilitie 71947 - Boiler - Brya COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	NC 28081-3379, Phone: 704-250 s Operations/Zone 7 Supervisor, L an - 2007 - Penthouse - Active State of North Carolina Smith, Jeremy 11/06/2020 Certificate Blocking 23-Undefined Boiler Violations	-5017 INC Charlotte, Phone: 704-250-5017, Cell:980- Violations This Object: 1 ENTERED BY: Smith, Jeremy
500 Laureate V Contact: Cha	Way, , Kannapolis, rles Kraus, Facilitie 71947 - Boiler - Brya COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	NC 28081-3379, Phone: 704-250 s Operations/Zone 7 Supervisor, L an - 2007 - Penthouse - Active State of North Carolina Smith, Jeremy 11/06/2020 Certificate Blocking	-5017 INC Charlotte, Phone: 704-250-5017, Cell:980- Violations This Object: 1 ENTERED BY: Smith, Jeremy
500 Laureate V Contact: Cha	Way, , Kannapolis, rles Kraus, Facilitie 71947 - Boiler - Brya COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	NC 28081-3379, Phone: 704-250 s Operations/Zone 7 Supervisor, L an - 2007 - Penthouse - Active State of North Carolina Smith, Jeremy 11/06/2020 Certificate Blocking 23-Undefined Boiler Violations 363. Undefined Boiler Violations. 363. Undefined Boiler Violations. inspection every year. Contrary to	-5017 INC Charlotte, Phone: 704-250-5017, Cell:980- Violations This Object: 1 ENTERED BY: Smith, Jeremy

Location: Paul J Rizzo Conference Center Location #: 1817817 150 Dubose Home Ln, , Chapel Hill, NC 27517-8944, Phone: 919-913-2098 Contact: There is no contact information available for this location. Violations: 1

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

COMPANY:	Hartford Steam Boiler	
INSPECTOR:	Ollison, Jr., James C.	
OPENED:	06/11/2020	ENTERED BY: Keyes, Amanda
CLOSED:		CLOSED BY:
TYPE:	Certificate Blocking	
CATEGORY:	25-Operation of PRDs NCA	C 13-13.0405
SUBCATEGORY	396. Missing nameplate.	
CONDITION:	396. Operation of PRDs NC	AC 13-13.0405: Missing nameplate.
		e with one set at a pressure not exceeding the ressure determined by the manufacturer. The ASME/NB certified.

Location: Pilot View Baptist Church

Location #: 1819495 Violations: 2

7173 Prospect Church Rd, , Thomasville, NC 27360-8839, Phone: 336-886-5867/336-431-5872 **Contact:** There is no contact information available for this location.

		-
Hartford Steam Boiler		
Leonard, Shannon D.		
12/15/2020	ENTERED BY:	Judd, Janie
	CLOSED BY:	
Certificate Blocking		
01-LWCO and Flow Sensing Devic	es NCAC 13-13.0	409
006. Low water cutoff device inope	rative or bypassed	d.
006. LWCO and Flow Sensing Dev inoperative or bypassed.	ices NCAC 13-13	.0409: Low water cutoff device
006. Repair or replace the inoperate ensure proper operation.	ble low water fuel	cutoff control and test to
Hartford Steam Boiler		
Leonard, Shannon D.		
12/15/2020	ENTERED BY:	Judd, Janie
	CLOSED BY:	
Certificate Blocking		
01-LWCO and Flow Sensing Devic	es NCAC 13-13.0	409
007. Accumulation of sediment in f	oat chamber.	
007. LWCO and Flow Sensing Dev sediment in float chamber.	ices NCAC 13-13	.0409: Accumulation of
	Leonard, Shannon D. 12/15/2020 Certificate Blocking 01-LWCO and Flow Sensing Devic 006. Low water cutoff device inope 006. LWCO and Flow Sensing Dev inoperative or bypassed. 006. Repair or replace the inoperat ensure proper operation. Hartford Steam Boiler Leonard, Shannon D. 12/15/2020 Certificate Blocking 01-LWCO and Flow Sensing Devic	Leonard, Shannon D. 12/15/2020 ENTERED BY: Certificate Blocking 01-LWCO and Flow Sensing Devices NCAC 13-13.0 006. Low water cutoff device inoperative or bypassed 006. LWCO and Flow Sensing Devices NCAC 13-13 inoperative or bypassed. 006. Repair or replace the inoperable low water fuel ensure proper operation. Hartford Steam Boiler Leonard, Shannon D. 12/15/2020 ENTERED BY: Certificate Blocking 01-LWCO and Flow Sensing Devices NCAC 13-13.0 007. Accumulation of sediment in float chamber.

Location:	Professional Rental Services	<b>Locati</b> 27030-5602, Phone: 336-786-614	on #: 1821288 Violations: 1
	-		es, Phone: 336-786-6148, Cell:336-755-7699
	Object: NC345478 - Boiler - Hurs	st - 2002 - Blr Rm - Active	Violations This Object: 1
	COMPANY:	Hartford Steam Boiler	
	INSPECTOR:	Leonard, Shannon D.	
	OPENED:	01/15/2021	ENTERED BY: Judd, Janie
	CLOSED:		CLOSED BY:
	TYPE:	Certificate Blocking	
	CATEGORY:	23-Undefined Boiler Violations	
	SUBCATEGORY	' 363. Undefined Boiler Violations.	
	CONDITION:		oiler not operating at time of inspection; low relief device (PRD) could not be tested to verify
	REQUIREMENT:	when it is operating so that the LWC operation. As an alternative, a detail	chedule a inspection of this boiler at a time CO's and PRD may be tested to verify proper iled service report or boiler log that includes sting of these controls is also acceptable.
Location:	Statesville Family YMCA 828 Wesley Dr, , Statesville, NC	<b>Locati</b> 28677-3355, Phone: 704-873-9622	on #: 1845601 Violations: 5
	Contact: Paxton Hix, Facilities D	irector, Statesville Family YMCA, , C	ell:704-880-4915
	Object: NC265007 - Boiler - Rein	mers - 1993 - Mens Steam Rm - Acti	ve Violations This Object: 1
	COMPANY:	Hartford Steam Boiler	
	INSPECTOR:	Leonard, Shannon D.	

•••••••			
INSPECTOR:	Leonard, Shannon D.		
OPENED:	12/16/2020	ENTERED BY:	Judd, Janie
CLOSED:		CLOSED BY:	
TYPE:	Certificate Blocking		
CATEGORY:	23-Undefined Boiler Violations		
SUBCATEGORY	363. Undefined Boiler Violations.		
CONDITION:	363. Undefined Boiler Violations. el inspection; safety controls could no	•	
REQUIREMENT:	363. Undefined Boiler Violations. S electric steam generator is operatin verify proper operation. As an alter includes documentation of the succ acceptable.	ng so that the safet native, a detailed s	ty controls may be tested to service report or log that

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC351556 - Boiler - Rheem/Ruud - 2003 - Pool Mech Rm - Active Violations This Object: 1

COMPANY:	Hartford Steam Boiler		
INSPECTOR:	Leonard, Shannon D.		
OPENED:	12/16/2020	ENTERED BY:	Judd, Janie
CLOSED:		CLOSED BY:	
TYPE:	Certificate Blocking		
CATEGORY:	06-Thermometer NCAC 13-13.0410	0	
SUBCATEGORY	111. Thermometer inoperative.		
CONDITION:	111. Thermometer NCAC 13-13.04	10: Thermometer	inoperative.
REQUIREMENT:	111. Replace inoperative thermometemperature in degrees Fahrenheit range of approximately 2 times the than 1 1/2 times the intended operating temperature.	of the water. The intended operatin	thermometer shall have a g temperature but not less

Object: NC351557 - Boiler - Rheem/Ruud - 2003 - Pool Mech Rm - Active Violations This Object: 1

COMPANY:	Hartford Steam Boiler		
INSPECTOR:	Leonard, Shannon D.		
OPENED:	12/16/2020	ENTERED BY:	Judd, Janie
CLOSED:		CLOSED BY:	
TYPE:	Certificate Blocking		
CATEGORY:	06-Thermometer NCAC 13-13.041	0	
SUBCATEGORY	Y 111. Thermometer inoperative.		
CONDITION:	111. Thermometer NCAC 13-13.04	410: Thermometer	inoperative.
REQUIREMENT	: 111. Replace inoperative thermom temperature in degrees Fahrenhei range of approximately 2 times the than 1 1/2 times the intended oper intended operating temperature.	t of the water. The intended operatir	thermometer shall have a ig temperature but not less

**Object:** NC380587 - Boiler - Fulton - 2008 - Ladies Steam Rm - Active **Violations This Object:** 1

COMPANY:	Hartford Steam Boiler		
INSPECTOR:	Leonard, Shannon D.		
OPENED:	12/16/2020	ENTERED BY:	Judd, Janie
CLOSED:		CLOSED BY:	
TYPE:	Certificate Blocking		
CATEGORY:	23-Undefined Boiler Violations		
SUBCATEGORY	363. Undefined Boiler Violations.		
CONDITION:	363. Undefined Boiler Violations: e inspection; safety controls could no	5	
REQUIREMENT:	363. Undefined Boiler Violations. S electric steam generator is operatin verify proper operation. As an alter includes documentation of the succ acceptable.	ng so that the safe native, a detailed s	ty controls may be tested to service report or log that

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

<b>Object:</b> NC409027	- Boiler - Raypak - 2014 - Po	ol Mech Rm - Active Violatio	ns This Object: 1
COI	MPANY: Hartford Stean	n Boiler	
INS	PECTOR: Leonard, Shar	non D.	
OPE	<b>NED:</b> 12/16/2020	ENTERED BY:	Judd, Janie
CLC	OSED:	CLOSED BY:	
TYF	E: Certificate Blo	cking	
CA	EGORY: 24-Installation	of PRDs NCAC 13-13.0405	
SUE	SCATEGORY 381. Incorrect	pressure relieving device(s) for the ap	oplication.
COI		n of PRDs NCAC 13-13.0405: Non-te ure relief device (PRD) installed on H	
REC	pressure reliev relieving capa equipped with	he current PRD with an ASME/NB sta ring type PRD having a set pressure of rity of 627,000 BTU/Hour or more. The a try-lever and the PRD discharge mu ithin 6" of the mech room floor.)	of 160 PSI or less and a e replacement PRD must be
cation: Sterilelink Inc 3036 Forest Park Dr	, , Randleman, NC 27317-7	Location #: 3810293	Violations: 1
	Wright, Sterilelink Inc, Phor		

bject: NC413585 - Boiler - Chro	malox - 2002 - Blr Rm - Active	Violations This Object: 1
COMPANY:	Hartford Steam Boiler	
INSPECTOR:	Leonard, Shannon D.	
OPENED:	01/20/2021	ENTERED BY: Judd, Janie
CLOSED:		CLOSED BY:
TYPE:	Certificate Blocking	
CATEGORY:	23-Undefined Boiler Violations	
SUBCATEGORY	363. Undefined Boiler Violations	
	363. Undefined Boiler Violations devices could not be tested to v	<ul> <li>Boiler not operating at time of inspection: Safety erify proper operation</li> </ul>
	electric steam generator is oper- verify proper operation. As an al	S. Schedule a reinspection at a time when the ating so that the safety devices may be tested to ternative, a detailed service report or boiler log the successful testing of these controls is also

Location: Storopack Packaging Systems USA Location #: 1839256 Violations: 1 2598 Empire Dr Ste G, , Winston Salem, NC 27103-6763, Phone: 336-765-7767 Contact: Attn Anne Ward, Storopack Packaging Systems USA, Phone: 336-765-7767

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object:	NC279022 - Boiler - Yo	rk Shipley - 1987 - Blr Rm - Active	Violatio	ns This Object: 1
	COMPANY:	Hartford Steam Boiler		
	INSPECTOR:	Leonard, Shannon D.		
	OPENED:	01/22/2021	ENTERED BY:	Judd, Janie
	CLOSED:		CLOSED BY:	
	TYPE:	Certificate Blocking		
	CATEGORY:	23-Undefined Boiler Violations		
	SUBCATEGOR	Y 363. Undefined Boiler Violations.		
	CONDITION:	363. Undefined Boiler Violations.	Stop valve inopera	tive.
		: 363. Undefined Boiler Violations. replacement stop valve must be of steam working pressure rating on	lesigned for steam	
ation: Surry Cl	hamicale	LOCA	ation #: 1834066	Violations: 1
241 Hicl	kory St, , Mount Airy, NC	27030-2211, Phone: 336-786-460 hemicals Inc, Phone: 336-786-460	)7 X17	
241 Hick Contact	kory St, , Mount Airy, NC <b>t:</b> Travis Tolbert, Surry C	27030-2211, Phone: 336-786-460	)7 X17 7 X17	ns This Object: 1
241 Hick Contact	kory St, , Mount Airy, NC t: Travis Tolbert, Surry C NC267195 - Boiler - Fu COMPANY:	27030-2211, Phone: 336-786-460 hemicals Inc, Phone: 336-786-460	)7 X17 7 X17	
241 Hick Contact	kory St, , Mount Airy, NC t: Travis Tolbert, Surry C NC267195 - Boiler - Ful	27030-2211, Phone: 336-786-460 hemicals Inc, Phone: 336-786-460 ton - 1994 - Blr Rm - Active Hartford Steam Boiler Leonard, Shannon D.	)7 X17 7 X17	
241 Hick Contact	kory St, , Mount Airy, NC t: Travis Tolbert, Surry C NC267195 - Boiler - Fu COMPANY: INSPECTOR: OPENED:	27030-2211, Phone: 336-786-460 hemicals Inc, Phone: 336-786-460 ton - 1994 - Blr Rm - Active Hartford Steam Boiler	7 X17 7 X17 Violation ENTERED BY:	
241 Hick Contact	kory St, , Mount Airy, NC t: Travis Tolbert, Surry C NC267195 - Boiler - Fu COMPANY: INSPECTOR: OPENED: CLOSED:	27030-2211, Phone: 336-786-460 hemicals Inc, Phone: 336-786-460 ton - 1994 - Blr Rm - Active Hartford Steam Boiler Leonard, Shannon D. 12/15/2020	07 X17 7 X17 Violatio	ns This Object: 1
241 Hick Contact	kory St, , Mount Airy, NC t: Travis Tolbert, Surry C NC267195 - Boiler - Fu COMPANY: INSPECTOR: OPENED: CLOSED: TYPE:	27030-2211, Phone: 336-786-460 hemicals Inc, Phone: 336-786-460 ton - 1994 - Blr Rm - Active Hartford Steam Boiler Leonard, Shannon D. 12/15/2020 Certificate Blocking	7 X17 7 X17 Violation ENTERED BY: CLOSED BY:	ns This Object: 1
241 Hick Contact	kory St, , Mount Airy, NC t: Travis Tolbert, Surry C NC267195 - Boiler - Ful COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	27030-2211, Phone: 336-786-460 hemicals Inc, Phone: 336-786-460 ton - 1994 - Blr Rm - Active Hartford Steam Boiler Leonard, Shannon D. 12/15/2020 Certificate Blocking 25-Operation of PRDs NCAC 13-	7 X17 7 X17 Violation ENTERED BY: CLOSED BY:	ns This Object: 1
241 Hick Contact	kory St, , Mount Airy, NC t: Travis Tolbert, Surry C NC267195 - Boiler - Ful COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	27030-2211, Phone: 336-786-460 hemicals Inc, Phone: 336-786-460 ton - 1994 - Blr Rm - Active Hartford Steam Boiler Leonard, Shannon D. 12/15/2020 Certificate Blocking	7 X17 7 X17 Violation ENTERED BY: CLOSED BY:	ns This Object: 1
241 Hick Contact	kory St, , Mount Airy, NC t: Travis Tolbert, Surry C NC267195 - Boiler - Ful COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	27030-2211, Phone: 336-786-460 hemicals Inc, Phone: 336-786-460 ton - 1994 - Blr Rm - Active Hartford Steam Boiler Leonard, Shannon D. 12/15/2020 Certificate Blocking 25-Operation of PRDs NCAC 13-	7 X17 7 X17 Violation ENTERED BY: CLOSED BY: 13.0405	n <b>s This Object:</b> 1 Judd, Janie

**Location:** Tailored Chemical Products

Location #: 332360 Violations: 1

1120 Tate Blvd SE, , Hickory, NC 28602-4025, Phone: 828-324-0149 Contact: Tom Stanek, Plant Manager, Tailored Chemical Products Inc, Phone: 828-324-0149, Cell:940-597-7305

0	bject: NC36	63847 - Boiler - Cle	aver Brooks - 1994 - Blr Area - Act	ve Violatio	ons This Object: 1
		COMPANY:	State of North Carolina		
		INSPECTOR:	Smith, Jeremy		
		OPENED:	09/08/2020	ENTERED BY:	Smith, Jeremy
		CLOSED:		CLOSED BY:	· · · ·
		TYPE:	Certificate Blocking		
		CATEGORY:	23-Undefined Boiler Violations		
		SUBCATEGOR	363. Undefined Boiler Violations.		
		CONDITION:	363. Undefined Boiler Violations. inspection every year. Contrary to not been completed on an annua 4/12/2018.	13 NCAC 13.021	1(b), an external inspection ha
		REQUIREMENT	: 363. Undefined Boiler Violations. completed. Contact your inspecto schedule an external inspection.		
52		t, , Asheville, NC	<b>Loca</b> 28801-8105, Phone: 828-253-8304 ce Mechanic II, Thomas Wolfe Mer		<b>Violations:</b> 2 3-253-8304
52 C	2 N Market S contact: Jim Object: NC4 <sup>2</sup>	t, , Asheville, NC Muhlig, Maintenan 18769 - Boiler - AIC	28801-8105, Phone: 828-253-8304	norial, Phone: 828	
52 C	2 N Market S contact: Jim Object: NC4 <sup>2</sup>	it, , Asheville, NC Muhlig, Maintenan 18769 - Boiler - AIC - Active	28801-8105, Phone: 828-253-8304 ce Mechanic II, Thomas Wolfe Mer SA - 2018 - Old Kentucky Home E	norial, Phone: 828	-253-8304
52 C	2 N Market S contact: Jim Object: NC4 <sup>2</sup>	t, , Asheville, NC Muhlig, Maintenand 18769 - Boiler - AIC - Active COMPANY:	28801-8105, Phone: 828-253-8304 ce Mechanic II, Thomas Wolfe Mer CSA - 2018 - Old Kentucky Home E Hartford Steam Boiler	norial, Phone: 828	-253-8304
52 C	2 N Market S contact: Jim Object: NC4 <sup>2</sup>	it, , Asheville, NC Muhlig, Maintenand 18769 - Boiler - AIC - Active COMPANY: INSPECTOR:	28801-8105, Phone: 828-253-8304 ce Mechanic II, Thomas Wolfe Men CSA - 2018 - Old Kentucky Home E Hartford Steam Boiler Possidente, James	norial, Phone: 828 Blr Rm <b>Violatio</b>	-253-8304 ons This Object: 1
52 C	2 N Market S contact: Jim Object: NC4 <sup>2</sup>	it, , Asheville, NC Muhlig, Maintenand 18769 - Boiler - AIC - Active COMPANY: INSPECTOR: OPENED:	28801-8105, Phone: 828-253-8304 ce Mechanic II, Thomas Wolfe Mer CSA - 2018 - Old Kentucky Home E Hartford Steam Boiler	norial, Phone: 828 Blr Rm <b>Violatio</b> ENTERED BY:	-253-8304 ons This Object: 1
52 C	2 N Market S contact: Jim Object: NC4 <sup>2</sup>	it, , Asheville, NC Muhlig, Maintenand 18769 - Boiler - AlC - Active COMPANY: INSPECTOR: OPENED: CLOSED:	28801-8105, Phone: 828-253-8304 ce Mechanic II, Thomas Wolfe Mer C SA - 2018 - Old Kentucky Home E Hartford Steam Boiler Possidente, James 01/07/2021	norial, Phone: 828 Blr Rm <b>Violatio</b>	-253-8304 ons This Object: 1
52 C	2 N Market S contact: Jim Object: NC4 <sup>2</sup>	it, , Asheville, NC Muhlig, Maintenand 18769 - Boiler - AIC - Active COMPANY: INSPECTOR: OPENED: CLOSED: TYPE:	28801-8105, Phone: 828-253-8304 ce Mechanic II, Thomas Wolfe Men C SA - 2018 - Old Kentucky Home E Hartford Steam Boiler Possidente, James 01/07/2021 Certificate Blocking	norial, Phone: 828 Blr Rm <b>Violatio</b> ENTERED BY:	-253-8304 ons This Object: 1
52 C	2 N Market S contact: Jim Object: NC4 <sup>2</sup>	it, , Asheville, NC Muhlig, Maintenand 18769 - Boiler - AIC - Active COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	28801-8105, Phone: 828-253-8304 ce Mechanic II, Thomas Wolfe Men C SA - 2018 - Old Kentucky Home E Hartford Steam Boiler Possidente, James 01/07/2021 Certificate Blocking 23-Undefined Boiler Violations	norial, Phone: 828 Blr Rm <b>Violatio</b> ENTERED BY:	-253-8304 ons This Object: 1
52 C	2 N Market S contact: Jim Object: NC4 <sup>2</sup>	it, , Asheville, NC Muhlig, Maintenand 18769 - Boiler - AlC - Active COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY: SUBCATEGORY	28801-8105, Phone: 828-253-8304 ce Mechanic II, Thomas Wolfe Mer C SA - 2018 - Old Kentucky Home E Hartford Steam Boiler Possidente, James 01/07/2021 Certificate Blocking 23-Undefined Boiler Violations ( 363. Undefined Boiler Violations.	norial, Phone: 828 Blr Rm Violatio ENTERED BY: CLOSED BY:	s-253-8304 ons This Object: 1 Putek, Terry
52 C	2 N Market S contact: Jim Object: NC4 <sup>2</sup>	it, , Asheville, NC Muhlig, Maintenand 18769 - Boiler - AIC - Active COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	28801-8105, Phone: 828-253-8304 ce Mechanic II, Thomas Wolfe Men C SA - 2018 - Old Kentucky Home E Hartford Steam Boiler Possidente, James 01/07/2021 Certificate Blocking 23-Undefined Boiler Violations	norial, Phone: 828 Blr Rm Violatio ENTERED BY: CLOSED BY:	s-253-8304 ons This Object: 1 Putek, Terry

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

	Object:	NC418770 - Boiler - Alo Bsmt - Active	CSA - 2018 - Old Kentucky Home Blr Rm	Violatio	ns This Object: 1
		COMPANY:	Hartford Steam Boiler		
		INSPECTOR:	Possidente, James		
		OPENED:	01/07/2021 ENT	ERED BY:	Putek, Terry
		CLOSED:	CLO	SED BY:	-
		TYPE:	Certificate Blocking		
		CATEGORY:	26-Undefined Pressure Relieving Device	s Violations	;
		SUBCATEGOR	<b>Y</b> 399. Undefined Pressure Relieving Devi	ces Violatio	าร.
		CONDITION:	399. Undefined Pressure Relieving Device relief valve during inspection. Owner refu		ns. Unable to test pressure
		REQUIREMENT	: 399. Undefined Pressure Relieving Devic when someone will be able to open the b tested.		
ocation:	5611 Hil		<b>Location #:</b> NC 27606-1534, Phone: 919-851-1236		Violations: 1
ocation:	5611 Hil <b>Contact</b>	lsborough St, , Raleigh, :: John Elliason, Manage		851-1236	Violations: 1 ns This Object: 1
ocation:	5611 Hil <b>Contact</b>	lsborough St, , Raleigh, :: John Elliason, Manage	NC 27606-1534, Phone: 919-851-1236 r, West German Garage Inc, Phone: 919-	851-1236	
ocation:	5611 Hil <b>Contact</b>	Isborough St, , Raleigh, :: John Elliason, Manage NC356708 - PV - Manc	NC 27606-1534, Phone: 919-851-1236 r, West German Garage Inc, Phone: 919- hester - 1999 - Outside - Active State of North Carolina	851-1236	
ocation:	5611 Hil <b>Contact</b>	Isborough St, , Raleigh, :: John Elliason, Manage NC356708 - PV - Manc COMPANY:	NC 27606-1534, Phone: 919-851-1236 er, West German Garage Inc, Phone: 919- hester - 1999 - Outside - Active State of North Carolina Fish, Emily	851-1236	ns This Object: 1
ocation:	5611 Hil <b>Contact</b>	Isborough St, , Raleigh, : John Elliason, Manage NC356708 - PV - Manc COMPANY: INSPECTOR:	NC 27606-1534, Phone: 919-851-1236 pr, West German Garage Inc, Phone: 919- hester - 1999 - Outside - Active State of North Carolina Fish, Emily 10/15/2020	851-1236 Violatio	
ocation:	5611 Hil <b>Contact</b>	Isborough St, , Raleigh, :: John Elliason, Manage NC356708 - PV - Manc COMPANY: INSPECTOR: OPENED:	NC 27606-1534, Phone: 919-851-1236 pr, West German Garage Inc, Phone: 919- hester - 1999 - Outside - Active State of North Carolina Fish, Emily 10/15/2020	851-1236 Violatio ERED BY:	ns This Object: 1
ocation:	5611 Hil <b>Contact</b>	Isborough St, , Raleigh, :: John Elliason, Manage NC356708 - PV - Manc COMPANY: INSPECTOR: OPENED: CLOSED:	NC 27606-1534, Phone: 919-851-1236 r, West German Garage Inc, Phone: 919- hester - 1999 - Outside - Active State of North Carolina Fish, Emily 10/15/2020 ENT CLO	851-1236 Violatio ERED BY:	ns This Object: 1

CONDITION: 032. Pressure Gauges NCAC 13-13.0407: Incorrect range or insufficient pointer travel.

**REQUIREMENT:** 032. Install a pressure gauge on the equipment that is visible to the operator from the floor or work platform. Gauge must be the proper range in accordance with NC Administrative Code, Title 13, Chapter 13, Section .0407. Please call Emily Fish at (919) 268-0725 when ready for reinspection.

Location: Williamson Cleaners

Location #: 1844175 Violations: 1

3711 Peppermill Dr N Ste G, Wilson, NC 27896-7390, Phone: 252-205-6180 **Contact:** Attn James Min, Owner, Williamson Cleaners, Phone: 252-237-1828, Cell:336-837-7025

	Object: NC34	2375 - Boiler - Colu	umbia - 2002 - Blr Rm - Active	Violations This Object: 1
		COMPANY:	State of North Carolina	
		INSPECTOR:	Harrell, Danny	
		OPENED:	01/19/2021	ENTERED BY: Harrell, Danny
		CLOSED:		CLOSED BY:
		TYPE:	Certificate Blocking	
		CATEGORY:	03-Water Gauge Glass NCAC 1	3-13.0408
		SUBCATEGORY	•	
		CONDITION:	058. Water Gauge Glass NCAC	0
		REQUIREMENT:		ng gauge and test to ensure proper operation. 00-3098 when the repair is completed.
ocation:		Retirement Commu	5	cation #: 1844569 Violations: 1
			NC 27526-3602, Phone: 919-55	
	Contact: Jimn	ny Richardson, Mai	ntenance Supervisor, Windsor P	oint Retirement Community, Phone: 919-552-4580
	Object: NC38		2010 - Blr Rm - Active	Violations This Object: 1
		COMPANY:	Hartford Steam Boiler	
		INSPECTOR:	SORRENTINO, SEAN	
		OPENED:	11/13/2020	ENTERED BY: Keyes, Amanda
		CLOSED:		CLOSED BY:
		TYPE:	Certificate Blocking	
		CATEGORY:	01-Installation	
		SUBCATEGORY	413. Cracking.	
		CONDITION:	413. Installation: Cracking.	
			Ŭ	ding is required, a qualified "R" certificate holder is
ocation:	Woodmark Ori	REQUIREMENT:	413. Repair the cracking. If well necessary to perform the work.	ding is required, a qualified "R" certificate holder is
ocation:	Woodmark Ori 1920 Jarrell St	REQUIREMENT:	413. Repair the cracking. If well necessary to perform the work.	cation #: 1223157 Violations: 2
ocation:	1920 Jarrell St	REQUIREMENT: ginals , , High Point, NC	413. Repair the cracking. If well necessary to perform the work. Lo 27260-8812, Phone: 336-841-64	cation #: 1223157 Violations: 2
ocation:	1920 Jarrell St Contact: Attn	REQUIREMENT: ginals , , High Point, NC Bobby Cook, Maint 4705 - Boiler - Rier	413. Repair the cracking. If well necessary to perform the work. Loc 27260-8812, Phone: 336-841-64 tenance Supervisor, Woodmark ( mers - 1985 - Skirting - Active	cation #: 1223157 Violations: 2
ocation:	1920 Jarrell St Contact: Attn	REQUIREMENT: ginals , , High Point, NC Bobby Cook, Maint 4705 - Boiler - Rier COMPANY:	413. Repair the cracking. If well necessary to perform the work. Loc 27260-8812, Phone: 336-841-64 tenance Supervisor, Woodmark ( mers - 1985 - Skirting - Active Hartford Steam Boiler	cation #: 1223157 Violations: 2 409 Driginals Inc, Phone: 336-841-6409 X138
ocation:	1920 Jarrell St Contact: Attn	REQUIREMENT: ginals , , High Point, NC Bobby Cook, Maint 4705 - Boiler - Rier COMPANY: INSPECTOR:	413. Repair the cracking. If well necessary to perform the work. Loc 27260-8812, Phone: 336-841-64 tenance Supervisor, Woodmark ( mers - 1985 - Skirting - Active Hartford Steam Boiler Leonard, Shannon D.	cation #: 1223157 Violations: 2 109 Driginals Inc, Phone: 336-841-6409 X138 Violations This Object: 2
ocation:	1920 Jarrell St Contact: Attn	REQUIREMENT: ginals , , High Point, NC Bobby Cook, Maint 4705 - Boiler - Rier COMPANY: INSPECTOR: OPENED:	413. Repair the cracking. If well necessary to perform the work. Loc 27260-8812, Phone: 336-841-64 tenance Supervisor, Woodmark ( mers - 1985 - Skirting - Active Hartford Steam Boiler	cation #: 1223157 Violations: 2 109 Driginals Inc, Phone: 336-841-6409 X138 Violations This Object: 2 ENTERED BY: Judd, Janie
ocation:	1920 Jarrell St Contact: Attn	REQUIREMENT: ginals , , High Point, NC Bobby Cook, Maint 4705 - Boiler - Rier COMPANY: INSPECTOR: OPENED: CLOSED:	413. Repair the cracking. If well necessary to perform the work. 27260-8812, Phone: 336-841-64 tenance Supervisor, Woodmark ( mers - 1985 - Skirting - Active Hartford Steam Boiler Leonard, Shannon D. 12/22/2020	cation #: 1223157 Violations: 2 109 Driginals Inc, Phone: 336-841-6409 X138 Violations This Object: 2
ocation:	1920 Jarrell St Contact: Attn	REQUIREMENT: ginals , , High Point, NC Bobby Cook, Maint 4705 - Boiler - Rier COMPANY: INSPECTOR: OPENED: CLOSED: TYPE:	413. Repair the cracking. If well necessary to perform the work. Loc 27260-8812, Phone: 336-841-64 tenance Supervisor, Woodmark ( mers - 1985 - Skirting - Active Hartford Steam Boiler Leonard, Shannon D. 12/22/2020 Certificate Blocking	09 Driginals Inc, Phone: 336-841-6409 X138 Violations This Object: 2 ENTERED BY: Judd, Janie CLOSED BY:
ocation:	1920 Jarrell St Contact: Attn	REQUIREMENT: ginals , , High Point, NC Bobby Cook, Maint 4705 - Boiler - Rier COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	413. Repair the cracking. If well necessary to perform the work. 27260-8812, Phone: 336-841-64 tenance Supervisor, Woodmark ( mers - 1985 - Skirting - Active Hartford Steam Boiler Leonard, Shannon D. 12/22/2020 Certificate Blocking 01-LWCO and Flow Sensing De	cation #: 1223157 Violations: 2 109 Driginals Inc, Phone: 336-841-6409 X138 Violations This Object: 2 ENTERED BY: Judd, Janie CLOSED BY:
.ocation:	1920 Jarrell St Contact: Attn	REQUIREMENT: ginals , , High Point, NC Bobby Cook, Maint 4705 - Boiler - Rier COMPANY: INSPECTOR: OPENED: CLOSED: TYPE: CATEGORY:	413. Repair the cracking. If well necessary to perform the work. 27260-8812, Phone: 336-841-64 tenance Supervisor, Woodmark ( mers - 1985 - Skirting - Active Hartford Steam Boiler Leonard, Shannon D. 12/22/2020 Certificate Blocking 01-LWCO and Flow Sensing De 7015. Pipe size too small.	cation #: 1223157 Violations: 2 109 Driginals Inc, Phone: 336-841-6409 X138 Violations This Object: 2 ENTERED BY: Judd, Janie CLOSED BY:

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

COMPANY:	Hartford Steam Boiler		
INSPECTOR:	Leonard, Shannon D.		
OPENED:	12/22/2020	ENTERED BY:	Judd, Janie
CLOSED:		CLOSED BY:	
TYPE:	Certificate Blocking		
CATEGORY:	26-Undefined Pressure Relieving D	evices Violations	
SUBCATEGORY	399. Undefined Pressure Relieving	Devices Violations	
CONDITION:	399. Undefined Pressure Relieving discharge piping improper material.		. Pressure relief device(PRD)
REQUIREMENT:	399. Undefined Pressure Relieving discharge piping with proper black piping must be piped full size to a s	steel pipe. The repla	acement PRD discharge

Violations This Report: 93

Locations This Report: 61