

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Location:** (CABARRUS CS) Beverly Hills Elem **Location #:** 1768208 **Violations:** 1  
87 Palaside Dr NE, , Concord, NC 28025-3056, Phone: 704-782-0115  
**Contact:** Cabarrus County Schools, Phone: 704-262-6239/704-786-6191

**Object:** NC291622 - Boiler - Weil-McLain - 1998 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Clay, Steven D.  
**OPENED:** 02/17/2022 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 396. Missing nameplate.  
**CONDITION:** 396. Operation of PRDs NCAC 13-13.0405: PRD nameplate unreadable  
**REQUIREMENT:** 396. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

---

**Location:** (CABARRUS CS) Cabarrus County Opportunity School **Location #:** 1792956 **Violations:** 1  
120 Marsh Ave NW, , Concord, NC 28025-4889, Phone: 704-793-1736  
**Contact:** Cabarrus County Schools, Phone: 704-262-6239/704-786-6191

**Object:** NC291623 - Boiler - Weil-McLain - 1998 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Clay, Steven D.  
**OPENED:** 02/17/2022 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 394. Valve inoperative.  
**CONDITION:** 394. Operation of PRDs NCAC 13-13.0405: Valve inoperative: PRD was leaking at base and from weephole  
**REQUIREMENT:** 394. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

---

**Location:** (CABARRUS CS) Carl A Furr Elem **Location #:** 2002374 **Violations:** 1  
2725 Clover Rd NW, , Concord, NC 28027-3804, Phone: 704-788-4300  
**Contact:** Cabarrus County Schools, Phone: 704-262-6239/704-786-6191

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

**Object:** NC364598 - Boiler - Weil-McLain - 2006 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Clay, Steven D.  
**OPENED:** 02/15/2022  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations. The installer put the wrong ASME nameplate on.  
**REQUIREMENT:** 363. Undefined Boiler Violations. Customer is to obtain and fill out the needed form and have the manufacturer send the correct AMSE nameplate for attachment.

**Location:** (CABARRUS CS) Jay M Robinson High

**Location #:** 1801478

**Violations:** 2

300 Pitts School Rd NW, , Concord, NC 28027-2823, Phone: 704-788-4500

**Contact:** Cabarrus County Schools, Phone: 704-262-6239/704-786-6191

**Object:** NC326551 - Boiler - Weil-McLain - 2000 - Blr Rm - Active

**Violations This Object:** 2

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Clay, Steven D.  
**OPENED:** 02/16/2022  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409  
**SUBCATEGORY** 009. Water level control inoperative or bypassed.  
**CONDITION:** 009. LWCO and Flow Sensing Devices NCAC 13-13.0409: Water level control inoperative or bypassed.  
**REQUIREMENT:** 009. Repair or replace the inoperable water level control and test to ensure proper operation.

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Clay, Steven D.  
**OPENED:** 02/16/2022  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 24-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 379. Discharge piping too small.  
**CONDITION:** 379. Installation of PRDs NCAC 13-13.0405: Discharge piping too small.  
**REQUIREMENT:** 379. Repipe the discharge line full size to a safe point of discharge.

**Location:** (CHEROKEE CS) Hiwassee Dam Union Elem/Middle/High

**Location #:** 1797763

**Violations:** 1

7755 Highway 294, , Murphy, NC 28906-4939, Phone: 828-644-5115

**Contact:** Boone Roberts, Custodian, Hiwassee Dam Union Elem/Middle/High, Phone: 828-837-2722

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC304360 - PV - Manchester - 1994 - Carpentry Shop - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 12/09/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 07-Undefined Pressure Vessels Violations  
**SUBCATEGORY** 479. Undefined Pressure Vessels Violations.  
**CONDITION:** 479. Undefined Pressure Vessels Violations: this vessel could not be started and is no longer in use but it has not been properly disconnected  
**REQUIREMENT:** 479. Undefined Pressure Vessels Violations: Disconnect the vessel from all sources of potential energy including electricity. Call for a follow up once the work is complete.

---

**Location:** (CHEROKEE CS) Murphy Middle **Location #:** 1812752 **Violations:** 1  
65 Middle School Dr, , Murphy, NC 28906-5111, Phone: 828-837-0160  
**Contact:** Attn Shawn Johnson, Cherokee County School District, Phone: 828-644-9325, Cell:828-557-4805

---

**Object:** NC284555 - Boiler - H B Smith - 1997 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 12/09/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409  
**SUBCATEGORY** 006. Low water cutoff device inoperative or bypassed.  
**CONDITION:** 006. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device inoperative or bypassed: Failed to test properly by flushing.  
**REQUIREMENT:** 006. Repair or replace the inoperable low water fuel cutoff control and test to ensure proper operation.

---

**Location:** (COLUMBUS CS) Acme Delco Elem **Location #:** 1761932 **Violations:** 2  
16337 Old Lake Rd, , Riegelwood, NC 28456-7077, Phone: 910-655-2957  
**Contact:** Attn Tim Ward, Plant Operations, Columbus County Schools, Phone: 910-642-0161, Cell:910-770-2303

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC252134 - Boiler - Weil-McLain - 1990 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Rudolph, Jay

**OPENED:** 11/04/2021

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 12-Casing, Stack Breeching and Flue

**SUBCATEGORY** 211. Combustion gas leaks.

**CONDITION:** 211. Casing, Stack Breeching and Flue: Combustion gas leaks.

**REQUIREMENT:** 211. Repair all combustion gas leaks in the casing, stack breeching, or flue.

---

**Object:** NC259063 - Boiler - Weil-McLain - 1992 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Rudolph, Jay

**OPENED:** 11/04/2021

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 23-Undefined Boiler Violations

**SUBCATEGORY** 363. Undefined Boiler Violations.

**CONDITION:** 363. Undefined Boiler Violations. Boiler was not operating during inspection

**REQUIREMENT:** 363. Undefined Boiler Violations. Reschedule inspection for a time when the boiler is operating so that safety devices can be verified to operate properly.

---

**Location:** (COLUMBUS CS) Chadbourn Elem

**Location #:** 1775696

**Violations:** 1

409 E 3rd Ave, , Chadbourn, NC 28431-1911, Phone: 910-654-3825

**Contact:** Attn Tim Ward, Plant Operations, Columbus County Schools, Phone: 910-642-0161, Cell:910-770-2303

---

**Object:** NC135804 - Boiler - Weil-McLain - 1975 - Gym - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Rudolph, Jay

**OPENED:** 11/05/2021

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 23-Undefined Boiler Violations

**SUBCATEGORY** 363. Undefined Boiler Violations.

**CONDITION:** 363. Undefined Boiler Violations. Boiler not operating.

**REQUIREMENT:** 363. Undefined Boiler Violations. Reschedule inspection for a time when the boiler is operating so that safety devices can be verified to operate properly.

---

**Location:** (COLUMBUS CS) East Columbus High

**Location #:** 1785232

**Violations:** 3

32 Gator Ln, , Lake Waccamaw, NC 28450-2257, Phone: 910-646-4094

**Contact:** Attn Tim Ward, Plant Operations, Columbus County Schools, Phone: 910-642-0161, Cell:910-770-2303

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC257092 - Boiler - Weil-McLain - 1992 - Blr Rm - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 11/04/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409  
**SUBCATEGORY** 006. Low water cutoff device inoperative or bypassed.  
**CONDITION:** 006. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device inoperative or bypassed.  
**REQUIREMENT:** 006. Repair or replace the inoperable low water fuel cutoff control and test to ensure proper operation.

**ENTERED BY:** Judd, Janie  
**CLOSED BY:**

---

**Object:** NC257093 - Boiler - Weil-McLain - 1992 - Blr Rm - Active

**Violations This Object:** 2

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 11/04/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409  
**SUBCATEGORY** 006. Low water cutoff device inoperative or bypassed.  
**CONDITION:** 006. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device inoperative or bypassed.  
**REQUIREMENT:** 006. Repair or replace the inoperable low water fuel cutoff control and test to ensure proper operation.

**ENTERED BY:** Judd, Janie  
**CLOSED BY:**

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 11/04/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 270. Water Leaks.  
**CONDITION:** 270. Boiler Components: Water Leaks: Water leaks from segment joint.  
**REQUIREMENT:** 270. Repair the water leaks identified on the inspection report.

**ENTERED BY:** Judd, Janie  
**CLOSED BY:**

---

**Location:** (COLUMBUS CS) Evergreen Elem

**Location #:** 1787118

**Violations:** 1

7211 Old Highway 74, , Evergreen, NC 28438-9639, Phone: 910-654-3502

**Contact:** Attn Tim Ward, Plant Operations, Columbus County Schools, Phone: 910-642-0161, Cell:910-770-2303

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC279527 - Boiler - Weil-McLain - 1996 - Gym - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Rudolph, Jay

**OPENED:** 11/05/2021

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 23-Undefined Boiler Violations

**SUBCATEGORY** 363. Undefined Boiler Violations.

**CONDITION:** 363. Undefined Boiler Violations: Boiler not operating.

**REQUIREMENT:** 363. Undefined Boiler Violations: Reschedule inspection for a time when the boiler is operating so that safety devices can be verified to operate properly.

---

**Location:** (COLUMBUS CS) South Columbus High

**Location #:** 1830238

**Violations:** 2

40 Stallion Dr, , Tabor City, NC 28463-9626, Phone: 910-653-4073

**Contact:** Attn Tim Ward, Plant Operations, Columbus County Schools, Phone: 910-642-0161, Cell:910-770-2303

---

**Object:** NC257089 - Boiler - Weil-McLain - 1992 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Rudolph, Jay

**OPENED:** 11/04/2021

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409

**SUBCATEGORY** 006. Low water cutoff device inoperative or bypassed.

**CONDITION:** 006. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device inoperative or bypassed.

**REQUIREMENT:** 006. Repair or replace the inoperable low water fuel cutoff control and test to ensure proper operation.

---

**Object:** NC257091 - Boiler - Weil-McLain - 1992 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Rudolph, Jay

**OPENED:** 11/04/2021

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409

**SUBCATEGORY** 006. Low water cutoff device inoperative or bypassed.

**CONDITION:** 006. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device inoperative or bypassed.

**REQUIREMENT:** 006. Repair or replace the inoperable low water fuel cutoff control and test to ensure proper operation.

---

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Location:** (COLUMBUS CS) West Columbus High **Location #:** 1842827 **Violations:** 2  
7294 Andrew Jackson Hwy SW, , Cerro Gordo, NC 28430-9258, Phone: 910-654-6111  
**Contact:** Attn Tim Ward, Plant Operations, Columbus County Schools, Phone: 910-642-0161, Cell:910-770-2303

**Object:** NC272374 - Boiler - Weil-McLain - 1995 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 11/05/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations: Boiler not operating.  
**REQUIREMENT:** 363. Undefined Boiler Violations: Reschedule inspection for a time when the boiler is operating so that safety devices can be verified to operate properly.

**Object:** NC308726 - Boiler - Weil-McLain - 1999 - Auditorium - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 11/05/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 395. Valve leaking.  
**CONDITION:** 395. Operation of PRDs NCAC 13-13.0405: Valve leaking: Pressure relief device leaking.  
**REQUIREMENT:** 395. Replace with a ASME/NB certified pressure relief device with a set pressure of not greater than 50 psig, with a relief capacity of not less than 690,000 BTU/hr, and with a testing lever.

---

**Location:** (DPS-C) Albemarle CI - 4580 **Location #:** 1762698 **Violations:** 2  
44150 Airport Rd, , New London, NC 28127-9597, Phone: 704-422-3036  
**Contact:** Ricky Maness, Maintenance Supervisor, Albemarle CI - 4580, Phone: 704-422-2600/702-422-3036



# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC296308 - Boiler - Burnham - 1998 - Core Bldg Mech Rm 1244 - **Violations This Object:** 1  
Active

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 01/06/2022 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 397. Try lever inoperative.  
**CONDITION:** 397. Operation of PRDs NCAC 13-13.0405: Try lever inoperative.  
**REQUIREMENT:** 397. Install a new ASME/NB stamped PRD having a set pressure of 60 PSI or less and a relieving capacity of 2,318,000 BTU/Hour or more. The replacement PRD must be equipped with a functioning try-lever and the PRD discharge must be piped full size to a safe location (i.e. within 6" of the boiler room floor)

---

**Object:** NC414836 - Boiler - Cleveland Range - 2015 - Kitchen - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 01/06/2022 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 13-Burners and Fuel Supply Systems  
**SUBCATEGORY** 235. No emergency fuel shut off switch.  
**CONDITION:** 235. Burners and Fuel Supply Systems: No emergency fuel shut off switch.  
**REQUIREMENT:** 235. Install an emergency fuel shut off switch at each egress from the boiler room to shut off all fuel to the boilers.

---

**Location:** (DPS-C) Lanesboro CI - 4865 **Location #:** 1805021 **Violations:** 1  
552 Prison Camp Rd, , Polkton, NC 28135-6118, Phone: 704-695-1013  
**Contact:** NC Dept Of Public Safety - 13101, Phone: 919-716-3422

---

**Object:** NC340797 - Boiler - Cleaver Brooks - 2002 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Clay, Steven D.  
**OPENED:** 11/01/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations. Boiler can not run due to faulty modulating motor. Part is on order with C&C Boiler but is currently not available to nation wide parts shortage. Boiler is not in use and tagged out.  
**REQUIREMENT:** 363. Undefined Boiler Violations. Repair boiler as required. Part needed to repair is on backorder.

---



# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Location:** (DPS-C) Lanesboro Minimum CI - 3510      **Location #:** 1770840      **Violations:** 3  
248 Prison Camp Rd, , Polkton, NC 28135-6115, Phone: 704-694-2622  
**Contact:** Ernie Thomas, Maintenance Supervisor, Brown Creek CI - 3510, Phone: 704-694-2622 X222 X285

**Object:** NC251876 - Boiler - Peerless - 1991 - Blr Rm Unit 6 - Active      **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Clay, Steven D.  
**OPENED:** 07/19/2021      **ENTERED BY:** Putek, Terry  
**CLOSED:**      **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409  
**SUBCATEGORY** 022. Faulty electrical wiring.  
**CONDITION:** 022. LWCO and Flow Sensing Devices NCAC 13-13.0409: Faulty electrical wiring. LWCO (float) wired backwards.  
**REQUIREMENT:** 022. Repair or replace the faulty electrical wiring and test control to ensure proper operation.

**Object:** NC251882 - Boiler - Lochinvar - 1991 - Blr Rm Unit 5 - Active      **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Clay, Steven D.  
**OPENED:** 07/19/2021      **ENTERED BY:** Putek, Terry  
**CLOSED:**      **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 24-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 378. Discharge opening directed improperly.  
**CONDITION:** 378. Installation of PRDs NCAC 13-13.0405: Discharge opening directed improperly. Discharge piping not installed on PRD.  
**REQUIREMENT:** 378. Redirect the discharge to a safe point at required in NCAC 13-13.0405.

**Object:** NC396137 - Boiler - Teledyne Laars - 2011 - Outside Admin Bldg - Active      **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Clay, Steven D.  
**OPENED:** 07/22/2021      **ENTERED BY:** Putek, Terry  
**CLOSED:**      **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations. Boiler would not run for inspection due to controls and hot weather.  
**REQUIREMENT:** 363. Undefined Boiler Violations. Schedule the inspection when the boiler is in operation so that safety devices can be tested.

---

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Location:** (DPS-C) NCCIW - 3010 **Location #:** 1779964 **Violations:** 2  
1034 Bragg St, , Raleigh, NC 27610-3846, Phone: 919-733-4340  
**Contact:** Phillip Jones, Maintenance Supervisor, NCCIW - 3010, Phone: 919-508-1690

**Object:** NC381483 - Boiler - PVI Industries - 2010 - Falcom Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** SORRENTINO, SEAN  
**OPENED:** 12/08/2020 **ENTERED BY:** Keyes, Amanda  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 270. Water Leaks.  
**CONDITION:** 270. Boiler Components: Water Leaks.  
**REQUIREMENT:** 270. Repair the water leaks identified on the inspection report. If welding is required, a qualified "R" certificate holder is necessary to perform the repair.

**Object:** NC401596 - Boiler - PVI Industries - 2014 - Sparrow N - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** SORRENTINO, SEAN  
**OPENED:** 12/08/2020 **ENTERED BY:** Keyes, Amanda  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 270. Water Leaks.  
**CONDITION:** 270. Boiler Components: Water Leaks. Tank leaking at unknown location.  
**REQUIREMENT:** 270. Repair the water leaks identified on the inspection report. If welding is required, a qualified "R" certificate holder is necessary to perform the repair.

---

**Location:** (DPS-J) Stonewall Jackson School **Location #:** 1833119 **Violations:** 1  
850 Holshouser Rd, , Concord, NC 28027-7078, Phone: 704-786-9163  
**Contact:** Donny Edwards, Director, Stonewall Jackson School, Phone: 704-786-9163

**Object:** NC369751 - Boiler - Lochinvar - 2007 - Cabarrus YDC - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Clay, Steven D.  
**OPENED:** 11/29/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations. Boiler would not run due to being disassembled for maintenance.  
**REQUIREMENT:** 363. Undefined Boiler Violations. Boiler will need to be repaired so that it can operate to complete inspection process or disconnected from use.

---

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Location:** (FSU) Jones Student Center **Location #:** 1931441 **Violations:** 1  
1200 Murchison Rd, , Fayetteville, NC 28301-4252, Phone: 910-672-1881  
**Contact:** Attn Allen Hearon PO#0032868, Facility Management, Fayetteville State University, Phone: 910-672-1881,  
**Object:** NC397629 - Boiler - Aerco - 2013 - Blr Rm Behind New Addition - **Violations This Object:** 1  
Active

---

<b>COMPANY:</b>	Hartford Steam Boiler	
<b>INSPECTOR:</b>	Rudolph, Jay	
<b>OPENED:</b>	09/30/2021	<b>ENTERED BY:</b> Judd, Janie
<b>CLOSED:</b>		<b>CLOSED BY:</b>
<b>TYPE:</b>	Certificate Blocking	
<b>CATEGORY:</b>	23-Undefined Boiler Violations	
<b>SUBCATEGORY</b>	363. Undefined Boiler Violations.	
<b>CONDITION:</b>	363. Undefined Boiler Violations. Boiler not running.	
<b>REQUIREMENT:</b>	363. Undefined Boiler Violations. Reschedule inspection for a time when the boiler is operating so that safety devices can be verified to operate properly	

---

**Location:** (FSU) Nursing School **Location #:** 2864083 **Violations:** 1  
1200 Murchison Rd, , Fayetteville, NC 28301-4252, Phone: 910-672-1433  
**Contact:** Attn Allen Hearon PO#0032868, Facility Management, Fayetteville State University, Phone: 910-672-1881,  
**Object:** NC382403 - Boiler - Hydrotherm - 2010 - Mech Rm 1st Flr - Active **Violations This Object:** 1

---

<b>COMPANY:</b>	Hartford Steam Boiler	
<b>INSPECTOR:</b>	Rudolph, Jay	
<b>OPENED:</b>	09/30/2021	<b>ENTERED BY:</b> Judd, Janie
<b>CLOSED:</b>		<b>CLOSED BY:</b>
<b>TYPE:</b>	Certificate Blocking	
<b>CATEGORY:</b>	23-Undefined Boiler Violations	
<b>SUBCATEGORY</b>	363. Undefined Boiler Violations.	
<b>CONDITION:</b>	363. Undefined Boiler Violations. Boiler not operating.	
<b>REQUIREMENT:</b>	363. Undefined Boiler Violations. Reschedule inspection for a time when the boiler is operating so that safety devices can be verified to operate properly.	

---

**Location:** (FTCC) Spring Lake Campus **Location #:** 1831819 **Violations:** 1  
171 Laketree Blvd, , Spring Lake, NC 28390-3189, Phone: 910-678-1000  
**Contact:** Attn Scott Ivy, Maintenance Supervisor, Fayetteville Technical Community College, , Cell:910-740-7838

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC352133 - Boiler - Weil-McLain - 2003 - Blr Rm - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 10/07/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 395. Valve leaking.  
**CONDITION:** 395. Operation of PRDs NCAC 13-13.0405: Pressure relief device leaking.  
**REQUIREMENT:** 395. Immediately replace with a ASME/NB certified pressure relief device with a set pressure of not greater than 50 psig, with a relief capacity of not less than 1,904,000 BTU/hr, and with a testing lever.

---

**Location:** (FTCC) YMCA Sandhills

**Location #:** 2227097

**Violations:** 2

2717 Fort Bragg Rd, , Fayetteville, NC 28303-4720, Phone: 910-426-9622

**Contact:** Attn Scott Ivy, Maintenance Supervisor, Fayetteville Technical Community College, , Cell:910-740-7838

---

**Object:** NC379617 - Boiler - Reimers - 2009 - Womens Steam Rm - Active

**Violations This Object:** 2

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 09/15/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 03-Water Gauge Glass NCAC 13-13.0408  
**SUBCATEGORY** 058. Leaking.  
**CONDITION:** 058. Water Gauge Glass NCAC 13-13.0408: Leaking.  
**REQUIREMENT:** 058. Repair or replace the leaking gauge and test to ensure proper operation.

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 09/15/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 395. Valve leaking.  
**CONDITION:** 395. Operation of PRDs NCAC 13-13.0405: Valve leaking: Pressure relief device leaking.  
**REQUIREMENT:** 395. Replace pressure relief device with a ASME/NB certified pressure relief device with a set pressure of not greater than 100 psig, with a relief capacity of not less than 105 pounds per hour, and with a testing lever.

---

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Location:** (GRAHAM CS) Robbinsville High & Middle **Location #:** 1824861 **Violations:** 1  
301 Sweetwater Rd, , Robbinsville, NC 28771-9435, Phone: 828-479-3330 HIGH/828-479-8488 MIDDLE  
**Contact:** Attn Patrick Nicholes, Maintenance Supervisor, Graham County Schools, Phone: 828-479-6636

**Object:** NC321896 - Boiler - Teledyne Laars - 2000 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 02/17/2022 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 395. Valve leaking.  
**CONDITION:** 395. Operation of PRDs NCAC 13-13.0405: Valve leaking.  
**REQUIREMENT:** 395. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

---

**Location:** (HENDERSON) County Courthouse **Location #:** 1796551 **Violations:** 3  
200 N Grove St Ste 163, , Hendersonville, NC 28792-5027, Phone: 828-808-9701  
**Contact:** Chris Hill, Maintenance Supervisor, Henderson County Courthouse, Phone: 828 458 4882

**Object:** NC270732 - Boiler - PVI Industries - 1994 - Court Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 01/14/2022 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 273. Shell leaks.  
**CONDITION:** 273. Boiler Components: Shell leaks.  
**REQUIREMENT:** 273. Repair the leaking shell. If weld repairs are required, a qualified "R" certificate holder is necessary to perform the work.

**Object:** NC387653 - PV - Niles Steel - 2011 - Court Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 01/14/2022 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 04-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 452. Set pressure too high.  
**CONDITION:** 452. Installation of PRDs NCAC 13-13.0405: Set pressure too high.  
**REQUIREMENT:** 452. Replace the pressure relieving device with one with a set pressure no higher than the maximum allowable working pressure as determined by the manufacturer.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

**Object:** NC409134 - Boiler - Weil-McLain - 2016 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Possidente, James

**OPENED:** 01/14/2022

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 24-Installation of PRDs NCAC 13-13.0405

**SUBCATEGORY** 372. Set pressure too high.

**CONDITION:** 372. Installation of PRDs NCAC 13-13.0405: Set pressure too high.

**REQUIREMENT:** 372. Replace the pressure relieving device with one with a set pressure no higher than the maximum allowable working pressure as determined by the manufacturer.

**Location:** (HENDERSON) County Detention Center

**Location #:** 1796552

**Violations:** 2

200 N Grove St Ste 223, , Hendersonville, NC 28792-5027, Phone: 828-808-9701

**Contact:** Thad Ninnemann, Maintenance Director, Henderson County Detention Center, Phone: 828-808-9701,

**Object:** NC324687 - Boiler - PVI Industries - 2000 - Courthouse Blr Rm - Active

**Violations This Object:** 2

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Possidente, James

**OPENED:** 01/14/2022

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 16-Boiler Components

**SUBCATEGORY** 273. Shell leaks.

**CONDITION:** 273. Boiler Components: Shell leaks.

**REQUIREMENT:** 273. Repair the leaking shell. If weld repairs are required, a qualified "R" certificate holder is necessary to perform the work.

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Possidente, James

**OPENED:** 01/14/2022

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 16-Boiler Components

**SUBCATEGORY** 273. Shell leaks.

**CONDITION:** 273. Boiler Components: Shell leaks.

**REQUIREMENT:** 273. Repair the leaking shell. If weld repairs are required, a qualified "R" certificate holder is necessary to perform the work.

**Location:** (HENDERSON) Social Services

**Location #:** 2285281

**Violations:** 3

1200 Spartanburg Hwy, , Hendersonville, NC 28792-5855, Phone: 828-697-4604

**Contact:** Henderson County Government, Phone: 828-697-4840

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC369389 - Boiler - Lochinvar - 2006 - Penthouse Blr Rm - Active      **Violations This Object:** 2

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 01/14/2022      **ENTERED BY:** Judd, Janie  
**CLOSED:**      **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 02-Pressure Gauges NCAC 13-13.0407  
**SUBCATEGORY** 035. Leaking.  
**CONDITION:** 035. Pressure Gauges NCAC 13-13.0407: Leaking.  
**REQUIREMENT:** 035. Install a pressure gauge on the equipment that is visible to the operator from the floor or work platform. Gauge must be the proper range in accordance with NC Administrative Code, Title 13, Chapter 13, Section .0407.

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 01/14/2022      **ENTERED BY:** Judd, Janie  
**CLOSED:**      **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 11-Exp Tanks & Htng Sys Piping NCAC 13-13.0412  
**SUBCATEGORY** 193. Leaking pipe/pipe joints.  
**CONDITION:** 193. Exp Tanks & Htng Sys Piping NCAC 13-13.0412: Leaking pipe/pipe joints.  
**REQUIREMENT:** 193. Repair or replace leaking piping/pipe joints.

---

**Object:** NC370806 - Boiler - Lochinvar - 2007 - Penthouse Blr Rm - Active      **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 01/14/2022      **ENTERED BY:** Judd, Janie  
**CLOSED:**      **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 11-Exp Tanks & Htng Sys Piping NCAC 13-13.0412  
**SUBCATEGORY** 193. Leaking pipe/pipe joints.  
**CONDITION:** 193. Exp Tanks & Htng Sys Piping NCAC 13-13.0412: Leaking pipe/pipe joints.  
**REQUIREMENT:** 193. Repair or replace leaking piping/pipe joints.

---

**Location:** (LENOIR) County Courthouse      **Location #:** 876965      **Violations:** 1  
130 S Queen St, , Kinston, NC 28501-4941, Phone: 252-559-6452  
**Contact:** Attn Chris Harper, Maintenance, Lenoir County Courthouse, Phone: 252-559-6452



# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC388930 - Boiler - Lochinvar - 2011 - Bsmt Rm J003 - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 10/22/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 395. Valve leaking.  
**CONDITION:** 395. Operation of PRDs NCAC 13-13.0405: Valve leaking: Pressure relief device leaking.  
**REQUIREMENT:** 395. Replace pressure relief device with a ASME/NB certified pressure relief device with a set pressure of not greater than 160 psig, with a relief capacity of not less than 1016 KBH, and with a testing lever.

---

**Location:** (MARTIN CS) Rodgers Elem **Location #:** 1825274 **Violations:** 1  
2277 Rodgers School Rd, , Williamston, NC 27892-8249, Phone: 252-792-6637  
**Contact:** Martin County Schools, Phone: 252-792-1575

---

**Object:** NC303644 - Boiler - Weil-McLain - 1996 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 10/19/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 12-Casing, Stack Breeching and Flue  
**SUBCATEGORY** 211. Combustion gas leaks.  
**CONDITION:** 211. Casing, Stack Breeching and Flue: Combustion gas leaks.  
**REQUIREMENT:** 211. Repair all combustion gas leaks in the casing, stack breeching, or flue.

---

**Location:** (MH UNIV) Chambers Gym **Location #:** 1930561 **Violations:** 1  
227 Bailey St, , Mars Hill, NC 28754 , Phone: 828-689-1201  
**Contact:** Attn David May, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:864-653-0230

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC422574 - Boiler - Weil-McLain - 2019 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Possidente, James

**OPENED:** 12/08/2021

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409

**SUBCATEGORY** 003. Required manual reset low water cutoff device not installed.

**CONDITION:** 003. LWCO and Flow Sensing Devices NCAC 13-13.0409: Required manual reset low water cutoff device not installed: LWCO required manual reset not installed on secondary

**REQUIREMENT:** 003. Install a low-water fuel cutoff device (LWCO) designed for the appropriate service (Steam or Hot Water) that is equipped with a manual reset; or install a manual reset on the existing low water fuel cutoff if appropriate. When the LWCO shuts off the fuel supply to the boiler in the event of a low water condition, the fuel supply must be restarted manually by an operator. Test to ensure proper operation.

---

**Location:** (MH UNIV) Loral Hall

**Location #:** 3352814

**Violations:** 1

143 Womens Hill Dr, , Mars Hill, NC 28754 , Phone: 828-689-1201

**Contact:** Attn David May, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:864-653-0230

---

**Object:** NC393784 - Boiler - A O Smith - 2013 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Possidente, James

**OPENED:** 12/08/2021

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 23-Undefined Boiler Violations

**SUBCATEGORY** 363. Undefined Boiler Violations.

**CONDITION:** 363. Undefined Boiler Violations. The boiler is out of service but not properly disconnected.

**REQUIREMENT:** 363. Undefined Boiler Violations: Properly disconnect the boiler from all sources of potential energy including fuel and electricity.

---

**Location:** (NC A&T) Band Bldg

**Location #:** 1776866

**Violations:** 1

1120 E Bessemer Ave, , Greensboro, NC 27405-7106, Phone: 336-334-7025

**Contact:** NC A & T State University, Phone: 336-334-3806

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC007630 - Boiler - Atlantic - 1948 - Blr Rm 1 - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Leonard, Shannon D.

**OPENED:** 11/01/2021

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 16-Boiler Components

**SUBCATEGORY** 275. Tube/tube ends leak.

**CONDITION:** 275. Boiler Components: Tube/tube ends leak: Leak of unknown origin. Possible tube or tube sheet leakage, but exact source could not be verified.

**REQUIREMENT:** 275. Repair the leaking tubes/tube ends. If weld repairs are required, a qualified "R" certificate holder is necessary to perform the work.

---

**Location:** (NC A&T) C H Moore Agricultural

**Location #:** 1900558

**Violations:** 1

1601 E Market St, , Greensboro, NC 27411-0002, Phone: 336-334-7025

**Contact:** NC A & T State University, Phone: 336-334-3806

---

**Object:** NC343287 - Boiler - Lochinvar - 2003 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Leonard, Shannon D.

**OPENED:** 02/02/2022

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405

**SUBCATEGORY** 395. Valve leaking.

**CONDITION:** 395. Operation of PRDs NCAC 13-13.0405: Valve leaking.

**REQUIREMENT:** 395. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

---

**Location:** (NCSU) Carter Finley Stadium 135-Z5

**Location #:** 1917508

**Violations:** 2

4600 Trinity Rd, , Raleigh, NC 27607-3924, Phone: 919-513-6485

**Contact:** Attn Chris Hill, Engineering Architectural Tech, NC State University Zone 5, Phone: 919-513-6312

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

**Object:** NC432465 - PV - Reco - 2012 - MURPHY - Active

**Violations This Object:** 2

**COMPANY:** State of North Carolina

**INSPECTOR:** Fish, Emily

**OPENED:** 12/14/2021

**ENTERED BY:** Fish, Emily

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 01-Installation

**SUBCATEGORY** 415. Corrosion.

**CONDITION:** 415. Installation: Corrosion.

**REQUIREMENT:** 415. Repair the corrosion. If welding is required, a qualified "R" certificate holder is necessary to perform the work.

**COMPANY:** State of North Carolina

**INSPECTOR:** Fish, Emily

**OPENED:** 12/14/2021

**ENTERED BY:** Fish, Emily

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 08-Unqual Orgs: Repair/Alteration NCAC 13-13.0401

**SUBCATEGORY** 491. Unauthorized Repair.

**CONDITION:** 491. Unauthorized Repair.

**REQUIREMENT:** Repairs conducted on this regulated vessel were done by an unqualified organization/individual and must be removed and replaced by a qualified organization.

**Location:** (UNCC) Facilities Operations

**Location #:** 2550379

**Violations:** 1

9201 University City Blvd, , Charlotte, NC 28223-0001, Phone: 704-687-2199

**Contact:** Attn Kelly Herron, UNC Charlotte, Phone: 704-687-0567

**Object:** NC331573 - Boiler - Aerco - 2004 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Clay, Steven D.

**OPENED:** 11/10/2021

**ENTERED BY:** Putek, Terry

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 23-Undefined Boiler Violations

**SUBCATEGORY** 363. Undefined Boiler Violations.

**CONDITION:** 363. Undefined Boiler Violations. HX cracked. Unit tagged out. Awaiting parts.

**REQUIREMENT:** 363. Undefined Boiler Violations. Repair cracking. If welding is required a qualified 'R' certificate holder is necessary to perform the work.

**Location:** (WU) Bridges Hall

**Location #:** 1880967

**Violations:** 1

216 Cedar St, , Wingate, NC 28174-5495, Phone: 800-755-5550

**Contact:** Attn Richard Helms, Manager, Wingate University, Phone: 800-755-5550, Cell:704-507-1962

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC222281 - Boiler - Peerless - 1986 - Mech Rm - Active

**Violations This Object:** 1

---

<b>COMPANY:</b>	Hartford Steam Boiler	
<b>INSPECTOR:</b>	Clay, Steven D.	
<b>OPENED:</b>	11/15/2021	<b>ENTERED BY:</b> Putek, Terry
<b>CLOSED:</b>		<b>CLOSED BY:</b>
<b>TYPE:</b>	Certificate Blocking	
<b>CATEGORY:</b>	13-Burners and Fuel Supply Systems	
<b>SUBCATEGORY</b>	231. Leaking automatic gas valve.	
<b>CONDITION:</b>	231. Burners and Fuel Supply Systems: Leaking automatic gas valve.	
<b>REQUIREMENT:</b>	231. Repair or replace the leaking automatic gas valve.	

---

**Location:** (WU) New Stadium Training Bldg

**Location #:** 1814520

**Violations:** 1

660 N Main St, , Wingate, NC 28174-6760, Phone: 704-233-8218

**Contact:** Attn Richard Helms, Manager, Wingate University, Phone: 800-755-5550, Cell:704-507-1962

---

**Object:** NC297025 - Boiler - Eafco - 1998 - Blr Rm - Active

**Violations This Object:** 1

---

<b>COMPANY:</b>	Hartford Steam Boiler	
<b>INSPECTOR:</b>	Clay, Steven D.	
<b>OPENED:</b>	11/15/2021	<b>ENTERED BY:</b> Putek, Terry
<b>CLOSED:</b>		<b>CLOSED BY:</b>
<b>TYPE:</b>	Certificate Blocking	
<b>CATEGORY:</b>	01-LWCO and Flow Sensing Devices NCAC 13-13.0409	
<b>SUBCATEGORY</b>	001. Low water cutoff device not installed.	
<b>CONDITION:</b>	001. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device not installed.	
<b>REQUIREMENT:</b>	001. Equip the boiler with a low water fuel cutoff device (LWCO) designed for the appropriate service (Steam or Hot Water) that is equipped with a manual reset. When the LWCO shuts off the fuel supply to the boiler in the event of a low water condition, the fuel supply must be restarted manually by an operator. Test to ensure proper operation.	

---

**Location:** Broughton Hospital New Hospital

**Location #:** 3904479

**Violations:** 2

1000 S Sterling St, , Morganton, NC 28655-3938, Phone: 828-433-2329

**Contact:** Bruce Elder, Maintenance Supervisor, Broughton Hospital New Hospital, Phone: 828 -608-4503

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

**Object:** NC409059 - Boiler - Bryan - 2013 - New Blr Rm - Active

**Violations This Object:** 2

**COMPANY:** State of North Carolina

**INSPECTOR:** Sims, Greg

**OPENED:** 01/12/2022

**ENTERED BY:** Davis, Greg

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 13-Burners and Fuel Supply Systems

**SUBCATEGORY** 236. Undefined Boiler Piping and Other Systems Violations.

**CONDITION:** 236. Burners and Fuel Supply Systems: Undefined Boiler Piping and Other Systems Violations. Boiler had a fireside incident possibly damaging the burner and safety interlocks

**REQUIREMENT:** 236. Undefined Boiler Piping and Other Systems Violations. Test burner and safety interlocks to assure proper operation.

**COMPANY:** State of North Carolina

**INSPECTOR:** Sims, Greg

**OPENED:** 01/12/2022

**ENTERED BY:** Davis, Greg

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 23-Undefined Boiler Violations

**SUBCATEGORY** 363. Undefined Boiler Violations.

**CONDITION:** 363. Undefined Boiler Violations. Boiler had fireside incident damaging outer casing.

**REQUIREMENT:** 363. Undefined Boiler Violations. Replace outer casings of the boiler.

**Location:** Clean Laundry Services

**Location #:** 1879873

**Violations:** 1

2103 Sullivan St, , Greensboro, NC 27405-7331, Phone: 336-897-0008

**Contact:** Andrew Trauschke, Clean Laundry Services, Phone: 336-210-1255

**Object:** NC351212 - Boiler - Superior Boiler Works - 2003 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Leonard, Shannon D.

**OPENED:** 11/01/2021

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405

**SUBCATEGORY** 395. Valve leaking.

**CONDITION:** 395. Operation of PRDs NCAC 13-13.0405: Valve leaking: Both pressure relief devices (PRD) leaking.

**REQUIREMENT:** 395. Replace the two leaking PRD's with ASME/NB stamped PRD's. The set pressure of each PRD must be rated at 150 PSI or less and the combined relieving capacities of the two replacement PRD's must be greater than or equal to 10,136 pounds of steam per hour.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Location:** Dale Earnhardt Inc **Location #:** 1781942 **Violations:** 1  
1675 Dale Earnhardt Hwy Ste 3, , Mooresville, NC 28115-8330, Phone: 704-662-8000 X3311  
**Contact:** Attn Bob Bauer, Shop Manager, Dale Earnhardt Inc, Phone: 704-662-8000 X3311, Cell:336-972-0393

**Object:** NC282929 - Boiler - Raypak - 1997 - Blr Rm WC 1 - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 01/11/2022 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations: Boiler not operating at time of inspection; flow switch and pressure relief device (PRD) could not be tested to verify proper operation.

**REQUIREMENT:** 363. Undefined Boiler Violations: Schedule a reinspection at a time when the boiler is operating so that the flow switch and PRD may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the controls is also acceptable

---

**Location:** Edwards Truck Service & Body Shop **Location #:** 871758 **Violations:** 1  
915 US Highway 117 Byp S, , Goldsboro, NC 27530-6320, Phone: 919-735-9784  
**Contact:** Diane Brock, Corporate Secretary, Edwards Truck Service & Body Shop, Phone: 919-735-9784

**Object:** NC363115 - PV - Trinity - 2005 - Outside Rear - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 02/11/2022 **ENTERED BY:** Keyes, Amanda  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 09-Pressure Gauges NCAC 13-13.0407  
**SUBCATEGORY** 031. Out of calibration.  
**CONDITION:** 031. Pressure Gauges NCAC 13-13.0407: Out of calibration.  
**REQUIREMENT:** 031. Recalibrate pressure gauge or replace with a calibrated gauge ranged in accordance with NC Administrative Code, Title 13, Chapter 13, Section .0407.

---

**Location:** Elevate Textile **Location #:** 1771590 **Violations:** 11  
1001 Turnpike Rd, , Raeford, NC 28376-8566, Phone: 910-875-3731  
**Contact:** Attn David Limbacher, Maintenance Manager, Elevate Textile INC, Phone: 910-875-3731 X472, Cell:910-



# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

**Object:** NC197933 - PV - Gcdmc - 1964 - Dye Kier #3 - Active

**Violations This Object:** 2

<b>COMPANY:</b>	Hartford Steam Boiler		
<b>INSPECTOR:</b>	Rudolph, Jay		
<b>OPENED:</b>	01/19/2022	<b>ENTERED BY:</b>	Keyes, Amanda
<b>CLOSED:</b>		<b>CLOSED BY:</b>	
<b>TYPE:</b>	Certificate Blocking		
<b>CATEGORY:</b>	04-Installation of PRDs NCAC 13-13.0405		
<b>SUBCATEGORY</b>	457. Try lever not installed.		
<b>CONDITION:</b>	457. Installation of PRDs NCAC 13-13.0405: Try lever not installed.		
<b>REQUIREMENT:</b>	457. Replace the relief valve with one with a try lever. The replacement relief valve must be ASME/NB certified.		
<b>COMPANY:</b>	Hartford Steam Boiler		
<b>INSPECTOR:</b>	Rudolph, Jay		
<b>OPENED:</b>	01/19/2022	<b>ENTERED BY:</b>	Keyes, Amanda
<b>CLOSED:</b>		<b>CLOSED BY:</b>	
<b>TYPE:</b>	Certificate Blocking		
<b>CATEGORY:</b>	05-Operation of PRDs NCAC 13-13.0405		
<b>SUBCATEGORY</b>	475. Valve leaking.		
<b>CONDITION:</b>	475. Operation of PRDs NCAC 13-13.0405: Valve leaking.		
<b>REQUIREMENT:</b>	475. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.		

**Object:** NC197936 - PV - Gcdmc - 1964 - Dye Kier #6 Expansion Tank - Active

**Violations This Object:** 1

<b>COMPANY:</b>	Hartford Steam Boiler		
<b>INSPECTOR:</b>	Rudolph, Jay		
<b>OPENED:</b>	01/19/2022	<b>ENTERED BY:</b>	Keyes, Amanda
<b>CLOSED:</b>		<b>CLOSED BY:</b>	
<b>TYPE:</b>	Certificate Blocking		
<b>CATEGORY:</b>	05-Operation of PRDs NCAC 13-13.0405		
<b>SUBCATEGORY</b>	475. Valve leaking.		
<b>CONDITION:</b>	475. Operation of PRDs NCAC 13-13.0405: Valve leaking.		
<b>REQUIREMENT:</b>	475. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.		

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC197938 - PV - Gcdmc - 1964 - Dye Kier #5 Expansion Tank - **Violations This Object:** 2  
Active

---

<b>COMPANY:</b>	Hartford Steam Boiler		
<b>INSPECTOR:</b>	Rudolph, Jay		
<b>OPENED:</b>	01/19/2022	<b>ENTERED BY:</b>	Keyes, Amanda
<b>CLOSED:</b>		<b>CLOSED BY:</b>	
<b>TYPE:</b>	Certificate Blocking		
<b>CATEGORY:</b>	04-Installation of PRDs NCAC 13-13.0405		
<b>SUBCATEGORY</b>	457. Try lever not installed.		
<b>CONDITION:</b>	457. Installation of PRDs NCAC 13-13.0405: Try lever not installed.		
<b>REQUIREMENT:</b>	457. Replace the relief valve with one with a try lever. The replacement relief valve must be ASME/NB certified.		
<b>COMPANY:</b>	Hartford Steam Boiler		
<b>INSPECTOR:</b>	Rudolph, Jay		
<b>OPENED:</b>	01/19/2022	<b>ENTERED BY:</b>	Keyes, Amanda
<b>CLOSED:</b>		<b>CLOSED BY:</b>	
<b>TYPE:</b>	Certificate Blocking		
<b>CATEGORY:</b>	05-Operation of PRDs NCAC 13-13.0405		
<b>SUBCATEGORY</b>	475. Valve leaking.		
<b>CONDITION:</b>	475. Operation of PRDs NCAC 13-13.0405: Valve leaking.		
<b>REQUIREMENT:</b>	475. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.		

---

**Object:** NC197940 - PV - Gcdmc - 1964 - Dye Kier #3 Expansion Tank - **Violations This Object:** 1  
Active

---

<b>COMPANY:</b>	Hartford Steam Boiler		
<b>INSPECTOR:</b>	Rudolph, Jay		
<b>OPENED:</b>	01/19/2022	<b>ENTERED BY:</b>	Keyes, Amanda
<b>CLOSED:</b>		<b>CLOSED BY:</b>	
<b>TYPE:</b>	Certificate Blocking		
<b>CATEGORY:</b>	05-Operation of PRDs NCAC 13-13.0405		
<b>SUBCATEGORY</b>	475. Valve leaking.		
<b>CONDITION:</b>	475. Operation of PRDs NCAC 13-13.0405: Valve leaking.		
<b>REQUIREMENT:</b>	475. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.		

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC197942 - PV - Gcdmc - 1964 - Dye Kier #2 Expansion Tank - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 01/19/2022 **ENTERED BY:** Keyes, Amanda  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 04-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 457. Try lever not installed.  
**CONDITION:** 457. Installation of PRDs NCAC 13-13.0405: Try lever not installed.  
**REQUIREMENT:** 457. Replace the relief valve with one with a try lever. The replacement relief valve must be ASME/NB certified.

---

**Object:** NC197943 - PV - Gcdmc - 1964 - Dye Kier #2 - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 01/19/2022 **ENTERED BY:** Keyes, Amanda  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 04-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 457. Try lever not installed.  
**CONDITION:** 457. Installation of PRDs NCAC 13-13.0405: Try lever not installed.  
**REQUIREMENT:** 457. Replace the relief valve with one with a try lever. The replacement relief valve must be ASME/NB certified.

---

**Object:** NC197944 - PV - Gcdmc - 1964 - Dye Kier #1 Expansion Tank - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 01/19/2022 **ENTERED BY:** Keyes, Amanda  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 04-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 457. Try lever not installed.  
**CONDITION:** 457. Installation of PRDs NCAC 13-13.0405: Try lever not installed.  
**REQUIREMENT:** 457. Replace the relief valve with one with a try lever. The replacement relief valve must be ASME/NB certified.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC197946 - PV - Perry Products - 1970 - Dye Kier #4 Expansion Tank - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 01/19/2022 **ENTERED BY:** Keyes, Amanda  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 04-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 457. Try lever not installed.  
**CONDITION:** 457. Installation of PRDs NCAC 13-13.0405: Try lever not installed.  
**REQUIREMENT:** 457. Replace the relief valve with one with a try lever. The replacement relief valve must be ASME/NB certified.

---

**Object:** NC366617 - PV - Gcdmc - 1995 - Jet #20 - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 01/20/2022 **ENTERED BY:** Keyes, Amanda  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 02-Manufacturer's Data Report & Nameplate  
**SUBCATEGORY** 431. Nameplate stamping is incorrect, missing, or illegible.  
**CONDITION:** 431. Manufacturer's Data Report & Nameplate: Nameplate stamping is incorrect, missing, or illegible.  
**REQUIREMENT:** 431. Obtain a replacement nameplate from the manufacturer or a replacement in accordance with the National Board Inspection Code.

---

**Location:** Four Seasons Dry Cleaners & Laundry **Location #:** 1790815 **Violations:** 1  
7015 Market St, , Wilmington, NC 28411-9729, Phone: 910-297-0362  
**Contact:** Attn Alvaro Cervants, Owner, Four Seasons Dry Cleaners & Laundry, Phone: 910-297-0362

---

**Object:** NC263815 - Boiler - Fulton - 1995 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 01/25/2022 **ENTERED BY:** Keyes, Amanda  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 03-Water Gauge Glass NCAC 13-13.0408  
**SUBCATEGORY** 058. Leaking.  
**CONDITION:** 058. Water Gauge Glass NCAC 13-13.0408: Leaking.  
**REQUIREMENT:** 058. Repair or replace the leaking gauge and test to ensure proper operation.

---

**Location:** Friendly Avenue Baptist Church **Location #:** 1791256 **Violations:** 3  
4800 W Friendly Ave, , Greensboro, NC 27410-4333, Phone: 336-292-3567  
**Contact:** There is no contact information available for this location.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

**Object:** NC072262 - Boiler - Crane - 1964 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 01/05/2022  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 275. Tube/tube ends leak.  
**CONDITION:** 275. Boiler Components: Tube/tube ends leak.  
**REQUIREMENT:** 275. Repair the leaking tubes/tube ends. If weld repairs are required, a qualified "R" certificate holder is necessary to perform the work.

**ENTERED BY:** Judd, Janie  
**CLOSED BY:**

**Object:** NC130891 - Boiler - Peerless - 1974 - Blr Rm - Active

**Violations This Object:** 2

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 01/05/2022  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 12-Casing, Stack Breeching and Flue  
**SUBCATEGORY** 211. Combustion gas leaks.  
**CONDITION:** 211. Casing, Stack Breeching and Flue: Combustion gas leaks: Combustion gas leak at burner support plate on front of boiler.  
**REQUIREMENT:** 211. Repair all combustion gas leaks in the casing, stack breeching, or flue.

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 01/05/2022  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations: Boiler not operating could not test low water cutoff (LWCO) or pressure relief device (PRD) for proper operation.  
**REQUIREMENT:** 363. Undefined Boiler Violations: Schedule a reinspection at a time when the boiler is operating so that the LWCO and PRD may be tested to verify operation. As an alternative a detailed boiler log or service report that provides documentation of the successful testing of the LWCO and PRD is also acceptable.

**ENTERED BY:** Judd, Janie  
**CLOSED BY:**

**ENTERED BY:** Judd, Janie  
**CLOSED BY:**

**Location:** Harris Regional Hospital

**Location #:** 1795916

**Violations:** 1

68 Hospital Rd, , Sylva, NC 28779-2722, Phone: 828-586-7000

**Contact:** Attn Mark Huston, Maintenance Supervisor, Harris Regional Hospital, , Cell:828-768-2837

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC046098 - Boiler - Kewanee - 1958 - West Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 09/16/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 275. Tube/tube ends leak.  
**CONDITION:** 275. Boiler Components: Tube/tube ends leak.  
**REQUIREMENT:** 275. Repair the leaking tubes/tube ends. If weld repairs are required, a qualified "R" certificate holder is necessary to perform the work.

---

**Location:** Huffman Hosiery Mills **Location #:** 1799130 **Violations:** 1  
4919 Hickory Blvd, , Granite Falls, NC 28630-8390, Phone: 828-396-2031  
**Contact:** Huffman Hosiery Mills Inc, Phone: 828-396-2031

---

**Object:** NC216497 - Boiler - Cleaver Brooks - 1969 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Richey, Paul D.  
**OPENED:** 02/22/2022 **ENTERED BY:** Keyes, Amanda  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 270. Water Leaks.  
**CONDITION:** 270. Boiler Components: Water Leaks.  
**REQUIREMENT:** 270. Repair the water leaks identified on the inspection report.

---

**Location:** John Umstead Hospital **Location #:** 1802165 **Violations:** 1  
1003 12th St, , Butner, NC 27509-1626, Phone: 919-575-7536  
**Contact:** Attn Edd Lovette, John Umstead Hospital, Phone: 919-575-7971

---

**Object:** NC401217 - Boiler - Cleaver Brooks - 2014 - New Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** SORRENTINO, SEAN  
**OPENED:** 02/14/2022 **ENTERED BY:** Keyes, Amanda  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 275. Tube/tube ends leak.  
**CONDITION:** 275. Boiler Components: Tube/tube ends leak.  
**REQUIREMENT:** 275. Repair the leaking tubes/tube ends. If weld repairs are required, a qualified "R" certificate holder is necessary to perform the work.

---

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External  
Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status:  
Active; Order Results by: Location Name; Then Order by: Address;

---

**Location:** Kernodle Clinic **Location #:** 1803545 **Violations:** 2  
1234 Huffman Mill Rd, , Burlington, NC 27215-8700, Phone: 336-538-2367  
**Contact:** Attn Chris Kidd, Manager, Kernodle Clinic, Phone: 336-538-2367

**Object:** NC271884 - Boiler - Raypak - 1994 - 2nd Flr Mech Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 01/20/2022 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations. Boiler not operating at time of inspection; flow switch and pressure relief device (PRD) could not be tested to verify proper operation.  
**REQUIREMENT:** 363. Undefined Boiler Violations. Schedule a reinspection at a time when the boiler is operating so that the flow switch and PRD may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the controls is also acceptable.

**Object:** NC271885 - Boiler - Raypak - 1994 - 2nd Flr Mech Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 01/20/2022 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations. Boiler not operating at time of inspection; flow switch and pressure relief device (PRD) could not be tested to verify proper operation.  
**REQUIREMENT:** 363. Undefined Boiler Violations. Schedule a reinspection at a time when the boiler is operating so that the flow switch and PRD may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the controls is also acceptable.

---

**Location:** La Quinta Inn & Suites Charlotte Airport South **Location #:** 1804616 **Violations:** 1  
4900 S Tryon St, , Charlotte, NC 28217-2404, Phone: 704-523-5599  
**Contact:** Calvin Williams, Maintenance, La Quinta Inn & Suites Charlotte Airport South, Phone: 704-523-5599



# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

**Object:** NC283314 - Boiler - Weben Jarco - 1998 - 2nd Flr Equip Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Clay, Steven D.

**OPENED:** 11/05/2021

**ENTERED BY:** Putek, Terry

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409

**SUBCATEGORY** 009. Water level control inoperative or bypassed.

**CONDITION:** 009. LWCO and Flow Sensing Devices NCAC 13-13.0409: Water level control inoperative or bypassed. LWCO has a leak.

**REQUIREMENT:** 009. Repair or replace the inoperable water level control and test to ensure proper operation.

**Location:** Lake Jeanette Cleaners

**Location #:** 442517

**Violations:** 1

417 Pisgah Church Rd, , Greensboro, NC 27455-2590, Phone: 336-288-1250

**Contact:** Chun Yi, Owner, Lake Jeanette Cleaners, Phone: 336-288-1250

**Object:** NC279241 - Boiler - Fulton - 1996 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Leonard, Shannon D.

**OPENED:** 01/15/2022

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 23-Undefined Boiler Violations

**SUBCATEGORY** 363. Undefined Boiler Violations.

**CONDITION:** 363. Undefined Boiler Violations: Boiler overdue for required external operating inspection.

**REQUIREMENT:** 363. Undefined Boiler Violations: An external operating inspection of this boiler must be completed as soon as possible in order to address this condition.

**Location:** Maple Leaf Health Care

**Location #:** 877725

**Violations:** 2

2640 Davie Ave, , Statesville, NC 28625-8256, Phone: 704-871-0705

**Contact:** There is no contact information available for this location.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC268662 - Boiler - Raypak - 1994 - Outside Mech Rm - Active **Violations This Object:** 2

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 11/17/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 270. Water Leaks.  
**CONDITION:** 270. Boiler Components: Water Leaks: Flow switch leaking past protective baffles  
**REQUIREMENT:** 270. Replace the leaking flow switch. Once complete test to verify proper operation.

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 11/17/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 277. Other component leaking.  
**CONDITION:** 277. Boiler Components: Other component leaking: Leakage of unknown origin.  
**REQUIREMENT:** 277. Make repairs as necessary to stop this leakage should the heat exchanger require replacement, the replacement heat exchanger must be constructed to ASME Code standards and registered with the national board and have a proper national board number included on the ASME Data Plate.

---

**Location:** Mars Hill Baptist Church **Location #:** 1808332 **Violations:** 1  
67 N Main St, , Mars Hill, NC 28754-9503, Phone: 828-689-2911  
**Contact:** Sharon Welsch, Secretary, Mars Hill Baptist Church, Phone: 828-689-2911

---

**Object:** NC262845 - Boiler - Burnham - 1993 - Bsmt Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 09/15/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409  
**SUBCATEGORY** 002. Only one of two low water cutoff devices required installed.  
**CONDITION:** 002. LWCO and Flow Sensing Devices NCAC 13-13.0409: Only one of two low water cutoff devices required installed.  
**REQUIREMENT:** 002. Install a second low-water fuel cutoff device (LWCO) designed for the appropriate service (Steam or Hot Water) that is equipped with a manual reset. When the LWCO shuts off the fuel supply to the boiler in the event of a low water condition, the fuel supply must be restarted manually by an operator. Test to ensure proper operation.

---

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Location:** Medicago USA **Location #:** 3005097 **Violations:** 1  
7 Triangle Dr, , Durham, NC 27709-0005, Phone: 919-313-9670

**Contact:** Attn Tatyana Blankenship, Director, Medicago USA Inc, Phone: 919-313-9670

**Object:** NC387341 - Boiler - Raypak - 2011 - Roof Terrace - Active **Violations This Object:** 1

---

<b>COMPANY:</b>	Hartford Steam Boiler	
<b>INSPECTOR:</b>	Richey, Paul D.	
<b>OPENED:</b>	02/08/2022	<b>ENTERED BY:</b> Keyes, Amanda
<b>CLOSED:</b>		<b>CLOSED BY:</b>
<b>TYPE:</b>	Certificate Blocking	
<b>CATEGORY:</b>	16-Boiler Components	
<b>SUBCATEGORY</b>	270. Water Leaks.	
<b>CONDITION:</b>	270. Boiler Components: Water Leaks.	
<b>REQUIREMENT:</b>	270. Repair the water leaks identified on the inspection report.	

---

**Location:** Mid Pines Inn & Country Club **Location #:** 480363 **Violations:** 1  
1010 Midland Rd, , Southern Pines, NC 28387-3122, Phone: 910-692-2114

**Contact:** Henry Hogan, Mid Pines Inn & Country Club, Phone: 910-693-7279

**Object:** NC376853 - Boiler - Hurst - 2005 - Blr Rm - Active **Violations This Object:** 1

---

<b>COMPANY:</b>	Hartford Steam Boiler	
<b>INSPECTOR:</b>	Rudolph, Jay	
<b>OPENED:</b>	02/16/2022	<b>ENTERED BY:</b> Keyes, Amanda
<b>CLOSED:</b>		<b>CLOSED BY:</b>
<b>TYPE:</b>	Certificate Blocking	
<b>CATEGORY:</b>	25-Operation of PRDs NCAC 13-13.0405	
<b>SUBCATEGORY</b>	395. Valve leaking.	
<b>CONDITION:</b>	395. Operation of PRDs NCAC 13-13.0405: Valve leaking.	
<b>REQUIREMENT:</b>	395. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.	

---

**Location:** Modern Polymers **Location #:** 1811239 **Violations:** 2  
875 W Academy St, , Cherryville, NC 28021-3143, Phone: 704-435-5825

**Contact:** Modern Polymers Inc, Phone: 704-435-5825

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC290533 - Boiler - Superior Boiler Works - 2000 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 01/05/2022 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 26-Undefined Pressure Relieving Devices Violations  
**SUBCATEGORY** 399. Undefined Pressure Relieving Devices Violations.  
**CONDITION:** 399. Undefined Pressure Relieving Devices Violations. Safety valves could not be tested during the inspection visit. No logs of previous testing.  
**REQUIREMENT:** 399. Undefined Pressure Relieving Devices Violations. Schedule a follow up inspection for a day and time when the safety valves can be tested or test the safety valves and document test in boiler log.

---

**Object:** NC408026 - Boiler - Cleaver Brooks - 2016 - Blr Rm Plt Rear - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 01/05/2022 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 26-Undefined Pressure Relieving Devices Violations  
**SUBCATEGORY** 399. Undefined Pressure Relieving Devices Violations.  
**CONDITION:** 399. Undefined Pressure Relieving Devices Violations. Safety valves could not be tested during the inspection visit. No logs of previous testing.  
**REQUIREMENT:** 399. Undefined Pressure Relieving Devices Violations. Schedule a follow up inspection for a day and time when the safety valves can be tested or test the safety valves and document test in boiler log.

---

**Location:** Murdoch Center **Location #:** 1812698 **Violations:** 1  
1600 E C St, , Butner, NC 27509-2530, Phone: 919-575-1181  
**Contact:** Attn Gwynn Long, Supervisor, DHHS Murdoch Center, Phone: 919-575-1181

---

**Object:** NC149064 - PV - Legion Industries - 1956 - Main Kitchen - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Richey, Paul D.  
**OPENED:** 02/09/2022 **ENTERED BY:** Keyes, Amanda  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 06-Undefined Pressure Relieving Devices Violations  
**SUBCATEGORY** 478. Undefined Pressure Relieving Devices Violations.  
**CONDITION:** 478. No steam to this object which makes it impossible to test PRD  
**REQUIREMENT:** 478. Restore steam to this kettle and test PRD or properly disconnect this object.

---

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External  
Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status:  
Active; Order Results by: Location Name; Then Order by: Address;

---

**Location:** National Guard Armory **Location #:** 1813530 **Violations:** 2  
201 W 9th Ave, , Lexington, NC 27292-3113, Phone: 336-248-2798  
**Contact:** Attn Blane Boyd, Director of Facility Maintenance, NGA Facilities Maintenance, Phone: 984-664-6094

**Object:** NC385597 - Boiler - Lochinvar - 2011 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 02/24/2022 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations. Boiler not operating at time of inspection; pressure relief device (PRD) and flow switch could not be tested to verify proper operation.  
**REQUIREMENT:** 363. Undefined Boiler Violations. Schedule a reinspection at a time when the boiler is operating so that the PRD and flow switch may be tested to verify proper operation. As an alternative a detailed service report or boiler log that includes documentation of the successful testing of this devices is also acceptable.

**Object:** NC385598 - Boiler - Lochinvar - 2011 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 02/24/2022 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations: Boiler not operating at time of inspection; pressure relief device (PRD) and flow switch could not be tested to verify proper operation.  
**REQUIREMENT:** 363. Undefined Boiler Violations: Schedule a reinspection at a time when the boiler is operating so that the PRD and flow switch may be tested to verify proper operation. As an alternative a detailed service report or boiler log that includes documentation of the successful testing of this devices is also acceptable.

---

**Location:** National Guard Armory **Location #:** 1813514 **Violations:** 1  
700 Charles St, , Monroe, NC 28112-5725, Phone: 704-283-5512  
**Contact:** National Guard Armory, Phone: 704-2835512

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC374095 - Boiler - Weil-McLain - 2008 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Clay, Steven D.

**OPENED:** 09/13/2021

**ENTERED BY:** Putek, Terry

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 05-Temperature Controls NCAC 13-13.0406

**SUBCATEGORY** 093. High limit temperature control inoperative.

**CONDITION:** 093. Temperature Controls NCAC 13-13.0406: High limit temperature control inoperative.

**REQUIREMENT:** 093. Repair or replace the inoperative high limit temperature control. Test to ensure proper operation.

---

**Location:** National Guard Armory

**Location #:** 1813555

**Violations:** 1

890 Withrow Rd, , Forest City, NC 28043-9697, Phone: 828-287-0669

**Contact:** Attn Blane Boyd, Director of Facility Maintenance, NGA Facilities Maintenance, Phone: 984-664-6094

---

**Object:** NC279743 - Boiler - Weil-McLain - 1996 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Possidente, James

**OPENED:** 01/11/2022

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405

**SUBCATEGORY** 395. Valve leaking.

**CONDITION:** 395. Operation of PRDs NCAC 13-13.0405: Valve leaking.

**REQUIREMENT:** 395. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

---

**Location:** NC School Of Science & Mathematics

**Location #:** 1813129

**Violations:** 1

1219 Broad St, , Durham, NC 27705-3577, Phone: 919-416-2672

**Contact:** NC School Of Science & Mathematics, Phone: 919-416-2793

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC212851 - Boiler - Kewanee - 1984 - Main Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** SORRENTINO, SEAN  
**OPENED:** 02/09/2022 **ENTERED BY:** Keyes, Amanda  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 395. Valve leaking.  
**CONDITION:** 395. Operation of PRDs NCAC 13-13.0405: Valve leaking.  
**REQUIREMENT:** 395. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

---

**Location:** NC Wesleyan College **Location #:** 1813234 **Violations:** 1  
3400 N Wesleyan Blvd, , Rocky Mount, NC 27804-8699, Phone: 252-985-5222  
**Contact:** Renee Bradley, Facility Administrator, NC Wesleyan College, Phone: 252-985-5574

---

**Object:** NC206070 - Boiler - Weil-McLain - 1982 - Nash Hall Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** SORRENTINO, SEAN  
**OPENED:** 02/03/2022 **ENTERED BY:** Keyes, Amanda  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 24-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 377. Try lever not installed.  
**CONDITION:** 377. Installation of PRDs NCAC 13-13.0405: Try lever not installed.  
**REQUIREMENT:** 377. Replace the relief valve with one with a try lever. The replacement valve must be ASME/NB certified.

---

**Location:** New Hangers Cleaners **Location #:** 1768002 **Violations:** 1  
1002 Alamance Church Rd, , Greensboro, NC 27406-3808, Phone: 336-272-8879  
**Contact:** Attn Jason Chi, New Hangers Cleaners, Phone: 336-272-8879, Cell:336-423-9133



# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC422358 - Boiler - Parker - 2017 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Leonard, Shannon D.

**OPENED:** 02/03/2022

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405

**SUBCATEGORY** 395. Valve leaking.

**CONDITION:** 395. Operation of PRDs NCAC 13-13.0405: Valve leaking.

**REQUIREMENT:** 395. Replace the leaking PRD with an ASME/NB stamped PRD having a set pressure of 125 PSI or less and a relieving capacity of 518 pounds of steam per hour or more. The replacement PRD must be mounted directly on the boiler in a vertical position and equipped with a try-lever. The inlet and the outlet piping for the PRD must also be piped full size and not reduced.

---

**Location:** Professional Rental Services

**Location #:** 1821288

**Violations:** 1

220 Frederick St, , Mount Airy, NC 27030-5602, Phone: 336-786-6148

**Contact:** Attn Mark Wilson, Maintenance, Professional Rental Services, Phone: 336-786-6148, Cell:336-755-7699

---

**Object:** NC345478 - Boiler - Hurst - 2002 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Leonard, Shannon D.

**OPENED:** 02/11/2022

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409

**SUBCATEGORY** 020. Leaking gasket or joints.

**CONDITION:** 020. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff (LWCO) gasket leaking on float basin

**REQUIREMENT:** 020. Replace the leaking LWCO float basin gasket in order to correct this condition.

---

**Location:** Quality Cleaners

**Location #:** 1821770

**Violations:** 1

52 Glen Rd Ste 106, , Garner, NC 27529-7972, Phone: 919-661-0437

**Contact:** Attn Seppi Sepahrom, Owner, Quality Cleaners, Phone: 919-661-0437

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC433613 - Boiler - Fulton - 2021 - BOILER 1 - Active

**Violations This Object:** 1

**COMPANY:** State of North Carolina

**INSPECTOR:** Kirkland, John

**OPENED:** 01/07/2022

**ENTERED BY:** Kirkland, John

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 13-Burners and Fuel Supply Systems

**SUBCATEGORY** 235. No emergency fuel shut off switch.

**CONDITION:** 235. Burners and Fuel Supply Systems: No emergency fuel shut off switch.

**REQUIREMENT:** 235. Install an emergency fuel shut off switch at each egress from the boiler room to shut off all fuel to the boilers. Once the ESTOP has been installed, contact John Kirkland @ 252-204-7789 for a follow-up inspection.

---

**Location:** Quality Used Parts & Sales & Service

**Location #:** 1807281

**Violations:** 1

5707 US Highway 264 W, , Washington, NC 27889-7692, Phone: 252-946-6495

**Contact:** There is no contact information available for this location.

---

**Object:** NC294692 - PV - Manchester - 1998 - Comp Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Rudolph, Jay

**OPENED:** 02/08/2022

**ENTERED BY:** Keyes, Amanda

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 09-Pressure Gauges NCAC 13-13.0407

**SUBCATEGORY** 030. Pressure gauge not installed.

**CONDITION:** 030. Pressure Gauges NCAC 13-13.0407: Pressure gauge not installed.

**REQUIREMENT:** 030. Install a pressure gauge on the equipment that is visible to the operator from the floor or work platform. Gauge must be the proper range in accordance with NC Administrative Code, Title 13, Chapter 13, Section .0407.

---

**Location:** Quality Veneer Co

**Location #:** 1822013

**Violations:** 1

237 E Teague Ave, , Liberty, NC 27298-0010, Phone: 336-622-2211

**Contact:** J Ritch Jr, Owner, Quality Veneer Co Inc, Phone: 336-622-2211, Cell:336-508-9975

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

**Object:** NC006178 - Boiler - ECIW - 1920 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Leonard, Shannon D.

**OPENED:** 02/03/2022

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 23-Undefined Boiler Violations

**SUBCATEGORY** 363. Undefined Boiler Violations.

**CONDITION:** 363. Undefined Boiler Violations: Boiler overdue for required internal certificate inspection.

**REQUIREMENT:** 363. Undefined Boiler Violations: Schedule an internal inspection of this boiler as soon as possible in order to address this issue.

**Location:** River Landing At Sandy Ridge

**Location #:** 1824609

**Violations:** 3

1575 John Knox Dr, , Colfax, NC 27235-9662, Phone: 336-668-4900

**Contact:** Eddie Hedrick, Manager, River Landing At Sandy Ridge, Phone: 336-668-4900

**Object:** NC311181 - Boiler - PVI Industries - 2001 - Main Mech Rm M26 - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Leonard, Shannon D.

**OPENED:** 02/14/2022

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 16-Boiler Components

**SUBCATEGORY** 275. Tube/tube ends leak.

**CONDITION:** 275. Boiler Components: Tube/tube ends leak: Possible tube leak front tube sheet of boiler.

**REQUIREMENT:** 275. Repair the leaking tubes/tube ends. If weld repairs are required, a qualified "R" certificate holder is necessary to perform the work.

**Object:** NC367358 - Boiler - Lochinvar - 2007 - Mech Rm A 309 - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Leonard, Shannon D.

**OPENED:** 02/14/2022

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409

**SUBCATEGORY** 020. Leaking gasket or joints.

**CONDITION:** 020. LWCO and Flow Sensing Devices NCAC 13-13.0409: Leaking gasket or joints: Flow switch leaking.

**REQUIREMENT:** 020. Replace the leaking flow switch in order to correct this issue.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC367359 - Boiler - Lochinvar - 2007 - Mech Rm A 309 - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 02/14/2022 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409  
**SUBCATEGORY** 020. Leaking gasket or joints.  
**CONDITION:** 020. LWCO and Flow Sensing Devices NCAC 13-13.0409: Leaking gasket or joints:  
Flow switch leaking  
**REQUIREMENT:** 020. Replace the leaking flow switch in order to correct this issue.

---

**Location:** Salem Business Park **Location #:** 1223044 **Violations:** 1  
3300 Old Lexington Rd, , Winston Salem, NC 27107-4119, Phone: 336-414-9060  
**Contact:** Gary Marshall, Manager, Salem Business Park Llc, Phone: 336-414-9060

---

**Object:** NC416446 - PV - Gcdmc - 1986 - Bldg 30 Dye - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 02/01/2022 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 04-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 457. Try lever not installed.  
**CONDITION:** 457. Installation of PRDs NCAC 13-13.0405: Try lever not installed.  
**REQUIREMENT:** 457. Replace the current PRD with an ASME/NB stamped PRD having a set pressure of 150 PSI or less and a relieving capacity sufficient to fully relieve pressure on this pressure vessel. The replacement PRD inlet and outlet must be piped full size and not reduced in any way, and the PRD must be equipped with a functioning try-lever.

---

**Location:** Southern Resin **Location #:** 1831002 **Violations:** 1  
3440 Denton Rd, , Thomasville, NC 27360-6168, Phone: 336-475-1348  
**Contact:** Attn Bill Hill, Manager, Southern Resin Inc, Phone: 336-475-1348

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC402005 - Boiler - Superior Boiler Works - 1995 - Polymer Plt - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 01/07/2022 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 395. Valve leaking.  
**CONDITION:** 395. Operation of PRDs NCAC 13-13.0405: Valve leaking: Both pressure relief device (PRD) leaking.  
**REQUIREMENT:** 395. Replace the leaking PRD's with ASME/NB stamped PRD's having set pressures of 150 PSI or less and a combined total relieving capacity of 4312 pounds of steam per hour or more.

---

**Location:** UFP Salisbury LLC **Location #:** 2158141 **Violations:** 1  
2815 Woodtech Dr, , Newton, NC 28658-8967, Phone: 704-855-1600  
**Contact:** Attn Roger Wooten, PalletOne Inc, Phone: 888-576-6618 X311

---

**Object:** NC367821 - PV - Silvan - 2007 - SE Corner Bldg 3 - Active **Violations This Object:** 1

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Hutchens, Mark  
**OPENED:** 02/23/2022 **ENTERED BY:** Hutchens, Mark  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 04-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 450. Pressure relieving devices not installed.  
**CONDITION:** 450. Installation of PRDs NCAC 13-13.0405: Pressure relieving devices not installed.  
**REQUIREMENT:** 450. Install a pressure relieving device in accordance with NCAC 13-13.0405.

---

**Violations This Report:** 104

**Locations This Report:** 68