

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Location: (ASV CS) Central Office **Location #:** 1775429 **Violations:** 2
85 Mountain St, , Asheville, NC 28801-3854, Phone: 828-350-7000
Contact: Tim Holcombe, Manager, Asheville City Schools, Phone: 828-350-7000/Maint 828-350-6196

Object: NC205160 - Boiler - Weil-McLain - 1982 - Blr Rm - Active **Violations This Object:** 2

COMPANY:	State of North Carolina	
INSPECTOR:	(By Request), the Owner/User	
OPENED:	01/13/2021	ENTERED BY: Putek, Terry
CLOSED:		CLOSED BY:
TYPE:	Certificate Blocking	
CATEGORY:	01-LWCO and Flow Sensing Devices NCAC 13-13.0409	
SUBCATEGORY	005. No provision to test low water cutoff device.	
CONDITION:	005. LWCO and Flow Sensing Devices NCAC 13-13.0409: No provision to test low water cutoff device.	
REQUIREMENT:	005. Equip the low water fuel cutoff device on the boiler with a vertical drain and blow-off valve assembly of not less than 3/4-inch nominal pipe size to allow for flushing and testing of the low water cutoff while the boiler is in operation.	
COMPANY:	State of North Carolina	
INSPECTOR:	(By Request), the Owner/User	
OPENED:	01/13/2021	ENTERED BY: Putek, Terry
CLOSED:		CLOSED BY:
TYPE:	Certificate Blocking	
CATEGORY:	24-Installation of PRDs NCAC 13-13.0405	
SUBCATEGORY	372. Set pressure too high.	
CONDITION:	372. Installation of PRDs NCAC 13-13.0405: Set pressure too high. Mawp is 50 psi and SV #1 is 75 psi.	
REQUIREMENT:	372. Replace the pressure relieving device with one with a set pressure no higher than the maximum allowable working pressure as determined by the manufacturer.	

Location: (ASV CS) Claxton Elem **Location #:** 1777561 **Violations:** 3
241 Merrimon Ave, , Asheville, NC 28801-1217, Phone: 828-350-6500
Contact: Tim Holcombe, Manager, Asheville City Schools, Phone: 828-350-7000/Maint 828-350-6196

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC262601 - Boiler - Weil-McLain - 1993 - Bsmt - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Possidente, James

OPENED: 01/13/2021

ENTERED BY: Putek, Terry

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409

SUBCATEGORY 005. No provision to test low water cutoff device.

CONDITION: 005. LWCO and Flow Sensing Devices NCAC 13-13.0409: No provision to test low water cutoff device.

REQUIREMENT: 005. Equip the low water fuel cutoff device on the boiler with a vertical drain and blow-off valve assembly of not less than 3/4-inch nominal pipe size to allow for flushing and testing of the low water cutoff while the boiler is in operation.

Object: NC262602 - Boiler - Weil-McLain - 1993 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Possidente, James

OPENED: 01/13/2021

ENTERED BY: Putek, Terry

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409

SUBCATEGORY 005. No provision to test low water cutoff device.

CONDITION: 005. LWCO and Flow Sensing Devices NCAC 13-13.0409: No provision to test low water cutoff device.

REQUIREMENT: 005. Equip the low water fuel cutoff device on the boiler with a vertical drain and blow-off valve assembly of not less than 3/4-inch nominal pipe size to allow for flushing and testing of the low water cutoff while the boiler is in operation.

Object: NC388477 - PV - Lochinvar - 2006 - Cafeteria Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Possidente, James

OPENED: 01/13/2021

ENTERED BY: Putek, Terry

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 04-Installation of PRDs NCAC 13-13.0405

SUBCATEGORY 461. Incorrect pressure relieving device(s) for the application.

CONDITION: 461. Installation of PRDs NCAC 13-13.0405: Incorrect pressure relieving device(s) for the application. The current valve is pressure only mounted horizontal.

REQUIREMENT: 461. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

Location: (ASV CS) Ira B Jones Elem

Location #: 1800336

Violations: 1

544 Kimberly Ave, , Asheville, NC 28804-2560, Phone: 828-350-6700

Contact: Tim Holcombe, Manager, Asheville City Schools, Phone: 828-350-7000/Maint 828-350-6196

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC288783 - Boiler - Weil-McLain - 1996 - New Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Possidente, James
OPENED: 01/12/2021 **ENTERED BY:** Putek, Terry
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409
SUBCATEGORY 005. No provision to test low water cutoff device.
CONDITION: 005. LWCO and Flow Sensing Devices NCAC 13-13.0409: No provision to test low water cutoff device.
REQUIREMENT: 005. Equip the low water fuel cutoff device on the boiler with a vertical drain and blow-off valve assembly of not less than 3/4-inch nominal pipe size to allow for flushing and testing of the low water cutoff while the boiler is in operation. Recommend installing probe type LWCO with test and reset button to allow testing the device.

Location: (ASV CS) Vance Elem **Location #:** 1839986 **Violations:** 1
98 Sulphur Springs Rd, , Asheville, NC 28806-2646, Phone: 828-250-6600
Contact: Tim Holcombe, Manager, Asheville City Schools, Phone: 828-350-7000/Maint 828-350-6196

Object: NC221780 - Boiler - Weil-McLain - 1986 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Possidente, James
OPENED: 01/13/2021 **ENTERED BY:** Putek, Terry
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409
SUBCATEGORY 005. No provision to test low water cutoff device.
CONDITION: 005. LWCO and Flow Sensing Devices NCAC 13-13.0409: No provision to test low water cutoff device.
REQUIREMENT: 005. Equip the low water fuel cutoff device on the boiler with a vertical drain and blow-off valve assembly of not less than 3/4-inch nominal pipe size to allow for flushing and testing of the low water cutoff while the boiler is in operation.

Location: (DPS-C) Columbus CI - 4355 **Location #:** 1778917 **Violations:** 2
1255 Prison Camp Rd, , Whiteville, NC 28472-4887, Phone: 910-642-3285
Contact: NC Dept Of Public Safety - 13101, Phone: 919-716-3422

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC382455 - Boiler - Cleveland Range - 2010 - Food Service - Active

Violations This Object: 2

COMPANY:	Hartford Steam Boiler		
INSPECTOR:	Rudolph, Jay		
OPENED:	11/24/2020	ENTERED BY:	Judd, Janie
CLOSED:		CLOSED BY:	
TYPE:	Certificate Blocking		
CATEGORY:	03-Water Gauge Glass NCAC 13-13.0408		
SUBCATEGORY	058. Leaking.		
CONDITION:	058. Water Gauge Glass NCAC 13-13.0408: Leaking.		
REQUIREMENT:	058. Repair or replace the leaking gauge and test to ensure proper operation.		
COMPANY:	Hartford Steam Boiler		
INSPECTOR:	Rudolph, Jay		
OPENED:	11/24/2020	ENTERED BY:	Judd, Janie
CLOSED:		CLOSED BY:	
TYPE:	Certificate Blocking		
CATEGORY:	25-Operation of PRDs NCAC 13-13.0405		
SUBCATEGORY	395. Valve leaking.		
CONDITION:	395. Operation of PRDs NCAC 13-13.0405: Valve leaking: Pressure relief device leaking.		
REQUIREMENT:	395. Replace with a ASME/NB certified pressure relief device with a set pressure of not greater than 15 psig, with a relief capacity of not less than 266 PPH, and with a testing lever installed.		

Location: (DPS-C) Harnett CI - 3805

Location #: 1795798

Violations: 1

1210 E McNeill St , Lillington, NC 27546-9184, Phone: 910-893-2751

Contact: Allen Tart, Maintenance Supervisor, Harnett CI - 3805, Phone: 910-893-2751

Object: NC430235 - PV - Lochinvar - 2016 - Kitchen Mech Rm - Active

Violations This Object: 1

COMPANY:	State of North Carolina		
INSPECTOR:	Fish, Emily		
OPENED:	03/16/2021	ENTERED BY:	Fish, Emily
CLOSED:		CLOSED BY:	
TYPE:	Certificate Blocking		
CATEGORY:	10-Thermometer NCAC 13-13.0410		
SUBCATEGORY	111. Thermometer inoperative.		
CONDITION:	111. Thermometer NCAC 13-13.0410: Thermometer inoperative.		
REQUIREMENT:	111. Replace inoperative thermometer at/in the vessel outlet to measure the temperature in degrees Fahrenheit of the water. The thermometer shall have a range of approximately 2 times the intended operating temperature but not less than 1 1/2 times the intended operating temperature, nor more than 4 times the intended operating temperature.		

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External
Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status:
Active; Order Results by: Location Name; Then Order by: Address;

Location: (DPS-C) NCCIW - 3010 **Location #:** 1779964 **Violations:** 2
1034 Bragg St, , Raleigh, NC 27610-3846, Phone: 919-733-4340
Contact: Phillip Jones, Maintenance Supervisor, NCCIW - 3010, Phone: 919-508-1690

Object: NC381483 - Boiler - PVI Industries - 2010 - Falcom Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: SORRENTINO, SEAN
OPENED: 12/08/2020 **ENTERED BY:** Keyes, Amanda
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 16-Boiler Components
SUBCATEGORY 270. Water Leaks.
CONDITION: 270. Boiler Components: Water Leaks.
REQUIREMENT: 270. Repair the water leaks identified on the inspection report. If welding is required, a qualified "R" certificate holder is necessary to perform the repair.

Object: NC401596 - Boiler - PVI Industries - 2014 - Sparrow N - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: SORRENTINO, SEAN
OPENED: 12/08/2020 **ENTERED BY:** Keyes, Amanda
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 16-Boiler Components
SUBCATEGORY 270. Water Leaks.
CONDITION: 270. Boiler Components: Water Leaks. Tank leaking at unknown location.
REQUIREMENT: 270. Repair the water leaks identified on the inspection report. If welding is required, a qualified "R" certificate holder is necessary to perform the repair.

Location: (LEE) O T Sloan Park **Location #:** 1815639 **Violations:** 2
1420 Bragg St, , Sanford, NC 27330-5435, Phone: 919-775-2107
Contact: Attn Russell Spivey, Lee County Government General Services, Phone: 919-718-4622

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC419417 - Boiler - Teledyne Laars - 2017 - Outside pool house - **Violations This Object:** 1
Active

COMPANY: State of North Carolina
INSPECTOR: Gunto III, Andrew
OPENED: 10/20/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations.
At the time of the 10/20/2020 inspection, this boiler was not in operation.
REQUIREMENT: 363. Undefined Boiler Violations.
At follow up inspection the boiler must be firing, and an operational demonstration will be need. This includes the verification of the high-limit temperature controls and its manual reset.

ENTERED BY: Gunto III, Andrew
CLOSED BY:

Object: NC419418 - Boiler - Teledyne Laars - 2017 - Outside pool house - **Violations This Object:** 1
Active

COMPANY: State of North Carolina
INSPECTOR: Gunto III, Andrew
OPENED: 10/20/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations.
At the time of the 10/20/2020 inspection, this boiler was not in operation.
REQUIREMENT: 363. Undefined Boiler Violations.
At follow up inspection the boiler must be firing, and an operational demonstration will be need. This includes the verification of the high-limit temperature controls and its manual reset.

ENTERED BY: Gunto III, Andrew
CLOSED BY:

Location: (MH UNIV) Brown Hall
150 Joe Anderson Dr, , Mars Hill, NC 28754-0370, Phone: 828-689-1201
Contact: Attn Henry H Haywood, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:828-206-

Location #: 1930569
Violations: 3

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC338996 - PV - LTC - 2002 - Bsmt Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Possidente, James
OPENED: 03/12/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 02-Manufacturer's Data Report & Nameplate
SUBCATEGORY 431. Nameplate stamping is incorrect, missing, or illegible.
CONDITION: 431. Manufacturer's Data Report & Nameplate: Nameplate stamping is incorrect, missing, or illegible. Dataplate could not be located.
REQUIREMENT: 431. Obtain a replacement nameplate from the manufacturer or a replacement in accordance with the National Board Inspection Code. Locate nameplate and make visible for inspection.

ENTERED BY: Putek, Terry

CLOSED BY:

Object: NC338997 - Boiler - Lochinvar - 2002 - Bsmt Blr Rm - Active

Violations This Object: 2

COMPANY: Hartford Steam Boiler
INSPECTOR: Possidente, James
OPENED: 03/12/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 08-Main Steam System NCAC 13-13.0411
SUBCATEGORY 126. Leaking pipe/pipe joints.
CONDITION: 126. Main Steam System NCAC 13-13.0411: Leaking pipe/pipe joints.
REQUIREMENT: 126. Repair or tighten leaking pipe/pipe joints.

ENTERED BY: Putek, Terry

CLOSED BY:

COMPANY: Hartford Steam Boiler
INSPECTOR: Possidente, James
OPENED: 03/12/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 12-Casing, Stack Breeching and Flue
SUBCATEGORY 214. Excessive corrosion.
CONDITION: 214. Casing, Stack Breeching and Flue: Excessive stack corrosion.
REQUIREMENT: 214. Repair or replace the casing, stack breeching or flue.

ENTERED BY: Putek, Terry

CLOSED BY:

Location: (MH UNIV) Gibson Hall

Location #: 1930563

Violations: 1

100 Joe Anderson Dr, , Mars Hill, NC 28754-0370, Phone: 828-689-1201

Contact: Attn Henry H Haywood, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:828-206-

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC099075 - Boiler - Weil-McLain - 1969 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Possidente, James

OPENED: 03/12/2021

ENTERED BY: Putek, Terry

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 25-Operation of PRDs NCAC 13-13.0405

SUBCATEGORY 395. Valve leaking.

CONDITION: 395. Operation of PRDs NCAC 13-13.0405: Valve leaking.

REQUIREMENT: 395. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

Location: (MH UNIV) Huffman Hall

Location #: 1930543

Violations: 1

130 Womens Hill Dr, , Mars Hill, NC 28754-0370, Phone: 828-689-1201

Contact: Attn Henry H Haywood, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:828-206-

Object: NC403705 - PV - LTC - 2015 - Rm B11 - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Possidente, James

OPENED: 02/23/2021

ENTERED BY: Putek, Terry

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 07-Undefined Pressure Vessels Violations

SUBCATEGORY 479. Undefined Pressure Vessels Violations.

CONDITION: 479. Undefined Pressure Vessels Violations. Pipe leaking.

REQUIREMENT: 479. Undefined Pressure Vessels Violations. Repair or replace leaking piping/pipe joints.

Location: (MH UNIV) McConnell Hall

Location #: 1930553

Violations: 1

54 College St, , Mars Hill, NC 28754-0370, Phone: 828-689-1201

Contact: Attn Henry H Haywood, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:828-206-

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External
Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status:
Active; Order Results by: Location Name; Then Order by: Address;

Object: NC270792 - Boiler - Weil-McLain - 1994 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Possidente, James

OPENED: 02/23/2021

ENTERED BY: Putek, Terry

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409

SUBCATEGORY 006. Low water cutoff device inoperative or bypassed.

CONDITION: 006. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device inoperative or bypassed.

REQUIREMENT: 006. Repair or replace the inoperable low water fuel cutoff control and test to ensure proper operation.

Location: (MH UNIV) Pittman Dining Hall

Location #: 1930566

Violations: 1

121 Cascade St, , Mars Hill, NC 28754-9135, Phone: 828-689-1201

Contact: Attn Henry H Haywood, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:828-206-

Object: NC262680 - Boiler - Peerless - 1993 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Possidente, James

OPENED: 03/12/2021

ENTERED BY: Putek, Terry

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 12-Casing, Stack Breeching and Flue

SUBCATEGORY 211. Combustion gas leaks.

CONDITION: 211. Casing, Stack Breeching and Flue: Combustion gas leaks.

REQUIREMENT: 211. Repair all combustion gas leaks in the casing, stack breeching, or flue.

Location: (MH UNIV) Stroup Hall

Location #: 1930538

Violations: 2

141 Womens Hill Dr, , Mars Hill, NC 28754-0370, Phone: 828-689-1201

Contact: Attn Henry H Haywood, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:828-206-

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC323874 - Boiler - Teledyne Laars - 2000 - Bsmt - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Possidente, James
OPENED: 02/23/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409
SUBCATEGORY 012. Flow switch inoperative or bypassed.
CONDITION: 012. LWCO and Flow Sensing Devices NCAC 13-13.0409: Flow switch inoperative or bypassed. (Leaking)
REQUIREMENT: 012. Install a flow switch that will shut off the fuel supply in case of stoppage of water flow or a low-water condition and test to ensure proper operation.

ENTERED BY: Putek, Terry

CLOSED BY:

Object: NC325457 - Boiler - Peerless - 2000 - Bsmt - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Possidente, James
OPENED: 02/23/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409
SUBCATEGORY 006. Low water cutoff device inoperative or bypassed.
CONDITION: 006. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device inoperative or bypassed. Primary LWCO inoperative.
REQUIREMENT: 006. Repair or replace the inoperable low water fuel cutoff control and test to ensure proper operation.

ENTERED BY: Putek, Terry

CLOSED BY:

Location: (MITCHELL CC) Campus Physical Plt

Location #: 1762133

Violations: 1

500 W Broad St, , Statesville, NC 28677-5264, Phone: 704-878-3200

Contact: Attn Chad Lackey, Director Safety & Security, Mitchell Community College,

Object: NC283176 - Boiler - Weil-McLain - 1997 - Mech Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Richey, Paul D.
OPENED: 03/17/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 25-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 395. Valve leaking.
CONDITION: 395. Operation of PRDs NCAC 13-13.0405: Valve leaking. PRD leaking past disc and seat.
REQUIREMENT: 395. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

ENTERED BY: Putek, Terry

CLOSED BY:

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Location: (NCCU) Heating Plant

Location #: 1796457

Violations: 1

1801 Fayetteville St, , Durham, NC 27707-3129, Phone: 919-530-6313

Contact: Attn Lori Blake Reid PO #P107428, NC Central University Shephard Station, Phone: 919-530-7244

Object: NC293050 - Boiler - Babcock & Wilcox - 1998 - Blr House Blr 1 - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: SORRENTINO, SEAN

OPENED: 11/18/2020

ENTERED BY: Keyes, Amanda

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. The boiler was not operating during this inspection per Sean Sorrentino inspection report.

REQUIREMENT: 363. You must operate this boiler for external inspection per Sean Sorrentino inspection report.

Location: (NCDOA) Museum Of Art

Location #: 1813946

Violations: 2

2110 Blue Ridge Rd, , Raleigh, NC 27607-6433, Phone: 919-839-6262

Contact: Chris Carter, Plant Maint Supervisor, Museum Of Art, Phone: 919-839-6262

Object: NC375706 - Boiler - Fulton - 2008 - New Blr Rm - Active

Violations This Object: 1

COMPANY: State of North Carolina

INSPECTOR: Smith, Jeremy

OPENED: 03/03/2021

ENTERED BY: Smith, Jeremy

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 8/19/2019.

REQUIREMENT: 363. Undefined Boiler Violations. An External Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC375707 - Boiler - Fulton - 2008 - New Blr Rm - Active

Violations This Object: 1

COMPANY: State of North Carolina

INSPECTOR: Smith, Jeremy

OPENED: 03/03/2021

ENTERED BY: Smith, Jeremy

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 8/19/2019.

REQUIREMENT: 363. Undefined Boiler Violations. An External Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.

Location: (NEW HANOVER) County Landfill

Location #: 1814354

Violations: 1

5210 US Highway 421 N, , Wilmington, NC 28401-2252, Phone: 910-815-3579

Contact: Attn Sam Hawes, New Hanover County Landfill, Phone: 910-815-3579

Object: NC282162 - PV - Buckeye - 1987 - Comp Shed - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 02/23/2021

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 07-Undefined Pressure Vessels Violations

SUBCATEGORY 479. Undefined Pressure Vessels Violations.

CONDITION: 479. Undefined Pressure Vessels Violations: Pressure gage inoperable.

REQUIREMENT: 479. Replace pressure gage. Range on gage must be approximately 2 times the intended operating pressure, however it shall not be less than 1.5 times the intended operating pressure nor more than 4 times the intended operating pressure.

Location: (UNC-CH) George M Horton Res Hall-136

Location #: 1900509

Violations: 2

411 Skipper Bowles Dr, , Chapel Hill, NC 27514-3434, Phone: 919-962-1271

Contact: Attn Lawrence Peoples, Manager, UNC Chapel Hill - Giles Horney Bldg 168, Phone: 919-843-8771

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC363063 - PV - Cemline - 2005 - Mech Rm - Active

Violations This Object: 2

COMPANY:	Hartford Steam Boiler		
INSPECTOR:	SORRENTINO, SEAN		
OPENED:	03/01/2021	ENTERED BY:	Keyes, Amanda
CLOSED:		CLOSED BY:	
TYPE:	Certificate Blocking		
CATEGORY:	04-Installation of PRDs NCAC 13-13.0405		
SUBCATEGORY	452. Set pressure too high.		
CONDITION:	452. Installation of PRDs NCAC 13-13.0405: Set pressure too high.		
REQUIREMENT:	452. Replace the pressure relieving device with one with a set pressure no higher than the maximum allowable working pressure as determined by the manufacturer.		
COMPANY:	Hartford Steam Boiler		
INSPECTOR:	SORRENTINO, SEAN		
OPENED:	07/31/2020	ENTERED BY:	Keyes, Amanda
CLOSED:		CLOSED BY:	
TYPE:	Certificate Blocking		
CATEGORY:	05-Operation of PRDs NCAC 13-13.0405		
SUBCATEGORY	475. Valve leaking.		
CONDITION:	475. Operation of PRDs NCAC 13-13.0405: Valve leaking.		
REQUIREMENT:	475. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.		

Location: (UNCC) Cameron Hall

Location #: 2316833

Violations: 1

9201 University City Blvd, , Charlotte, NC 28223-0001, Phone: 704-687-2199

Contact: Attn Kelly Herron, UNC Charlotte, Phone: 704-687-0567

Object: NC381153 - Boiler - Cleaver Brooks - 2010 - Equip Rm 42 - Active

Violations This Object: 1

COMPANY:	State of North Carolina		
INSPECTOR:	Smith, Jeremy		
OPENED:	03/03/2021	ENTERED BY:	Smith, Jeremy
CLOSED:		CLOSED BY:	
TYPE:	Certificate Blocking		
CATEGORY:	23-Undefined Boiler Violations		
SUBCATEGORY	363. Undefined Boiler Violations.		
CONDITION:	363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 8/26/2019.		
REQUIREMENT:	363. Undefined Boiler Violations. An External Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.		

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Location: (UNCC) Regional Utility Plt 1 **Location #:** 1930002 **Violations:** 1
9201 University City Blvd, , Charlotte, NC 28223-0001, Phone: 704-687-6993
Contact: Attn Kelly Herron, UNC Charlotte, Phone: 704-687-0567

Object: NC328646 - Boiler - Hurst - 2002 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Clay, Steven D.
OPENED: 02/10/2021 **ENTERED BY:** Putek, Terry
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 16-Boiler Components
SUBCATEGORY 275. Tube/tube ends leak.
CONDITION: 275. Boiler Components: Tube/tube ends leak. Boiler is down for repairs.
REQUIREMENT: 275. Repair the leaking tubes/tube ends. If weld repairs are required, a qualified "R" certificate holder is necessary to perform the work.

Location: (UNCC) Student Activity Center **Location #:** 1929965 **Violations:** 1
9201 University City Blvd, , Charlotte, NC 28223-0001, Phone: 704-687-6993
Contact: Attn Kelly Herron, UNC Charlotte, Phone: 704-687-0567

Object: NC305359 - Boiler - Teledyne Laars - 1995 - 3rd Level - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Clay, Steven D.
OPENED: 02/10/2021 **ENTERED BY:** Putek, Terry
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409
SUBCATEGORY 003. Required manual reset low water cutoff device not installed.
CONDITION: 003. LWCO and Flow Sensing Devices NCAC 13-13.0409: Required manual reset low water cutoff device not installed.
REQUIREMENT: 003. Install a low-water fuel cutoff device (LWCO) designed for the appropriate service (Steam or Hot Water) that is equipped with a manual reset; or install a manual reset on the existing low water fuel cutoff if appropriate. When the LWCO shuts off the fuel supply to the boiler in the event of a low water condition, the fuel supply must be restarted manually by an operator. Test to ensure proper operation.

Location: (UNCC) Woodward Hall Science & Technology Bldg **Location #:** 1827561 **Violations:** 1
9201 University City Blvd, , Charlotte, NC 28223-0001, Phone: 704-687-6993
Contact: Attn Kelly Herron, UNC Charlotte, Phone: 704-687-0567

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC428980 - Boiler - Chromalox - 2020 - Vivarium Blr Rm - Active **Violations This Object:** 1

COMPANY: State of North Carolina
INSPECTOR: Snuffer, Jimmy
OPENED: 02/02/2021 **ENTERED BY:** Snuffer, Jimmy
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 13-Burners and Fuel Supply Systems
SUBCATEGORY 235. No emergency fuel shut off switch.
CONDITION: 235. Burners and Fuel Supply Systems: No emergency fuel shut off switch.
REQUIREMENT: 235. Install an emergency fuel shut off switch at each egress from the boiler room to shut off all fuel to the boilers.

Location: (UNCG) Spartan Village **Location #:** 3345775 **Violations:** 1
1001 Union St, , Greensboro, NC 27403-2841, Phone: 336-334-5684
Contact: Attn Jon Soter, UNC Greensboro, Phone: 336-256-0434, Cell:336-587-1440

Object: NC394756 - Boiler - Aerco - 2012 - Bldg 3 Mech Rm 20 - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 02/26/2021 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations. Boiler not operating at time of inspection; pressure relief device (PRD) and low water cutoff (LWCO) could not be tested to verify proper operation.

REQUIREMENT: 363. Undefined Boiler Violations. Schedule a reinspection of this boiler at a time when it is operating so that the PRD and LWCO may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of these safety devices is acceptable.

Location: (UNCG) Spartan Village **Location #:** 3345776 **Violations:** 1
911 Union St, , Greensboro, NC 27403-2839, Phone: 336-334-5684
Contact: Attn Jon Soter, UNC Greensboro, Phone: 336-256-0434, Cell:336-587-1440

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC394757 - Boiler - Aerco - 2012 - Bldg 4 Mech Rm 6 - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 02/26/2021 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations. Boiler not operating at time of inspection; pressure relief device (PRD) and low water cutoff (LWCO) could not be tested to verify proper operation.

REQUIREMENT: 363. Undefined Boiler Violations. Schedule a reinspection of this boiler at a time when it is operating so that the PRD and LWCO may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the safety devices is acceptable.

Location: (UNCW) Education Bldg **Location #:** 1842184 **Violations:** 1
970 Reynolds Dr, , Wilmington, NC 28403-3201, Phone: 910-962-3102
Contact: Attn Ellen Boyd, UNC Wilmington, Phone: 910-962-3102

Object: NC410372 - Boiler - Fulton - 2016 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 01/26/2021 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 12-Casing, Stack Breeching and Flue
SUBCATEGORY 211. Combustion gas leaks.
CONDITION: 211. Casing, Stack Breeching and Flue: Combustion gas leaks.
REQUIREMENT: 211. Repair all combustion gas leaks in the casing, stack breeching, or flue.

Location: (WILSON CS) Stantonsburg Elem **Location #:** 1832556 **Violations:** 1
409 Main St, , Stantonsburg, NC 27883-8908, Phone: 252-399-7823
Contact: Attn Mark Letchworth, Director of Maintenance, Wilson County Schools, Phone: 252-399-7820, Cell:252-

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC383889 - Boiler - Weil-McLain - 2011 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: SORRENTINO, SEAN
OPENED: 02/23/2021 **ENTERED BY:** Keyes, Amanda
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 25-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 396. Missing nameplate.
CONDITION: 396. Operation of PRDs NCAC 13-13.0405: Missing nameplate.
REQUIREMENT: 396. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

Location: Bethpage United Methodist Church **Location #:** 1222913 **Violations:** 1
109 Fellowship Dr, , Kannapolis, NC 28081-9566, Phone: 704-932-5296
Contact: There is no contact information available for this location.

Object: NC410459 - Boiler - Weil-McLain - 2015 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Clay, Steven D.
OPENED: 03/16/2021 **ENTERED BY:** Putek, Terry
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations. Boiler was not in operation so that safety devices could be tested.
REQUIREMENT: 363. Undefined Boiler Violations. Schedule an inspection when the boiler is in operation so that safety devices can be tested.

Location: Boston Cleaners & Laundry **Location #:** 1769786 **Violations:** 1
2182 N Church St, , Burlington, NC 27217-3004, Phone: 336-226-9803
Contact: Attn Bill Robbins, Boston Cleaners & Laundry, Phone: 336-226-9803

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC371303 - Boiler - Parker - 2007 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Leonard, Shannon D.

OPENED: 12/18/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 03-Water Gauge Glass NCAC 13-13.0408

SUBCATEGORY 058. Leaking.

CONDITION: 058. Water Gauge Glass NCAC 13-13.0408: Leaking.

REQUIREMENT: 058. Repair or replace the leaking gauge and test to ensure proper operation.

Location: Bowen Cleaners

Location #: 1162007

Violations: 1

1990 Smythewyck Dr, , Greenville, NC 27858-6175, Phone: 252-321-2911

Contact: Attn Rich Volk, Equipment Manager, Bowen Cleaners, Phone: 252-321-2911

Object: NC411387 - Boiler - Parker - 2017 - Blr Rm Bldg Rear - Active

Violations This Object: 1

COMPANY: State of North Carolina

INSPECTOR: Smith, Jeremy

OPENED: 03/03/2021

ENTERED BY: Smith, Jeremy

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 4/24/2019.

REQUIREMENT: 363. Undefined Boiler Violations. An External Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.

Location: Branchview Quality Cleaners Llc

Location #: 1770134

Violations: 1

22 Branchview Dr NE, , Concord, NC 28025-3404, Phone: 704-784-9224

Contact: There is no contact information available for this location.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC291627 - Boiler - Fulton - 1998 - Blr Rm - Active

Violations This Object: 1

COMPANY: State of North Carolina

INSPECTOR: Smith, Jeremy

OPENED: 03/03/2021

ENTERED BY: Smith, Jeremy

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 7/25/2019.

REQUIREMENT: 363. Undefined Boiler Violations. An External Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.

Location: Clariant Corp West Plt

Location #: 292853

Violations: 2

625 E Catawba Ave, , Mount Holly, NC 28120-2270, Phone: 704-822-2168

Contact: Attn Dewayne Moore, Maintenance Planner, Clariant Corp West Plt, Phone: 704-822-2049, Cell:980-319-

Object: NC165549 - Boiler - Cleaver Brooks - 1976 - 250/500 HP Blr Rm - Active

Violations This Object: 1

COMPANY: State of North Carolina

INSPECTOR: Smith, Jeremy

OPENED: 03/03/2021

ENTERED BY: Smith, Jeremy

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 12/17/2019.

REQUIREMENT: 363. Undefined Boiler Violations. An External Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC237004 - Boiler - Cleaver Brooks - 1988 - 250/500 HP Blr Rm - Active **Violations This Object:** 1

COMPANY: State of North Carolina
INSPECTOR: Smith, Jeremy
OPENED: 03/03/2021 **ENTERED BY:** Smith, Jeremy
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 12/17/2019.
REQUIREMENT: 363. Undefined Boiler Violations. An External Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.

Location: Embassy Suites RDU Brier Creek **Location #:** 2698447 **Violations:** 1
8001 Arco Corporate Dr, , Raleigh, NC 27617-2010, Phone: 919-572-2200
Contact: Attn Gary Patel, Maintenance Mgr, Embassy Suites RDU Brier Creek, Phone: 919-484-0500

Object: NC380858 - Boiler - State Industries - 2009 - Wtr Htr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: SORRENTINO, SEAN
OPENED: 02/25/2021 **ENTERED BY:** Keyes, Amanda
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 16-Boiler Components
SUBCATEGORY 270. Water Leaks.
CONDITION: 270. Boiler Components: Water Leaks.
REQUIREMENT: 270. Repair the water leaks identified on the inspection report.

Location: Foothills Brewing Co **Location #:** 1790475 **Violations:** 1
638 W 4th St, , Winston Salem, NC 27101-2730, Phone: 336-777-3348
Contact: Jamie Bartholomaus, Co-Owner, Foothills Brewing Co, Phone: 336-777-3348

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC283771 - Boiler - Hurst - 1996 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Leonard, Shannon D.

OPENED: 02/19/2021

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations: High limit pressure switch manual reset is inoperative and/or broken.

REQUIREMENT: 363. Undefined Boiler Violations. Repair/replace the high limit pressure switch in order to correct this condition. If replacement is required, the replacement high limit pressure switch must be equipped with a functioning manual reset.

Location: Fulton Family YMCA

Location #: 1844837

Violations: 1

385 W Hanes Mill Rd, , Winston Salem, NC 27105-9626, Phone: 336-661-1093

Contact: There is no contact information available for this location.

Object: NC412588 - Boiler - Steamist - 2016 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Leonard, Shannon D.

OPENED: 10/21/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. Boiler not operating at time of inspection; could not test safety devices to verify proper operation.

REQUIREMENT: 363. Undefined Boiler Violations. Schedule a follow up inspection at a time when the boiler is operating so that the safety devices may be tested to verify proper operation. As an alternative a detailed service report or boiler log that includes documentation of the successful testing of the safety devices is also acceptable.

Location: Harrys On The Hill Llc

Location #: 1795964

Violations: 1

819 Patton Ave, , Asheville, NC 28806-3618, Phone: 828-252-3821

Contact: Jeff Barrett, Collision Repair Manager, Harrys On The Hill Llc, Phone: 828-252-3821

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC344092 - PV - Penway - 2002 - Outside Rear Body Shop - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Possidente, James
OPENED: 12/09/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 07-Undefined Pressure Vessels Violations
SUBCATEGORY 479. Undefined Pressure Vessels Violations.
CONDITION: 479. Undefined Pressure Vessels Violations. Vessel is out of service but has not been disconnected from all sources of potential energy including electricity.
REQUIREMENT: 479. Undefined Pressure Vessels Violations. Disconnect vessel from electricity and compressed air piping.

Location: Hertford Baptist Church

Location #: 1796868

Violations: 1

124 W Market St, , Hertford, NC 27944-1151, Phone: 252-426-7460

Contact: Hertford Baptist Church, Phone: 252-426-7460

Object: NC245123 - Boiler - Weil-McLain - 1990 - Blr Rm - Active

Violations This Object: 1

COMPANY: State of North Carolina
INSPECTOR: Harrell, Danny
OPENED: 03/08/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 16-Boiler Components
SUBCATEGORY 270. Water Leaks.
CONDITION: 270. Boiler Components: Water Leaks. Boiler is leaking between the rear two sections.
REQUIREMENT: 270. Repair the water leaks identified on the inspection report. Contact Danny Harrell @ 919-500-3098 when the repair is completed to schedule a re-inspection.

Location: High Country Tire & Service Station

Location #: 1797182

Violations: 1

8227 US Highway 441 S, , Sylva, NC 28779-7193, Phone: 828-586-0886

Contact: Attn Mickey & Sam McMahan, Owner, High Country Tire & Service Station, Phone: 828-586-0886

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC390660 - PV - Steel Fab - 2010 - Shop - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Possidente, James

OPENED: 12/08/2020

ENTERED BY: Putek, Terry

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 07-Undefined Pressure Vessels Violations

SUBCATEGORY 479. Undefined Pressure Vessels Violations.

CONDITION: 479. Undefined Pressure Vessels Violations. Pressure switch cover missing. 230 volt live wires exposed.

REQUIREMENT: 479. Undefined Pressure Vessels Violations. Install a pressure switch cover.

Location: Hillcrest Convalescent Center

Location #: 1797580

Violations: 1

1417 W Pettigrew St, , Durham, NC 27705-4820, Phone: 919-286-7705

Contact: Attn Ted Smith, Administrator, Hillcrest Convalescent Center, Phone: 919-286-7705, Cell:919-219-0426

Object: NC374967 - Boiler - Munchkin - 2007 - Mech Rm 1120 - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: SORRENTINO, SEAN

OPENED: 02/04/2021

ENTERED BY: Keyes, Amanda

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 24-Installation of PRDs NCAC 13-13.0405

SUBCATEGORY 377. Try lever not installed.

CONDITION: 377. Installation of PRDs NCAC 13-13.0405: Try lever not installed.

REQUIREMENT: 377. Replace the relief valve with one with a try lever. The replacement valve must be ASME/NB certified.

Location: Home Moravian Church

Location #: 1798465

Violations: 1

529 S Church St, , Winston Salem, NC 27101-5316, Phone: 336-722-6171

Contact: There is no contact information available for this location.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC357255 - Boiler - Hurst - 2004 - Bsmt Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Leonard, Shannon D.

OPENED: 03/11/2021

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. Boiler not operating at time of inspection; low water cutoff (LWCO) and pressure relief device (PRD) could not be tested to verify proper operation.

REQUIREMENT: 363. Undefined Boiler Violations. Schedule a reinspection at a time when the boiler is operating so that the LWCO and PRD may be tested to verify proper operation. As an alternative, a detailed service report or boiler log that includes documentation of the successful testing of the PRD and LWCO is also acceptable.

Location: Hudson Building

Location #: 1799097

Violations: 1

118 W State St, , Black Mountain, NC 28711-3419, Phone: 828-669-8711

Contact: Attn J Richard Hudson III, Owner, Hudson Building, Phone: 828-669-8711

Object: NC148875 - Boiler - Burnham - 1975 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Possidente, James

OPENED: 12/10/2020

ENTERED BY: Putek, Terry

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 03-Water Gauge Glass NCAC 13-13.0408

SUBCATEGORY 057. Drain inoperative.

CONDITION: 057. Water Gauge Glass NCAC 13-13.0408: Drain inoperative. Sight glass drain inoperative because sight glass is upside down.

REQUIREMENT: 057. Repair or replace the inoperable drain valve on the gauge and test to ensure proper operation.

Location: Kernersville Family YMCA

Location #: 1845634

Violations: 2

1113 W Mountain St, , Kernersville, NC 27284-2125, Phone: 336-996-2231

Contact: There is no contact information available for this location.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC399650 - Boiler - Stemist - 2013 - Suana - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Leonard, Shannon D.

OPENED: 10/14/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. Boiler not operating at time of inspection; low water cutoff (LWCO) and pressure relief device (PRD) could not be tested to verify proper operation.

REQUIREMENT: 363. Undefined Boiler Violations. Schedule a reinspection at a time when the boiler is operating so that the LWCO and PRD may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the flow switch and PRD is also acceptable.

Object: NC418867 - Boiler - Teledyne Laars - 1998 - Hot Tub Wtr Htr - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Leonard, Shannon D.

OPENED: 10/14/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. Boiler not operating at time of inspection; flow switch and pressure relief device (PRD) could not be tested to verify proper operation.

REQUIREMENT: 363. Undefined Boiler Violations. Schedule a reinspection at a time when the boiler is operating so that the flow switch and PRD may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the flow switch and PRD is also acceptable.

Location: Kim Dry Cleaners

Location #: 589892

Violations: 1

7463 Six Forks Rd, , Raleigh, NC 27615-6164, Phone: 919-916-5001

Contact: There is no contact information available for this location.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC430228 - Boiler - Fulton - 2020 - Blr 1 - Active

Violations This Object: 1

COMPANY: State of North Carolina

INSPECTOR: Fish, Emily

OPENED: 03/12/2021

ENTERED BY: Fish, Emily

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 13-Burners and Fuel Supply Systems

SUBCATEGORY 235. No emergency fuel shut off switch.

CONDITION: 235. Burners and Fuel Supply Systems: No emergency fuel shut off switch.

REQUIREMENT: 235. Install an emergency fuel shut off switch at each egress from the boiler room to shut off all fuel to the boilers.

Location: Krystal Cleaners

Location #: 1761037

Violations: 1

2645 N Main St Ste 100, , High Point, NC 27265-2886, Phone: 336-869-9594

Contact: Attn Sung Seo, Krystal Cleaners Inc, Phone: 336-869-9594

Object: NC412942 - Boiler - Fulton - 2017 - Blr Rm - Active

Violations This Object: 1

COMPANY: State of North Carolina

INSPECTOR: Smith, Jeremy

OPENED: 03/03/2021

ENTERED BY: Smith, Jeremy

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 5/7/2019.

REQUIREMENT: 363. Undefined Boiler Violations. An External Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.

Location: Longleaf Neuro Medical Treatment Center

Location #: 1813141

Violations: 1

4761 Ward Blvd, , Wilson, NC 27893-4359, Phone: 252-399-2112

Contact: There is no contact information available for this location.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC220872 - Boiler - Cleaver Brooks - 1987 - Blr Rm 3 - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: SORRENTINO, SEAN
OPENED: 03/15/2021 **ENTERED BY:** Keyes, Amanda
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 16-Boiler Components
SUBCATEGORY 275. Tube/tube ends leak.
CONDITION: 275. Boiler Components: Tube/tube ends leak.
REQUIREMENT: 275. Repair the leaking tubes/tube ends. If weld repairs are required, a qualified "R" certificate holder is necessary to perform the work.

Location: Maple Avenue Cleaners **Location #:** 1808112 **Violations:** 1
2111 Maple Ave, , Burlington, NC 27215-6853, Phone: 336-256-7749
Contact: Danny McPherson, Manager, Maple Avenue Cleaners, Phone: 336-256-7749

Object: NC362678 - Boiler - Columbia - 2006 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 03/10/2021 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations. Boiler overdue for internal inspection
REQUIREMENT: 363. Undefined Boiler Violations. Schedule an internal certificate inspection on this boiler as soon as possible.

Location: Marriott Springhill Suites **Location #:** 2443065 **Violations:** 2
12325 Johnston Rd, , Charlotte, NC 28277-3689, Phone: 704-817-1500
Contact: Sree Ballantyne Llc, Phone: 704-817-1500

Object: NC374594 - Boiler - Munchkin - 2008 - Wtr Htr Rm 1st Flr - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Clay, Steven D.
OPENED: 01/28/2021 **ENTERED BY:** Putek, Terry
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 24-Installation of PRDs NCAC 13-13.0405
SUBCATEGORY 372. Set pressure too high.
CONDITION: 372. Installation of PRDs NCAC 13-13.0405: Set pressure too high. Mawp is 30 psi and SV #1 is 150 psi.
REQUIREMENT: 372. Replace the pressure relieving device with one with a set pressure no higher than the maximum allowable working pressure as determined by the manufacturer.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC374595 - Boiler - Munchkin - 2008 - Wtr Htr Rm 1st Flr - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Clay, Steven D.
OPENED: 01/28/2021 **ENTERED BY:** Putek, Terry
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 24-Installation of PRDs NCAC 13-13.0405
SUBCATEGORY 372. Set pressure too high.
CONDITION: 372. Installation of PRDs NCAC 13-13.0405: Set pressure too high. Mawp is 30 psi and SV #1 is 125 psi.
REQUIREMENT: 372. Replace the pressure relieving device with one with a set pressure no higher than the maximum allowable working pressure as determined by the manufacturer.

Location: Mid Pines Inn & Country Club **Location #:** 480363 **Violations:** 1
1010 Midland Rd, , Southern Pines, NC 28387-3122, Phone: 910-692-2114
Contact: Attn Ricky Mathews, Maintenance Engineer, Mid Pines Inn & Country Club, Phone: 910-692-2114, Cell:

Object: NC048923 - Boiler - Orr & Sembower - 1959 - Bsmt Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 02/25/2021 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 16-Boiler Components
SUBCATEGORY 275. Tube/tube ends leak.
CONDITION: 275. Boiler Components: Tube/tube ends leak.
REQUIREMENT: 275. Repair the leaking tubes/tube ends. If weld repairs are required, a qualified "R" certificate holder is necessary to perform the work.

Location: Milkco Inc **Location #:** 482567 **Violations:** 1
220 Deaverview Rd, , Asheville, NC 28806-1710, Phone: 828-254-6851
Contact: Scott Willett, Maintenance, Milkco Inc, Phone: 828-400-0161

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC359767 - Boiler - Superior Boiler Works - 2005 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Possidente, James
OPENED: 03/08/2021 **ENTERED BY:** Putek, Terry
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 18-Furnace and Fireside
SUBCATEGORY 304. Furnace tube cracking.
CONDITION: 304. Furnace and Fireside: Furnace tube cracking. At least two tube ends cracked. First pass rear tube sheet.
REQUIREMENT: 304. Repair the crack in the furnace tube(s). If welding is required, a qualified "R" certificate holder is necessary to perform the work.

Location: Miller Coors Brewing Power House **Location #:** 3541901 **Violations:** 2
863 E Meadow Rd, , Eden, NC 27288-3636, Phone: 336-520-7897
Contact: Attn David Griffin, CEO, D H Griffin Companies, Phone: 336-855-7030

Object: NC399607 - Boiler - Babcock & Wilcox - 2014 - Blr 2 - Active **Violations This Object:** 1

COMPANY: State of North Carolina
INSPECTOR: Parker, Richard
OPENED: 03/11/2021 **ENTERED BY:** Parker, Richard
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Overdue for inspection.
REQUIREMENT: 363. Contact inspector and schedule inspection.

contact Richard Parker @ 336-202-8341

Object: NC399608 - Boiler - Babcock & Wilcox - 2013 - Blr 3 - Active **Violations This Object:** 1

COMPANY: State of North Carolina
INSPECTOR: Parker, Richard
OPENED: 03/11/2021 **ENTERED BY:** Parker, Richard
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Overdue for inspection.
REQUIREMENT: 363. Contact inspector and schedule inspection.

contact Richard Parker @ 336-202-8341

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External
Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status:
Active; Order Results by: Location Name; Then Order by: Address;

Location: MVP Group International **Location #:** 868307 **Violations:** 1
430 Gentry Rd, , Elkin, NC 28621-9241, Phone: 336-527-2281
Contact: Attn Don Taylor, Maintenance Manager, MVP Group International, Phone: 336-835-6020 X2235, Cell:336-

Object: NC212050 - Boiler - Cleaver Brooks - 1984 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 03/11/2021 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 03-Water Gauge Glass NCAC 13-13.0408
SUBCATEGORY 058. Leaking.
CONDITION: 058. Water Gauge Glass NCAC 13-13.0408: Leaking.
REQUIREMENT: 058. Repair or replace the leaking gauge and test to ensure proper operation.

Location: National Guard Armory **Location #:** 1813513 **Violations:** 2
292 NC Highway 65, , Reidsville, NC 27320-8897, Phone: 336-349-4428
Contact: Lee Lewis, National Guard Armory, Phone: 984-664-8009

Object: NC425270 - Boiler - Lochinvar - 2018 - Blr Rm - Active **Violations This Object:** 1

COMPANY: State of North Carolina
INSPECTOR: Parker, Richard
OPENED: 04/08/2020 **ENTERED BY:** Parker, Richard
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 25-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 391. Discharge piping not properly supported.
CONDITION: 391. Operation of PRDs NCAC 13-13.0405: Discharge piping not properly supported.
REQUIREMENT: 391. Support the relief valve discharge piping so it may not impose excessive stress on the relief valve.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC425271 - Boiler - Lochinvar - 2018 - Blr Rm - Active

Violations This Object: 1

COMPANY: State of North Carolina

INSPECTOR: Parker, Richard

OPENED: 04/08/2020

ENTERED BY: Parker, Richard

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 25-Operation of PRDs NCAC 13-13.0405

SUBCATEGORY 391. Discharge piping not properly supported.

CONDITION: 391. Operation of PRDs NCAC 13-13.0405: Discharge piping not properly supported.

REQUIREMENT: 391. Support the relief valve discharge piping so it may not impose excessive stress on the relief valve.

contact Richard Parker @ 336-202-8341

Location: National Guard Armory

Location #: 1813518

Violations: 2

3515 Armory Dr, , High Point, NC 27260-6101, Phone: 336-886-4724

Contact: SFC Michael Oliver, National Guard Armory, Phone: 984-661-1301

Object: NC389824 - Boiler - Lochinvar - 2012 - Blr Rm - Active

Violations This Object: 1

COMPANY: State of North Carolina

INSPECTOR: Johnson, Dean

OPENED: 01/28/2021

ENTERED BY: Johnson, Dean

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 02-Pressure Gauges NCAC 13-13.0407

SUBCATEGORY 031. Out of calibration.

CONDITION: 031. Pressure Gauges NCAC 13-13.0407: Pressure temperature gauge is out of calibration.

REQUIREMENT: 031. Install a pressure temperature gauge having a dial range of at least 1.5 to 4 times the operating pressure and temperature.

Object: NC389825 - Boiler - Lochinvar - 2012 - Blr Rm - Active

Violations This Object: 1

COMPANY: State of North Carolina

INSPECTOR: Johnson, Dean

OPENED: 01/28/2021

ENTERED BY: Johnson, Dean

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 02-Pressure Gauges NCAC 13-13.0407

SUBCATEGORY 031. Out of calibration.

CONDITION: 031. Pressure Gauges NCAC 13-13.0407: Pressure temperature gauge is out of calibration.

REQUIREMENT: 031. Install a pressure temperature gauge having a dial range of at least 1.5 to 4 times the operating pressure and temperature.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Location: Paul J Rizzo Conference Center **Location #:** 1817817 **Violations:** 1
150 Dubose Home Ln, , Chapel Hill, NC 27517-8944, Phone: 919-913-2098

Contact: There is no contact information available for this location.

Object: NC364029 - Boiler - Lochinvar - 2006 - Outside Dubose House - **Violations This Object:** 1
Active

COMPANY:	Hartford Steam Boiler	
INSPECTOR:	Ollison, Jr., James C.	
OPENED:	06/11/2020	ENTERED BY: Keyes, Amanda
CLOSED:		CLOSED BY:
TYPE:	Certificate Blocking	
CATEGORY:	25-Operation of PRDs NCAC 13-13.0405	
SUBCATEGORY	396. Missing nameplate.	
CONDITION:	396. Operation of PRDs NCAC 13-13.0405: Missing nameplate.	
REQUIREMENT:	396. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.	

Location: Regency Cleaners & Laundromat **Location #:** 1823714 **Violations:** 2
3912 University Dr, , Durham, NC 27707-2518, Phone: 919-493-5815

Contact: Attn Mike Foley, Owner, White Star Laundry & Cleaners, Phone: 919-286-2271

Object: NC248230 - Boiler - P M Lattner - 1990 - Blr Rm - Active **Violations This Object:** 2

COMPANY:	State of North Carolina	
INSPECTOR:	Gunto III, Andrew	
OPENED:	03/04/2021	ENTERED BY: Gunto III, Andrew
CLOSED:		CLOSED BY:
TYPE:	Certificate Blocking	
CATEGORY:	01-LWCO and Flow Sensing Devices NCAC 13-13.0409	
SUBCATEGORY	016. Pipe/fittings not sufficient schedule/grade.	
CONDITION:	016. LWCO and Flow Sensing Devices NCAC 13-13.0409: This boilers external LWCO is of the Float Type. The bolted on flange that holds the float assembly in place is missing a bolt, because the old bolt is broken off in the threaded hole.	
REQUIREMENT:	016. Repair the LWCO casting so that all of the float assembly bolts are in place. If the broken bolt can not be removed without modifying the casting, replace it.	

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

COMPANY: State of North Carolina
INSPECTOR: Gunto III, Andrew
OPENED: 03/04/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 02-Pressure Gauges NCAC 13-13.0407
SUBCATEGORY 032. Incorrect range or insufficient pointer travel.
CONDITION: 032. Pressure Gauges NCAC 13-13.0407: Incorrect range or insufficient pointer travel.
This boilers pressure gauge has a range of 0-100 psi. At the time of the 3/4/2021 Non-Cert External Inspection, this boilers normal operation pressure was around 85 psi.
REQUIREMENT: 032. Install a pressure gauge on the equipment that is visible to the operator from the floor or work platform. Gauge must be the proper range in accordance with NC Administrative Code, Title 13, Chapter 13, Section .0407.
13 NCAC 13 .0407 PRESSURE GAUGES
(a) Boilers and pressure vessels, other than water heaters, shall be provided with a pressure indicating gauge which is visible to the operator on the floor or normal work platform.
(b) Pressure gauges shall have a pressure range of not less than 1½ times the operating pressure, nor more than four times the operating pressure.
(d) Steam boilers shall be provided with a syphon or equivalent which will provide a water seal and protect the gauge from being damaged by the steam.

Location: Sonesta ES Suites Charlotte

Location #: 1832771

Violations: 2

7925 Forest Pine Dr, , Charlotte, NC 28273-4600, Phone: 704-527-6767

Contact: Attn Jessica Nugent, Sonesta ES Suites Charlotte, Phone: 704-954-4019

Object: NC395094 - PV - A O Smith - 2013 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Clay, Steven D.
OPENED: 03/22/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 01-Installation
SUBCATEGORY 413. Cracking.
CONDITION: 413. Installation: Cracking. Leak at bottom of tank.
REQUIREMENT: 413. Repair the cracking. If welding is required, a qualified "R" certificate holder is necessary to perform the work.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC395095 - PV - A O Smith - 2013 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Clay, Steven D.

OPENED: 03/22/2021

ENTERED BY: Putek, Terry

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 01-Installation

SUBCATEGORY 413. Cracking.

CONDITION: 413. Installation: Cracking. Leak at bottom of tank.

REQUIREMENT: 413. Repair the cracking. If welding is required, a qualified "R" certificate holder is necessary to perform the work.

Location: Statesville Family YMCA

Location #: 1845601

Violations: 2

828 Wesley Dr, , Statesville, NC 28677-3355, Phone: 704-873-9622

Contact: Paxton Hix, Facilities Director, Statesville Family YMCA, , Cell:704-880-4915

Object: NC265007 - Boiler - Reimers - 1993 - Mens Steam Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Leonard, Shannon D.

OPENED: 12/16/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. electrical steam generator not operating at time of inspection; safety controls could not be tested to verify proper operation.

REQUIREMENT: 363. Undefined Boiler Violations. Schedule a reinspection at a time when the electric steam generator is operating so that the safety controls may be tested to verify proper operation. As an alternative, a detailed service report or log that includes documentation of the successful testing of these controls is also acceptable.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC380587 - Boiler - Fulton - 2008 - Ladies Steam Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 12/16/2020 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations: electrical steam generator not operating at time of inspection; safety controls could not be tested to verify proper operation.
REQUIREMENT: 363. Undefined Boiler Violations. Schedule a reinspection at a time when the electric steam generator is operating so that the safety controls may be tested to verify proper operation. As an alternative, a detailed service report or log that includes documentation of the successful testing of these controls is also acceptable.

Location: Tailored Chemical Products **Location #:** 332360 **Violations:** 1
1120 Tate Blvd SE, , Hickory, NC 28602-4025, Phone: 828-324-0149
Contact: Greg Lowman, Plant Manager, Tailored Chemical Products Inc, Phone: 828-324-0149

Object: NC363847 - Boiler - Cleaver Brooks - 1994 - Blr Area - Active **Violations This Object:** 1

COMPANY: State of North Carolina
INSPECTOR: Smith, Jeremy
OPENED: 09/08/2020 **ENTERED BY:** Smith, Jeremy
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 4/12/2018.
REQUIREMENT: 363. Undefined Boiler Violations. An external Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.

Location: Twin Lakes Center **Location #:** 1838274 **Violations:** 1
100 Wade Coble Dr, , Burlington, NC 27215-9756, Phone: 336-538-1400
Contact: There is no contact information available for this location.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC363935 - Boiler - BBT - 2006 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 03/06/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 25-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 395. Valve leaking.
CONDITION: 395. Operation of PRDs NCAC 13-13.0405: Pressure Relief device (PRD) leaking.
REQUIREMENT: 395. Replace the leaking PRD with an ASME/NB stamped PRD having a set pressure of 58 PSI or less and a relieving capacity of 249,000 BTU/Hour or more. The replacement PRD must be equipped with a try lever and the PRD discharge must be piped full-size to a safe location (I.E. within 6" of the mechanical room floor).

Location: Valdese Weavers

Location #: 1222894

Violations: 1

705 Lovelady Rd NE, , Valdese, NC 28690-8856, Phone: 828-874-2181

Contact: Attn Lonnie Porter, Maintenance Mgr, Valdese Weavers Inc, Phone: 828-874-2181

Object: NC246193 - Boiler - Superior Boiler Works - 1991 - Blr Rm - Active

Violations This Object: 1

COMPANY: State of North Carolina
INSPECTOR: Smith, Jeremy
OPENED: 03/03/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 2/18/2019.
REQUIREMENT: 363. Undefined Boiler Violations. An External Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.

Location: West German Garage

Location #: 1842877

Violations: 1

5611 Hillsborough St, , Raleigh, NC 27606-1534, Phone: 919-851-1236

Contact: John Elliason, Manager, West German Garage Inc, Phone: 919-851-1236

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC356708 - PV - Manchester - 1999 - Outside - Active

Violations This Object: 1

COMPANY: State of North Carolina

INSPECTOR: Fish, Emily

OPENED: 10/15/2020

ENTERED BY: Fish, Emily

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 09-Pressure Gauges NCAC 13-13.0407

SUBCATEGORY 032. Incorrect range or insufficient pointer travel.

CONDITION: 032. Pressure Gauges NCAC 13-13.0407: Incorrect range or insufficient pointer travel.

2/25/2021 Owner has the correct gauge, but it is not installed yet. Emily Fish

REQUIREMENT: 032. Install a pressure gauge on the equipment that is visible to the operator from the floor or work platform. Gauge must be the proper range in accordance with NC Administrative Code, Title 13, Chapter 13, Section .0407. Please call Emily Fish at (919) 268-0725 when ready for reinspection.

Location: Williamson Cleaners

Location #: 1844175

Violations: 1

3711 Peppermill Dr N Ste G, , Wilson, NC 27896-7390, Phone: 252-205-6180

Contact: Attn James Min, Owner, Williamson Cleaners, Phone: 252-237-1828, Cell:336-837-7025

Object: NC342375 - Boiler - Columbia - 2002 - Blr Rm - Active

Violations This Object: 1

COMPANY: State of North Carolina

INSPECTOR: Harrell, Danny

OPENED: 01/19/2021

ENTERED BY: Harrell, Danny

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 03-Water Gauge Glass NCAC 13-13.0408

SUBCATEGORY 058. Leaking.

CONDITION: 058. Water Gauge Glass NCAC 13-13.0408: Leaking.

REQUIREMENT: 058. Repair or replace the leaking gauge and test to ensure proper operation. Contact Danny Harrell @ 919-500-3098 when the repair is completed.

Location: Zoom Dry Cleaning

Location #: 1816329

Violations: 1

200 W Peace St Ste 120, , Raleigh, NC 27603-1183, Phone: 919-838-8530

Contact: Lola Pedron, Manager, Zoom Dry Cleaning, Phone: 919-838-8530

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC373829 - Boiler - Fulton - 2007 - Blr Rm - Active

Violations This Object: 1

COMPANY: State of North Carolina

INSPECTOR: Smith, Jeremy

OPENED: 03/03/2021

ENTERED BY: Smith, Jeremy

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 6/18/2019.

REQUIREMENT: 363. Undefined Boiler Violations. An External Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.

Violations This Report: 83

Locations This Report: 63