

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Location: (ASV CS) Central Office **Location #:** 1775429 **Violations:** 2
85 Mountain St, , Asheville, NC 28801-3854, Phone: 828-350-7000
Contact: Tim Holcombe, Manager, Asheville City Schools, Phone: 828-350-7000/Maint 828-350-6196

Object: NC205160 - Boiler - Weil-McLain - 1982 - Blr Rm - Active **Violations This Object:** 2

COMPANY:	State of North Carolina	
INSPECTOR:	(By Request), the Owner/User	
OPENED:	01/13/2021	ENTERED BY: Putek, Terry
CLOSED:		CLOSED BY:
TYPE:	Certificate Blocking	
CATEGORY:	01-LWCO and Flow Sensing Devices NCAC 13-13.0409	
SUBCATEGORY	005. No provision to test low water cutoff device.	
CONDITION:	005. LWCO and Flow Sensing Devices NCAC 13-13.0409: No provision to test low water cutoff device.	
REQUIREMENT:	005. Equip the low water fuel cutoff device on the boiler with a vertical drain and blow-off valve assembly of not less than 3/4-inch nominal pipe size to allow for flushing and testing of the low water cutoff while the boiler is in operation.	
COMPANY:	State of North Carolina	
INSPECTOR:	(By Request), the Owner/User	
OPENED:	01/13/2021	ENTERED BY: Putek, Terry
CLOSED:		CLOSED BY:
TYPE:	Certificate Blocking	
CATEGORY:	24-Installation of PRDs NCAC 13-13.0405	
SUBCATEGORY	372. Set pressure too high.	
CONDITION:	372. Installation of PRDs NCAC 13-13.0405: Set pressure too high. Mawp is 50 psi and SV #1 is 75 psi.	
REQUIREMENT:	372. Replace the pressure relieving device with one with a set pressure no higher than the maximum allowable working pressure as determined by the manufacturer.	

Location: (ASV CS) Claxton Elem **Location #:** 1777561 **Violations:** 3
241 Merrimon Ave, , Asheville, NC 28801-1217, Phone: 828-350-6500
Contact: Tim Holcombe, Manager, Asheville City Schools, Phone: 828-350-7000/Maint 828-350-6196

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC262601 - Boiler - Weil-McLain - 1993 - Bsmt - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Possidente, James
OPENED: 01/13/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409
SUBCATEGORY 005. No provision to test low water cutoff device.
CONDITION: 005. LWCO and Flow Sensing Devices NCAC 13-13.0409: No provision to test low water cutoff device.
REQUIREMENT: 005. Equip the low water fuel cutoff device on the boiler with a vertical drain and blow-off valve assembly of not less than 3/4-inch nominal pipe size to allow for flushing and testing of the low water cutoff while the boiler is in operation.

ENTERED BY: Putek, Terry

CLOSED BY:

Object: NC262602 - Boiler - Weil-McLain - 1993 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Possidente, James
OPENED: 01/13/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409
SUBCATEGORY 005. No provision to test low water cutoff device.
CONDITION: 005. LWCO and Flow Sensing Devices NCAC 13-13.0409: No provision to test low water cutoff device.
REQUIREMENT: 005. Equip the low water fuel cutoff device on the boiler with a vertical drain and blow-off valve assembly of not less than 3/4-inch nominal pipe size to allow for flushing and testing of the low water cutoff while the boiler is in operation.

ENTERED BY: Putek, Terry

CLOSED BY:

Object: NC388477 - PV - Lochinvar - 2006 - Cafeteria Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Possidente, James
OPENED: 01/13/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 04-Installation of PRDs NCAC 13-13.0405
SUBCATEGORY 461. Incorrect pressure relieving device(s) for the application.
CONDITION: 461. Installation of PRDs NCAC 13-13.0405: Incorrect pressure relieving device(s) for the application. The current valve is pressure only mounted horizontal.
REQUIREMENT: 461. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

ENTERED BY: Putek, Terry

CLOSED BY:

Location: (ASV CS) Ira B Jones Elem

Location #: 1800336

Violations: 1

544 Kimberly Ave, , Asheville, NC 28804-2560, Phone: 828-350-6700

Contact: Tim Holcombe, Manager, Asheville City Schools, Phone: 828-350-7000/Maint 828-350-6196

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC288783 - Boiler - Weil-McLain - 1996 - New Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Possidente, James

OPENED: 01/12/2021

ENTERED BY: Putek, Terry

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409

SUBCATEGORY 005. No provision to test low water cutoff device.

CONDITION: 005. LWCO and Flow Sensing Devices NCAC 13-13.0409: No provision to test low water cutoff device.

REQUIREMENT: 005. Equip the low water fuel cutoff device on the boiler with a vertical drain and blow-off valve assembly of not less than 3/4-inch nominal pipe size to allow for flushing and testing of the low water cutoff while the boiler is in operation. Recommend installing probe type LWCO with test and reset button to allow testing the device.

Location: (ASV CS) Vance Elem

Location #: 1839986

Violations: 1

98 Sulphur Springs Rd, , Asheville, NC 28806-2646, Phone: 828-250-6600

Contact: Tim Holcombe, Manager, Asheville City Schools, Phone: 828-350-7000/Maint 828-350-6196

Object: NC221780 - Boiler - Weil-McLain - 1986 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Possidente, James

OPENED: 01/13/2021

ENTERED BY: Putek, Terry

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409

SUBCATEGORY 005. No provision to test low water cutoff device.

CONDITION: 005. LWCO and Flow Sensing Devices NCAC 13-13.0409: No provision to test low water cutoff device.

REQUIREMENT: 005. Equip the low water fuel cutoff device on the boiler with a vertical drain and blow-off valve assembly of not less than 3/4-inch nominal pipe size to allow for flushing and testing of the low water cutoff while the boiler is in operation.

Location: (BEAUFORT CO) County Courthouse

Location #: 1780498

Violations: 1

112 W 2nd St, , Washington, NC 27889-4940, Phone: 252-946-9629

Contact: Beaufort County Government, Phone: 252-946-9624

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC420619 - Boiler - Kiturami - 2016 - Bsmt Left Rear - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 04/06/2021 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 24-Installation of PRDs NCAC 13-13.0405
SUBCATEGORY 372. Set pressure too high.
CONDITION: 372. Installation of PRDs NCAC 13-13.0405: Set pressure too high.
REQUIREMENT: 372. Replace pressure relief device with a ASME/NB certified pressure relief device with a set pressure of not greater than 30 psig, with a relief capacity of not less than 200,000 BTU/hr and with a testing lever installed

Location: (CRAVEN CS) Bridgeton Elem **Location #:** 1770407 **Violations:** 3
230 Branch Canal Rd, , New Bern, NC 28560-7624, Phone: 252-514-6425
Contact: Craven County Public Schools, Phone: 252-514-6380

Object: NC346263 - Boiler - Weil-McLain - 2003 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 04/07/2021 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409
SUBCATEGORY 006. Low water cutoff device inoperative or bypassed.
CONDITION: 006. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device inoperative or bypassed.
REQUIREMENT: 006. Repair or replace the inoperable low water fuel cutoff control and test to ensure proper operation.

Object: NC346265 - PV - Rheem/Ruud - 2002 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 04/07/2021 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 10-Thermometer NCAC 13-13.0410
SUBCATEGORY 110. Thermometer not installed.
CONDITION: 110. Thermometer NCAC 13-13.0410: Thermometer not installed.
REQUIREMENT: 110. Install a thermometer at/in the vessel outlet to measure the temperature in degrees Fahrenheit of the water. The thermometer shall have a range of approximately 2 times the intended operating temperature but not less than 1 1/2 times the intended operating temperature, nor more than 4 times the intended operating temperature.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC346266 - PV - Rheem/Ruud - 1999 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 04/07/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 10-Thermometer NCAC 13-13.0410
SUBCATEGORY 110. Thermometer not installed.
CONDITION: 110. Thermometer NCAC 13-13.0410: Thermometer not installed.
REQUIREMENT: 110. Install a thermometer at/in the vessel outlet to measure the temperature in degrees Fahrenheit of the water. The thermometer shall have a range of approximately 2 times the intended operating temperature but not less than 1 1/2 times the intended operating temperature, nor more than 4 times the intended operating temperature.

Location: (CRAVEN CS) Creekside Elem

Location #: 2157338

Violations: 4

2790 Old Airport Rd, , New Bern, NC 28562-8734, Phone: 252-514-4360

Contact: Craven County Public Schools, Phone: 252-514-6380

Object: NC367471 - Boiler - Weil-McLain - 2007 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 04/08/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 16-Boiler Components
SUBCATEGORY 270. Water Leaks.
CONDITION: 270. Boiler Components: Water Leaks.
REQUIREMENT: 270. Repair the leak identified at the bottom between the last two boiler sections.

Object: NC367472 - Boiler - Weil-McLain - 2007 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 04/08/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 25-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 395. Valve leaking.
CONDITION: 395. Operation of PRDs NCAC 13-13.0405: Valve leaking: Pressure relief device leaking.
REQUIREMENT: 395. Repair or replace pressure relief device with a ASME/NB certified pressure relief device with a set pressure of not greater than 50 psig, with a relief capacity of not less than 1,358,000 BTU/hr, and a testing lever

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC367473 - Boiler - A O Smith - 2007 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 04/08/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 06-Thermometer NCAC 13-13.0410
SUBCATEGORY 110. Thermometer not installed.
CONDITION: 110. Thermometer NCAC 13-13.0410: Thermometer not installed.
REQUIREMENT: 110. Install a thermometer at/in the boiler outlet to measure the temperature in degrees Fahrenheit of the water. The thermometer shall have a range of approximately 2 times the intended operating temperature but not less than 1 1/2 times the intended operating temperature, nor more than 4 times the intended operating temperature.

ENTERED BY: Judd, Janie
CLOSED BY:

Object: NC367474 - Boiler - A O Smith - 2007 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 04/08/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 06-Thermometer NCAC 13-13.0410
SUBCATEGORY 110. Thermometer not installed.
CONDITION: 110. Thermometer NCAC 13-13.0410: Thermometer not installed.
REQUIREMENT: 110. Install a thermometer at/in the boiler outlet to measure the temperature in degrees Fahrenheit of the water. The thermometer shall have a range of approximately 2 times the intended operating temperature but not less than 1 1/2 times the intended operating temperature, nor more than 4 times the intended operating temperature.

ENTERED BY: Judd, Janie
CLOSED BY:

Location: (CRAVEN CS) Graham A Barden Elem
200 Cedar Dr, , Havelock, NC 28532-2187, Phone: 252-444-5100
Contact: Craven County Public Schools, Phone: 252-514-6380

Location #: 1793675

Violations: 2

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC229320 - Boiler - Weil-McLain - 1988 - Blr Rm - Active

Violations This Object: 2

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 04/08/2021

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations: Boiler not running.

REQUIREMENT: 363. Undefined Boiler Violations. Reschedule inspection for a time when the boiler can be run so safety devices can be verified to operate properly. If repairs cannot be completed in a timely fashion, or repairs are not be performed, disconnect the boiler.

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 04/08/2021

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 24-Installation of PRDs NCAC 13-13.0405

SUBCATEGORY 371. Inadequate relieving capacity.

CONDITION: 371. Installation of PRDs NCAC 13-13.0405: Inadequate relieving capacity.

REQUIREMENT: 371. Replace one or both pressure relief devices to obtain a capacity of not less than 3550 PPH. Set pressures are to be no greater than 50 psig, and a testing lever be installed on each pressure relief device.

Location: (CRAVEN CS) Havelock Elem

Location #: 1814386

Violations: 1

201 Cunningham Blvd, , Havelock, NC 28532-1908, Phone: 252-444-5106

Contact: Craven County Public Schools, Phone: 252-514-6380

Object: NC412018 - Boiler - Rheem/Ruud - 2016 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 04/08/2021

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 06-Thermometer NCAC 13-13.0410

SUBCATEGORY 110. Thermometer not installed.

CONDITION: 110. Thermometer NCAC 13-13.0410: Thermometer not installed.

REQUIREMENT: 110. Install a thermometer at/in the boiler outlet to measure the temperature in degrees Fahrenheit of the water. The thermometer shall have a range of approximately 2 times the intended operating temperature but not less than 1 1/2 times the intended operating temperature, nor more than 4 times the intended operating temperature.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Location: (CRAVEN CS) J T Barber Elem **Location #:** 1801046 **Violations:** 1
1700 Cobb St, , New Bern, NC 28560-3536, Phone: 252-514-6460
Contact: Craven County Public Schools, Phone: 252-514-6380

Object: NC263863 - Boiler - Weil-McLain - 1996 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 04/07/2021 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 25-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 394. Valve inoperative.
CONDITION: 394. Operation of PRDs NCAC 13-13.0405: Valve inoperative.
REQUIREMENT: 394. Replace pressure relieve devices with ASME/NB certified pressure relief device with a set pressure of not greater than 15 psig, with a combined relieve capacity of not less than 3270 PPH and with testing levers installed.

Location: (CRAVEN CS) Tucker Creek Middle **Location #:** 1838064 **Violations:** 3
200 Sermons Rd, , Havelock, NC 28532-7707, Phone: 252-444-7200
Contact: Craven County Public Schools, Phone: 252-514-6380

Object: NC282746 - Boiler - Weil-McLain - 1997 - Blr Rm Rear Cafeteria - **Violations This Object:** 1
Active

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 04/08/2021 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations: Boiler not operating.
REQUIREMENT: 363. Undefined Boiler Violations. Reschedule inspection for a time when the boiler is operating so that safety devices can be verified to operate properly.

Object: NC282747 - Boiler - Weil-McLain - 1997 - Blr Rm Rear Cafeteria - **Violations This Object:** 1
Active

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 04/08/2021 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations: Boiler not operating.
REQUIREMENT: 363. Undefined Boiler Violations: Reschedule inspection for a time when the boiler is operating so that safety devices can be verified to operate properly.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC386070 - PV - Trane - 2007 - Outside Chillers Cafeteria - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 04/08/2021 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 04-Installation of PRDs NCAC 13-13.0405
SUBCATEGORY 460. Seals broken/ missing.
CONDITION: 460. Installation of PRDs NCAC 13-13.0405: Seals broken/ missing: Pressure relief device tamper seal broken.
REQUIREMENT: 460. Replace pressure relief device. Set pressure not to be greater than 200 psig and with adequate capacity.

Location: (DPS-C) Columbus CI - 4355 **Location #:** 1778917 **Violations:** 2
1255 Prison Camp Rd, , Whiteville, NC 28472-4887, Phone: 910-642-3285
Contact: NC Dept Of Public Safety - 13101, Phone: 919-716-3422

Object: NC382455 - Boiler - Cleveland Range - 2010 - Food Service - **Violations This Object:** 2
Active

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 11/24/2020 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 03-Water Gauge Glass NCAC 13-13.0408
SUBCATEGORY 058. Leaking.
CONDITION: 058. Water Gauge Glass NCAC 13-13.0408: Leaking.
REQUIREMENT: 058. Repair or replace the leaking gauge and test to ensure proper operation.

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 11/24/2020 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 25-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 395. Valve leaking.
CONDITION: 395. Operation of PRDs NCAC 13-13.0405: Valve leaking: Pressure relief device leaking.
REQUIREMENT: 395. Replace with a ASME/NB certified pressure relief device with a set pressure of not greater than 15 psig, with a relief capacity of not less than 266 PPH, and with a testing lever installed.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Location: (DPS-C) NCCIW - 3010 **Location #:** 1779964 **Violations:** 2
1034 Bragg St, , Raleigh, NC 27610-3846, Phone: 919-733-4340
Contact: Phillip Jones, Maintenance Supervisor, NCCIW - 3010, Phone: 919-508-1690

Object: NC381483 - Boiler - PVI Industries - 2010 - Falcom Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: SORRENTINO, SEAN
OPENED: 12/08/2020 **ENTERED BY:** Keyes, Amanda
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 16-Boiler Components
SUBCATEGORY 270. Water Leaks.
CONDITION: 270. Boiler Components: Water Leaks.
REQUIREMENT: 270. Repair the water leaks identified on the inspection report. If welding is required, a qualified "R" certificate holder is necessary to perform the repair.

Object: NC401596 - Boiler - PVI Industries - 2014 - Sparrow N - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: SORRENTINO, SEAN
OPENED: 12/08/2020 **ENTERED BY:** Keyes, Amanda
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 16-Boiler Components
SUBCATEGORY 270. Water Leaks.
CONDITION: 270. Boiler Components: Water Leaks. Tank leaking at unknown location.
REQUIREMENT: 270. Repair the water leaks identified on the inspection report. If welding is required, a qualified "R" certificate holder is necessary to perform the repair.

Location: (ELCPPS) Northside Elem **Location #:** 1815298 **Violations:** 1
1062 Northside Rd, , Elizabeth City, NC 27909-8522, Phone: 252-335-4306
Contact: Marlean Wiltens, Director of Maintenance, Elizabeth City Pasquotank Public Schools, Phone: 252-335-

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC363140 - Boiler - PVI Industries - 2004 - Htr Rm - Active

Violations This Object: 1

COMPANY: State of North Carolina

INSPECTOR: Harrell, Danny

OPENED: 02/03/2021

ENTERED BY: Harrell, Danny

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 16-Boiler Components

SUBCATEGORY 270. Water Leaks.

CONDITION: 270. Boiler Components: Water Leaks. Water was leaking out of the bottom of the water heater jacket.

REQUIREMENT: 270. Repair the water leaks identified on the inspection report or replace the water heater. If any welding is performed as a means of repair it must be performed by an R stamp holder with a valid certificate to use the R stamp. Contact Danny Harrell @ 919-500-3098 when the repair or replacement is completed to schedule a re-inspection.

Location: (LEE) O T Sloan Park

Location #: 1815639

Violations: 2

1420 Bragg St, , Sanford, NC 27330-5435, Phone: 919-775-2107

Contact: Attn Russell Spivey, Lee County Government General Services, Phone: 919-718-4622

Object: NC419417 - Boiler - Teledyne Laars - 2017 - Outside pool house - Active

Violations This Object: 1

COMPANY: State of North Carolina

INSPECTOR: Gunto III, Andrew

OPENED: 10/20/2020

ENTERED BY: Gunto III, Andrew

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations.

At the time of the 10/20/2020 inspection, this boiler was not in operation.

REQUIREMENT: 363. Undefined Boiler Violations.

At follow up inspection the boiler must be firing, and an operational demonstration will be need. This includes the verification of the high-limit temperature controls and its manual reset.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC419418 - Boiler - Teledyne Laars - 2017 - Outside pool house - Active **Violations This Object:** 1

COMPANY: State of North Carolina
INSPECTOR: Gunto III, Andrew
OPENED: 10/20/2020 **ENTERED BY:** Gunto III, Andrew
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations.
At the time of the 10/20/2020 inspection, this boiler was not in operation.
REQUIREMENT: 363. Undefined Boiler Violations.
At follow up inspection the boiler must be firing, and an operational demonstration will be need. This includes the verification of the high-limit temperature controls and its manual reset.

Location: (MH UNIV) Brown Hall **Location #:** 1930569 **Violations:** 3
150 Joe Anderson Dr, , Mars Hill, NC 28754-0370, Phone: 828-689-1201
Contact: Attn Henry H Haywood, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:828-206-

Object: NC338996 - PV - LTC - 2002 - Bsmt Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Possidente, James
OPENED: 03/12/2021 **ENTERED BY:** Putek, Terry
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 02-Manufacturer's Data Report & Nameplate
SUBCATEGORY 431. Nameplate stamping is incorrect, missing, or illegible.
CONDITION: 431. Manufacturer's Data Report & Nameplate: Nameplate stamping is incorrect, missing, or illegible. Dataplate could not be located.
REQUIREMENT: 431. Obtain a replacement nameplate from the manufacturer or a replacement in accordance with the National Board Inspection Code. Locate nameplate and make visible for inspection.

Object: NC338997 - Boiler - Lochinvar - 2002 - Bsmt Blr Rm - Active **Violations This Object:** 2

COMPANY: Hartford Steam Boiler
INSPECTOR: Possidente, James
OPENED: 03/12/2021 **ENTERED BY:** Putek, Terry
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 08-Main Steam System NCAC 13-13.0411
SUBCATEGORY 126. Leaking pipe/pipe joints.
CONDITION: 126. Main Steam System NCAC 13-13.0411: Leaking pipe/pipe joints.
REQUIREMENT: 126. Repair or tighten leaking pipe/pipe joints.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

COMPANY: Hartford Steam Boiler
INSPECTOR: Possidente, James
OPENED: 03/12/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 12-Casing, Stack Breeching and Flue
SUBCATEGORY 214. Excessive corrosion.
CONDITION: 214. Casing, Stack Breeching and Flue: Excessive stack corrosion.
REQUIREMENT: 214. Repair or replace the casing, stack breeching or flue.

Location: (MH UNIV) Gibson Hall
100 Joe Anderson Dr, , Mars Hill, NC 28754-0370, Phone: 828-689-1201
Location #: 1930563 **Violations:** 1
Contact: Attn Henry H Haywood, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:828-206-

Object: NC099075 - Boiler - Weil-McLain - 1969 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Possidente, James
OPENED: 03/12/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 25-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 395. Valve leaking.
CONDITION: 395. Operation of PRDs NCAC 13-13.0405: Valve leaking.
REQUIREMENT: 395. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

Location: (MH UNIV) Huffman Hall
130 Womens Hill Dr, , Mars Hill, NC 28754-0370, Phone: 828-689-1201
Location #: 1930543 **Violations:** 1
Contact: Attn Henry H Haywood, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:828-206-

Object: NC403705 - PV - LTC - 2015 - Rm B11 - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Possidente, James
OPENED: 02/23/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 07-Undefined Pressure Vessels Violations
SUBCATEGORY 479. Undefined Pressure Vessels Violations.
CONDITION: 479. Undefined Pressure Vessels Violations. Pipe leaking.
REQUIREMENT: 479. Undefined Pressure Vessels Violations. Repair or replace leaking piping/pipe joints.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Location: (MH UNIV) McConnell Hall **Location #:** 1930553 **Violations:** 1
54 College St, , Mars Hill, NC 28754-0370, Phone: 828-689-1201
Contact: Attn Henry H Haywood, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:828-206-

Object: NC270792 - Boiler - Weil-McLain - 1994 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Possidente, James
OPENED: 02/23/2021 **ENTERED BY:** Putek, Terry
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409
SUBCATEGORY 006. Low water cutoff device inoperative or bypassed.
CONDITION: 006. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device inoperative or bypassed.
REQUIREMENT: 006. Repair or replace the inoperable low water fuel cutoff control and test to ensure proper operation.

Location: (MH UNIV) Pittman Dining Hall **Location #:** 1930566 **Violations:** 1
121 Cascade St, , Mars Hill, NC 28754-9135, Phone: 828-689-1201
Contact: Attn Henry H Haywood, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:828-206-

Object: NC262680 - Boiler - Peerless - 1993 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Possidente, James
OPENED: 03/12/2021 **ENTERED BY:** Putek, Terry
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 12-Casing, Stack Breeching and Flue
SUBCATEGORY 211. Combustion gas leaks.
CONDITION: 211. Casing, Stack Breeching and Flue: Combustion gas leaks.
REQUIREMENT: 211. Repair all combustion gas leaks in the casing, stack breeching, or flue.

Location: (MH UNIV) Stroup Hall **Location #:** 1930538 **Violations:** 2
141 Womens Hill Dr, , Mars Hill, NC 28754-0370, Phone: 828-689-1201
Contact: Attn Henry H Haywood, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:828-206-

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC323874 - Boiler - Teledyne Laars - 2000 - Bsmt - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Possidente, James
OPENED: 02/23/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409
SUBCATEGORY 012. Flow switch inoperative or bypassed.
CONDITION: 012. LWCO and Flow Sensing Devices NCAC 13-13.0409: Flow switch inoperative or bypassed. (Leaking)
REQUIREMENT: 012. Install a flow switch that will shut off the fuel supply in case of stoppage of water flow or a low-water condition and test to ensure proper operation.

ENTERED BY: Putek, Terry

CLOSED BY:

Object: NC325457 - Boiler - Peerless - 2000 - Bsmt - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Possidente, James
OPENED: 02/23/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409
SUBCATEGORY 006. Low water cutoff device inoperative or bypassed.
CONDITION: 006. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device inoperative or bypassed. Primary LWCO inoperative.
REQUIREMENT: 006. Repair or replace the inoperable low water fuel cutoff control and test to ensure proper operation.

ENTERED BY: Putek, Terry

CLOSED BY:

Location: (MITCHELL CC) Campus Physical Plt

Location #: 1762133

Violations: 1

500 W Broad St, , Statesville, NC 28677-5264, Phone: 704-878-3200

Contact: Attn Chad Lackey, Director Safety & Security, Mitchell Community College,

Object: NC283176 - Boiler - Weil-McLain - 1997 - Mech Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Richey, Paul D.
OPENED: 03/17/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 25-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 395. Valve leaking.
CONDITION: 395. Operation of PRDs NCAC 13-13.0405: Valve leaking. PRD leaking past disc and seat.
REQUIREMENT: 395. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

ENTERED BY: Putek, Terry

CLOSED BY:

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External
Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status:
Active; Order Results by: Location Name; Then Order by: Address;

Location: (NCCU) Heating Plant **Location #:** 1796457 **Violations:** 1
1801 Fayetteville St, , Durham, NC 27707-3129, Phone: 919-530-6313
Contact: Attn Lori Blake Reid PO #P107428, NC Central University Shephard Station, Phone: 919-530-7244

Object: NC293050 - Boiler - Babcock & Wilcox - 1998 - Blr House Blr 1 - **Violations This Object:** 1
Active

COMPANY: Hartford Steam Boiler
INSPECTOR: SORRENTINO, SEAN
OPENED: 11/18/2020 **ENTERED BY:** Keyes, Amanda
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. The boiler was not operating during this inspection per Sean Sorrentino inspection report.
REQUIREMENT: 363. You must operate this boiler for external inspection per Sean Sorrentino inspection report.

Location: (NCDOA) Museum Of Art **Location #:** 1813946 **Violations:** 1
2110 Blue Ridge Rd, , Raleigh, NC 27607-6433, Phone: 919-839-6262
Contact: Chris Carter, Plant Maint Supervisor, Museum Of Art, Phone: 919-839-6262

Object: NC375707 - Boiler - Fulton - 2008 - New Blr Rm - Active **Violations This Object:** 1

COMPANY: State of North Carolina
INSPECTOR: Smith, Jeremy
OPENED: 03/03/2021 **ENTERED BY:** Smith, Jeremy
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 8/19/2019.
REQUIREMENT: 363. Undefined Boiler Violations. An External Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.

Location: (NCSU) CVM Main Bldg 301-Z5 **Location #:** 3284982 **Violations:** 4
4700 Hillsborough St, , Raleigh, NC 27606-1428, Phone: 919-513-6485
Contact: Andrew Langdon, Manager, CVM Main Bldg 301-Z5, Phone: 919-513-6485

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC268652 - PV - Amsco - 1994 - Rm C 301 - Active

Violations This Object: 2

COMPANY: State of North Carolina
INSPECTOR: Fish, Emily
OPENED: 04/07/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 04-Installation of PRDs NCAC 13-13.0405
SUBCATEGORY 452. Set pressure too high.
CONDITION: 452. Installation of PRDs NCAC 13-13.0405: Set pressure too high.
REQUIREMENT: 452. Replace the pressure relieving device with one with a set pressure no higher than the maximum allowable working pressure as determined by the manufacturer.

COMPANY: State of North Carolina
INSPECTOR: Fish, Emily
OPENED: 04/07/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 07-Undefined Pressure Vessels Violations
SUBCATEGORY 479. Undefined Pressure Vessels Violations.
CONDITION: 479. Undefined Pressure Vessels Violations. Door seals deteriorated.
REQUIREMENT: 479. Undefined Pressure Vessels Violations. Replace door seals.

Object: NC268653 - PV - Amsco - 1994 - Rm C 301 - Active

Violations This Object: 1

COMPANY: State of North Carolina
INSPECTOR: Fish, Emily
OPENED: 04/07/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 07-Undefined Pressure Vessels Violations
SUBCATEGORY 479. Undefined Pressure Vessels Violations.
CONDITION: 479. Undefined Pressure Vessels Violations. Door seals deteriorated.
REQUIREMENT: 479. Undefined Pressure Vessels Violations. Replace door seals.

Object: NC400566 - PV - Amsco - 1979 - Bldg 301 Rm C303 - Active

Violations This Object: 1

COMPANY: State of North Carolina
INSPECTOR: Fish, Emily
OPENED: 04/07/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 07-Undefined Pressure Vessels Violations
SUBCATEGORY 479. Undefined Pressure Vessels Violations.
CONDITION: 479. Undefined Pressure Vessels Violations. Door seal deteriorated.
REQUIREMENT: 479. Undefined Pressure Vessels Violations. Replace door seals.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Location: (NCSU) Terry Companion Animal Medical Ctr CVM-Z5 **Location #:** 2930475 **Violations:** 2
1052 William Moore Dr, , Raleigh, NC 27607-4065, Phone: 919-513-6485
Contact: Andrew Langdon, Terry Companion Animal Medical Ctr, Phone: 919-513-6485

Object: NC384734 - PV - Bradford White - 2009 - Mech Rm 1480 - Active **Violations This Object:** 2

COMPANY: State of North Carolina
INSPECTOR: Fish, Emily
OPENED: 04/06/2021 **ENTERED BY:** Fish, Emily
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 04-Installation of PRDs NCAC 13-13.0405
SUBCATEGORY 450. Pressure relieving devices not installed.
CONDITION: 450. Installation of PRDs NCAC 13-13.0405: Pressure relieving devices not installed. PRDs on boilers accepted for hot water storage tank so no imminent danger.
REQUIREMENT: 450. Install a pressure relieving device in accordance with NCAC 13-13.0405.

COMPANY: State of North Carolina
INSPECTOR: Fish, Emily
OPENED: 04/06/2021 **ENTERED BY:** Fish, Emily
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 10-Thermometer NCAC 13-13.0410
SUBCATEGORY 110. Thermometer not installed.
CONDITION: 110. Thermometer NCAC 13-13.0410: Thermometer not installed.
REQUIREMENT: 110. Install a thermometer at/in the vessel outlet to measure the temperature in degrees Fahrenheit of the water. The thermometer shall have a range of approximately 2 times the intended operating temperature but not less than 1 1/2 times the intended operating temperature, nor more than 4 times the intended operating temperature.

Location: (NEW HANOVER) County Landfill **Location #:** 1814354 **Violations:** 1
5210 US Highway 421 N, , Wilmington, NC 28401-2252, Phone: 910-815-3579
Contact: Attn Sam Hawes, New Hanover County Landfill, Phone: 910-815-3579

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC282162 - PV - Buckeye - 1987 - Comp Shed - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 02/23/2021

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 07-Undefined Pressure Vessels Violations

SUBCATEGORY 479. Undefined Pressure Vessels Violations.

CONDITION: 479. Undefined Pressure Vessels Violations: Pressure gage inoperable.

REQUIREMENT: 479. Replace pressure gage. Range on gage must be approximately 2 times the intended operating pressure, however it shall not be less than 1.5 times the intended operating pressure nor more than 4 times the intended operating pressure.

Location: (OCPS) Hillsborough Elem

Location #: 1797655

Violations: 1

402 N Nash St, , Hillsborough, NC 27278-2032, Phone: 919-732-8126

Contact: Attn Buster Crabtree, Orange County Schools, Phone: 919-732-8126

Object: NC364038 - Boiler - Weil-McLain - 2005 - Gym Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: SORRENTINO, SEAN

OPENED: 03/19/2021

ENTERED BY: Keyes, Amanda

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Water level in gauge glass out of sight high.

REQUIREMENT: 363. Repair and clean the water column to restore proper operation.

Location: (ONSLOW) Farmers Market Bldg

Location #: 1829550

Violations: 1

4024 Richlands Hwy, , Jacksonville, NC 28540-8872, Phone: 910-455-0334

Contact: Onslow County Government, Phone: 910-455-0334

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC334670 - Boiler - Peerless - 2001 - Outside Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 03/23/2021 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 25-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 395. Valve leaking.
CONDITION: 395. Operation of PRDs NCAC 13-13.0405: Pressure Relief Device leaking.
REQUIREMENT: 395. Replace with a ASME/NB certified pressure relief device with a set pressure of not greater than 50 PSIG with a relief capacity of not less than 1,029,000 BTU/HR and with a testing lever installed.

Location: (RRGSD) Roanoke Rapids High **Location #:** 1824808 **Violations:** 2
800 Hamilton St, , Roanoke Rapids, NC 27870-2708, Phone: 252-519-7121
Contact: Attn Robbie Clements, Maintenance Director, Roanoke Rapids City Schools, Phone: 252-578-4171

Object: NC048249 - Boiler - National US - 1959 - Gym Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: SORRENTINO, SEAN
OPENED: 04/21/2021 **ENTERED BY:** Keyes, Amanda
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 25-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 395. Valve leaking.
CONDITION: 395. Operation of PRDs NCAC 13-13.0405: Valve leaking.
REQUIREMENT: 395. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

Object: NC423945 - Boiler - Weil-McLain - 2019 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: SORRENTINO, SEAN
OPENED: 04/21/2021 **ENTERED BY:** Keyes, Amanda
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 24-Installation of PRDs NCAC 13-13.0405
SUBCATEGORY 371. Inadequate relieving capacity.
CONDITION: 371. Installation of PRDs NCAC 13-13.0405: Inadequate relieving capacity.
REQUIREMENT: 371. Replace the pressure relieving device with one with a capacity required by the boiler manufacturer.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External
Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status:
Active; Order Results by: Location Name; Then Order by: Address;

Location: (UNCA) Carol Belk Theater **Location #:** 1903686 **Violations:** 1
1 University Hts, , Asheville, NC 28804-3251, Phone: 828-251-6038
Contact: Attn Jay Small, HVAC Supervisor, UNC Asheville, Phone: 828-250-3964

Object: NC299507 - Boiler - Lochinvar - 1999 - Blr Rm - Active **Violations This Object:** 1

COMPANY:	Hartford Steam Boiler	
INSPECTOR:	Possidente, James	
OPENED:	04/06/2021	ENTERED BY: Putek, Terry
CLOSED:		CLOSED BY:
TYPE:	Certificate Blocking	
CATEGORY:	16-Boiler Components	
SUBCATEGORY	270. Water Leaks.	
CONDITION:	270. Boiler Components: Water Leaks. Manifold flange leaking.	
REQUIREMENT:	270. Repair the water leaks identified on the inspection report.	

Location: (UNCA) Founders Residence Hall **Location #:** 1903690 **Violations:** 2
1 University Hts, , Asheville, NC 28804-3251, Phone: 828-251-6038
Contact: Attn Jay Small, HVAC Supervisor, UNC Asheville, Phone: 828-250-3964

Object: NC203365 - Boiler - PVI Industries - 1981 - Highrise Dorm Equip **Violations This Object:** 1
Rm - Active

COMPANY:	Hartford Steam Boiler	
INSPECTOR:	Possidente, James	
OPENED:	04/06/2021	ENTERED BY: Putek, Terry
CLOSED:		CLOSED BY:
TYPE:	Certificate Blocking	
CATEGORY:	16-Boiler Components	
SUBCATEGORY	276. Manway gasket leaks.	
CONDITION:	276. Boiler Components: Manway gasket leaks.	
REQUIREMENT:	276. Replace the leaking manway gasket. If weld repairs are required to reestablish the seating surface, a qualified "R" certificate holder is necessary to perform the work.	

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC203366 - Boiler - PVI Industries - 1981 - Highrise Dorm Equip Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Possidente, James
OPENED: 04/06/2021 **ENTERED BY:** Putek, Terry
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 16-Boiler Components
SUBCATEGORY 276. Manway gasket leaks.
CONDITION: 276. Boiler Components: Manway gasket leaks.
REQUIREMENT: 276. Replace the leaking manway gasket. If weld repairs are required to reestablish the seating surface, a qualified "R" certificate holder is necessary to perform the work.

Location: (UNCC) Cameron Hall **Location #:** 2316833 **Violations:** 1
9201 University City Blvd, , Charlotte, NC 28223-0001, Phone: 704-687-2199
Contact: Attn Kelly Herron, UNC Charlotte, Phone: 704-687-0567

Object: NC381153 - Boiler - Cleaver Brooks - 2010 - Equip Rm 42 - Active **Violations This Object:** 1

COMPANY: State of North Carolina
INSPECTOR: Smith, Jeremy
OPENED: 03/03/2021 **ENTERED BY:** Smith, Jeremy
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 8/26/2019.
REQUIREMENT: 363. Undefined Boiler Violations. An External Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.

Location: (UNCC) Regional Utility Plt 1 **Location #:** 1930002 **Violations:** 1
9201 University City Blvd, , Charlotte, NC 28223-0001, Phone: 704-687-6993
Contact: Attn Kelly Herron, UNC Charlotte, Phone: 704-687-0567

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC328646 - Boiler - Hurst - 2002 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Clay, Steven D.

OPENED: 02/10/2021

ENTERED BY: Putek, Terry

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 16-Boiler Components

SUBCATEGORY 275. Tube/tube ends leak.

CONDITION: 275. Boiler Components: Tube/tube ends leak. Boiler is down for repairs.

REQUIREMENT: 275. Repair the leaking tubes/tube ends. If weld repairs are required, a qualified "R" certificate holder is necessary to perform the work.

Location: (UNCC) Student Activity Center

Location #: 1929965

Violations: 1

9201 University City Blvd, , Charlotte, NC 28223-0001, Phone: 704-687-6993

Contact: Attn Kelly Herron, UNC Charlotte, Phone: 704-687-0567

Object: NC305359 - Boiler - Teledyne Laars - 1995 - 3rd Level - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Clay, Steven D.

OPENED: 02/10/2021

ENTERED BY: Putek, Terry

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409

SUBCATEGORY 003. Required manual reset low water cutoff device not installed.

CONDITION: 003. LWCO and Flow Sensing Devices NCAC 13-13.0409: Required manual reset low water cutoff device not installed.

REQUIREMENT: 003. Install a low-water fuel cutoff device (LWCO) designed for the appropriate service (Steam or Hot Water) that is equipped with a manual reset; or install a manual reset on the existing low water fuel cutoff if appropriate. When the LWCO shuts off the fuel supply to the boiler in the event of a low water condition, the fuel supply must be restarted manually by an operator. Test to ensure proper operation.

Location: (UNCG) Spartan Village

Location #: 3345775

Violations: 1

1001 Union St, , Greensboro, NC 27403-2841, Phone: 336-334-5684

Contact: Attn Jon Soter, UNC Greensboro, Phone: 336-256-0434, Cell:336-587-1440

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC394756 - Boiler - Aerco - 2012 - Bldg 3 Mech Rm 20 - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 04/07/2021 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409
SUBCATEGORY 006. Low water cutoff device inoperative or bypassed.
CONDITION: 006. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device inoperative or bypassed.
REQUIREMENT: 006. Repair or replace the inoperable low water fuel cutoff control and test to ensure proper operation.

Location: Acucote Inc **Location #:** 1762012 **Violations:** 1
910 E Elm St, , Graham, NC 27253-1908, Phone: 336-578-1800
Contact: Addison Gurganious, Process Engineer, Acucote Inc, Phone: 336-578-1800 X221

Object: NC394426 - Boiler - Weil-McLain - 2013 - Production Area - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 04/22/2021 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409
SUBCATEGORY 006. Low water cutoff device inoperative or bypassed.
CONDITION: 006. LWCO and Flow Sensing Devices NCAC 13-13.0409: Secondary Low water cutoff (LWCO) device inoperative.
REQUIREMENT: 006. Repair or replace the inoperable low water fuel cutoff control and test to ensure proper operation.

Location: Boston Cleaners & Laundry **Location #:** 1769786 **Violations:** 1
2182 N Church St, , Burlington, NC 27217-3004, Phone: 336-226-9803
Contact: Attn Bill Robbins, Boston Cleaners & Laundry, Phone: 336-226-9803

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC371303 - Boiler - Parker - 2007 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Leonard, Shannon D.

OPENED: 12/18/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 03-Water Gauge Glass NCAC 13-13.0408

SUBCATEGORY 058. Leaking.

CONDITION: 058. Water Gauge Glass NCAC 13-13.0408: Leaking.

REQUIREMENT: 058. Repair or replace the leaking gauge and test to ensure proper operation.

Location: Clariant Corp West Plt

Location #: 292853

Violations: 2

625 E Catawba Ave, , Mount Holly, NC 28120-2270, Phone: 704-822-2168

Contact: Attn Dewayne Moore, Maintenance Planner, Clariant Corp West Plt, Phone: 704-822-2049, Cell:980-319-

Object: NC165549 - Boiler - Cleaver Brooks - 1976 - 250/500 HP Blr Rm - Active

Violations This Object: 1

COMPANY: State of North Carolina

INSPECTOR: Smith, Jeremy

OPENED: 03/03/2021

ENTERED BY: Smith, Jeremy

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 12/17/2019.

REQUIREMENT: 363. Undefined Boiler Violations. An External Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC237004 - Boiler - Cleaver Brooks - 1988 - 250/500 HP Blr Rm - Active **Violations This Object:** 1

COMPANY: State of North Carolina
INSPECTOR: Smith, Jeremy
OPENED: 03/03/2021 **ENTERED BY:** Smith, Jeremy
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 12/17/2019.
REQUIREMENT: 363. Undefined Boiler Violations. An External Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.

Location: CT Commercial Paper **Location #:** 1773959 **Violations:** 1
349 S Main St, , Oakboro, NC 28129-7719, Phone: 704-485-3212
Contact: Dave Delany, Maintenance Technician, CT Commercial Paper Llc, Phone: 704-485-3212

Object: NC414878 - Boiler - Cleaver Brooks - 2015 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Clay, Steven D.
OPENED: 03/24/2021 **ENTERED BY:** Putek, Terry
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 16-Boiler Components
SUBCATEGORY 274. Tubesheet leaks.
CONDITION: 274. Boiler Components: Tubesheet leaks. Leak noted in one tube left side of rear tubesheet.
REQUIREMENT: 274. Repair the leaking tubesheet. If weld repairs are required, a qualified "R" certificate holder is necessary to perform the work.

Location: Embassy Suites RDU Brier Creek **Location #:** 2698447 **Violations:** 1
8001 Arco Corporate Dr, , Raleigh, NC 27617-2010, Phone: 919-572-2200
Contact: Attn Gary Patel, Maintenance Mgr, Embassy Suites RDU Brier Creek, Phone: 919-484-0500

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC380858 - Boiler - State Industries - 2009 - Wtr Htr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: SORRENTINO, SEAN
OPENED: 02/25/2021 **ENTERED BY:** Keyes, Amanda
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 16-Boiler Components
SUBCATEGORY 270. Water Leaks.
CONDITION: 270. Boiler Components: Water Leaks.
REQUIREMENT: 270. Repair the water leaks identified on the inspection report.

Location: Five Star Cleaners **Location #:** 1789558 **Violations:** 2
623 E Dixie Dr, , Asheboro, NC 27203-7036, Phone: 336-625-5336
Contact: Attn Bong Cha, Five Star Cleaners, Phone: 336-625-5336, Cell:336-324-2764

Object: NC363284 - Boiler - Fulton - 2006 - Blr Rm - Active **Violations This Object:** 2

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 03/27/2021 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 03-Water Gauge Glass NCAC 13-13.0408
SUBCATEGORY 054. Glass is too cloudy to see water level.
CONDITION: 054. Water Gauge Glass NCAC 13-13.0408: Glass is too cloudy to see water level.
REQUIREMENT: 054. Clean or replace gauge glass with material designed for temperature and service.

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 03/27/2021 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 12-Casing, Stack Breeching and Flue
SUBCATEGORY 211. Combustion gas leaks.
CONDITION: 211. Casing, Stack Breeching and Flue: Combustion gas leaks: Potential combustion gas leak due to hole in stack at connection to boiler.
REQUIREMENT: 211. Repair all combustion gas leaks in the casing, stack breeching, or flue: Repair boiler stack in order to eliminate possible combustion gas leak.

Location: Fulton Family YMCA **Location #:** 1844837 **Violations:** 1
385 W Hanes Mill Rd, , Winston Salem, NC 27105-9626, Phone: 336-661-1093
Contact: There is no contact information available for this location.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC412588 - Boiler - Steamist - 2016 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 10/21/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations. Boiler not operating at time of inspection; could not test safety devices to verify proper operation.
REQUIREMENT: 363. Undefined Boiler Violations. Schedule a follow up inspection at a time when the boiler is operating so that the safety devices may be tested to verify proper operation. As an alternative a detailed service report or boiler log that includes documentation of the successful testing of the safety devices is also acceptable.

Location: Graham Dyeing & Finishing

Location #: 1793692

Violations: 1

240 Hawkins St, , Burlington, NC 27217-3926, Phone: 336-228-9981

Contact: Graham Dyeing & Finishing Inc, Phone: 336-228-9981

Object: NC079212 - Boiler - Cleaver Brooks - 1966 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 04/05/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 09-Bottom Blow and Drain Systems NCAC 13-13.0411
SUBCATEGORY 153. Valve(s) stem gland leaking.
CONDITION: 153. Bottom Blow and Drain Systems NCAC 13-13.0411: Slow opening blowdown valve leaking.
REQUIREMENT: 153. Repair by repacking and tightening the gland seal on the blowdown valve, or replace the leaking slow opening blowdown valve in order to correct this condition. If the replacement of the blowdown valve is required, the replacement valve must be rated for steam service and a minimum steam working pressure of 150 PSI.

Location: Hertford Baptist Church

Location #: 1796868

Violations: 1

124 W Market St, , Hertford, NC 27944-1151, Phone: 252-426-7460

Contact: Hertford Baptist Church, Phone: 252-426-7460

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC245123 - Boiler - Weil-McLain - 1990 - Blr Rm - Active

Violations This Object: 1

COMPANY: State of North Carolina

INSPECTOR: Harrell, Danny

OPENED: 03/08/2021

ENTERED BY: Harrell, Danny

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 16-Boiler Components

SUBCATEGORY 270. Water Leaks.

CONDITION: 270. Boiler Components: Water Leaks. Boiler is leaking between the rear two sections.

REQUIREMENT: 270. Repair the water leaks identified on the inspection report. Contact Danny Harrell @ 919-500-3098 when the repair is completed to schedule a re-inspection.

Location: High Country Tire & Service Station

Location #: 1797182

Violations: 1

8227 US Highway 441 S, , Sylva, NC 28779-7193, Phone: 828-586-0886

Contact: Attn Mickey & Sam McMahan, Owner, High Country Tire & Service Station, Phone: 828-586-0886

Object: NC390660 - PV - Steel Fab - 2010 - Shop - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Possidente, James

OPENED: 12/08/2020

ENTERED BY: Putek, Terry

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 07-Undefined Pressure Vessels Violations

SUBCATEGORY 479. Undefined Pressure Vessels Violations.

CONDITION: 479. Undefined Pressure Vessels Violations. Pressure switch cover missing. 230 volt live wires exposed.

REQUIREMENT: 479. Undefined Pressure Vessels Violations. Install a pressure switch cover.

Location: Hudson Building

Location #: 1799097

Violations: 1

118 W State St, , Black Mountain, NC 28711-3419, Phone: 828-669-8711

Contact: Attn J Richard Hudson III, Owner, Hudson Building, Phone: 828-669-8711, Cell:828-777-5711

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC148875 - Boiler - Burnham - 1975 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Possidente, James

OPENED: 12/10/2020

ENTERED BY: Putek, Terry

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 03-Water Gauge Glass NCAC 13-13.0408

SUBCATEGORY 057. Drain inoperative.

CONDITION: 057. Water Gauge Glass NCAC 13-13.0408: Drain inoperative. Sight glass drain inoperative because sight glass is upside down.

REQUIREMENT: 057. Repair or replace the inoperable drain valve on the gauge and test to ensure proper operation.

Location: James Sprunt Community College

Location #: 1801347

Violations: 1

133 James Sprunt Dr, , Kenansville, NC 28349-0398, Phone: 910-296-2400

Contact: Dennis Sutton, Maintenance Director, James Sprunt Community College, , Cell:910-290-0755

Object: NC305518 - Boiler - Burnham - 1997 - Helen Boyett Bldg Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Rudolph, Jay

OPENED: 04/13/2021

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 25-Operation of PRDs NCAC 13-13.0405

SUBCATEGORY 395. Valve leaking.

CONDITION: 395. Operation of PRDs NCAC 13-13.0405: Valve leaking: Pressure relief device leaking.

REQUIREMENT: 395. Repair system or pressure relief device or replace pressure relief device with a ASME/NB certified pressure relief device with a set pressure not to exceed the maximum allowable working pressure as noted by manufacturer, with a relief capacity of not less than 653,000 BTU/hr, and with a testing lever.

Location: Kernersville Family YMCA

Location #: 1845634

Violations: 2

1113 W Mountain St, , Kernersville, NC 27284-2125, Phone: 336-996-2231

Contact: There is no contact information available for this location.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC399650 - Boiler - Stemist - 2013 - Suana - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Leonard, Shannon D.

OPENED: 10/14/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. Boiler not operating at time of inspection; low water cutoff (LWCO) and pressure relief device (PRD) could not be tested to verify proper operation.

REQUIREMENT: 363. Undefined Boiler Violations. Schedule a reinspection at a time when the boiler is operating so that the LWCO and PRD may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the flow switch and PRD is also acceptable.

Object: NC418867 - Boiler - Teledyne Laars - 1998 - Hot Tub Wtr Htr - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler

INSPECTOR: Leonard, Shannon D.

OPENED: 10/14/2020

ENTERED BY: Judd, Janie

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. Boiler not operating at time of inspection; flow switch and pressure relief device (PRD) could not be tested to verify proper operation.

REQUIREMENT: 363. Undefined Boiler Violations. Schedule a reinspection at a time when the boiler is operating so that the flow switch and PRD may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the flow switch and PRD is also acceptable.

Location: Kim Dry Cleaners

Location #: 589892

Violations: 1

7463 Six Forks Rd, , Raleigh, NC 27615-6164, Phone: 919-916-5001

Contact: There is no contact information available for this location.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC430228 - Boiler - Fulton - 2020 - Blr 1 - Active

Violations This Object: 1

COMPANY: State of North Carolina

INSPECTOR: Fish, Emily

OPENED: 03/12/2021

ENTERED BY: Fish, Emily

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 13-Burners and Fuel Supply Systems

SUBCATEGORY 235. No emergency fuel shut off switch.

CONDITION: 235. Burners and Fuel Supply Systems: No emergency fuel shut off switch.

REQUIREMENT: 235. Install an emergency fuel shut off switch at each egress from the boiler room to shut off all fuel to the boilers.

Location: Krystal Cleaners

Location #: 1761037

Violations: 1

2645 N Main St Ste 100, , High Point, NC 27265-2886, Phone: 336-869-9594

Contact: Attn Sung Seo, Krystal Cleaners Inc, Phone: 336-869-9594

Object: NC412942 - Boiler - Fulton - 2017 - Blr Rm - Active

Violations This Object: 1

COMPANY: State of North Carolina

INSPECTOR: Smith, Jeremy

OPENED: 03/03/2021

ENTERED BY: Smith, Jeremy

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 5/7/2019.

REQUIREMENT: 363. Undefined Boiler Violations. An External Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.

Location: La Quinta Inn & Suites

Location #: 1804615

Violations: 4

2020 Griffith Rd, , Winston Salem, NC 27103-5509, Phone: 336-765-8777

Contact: Attn Kim Joyner, General Manager, La Quinta Inn & Suites, Phone: 336-765-8777

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC293074 - Boiler - A O Smith - 1998 - Blr Rm 2nd Flr - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 04/19/2021 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 06-Thermometer NCAC 13-13.0410
SUBCATEGORY 111. Thermometer inoperative.
CONDITION: 111. Thermometer NCAC 13-13.0410: Thermometer inoperative.
REQUIREMENT: 111. Replace inoperative thermometer at/in the boiler outlet to measure the temperature in degrees Fahrenheit of the water. The thermometer shall have a range of approximately 2 times the intended operating temperature but not less than 1 1/2 times the intended operating temperature, nor more than 4 times the intended operating temperature.

Object: NC394482 - PV - State Industries - 2013 - Blr Rm 2nd Flr - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 04/19/2021 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 04-Installation of PRDs NCAC 13-13.0405
SUBCATEGORY 459. Discharge piping too small.
CONDITION: 459. Installation of PRDs NCAC 13-13.0405: Discharge piping too small: Discharge piping too small: Pressure relief device (PRD) discharge header piping for this hot water storage tank and two others that are connected to the header is too small.
REQUIREMENT: 459. Replace the PRD discharge header piping with piping having a cross sectional area of 3 inches or greater in order to correct this condition.

Object: NC394483 - PV - State Industries - 2013 - Blr Rm 2nd Flr - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 04/19/2021 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 04-Installation of PRDs NCAC 13-13.0405
SUBCATEGORY 459. Discharge piping too small.
CONDITION: 459. Installation of PRDs NCAC 13-13.0405: Discharge piping too small: Discharge piping too small: Pressure relief device (PRD) discharge header piping for this hot water storage tank and two others that are connected to the header is too small.
REQUIREMENT: 459. Replace the PRD discharge header piping with piping having a cross sectional area of 3 inches or greater in order to correct this condition.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC394484 - PV - State Industries - 2013 - Blr Rm 2nd Flr - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 04/19/2021 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 04-Installation of PRDs NCAC 13-13.0405
SUBCATEGORY 459. Discharge piping too small.
CONDITION: 459. Installation of PRDs NCAC 13-13.0405: Discharge piping too small: Pressure relief device (PRD) discharge header piping for this hot water storage tank and two others that are connected to the header is too small.
REQUIREMENT: 459. Replace the PRD discharge header piping with piping having a cross sectional area of 3 inches or greater in order to correct this condition.

Location: Longleaf Neuro Medical Treatment Center **Location #:** 1813141 **Violations:** 1
4761 Ward Blvd, , Wilson, NC 27893-4359, Phone: 252-399-2112
Contact: There is no contact information available for this location.

Object: NC220872 - Boiler - Cleaver Brooks - 1987 - Blr Rm 3 - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: SORRENTINO, SEAN
OPENED: 03/15/2021 **ENTERED BY:** Keyes, Amanda
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 16-Boiler Components
SUBCATEGORY 275. Tube/tube ends leak.
CONDITION: 275. Boiler Components: Tube/tube ends leak.
REQUIREMENT: 275. Repair the leaking tubes/tube ends. If weld repairs are required, a qualified "R" certificate holder is necessary to perform the work.

Location: Milkco Inc **Location #:** 482567 **Violations:** 1
220 Deaverview Rd, , Asheville, NC 28806-1710, Phone: 828-254-6851
Contact: Scott Willett, Maintenance, Milkco Inc, Phone: 828-400-0161

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC359767 - Boiler - Superior Boiler Works - 2005 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Possidente, James
OPENED: 03/08/2021 **ENTERED BY:** Putek, Terry
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 18-Furnace and Fireside
SUBCATEGORY 304. Furnace tube cracking.
CONDITION: 304. Furnace and Fireside: Furnace tube cracking. At least two tube ends cracked. First pass rear tube sheet.
REQUIREMENT: 304. Repair the crack in the furnace tube(s). If welding is required, a qualified "R" certificate holder is necessary to perform the work.

Location: Miller Coors Brewing Power House **Location #:** 3541901 **Violations:** 2
863 E Meadow Rd, , Eden, NC 27288-3636, Phone: 336-520-7897
Contact: Attn David Griffin, CEO, D H Griffin Companies, Phone: 336-855-7030

Object: NC399607 - Boiler - Babcock & Wilcox - 2014 - Blr 2 - Active **Violations This Object:** 1

COMPANY: State of North Carolina
INSPECTOR: Parker, Richard
OPENED: 03/11/2021 **ENTERED BY:** Parker, Richard
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Overdue for inspection.
REQUIREMENT: 363. Contact inspector and schedule inspection.

contact Richard Parker @ 336-202-8341

Object: NC399608 - Boiler - Babcock & Wilcox - 2013 - Blr 3 - Active **Violations This Object:** 1

COMPANY: State of North Carolina
INSPECTOR: Parker, Richard
OPENED: 03/11/2021 **ENTERED BY:** Parker, Richard
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Overdue for inspection.
REQUIREMENT: 363. Contact inspector and schedule inspection.

contact Richard Parker @ 336-202-8341

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Location: National Guard Armory **Location #:** 1813513 **Violations:** 2
292 NC Highway 65, , Reidsville, NC 27320-8897, Phone: 336-349-4428
Contact: Lee Lewis, National Guard Armory, Phone: 984-664-8009

Object: NC425270 - Boiler - Lochinvar - 2018 - Blr Rm - Active **Violations This Object:** 1

COMPANY: State of North Carolina
INSPECTOR: Parker, Richard
OPENED: 04/08/2020 **ENTERED BY:** Parker, Richard
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 25-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 391. Discharge piping not properly supported.
CONDITION: 391. Operation of PRDs NCAC 13-13.0405: Discharge piping not properly supported.
REQUIREMENT: 391. Support the relief valve discharge piping so it may not impose excessive stress on the relief valve.

Object: NC425271 - Boiler - Lochinvar - 2018 - Blr Rm - Active **Violations This Object:** 1

COMPANY: State of North Carolina
INSPECTOR: Parker, Richard
OPENED: 04/08/2020 **ENTERED BY:** Parker, Richard
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 25-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 391. Discharge piping not properly supported.
CONDITION: 391. Operation of PRDs NCAC 13-13.0405: Discharge piping not properly supported.
REQUIREMENT: 391. Support the relief valve discharge piping so it may not impose excessive stress on the relief valve.

contact Richard Parker @ 336-202-8341

Location: One Hour Klean **Location #:** 1816368 **Violations:** 1
1785 W Webb Ave, , Burlington, NC 27217-1141, Phone: 336-228-8013
Contact: Attn Jeff Bowland, Manager, One Hour Klean Inc, Phone: 336-228-8013

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC296883 - Boiler - Hurst - 1999 - Blr Rm - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 04/02/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 25-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 395. Valve leaking.
CONDITION: 395. Operation of PRDs NCAC 13-13.0405: Valve leaking: Pressure relief device (PRD) leaking.
REQUIREMENT: 395. Replace the leaking PRD with an ASME/NB stamped PRD having a set pressure of 150 PSI or less and a relieving capacity of 863 pounds of steam per hour or more. The replacement PRD must be equipped with a try-lever and the PRD discharge must be piped full size to a safe location and properly supported.

Location: Paul J Rizzo Conference Center

Location #: 1817817

Violations: 1

150 Dubose Home Ln, , Chapel Hill, NC 27517-8944, Phone: 919-913-2098

Contact: There is no contact information available for this location.

Object: NC364029 - Boiler - Lochinvar - 2006 - Outside Dubose House - Active

Violations This Object: 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Ollison, Jr., James C.
OPENED: 06/11/2020
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 25-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 396. Missing nameplate.
CONDITION: 396. Operation of PRDs NCAC 13-13.0405: Missing nameplate.
REQUIREMENT: 396. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

Location: Quality Inn

Location #: 1779023

Violations: 1

1633 Winston Rd, , Jonesville, NC 28642-0126, Phone: 336-835-9400

Contact: Anita Darnell, Manager, Quality Inn, Phone: 336-835-9400

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC391771 - Boiler - A O Smith - 2013 - Blr Rm Bldg Left Side - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 04/20/2021 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 02-Pressure Gauges NCAC 13-13.0407
SUBCATEGORY 033. Inoperative.
CONDITION: 033. Pressure Gauges NCAC 13-13.0407: Inoperative: Combination temperature/pressure gauge inoperative.
REQUIREMENT: 033. Replace the inoperative combination temperature/pressure gauge. The replacement gauge must have a maximum measuring range of 1.5 to 4 times the normal operating temperature in degrees Fahrenheit and pressure in PSI of the boiler (Boiler maximum temperature and pressure rated at 250 degrees Fahrenheit and 160 psi)

Location: Sonesta ES Suites Charlotte **Location #:** 1832771 **Violations:** 2
7925 Forest Pine Dr, , Charlotte, NC 28273-4600, Phone: 704-527-6767
Contact: Attn Jessica Nugent, Sonesta ES Suites Charlotte, Phone: 704-954-4019

Object: NC395094 - PV - A O Smith - 2013 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Clay, Steven D.
OPENED: 03/22/2021 **ENTERED BY:** Putek, Terry
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 01-Installation
SUBCATEGORY 413. Cracking.
CONDITION: 413. Installation: Cracking. Leak at bottom of tank.
REQUIREMENT: 413. Repair the cracking. If welding is required, a qualified "R" certificate holder is necessary to perform the work.

Object: NC395095 - PV - A O Smith - 2013 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Clay, Steven D.
OPENED: 03/22/2021 **ENTERED BY:** Putek, Terry
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 01-Installation
SUBCATEGORY 413. Cracking.
CONDITION: 413. Installation: Cracking. Leak at bottom of tank.
REQUIREMENT: 413. Repair the cracking. If welding is required, a qualified "R" certificate holder is necessary to perform the work.

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Location: Statesville Family YMCA **Location #:** 1845601 **Violations:** 2
828 Wesley Dr, , Statesville, NC 28677-3355, Phone: 704-873-9622
Contact: Paxton Hix, Facilities Director, Statesville Family YMCA, , Cell:704-880-4915

Object: NC265007 - Boiler - Reimers - 1993 - Mens Steam Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 12/16/2020 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations. electrical steam generator not operating at time of inspection; safety controls could not be tested to verify proper operation.
REQUIREMENT: 363. Undefined Boiler Violations. Schedule a reinspection at a time when the electric steam generator is operating so that the safety controls may be tested to verify proper operation. As an alternative, a detailed service report or log that includes documentation of the successful testing of these controls is also acceptable.

Object: NC380587 - Boiler - Fulton - 2008 - Ladies Steam Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 12/16/2020 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations: electrical steam generator not operating at time of inspection; safety controls could not be tested to verify proper operation.
REQUIREMENT: 363. Undefined Boiler Violations. Schedule a reinspection at a time when the electric steam generator is operating so that the safety controls may be tested to verify proper operation. As an alternative, a detailed service report or log that includes documentation of the successful testing of these controls is also acceptable.

Location: Teds Laundromat **Location #:** 1835016 **Violations:** 3
114 E Main St, , Sylva, NC 28779-2810, Phone: 828-586-2910
Contact: Kevin Hensley, Manager, Teds Laundromat, Phone: 828-586-2910

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC411982 - Boiler - Sermeta - 2016 - Blr Rm - Active

Violations This Object: 3

COMPANY: Hartford Steam Boiler
INSPECTOR: Possidente, James
OPENED: 04/08/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 02-Pressure Gauges NCAC 13-13.0407
SUBCATEGORY 035. Leaking.
CONDITION: 035. Pressure Gauges NCAC 13-13.0407: Leaking.
REQUIREMENT: 035. Install a pressure gauge on the equipment that is visible to the operator from the floor or work platform. Gauge must be the proper range in accordance with NC Administrative Code, Title 13, Chapter 13, Section .0407.

ENTERED BY: Putek, Terry

CLOSED BY:

COMPANY: Hartford Steam Boiler
INSPECTOR: Possidente, James
OPENED: 04/08/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 11-Exp Tanks & Htng Sys Piping NCAC 13-13.0412
SUBCATEGORY 197. Bladder in bladder-type tank perforated or not charged.
CONDITION: 197. Exp Tanks & Htng Sys Piping NCAC 13-13.0412: Bladder in bladder-type tank perforated or not charged.
REQUIREMENT: 197. Repair or replace bladder/expansion tank with one designed and constructed to ASME Section VIII, Div 1 with an allowable working pressure of at least that of the system.

ENTERED BY: Putek, Terry

CLOSED BY:

COMPANY: Hartford Steam Boiler
INSPECTOR: Possidente, James
OPENED: 04/08/2021
CLOSED:
TYPE: Certificate Blocking
CATEGORY: 25-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 395. Valve leaking.
CONDITION: 395. Operation of PRDs NCAC 13-13.0405: Valve leaking.
REQUIREMENT: 395. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

ENTERED BY: Putek, Terry

CLOSED BY:

Location: Tryon Palace Historic Sites & Gardens

Location #: 1838022

Violations: 1

610 Pollock St, , New Bern, NC 28562-5614, Phone: 252-514-4900

Contact: Randy Gurley, Maintenance Supervisor, Tryon Palace Historic Sites & Gardens, Phone: 252-639-3551

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC326274 - Boiler - Weil-McLain - 2000 - Stanley House - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Rudolph, Jay
OPENED: 04/06/2021 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 01-LWCO and Flow Sensing Devices NCAC 13-13.0409
SUBCATEGORY 005. No provision to test low water cutoff device.
CONDITION: 005. LWCO and Flow Sensing Devices NCAC 13-13.0409: No provision to test low water cutoff device.
REQUIREMENT: 005. Equip the low water fuel cutoff device on the boiler with a vertical drain and blow-off valve assembly of not less than 3/4-inch nominal pipe size to allow for flushing and testing of the low water cutoff while the boiler is in operation.

Location: Twin Lakes Center **Location #:** 1838274 **Violations:** 1
100 Wade Coble Dr, , Burlington, NC 27215-9756, Phone: 336-538-1400
Contact: There is no contact information available for this location.

Object: NC363935 - Boiler - BBT - 2006 - Blr Rm - Active **Violations This Object:** 1

COMPANY: Hartford Steam Boiler
INSPECTOR: Leonard, Shannon D.
OPENED: 03/06/2021 **ENTERED BY:** Judd, Janie
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 25-Operation of PRDs NCAC 13-13.0405
SUBCATEGORY 395. Valve leaking.
CONDITION: 395. Operation of PRDs NCAC 13-13.0405: Pressure Relief device (PRD) leaking.
REQUIREMENT: 395. Replace the leaking PRD with an ASME/NB stamped PRD having a set pressure of 58 PSI or less and a relieving capacity of 249,000 BTU/Hour or more. The replacement PRD must be equipped with a try lever and the PRD discharge must be piped full-size to a safe location (I.E. within 6" of the mechanical room floor).

Location: Valdese Weavers **Location #:** 1222894 **Violations:** 1
705 Lovelady Rd NE, , Valdese, NC 28690-8856, Phone: 828-874-2181
Contact: Attn Lonnie Porter, Maintenance Mgr, Valdese Weavers Inc, Phone: 828-874-2181

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC246193 - Boiler - Superior Boiler Works - 1991 - Blr Rm - Active **Violations This Object:** 1

COMPANY: State of North Carolina
INSPECTOR: Smith, Jeremy
OPENED: 03/03/2021 **ENTERED BY:** Smith, Jeremy
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 23-Undefined Boiler Violations
SUBCATEGORY 363. Undefined Boiler Violations.
CONDITION: 363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 2/18/2019.
REQUIREMENT: 363. Undefined Boiler Violations. An External Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.

Location: West German Garage **Location #:** 1842877 **Violations:** 1
5611 Hillsborough St, , Raleigh, NC 27606-1534, Phone: 919-851-1236
Contact: John Elliason, Manager, West German Garage Inc, Phone: 919-851-1236

Object: NC356708 - PV - Manchester - 1999 - Outside - Active **Violations This Object:** 1

COMPANY: State of North Carolina
INSPECTOR: Fish, Emily
OPENED: 10/15/2020 **ENTERED BY:** Fish, Emily
CLOSED: **CLOSED BY:**
TYPE: Certificate Blocking
CATEGORY: 09-Pressure Gauges NCAC 13-13.0407
SUBCATEGORY 032. Incorrect range or insufficient pointer travel.
CONDITION: 032. Pressure Gauges NCAC 13-13.0407: Incorrect range or insufficient pointer travel.

2/25/2021 Owner has the correct gauge, but it is not installed yet. Emily Fish
REQUIREMENT: 032. Install a pressure gauge on the equipment that is visible to the operator from the floor or work platform. Gauge must be the proper range in accordance with NC Administrative Code, Title 13, Chapter 13, Section .0407. Please call Emily Fish at (919) 268-0725 when ready for reinspection.

Location: Zoom Dry Cleaning **Location #:** 1816329 **Violations:** 1
200 W Peace St Ste 120, , Raleigh, NC 27603-1183, Phone: 919-838-8530
Contact: Lola Pedron, Manager, Zoom Dry Cleaning, Phone: 919-838-8530

Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

Object: NC373829 - Boiler - Fulton - 2007 - Blr Rm - Active

Violations This Object: 1

COMPANY: State of North Carolina

INSPECTOR: Smith, Jeremy

OPENED: 03/03/2021

ENTERED BY: Smith, Jeremy

CLOSED:

CLOSED BY:

TYPE: Certificate Blocking

CATEGORY: 23-Undefined Boiler Violations

SUBCATEGORY 363. Undefined Boiler Violations.

CONDITION: 363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 6/18/2019.

REQUIREMENT: 363. Undefined Boiler Violations. An External Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.

Violations This Report: 102

Locations This Report: 67