

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Location:** (ASU) Water Treatment Plt #602 **Location #:** 1880048 **Violations:** 2  
800 Rainbow Trl, , Boone, NC 28607-9339, Phone: 828-262-8633  
**Contact:** Attn Jeanette Lyons, Appalachian State University, Phone: 828-262-3190

**Object:** NC383403 - Boiler - Raypak - 2009 - Front Mech Rm Double Doors **Violations This Object:** 2  
- Active

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Hutchens, Mark  
**OPENED:** 05/05/2021 **ENTERED BY:** Hutchens, Mark  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations. E-Stop failed to lock out boiler when tested.  
**REQUIREMENT:** 363. Undefined Boiler Violations. Repair or replace E-Stop and tested operation make sure working correct on boiler.

**COMPANY:** State of North Carolina  
**INSPECTOR:** Hutchens, Mark  
**OPENED:** 05/05/2021 **ENTERED BY:** Hutchens, Mark  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 396. Missing nameplate.  
**CONDITION:** 396. Operation of PRDs NCAC 13-13.0405: Missing nameplate. Unable to read information on tag.  
**REQUIREMENT:** 396. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

---

**Location:** (ASV CS) Central Office **Location #:** 1775429 **Violations:** 2  
85 Mountain St, , Asheville, NC 28801-3854, Phone: 828-350-7000  
**Contact:** Tim Holcombe, Manager, Asheville City Schools, Phone: 828-350-7000/Maint 828-350-6196

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

**Object:** NC205160 - Boiler - Weil-McLain - 1982 - Blr Rm - Active

**Violations This Object:** 2

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 01/13/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409  
**SUBCATEGORY** 005. No provision to test low water cutoff device.  
**CONDITION:** 005. LWCO and Flow Sensing Devices NCAC 13-13.0409: No provision to test low water cutoff device.  
**REQUIREMENT:** 005. Equip the low water fuel cutoff device on the boiler with a vertical drain and blow-off valve assembly of not less than 3/4-inch nominal pipe size to allow for flushing and testing of the low water cutoff while the boiler is in operation.

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 01/13/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 24-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 372. Set pressure too high.  
**CONDITION:** 372. Installation of PRDs NCAC 13-13.0405: Set pressure too high. Mawp is 50 psi and SV #1 is 75 psi.  
**REQUIREMENT:** 372. Replace the pressure relieving device with one with a set pressure no higher than the maximum allowable working pressure as determined by the manufacturer.

---

**Location:** (ASV CS) Claxton Elem

**Location #:** 1777561

**Violations:** 3

241 Merrimon Ave, , Asheville, NC 28801-1217, Phone: 828-350-6500

**Contact:** Tim Holcombe, Manager, Asheville City Schools, Phone: 828-350-7000/Maint 828-350-6196

---

**Object:** NC262601 - Boiler - Weil-McLain - 1993 - Bsmt - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 01/13/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409  
**SUBCATEGORY** 005. No provision to test low water cutoff device.  
**CONDITION:** 005. LWCO and Flow Sensing Devices NCAC 13-13.0409: No provision to test low water cutoff device.  
**REQUIREMENT:** 005. Equip the low water fuel cutoff device on the boiler with a vertical drain and blow-off valve assembly of not less than 3/4-inch nominal pipe size to allow for flushing and testing of the low water cutoff while the boiler is in operation.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC262602 - Boiler - Weil-McLain - 1993 - Blr Rm - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 01/13/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409  
**SUBCATEGORY** 005. No provision to test low water cutoff device.  
**CONDITION:** 005. LWCO and Flow Sensing Devices NCAC 13-13.0409: No provision to test low water cutoff device.  
**REQUIREMENT:** 005. Equip the low water fuel cutoff device on the boiler with a vertical drain and blow-off valve assembly of not less than 3/4-inch nominal pipe size to allow for flushing and testing of the low water cutoff while the boiler is in operation.

**ENTERED BY:** Putek, Terry

**CLOSED BY:**

---

**Object:** NC388477 - PV - Lochinvar - 2006 - Cafeteria Blr Rm - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 01/13/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 04-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 461. Incorrect pressure relieving device(s) for the application.  
**CONDITION:** 461. Installation of PRDs NCAC 13-13.0405: Incorrect pressure relieving device(s) for the application. The current valve is pressure only mounted horizontal.  
**REQUIREMENT:** 461. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

**ENTERED BY:** Putek, Terry

**CLOSED BY:**

---

**Location:** (ASV CS) Ira B Jones Elem

**Location #:** 1800336

**Violations:** 1

544 Kimberly Ave, , Asheville, NC 28804-2560, Phone: 828-350-6700

**Contact:** Tim Holcombe, Manager, Asheville City Schools, Phone: 828-350-7000/Maint 828-350-6196

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC288783 - Boiler - Weil-McLain - 1996 - New Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 01/12/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409  
**SUBCATEGORY** 005. No provision to test low water cutoff device.  
**CONDITION:** 005. LWCO and Flow Sensing Devices NCAC 13-13.0409: No provision to test low water cutoff device.  
**REQUIREMENT:** 005. Equip the low water fuel cutoff device on the boiler with a vertical drain and blow-off valve assembly of not less than 3/4-inch nominal pipe size to allow for flushing and testing of the low water cutoff while the boiler is in operation. Recommend installing probe type LWCO with test and reset button to allow testing the device.

---

**Location:** (ASV CS) Vance Elem **Location #:** 1839986 **Violations:** 1  
98 Sulphur Springs Rd, , Asheville, NC 28806-2646, Phone: 828-250-6600  
**Contact:** Tim Holcombe, Manager, Asheville City Schools, Phone: 828-350-7000/Maint 828-350-6196

---

**Object:** NC221780 - Boiler - Weil-McLain - 1986 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 01/13/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409  
**SUBCATEGORY** 005. No provision to test low water cutoff device.  
**CONDITION:** 005. LWCO and Flow Sensing Devices NCAC 13-13.0409: No provision to test low water cutoff device.  
**REQUIREMENT:** 005. Equip the low water fuel cutoff device on the boiler with a vertical drain and blow-off valve assembly of not less than 3/4-inch nominal pipe size to allow for flushing and testing of the low water cutoff while the boiler is in operation.

---

**Location:** (BEAUFORT CO) County Courthouse **Location #:** 1780498 **Violations:** 1  
112 W 2nd St, , Washington, NC 27889-4940, Phone: 252-946-9629  
**Contact:** Beaufort County Government, Phone: 252-946-9624

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC420619 - Boiler - Kiturami - 2016 - Bsmt Left Rear - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 04/06/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 24-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 372. Set pressure too high.  
**CONDITION:** 372. Installation of PRDs NCAC 13-13.0405: Set pressure too high.  
**REQUIREMENT:** 372. Replace pressure relief device with a ASME/NB certified pressure relief device with a set pressure of not greater than 30 psig, with a relief capacity of not less than 200,000 BTU/hr and with a testing lever installed

---

**Location:** (CARTERET CS) Newport Elem **Location #:** 1814584 **Violations:** 1  
219 Chatham St, , Newport, NC 28570-8514, Phone: 252-223-4201  
**Contact:** Carteret County Public Schools, Phone: 252-728-5115

---

**Object:** NC372175 - Boiler - Weil-McLain - 2008 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 05/06/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 395. Valve leaking.  
**CONDITION:** 395. Operation of PRDs NCAC 13-13.0405: Valve leaking: Pressure relief device leaking  
**REQUIREMENT:** 395. Replace the pressure relief device with a ASME/NB certified pressure relief device with a set pressure not exceeding 50 psig, with a relief capacity of not less than 2452 KBH, and with a testing lever.

---

**Location:** (CRAVEN CS) Bridgeton Elem **Location #:** 1770407 **Violations:** 3  
230 Branch Canal Rd, , New Bern, NC 28560-7624, Phone: 252-514-6425  
**Contact:** Craven County Public Schools, Phone: 252-514-6380

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC346263 - Boiler - Weil-McLain - 2003 - Blr Rm - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 04/07/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409  
**SUBCATEGORY** 006. Low water cutoff device inoperative or bypassed.  
**CONDITION:** 006. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device inoperative or bypassed.  
**REQUIREMENT:** 006. Repair or replace the inoperable low water fuel cutoff control and test to ensure proper operation.

**ENTERED BY:** Judd, Janie

**CLOSED BY:**

---

**Object:** NC346265 - PV - Rheem/Ruud - 2002 - Blr Rm - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 04/07/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 10-Thermometer NCAC 13-13.0410  
**SUBCATEGORY** 110. Thermometer not installed.  
**CONDITION:** 110. Thermometer NCAC 13-13.0410: Thermometer not installed.  
**REQUIREMENT:** 110. Install a thermometer at/in the vessel outlet to measure the temperature in degrees Fahrenheit of the water. The thermometer shall have a range of approximately 2 times the intended operating temperature but not less than 1 1/2 times the intended operating temperature, nor more than 4 times the intended operating temperature.

**ENTERED BY:** Judd, Janie

**CLOSED BY:**

---

**Object:** NC346266 - PV - Rheem/Ruud - 1999 - Blr Rm - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 04/07/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 10-Thermometer NCAC 13-13.0410  
**SUBCATEGORY** 110. Thermometer not installed.  
**CONDITION:** 110. Thermometer NCAC 13-13.0410: Thermometer not installed.  
**REQUIREMENT:** 110. Install a thermometer at/in the vessel outlet to measure the temperature in degrees Fahrenheit of the water. The thermometer shall have a range of approximately 2 times the intended operating temperature but not less than 1 1/2 times the intended operating temperature, nor more than 4 times the intended operating temperature.

**ENTERED BY:** Judd, Janie

**CLOSED BY:**

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Location:** (CRAVEN CS) Creekside Elem **Location #:** 2157338 **Violations:** 4  
2790 Old Airport Rd, , New Bern, NC 28562-8734, Phone: 252-514-4360  
**Contact:** Craven County Public Schools, Phone: 252-514-6380

**Object:** NC367471 - Boiler - Weil-McLain - 2007 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 04/08/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 270. Water Leaks.  
**CONDITION:** 270. Boiler Components: Water Leaks.  
**REQUIREMENT:** 270. Repair the leak identified at the bottom between the last two boiler sections.

**Object:** NC367472 - Boiler - Weil-McLain - 2007 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 04/08/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 395. Valve leaking.  
**CONDITION:** 395. Operation of PRDs NCAC 13-13.0405: Valve leaking: Pressure relief device leaking.  
**REQUIREMENT:** 395. Repair or replace pressure relief device with a ASME/NB certified pressure relief device with a set pressure of not greater than 50 psig, with a relief capacity of not less than 1,358,000 BTU/hr, and a testing lever

**Object:** NC367473 - Boiler - A O Smith - 2007 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 04/08/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 06-Thermometer NCAC 13-13.0410  
**SUBCATEGORY** 110. Thermometer not installed.  
**CONDITION:** 110. Thermometer NCAC 13-13.0410: Thermometer not installed.  
**REQUIREMENT:** 110. Install a thermometer at/in the boiler outlet to measure the temperature in degrees Fahrenheit of the water. The thermometer shall have a range of approximately 2 times the intended operating temperature but not less than 1 1/2 times the intended operating temperature, nor more than 4 times the intended operating temperature.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

**Object:** NC367474 - Boiler - A O Smith - 2007 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 04/08/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 06-Thermometer NCAC 13-13.0410  
**SUBCATEGORY** 110. Thermometer not installed.  
**CONDITION:** 110. Thermometer NCAC 13-13.0410: Thermometer not installed.  
**REQUIREMENT:** 110. Install a thermometer at/in the boiler outlet to measure the temperature in degrees Fahrenheit of the water. The thermometer shall have a range of approximately 2 times the intended operating temperature but not less than 1 1/2 times the intended operating temperature, nor more than 4 times the intended operating temperature.

**ENTERED BY:** Judd, Janie

**CLOSED BY:**

**Location:** (CRAVEN CS) Graham A Barden Elem

**Location #:** 1793675

**Violations:** 2

200 Cedar Dr, , Havelock, NC 28532-2187, Phone: 252-444-5100

**Contact:** Craven County Public Schools, Phone: 252-514-6380

**Object:** NC229320 - Boiler - Weil-McLain - 1988 - Blr Rm - Active

**Violations This Object:** 2

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 04/08/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations: Boiler not running.  
**REQUIREMENT:** 363. Undefined Boiler Violations. Reschedule inspection for a time when the boiler can be run so safety devices can be verified to operate properly. If repairs cannot be completed in a timely fashion, or repairs are not be performed, disconnect the boiler.

**ENTERED BY:** Judd, Janie

**CLOSED BY:**

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Rudolph, Jay

**OPENED:** 04/08/2021

**CLOSED:**

**TYPE:** Certificate Blocking

**CATEGORY:** 24-Installation of PRDs NCAC 13-13.0405

**SUBCATEGORY** 371. Inadequate relieving capacity.

**CONDITION:** 371. Installation of PRDs NCAC 13-13.0405: Inadequate relieving capacity.

**REQUIREMENT:** 371. Replace one or both pressure relief devices to obtain a capacity of not less than 3550 PPH. Set pressures are to be no greater than 50 psig, and a testing lever be installed on each pressure relief device.

**ENTERED BY:** Judd, Janie

**CLOSED BY:**

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Location:** (CRAVEN CS) Havelock Elem **Location #:** 1814386 **Violations:** 1  
201 Cunningham Blvd, , Havelock, NC 28532-1908, Phone: 252-444-5106  
**Contact:** Craven County Public Schools, Phone: 252-514-6380

**Object:** NC412018 - Boiler - Rheem/Ruud - 2016 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 04/08/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 06-Thermometer NCAC 13-13.0410  
**SUBCATEGORY** 110. Thermometer not installed.  
**CONDITION:** 110. Thermometer NCAC 13-13.0410: Thermometer not installed.  
**REQUIREMENT:** 110. Install a thermometer at/in the boiler outlet to measure the temperature in degrees Fahrenheit of the water. The thermometer shall have a range of approximately 2 times the intended operating temperature but not less than 1 1/2 times the intended operating temperature, nor more than 4 times the intended operating temperature.

---

**Location:** (CRAVEN CS) J T Barber Elem **Location #:** 1801046 **Violations:** 1  
1700 Cobb St, , New Bern, NC 28560-3536, Phone: 252-514-6460  
**Contact:** Craven County Public Schools, Phone: 252-514-6380

**Object:** NC263863 - Boiler - Weil-McLain - 1996 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 04/07/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 394. Valve inoperative.  
**CONDITION:** 394. Operation of PRDs NCAC 13-13.0405: Valve inoperative.  
**REQUIREMENT:** 394. Replace pressure relieve devices with ASME/NB certified pressure relief device with a set pressure of not greater than 15 psig, with a combined relieve capacity of not less than 3270 PPH and with testing levers installed.

---

**Location:** (CRAVEN CS) Tucker Creek Middle **Location #:** 1838064 **Violations:** 3  
200 Sermons Rd, , Havelock, NC 28532-7707, Phone: 252-444-7200  
**Contact:** Craven County Public Schools, Phone: 252-514-6380

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC282746 - Boiler - Weil-McLain - 1997 - Blr Rm Rear Cafeteria - **Violations This Object:** 1  
Active

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 04/08/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations: Boiler not operating.  
**REQUIREMENT:** 363. Undefined Boiler Violations. Reschedule inspection for a time when the boiler is operating so that safety devices can be verified to operate properly.

**Object:** NC282747 - Boiler - Weil-McLain - 1997 - Blr Rm Rear Cafeteria - **Violations This Object:** 1  
Active

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 04/08/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations: Boiler not operating.  
**REQUIREMENT:** 363. Undefined Boiler Violations: Reschedule inspection for a time when the boiler is operating so that safety devices can be verified to operate properly.

**Object:** NC386070 - PV - Trane - 2007 - Outside Chillers Cafeteria - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 04/08/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 04-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 460. Seals broken/ missing.  
**CONDITION:** 460. Installation of PRDs NCAC 13-13.0405: Seals broken/ missing: Pressure relief device tamper seal broken.  
**REQUIREMENT:** 460. Replace pressure relief device. Set pressure not to be greater than 200 psig and with adequate capacity.

---

**Location:** (DPS-C) Columbus CI - 4355 **Location #:** 1778917 **Violations:** 2  
1255 Prison Camp Rd, , Whiteville, NC 28472-4887, Phone: 910-642-3285  
**Contact:** NC Dept Of Public Safety - 13101, Phone: 919-716-3422

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

**Object:** NC382455 - Boiler - Cleveland Range - 2010 - Food Service - Active **Violations This Object:** 2

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 11/24/2020 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 03-Water Gauge Glass NCAC 13-13.0408  
**SUBCATEGORY** 058. Leaking.  
**CONDITION:** 058. Water Gauge Glass NCAC 13-13.0408: Leaking.  
**REQUIREMENT:** 058. Repair or replace the leaking gauge and test to ensure proper operation.

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 11/24/2020 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 395. Valve leaking.  
**CONDITION:** 395. Operation of PRDs NCAC 13-13.0405: Valve leaking: Pressure relief device leaking.  
**REQUIREMENT:** 395. Replace with a ASME/NB certified pressure relief device with a set pressure of not greater than 15 psig, with a relief capacity of not less than 266 PPH, and with a testing lever installed.

---

**Location:** (DPS-C) Craggy CC - 4630 **Location #:** 1786753 **Violations:** 1  
2992 Riverside Dr, , Asheville, NC 28804-8601, Phone: 828-645-5315  
**Contact:** Mike Ball, Assistant Superintendant Custy/Pps, Craggy CC - 4630, Phone: 828-645-5315 X225

**Object:** NC337255 - PV - American - 2001 - Bldg 3 Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 05/10/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 07-Undefined Pressure Vessels Violations  
**SUBCATEGORY** 479. Undefined Pressure Vessels Violations.  
**CONDITION:** 479. Undefined Pressure Vessels Violations. Water leaking from upper shell at PRV nipple area.  
**REQUIREMENT:** 479. Undefined Pressure Vessels Violations. Repair the water leaks identified.

---

**Location:** (DPS-C) NCCIW - 3010 **Location #:** 1779964 **Violations:** 2  
1034 Bragg St, , Raleigh, NC 27610-3846, Phone: 919-733-4340  
**Contact:** Phillip Jones, Maintenance Supervisor, NCCIW - 3010, Phone: 919-508-1690

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC381483 - Boiler - PVI Industries - 2010 - Falcom Blr Rm - Active **Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** SORRENTINO, SEAN  
**OPENED:** 12/08/2020 **ENTERED BY:** Keyes, Amanda  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 270. Water Leaks.  
**CONDITION:** 270. Boiler Components: Water Leaks.  
**REQUIREMENT:** 270. Repair the water leaks identified on the inspection report. If welding is required, a qualified "R" certificate holder is necessary to perform the repair.

---

**Object:** NC401596 - Boiler - PVI Industries - 2014 - Sparrow N - Active **Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** SORRENTINO, SEAN  
**OPENED:** 12/08/2020 **ENTERED BY:** Keyes, Amanda  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 270. Water Leaks.  
**CONDITION:** 270. Boiler Components: Water Leaks. Tank leaking at unknown location.  
**REQUIREMENT:** 270. Repair the water leaks identified on the inspection report. If welding is required, a qualified "R" certificate holder is necessary to perform the repair.

---

**Location:** (ELCPPS) Central Elem **Location #:** 1775353 **Violations:** 1  
1059 US Highway 17 S, , Elizabeth City, NC 27909-7628, Phone: 252-335-4306  
**Contact:** Marlean Wiltens, Director of Maintenance, Elizabeth City Pasquotank Public Schools, Phone: 252-335-

---

**Object:** NC259109 - PV - Reco - 1992 - Blr Rm - Active **Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Richey, Paul D.  
**OPENED:** 04/27/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 07-Undefined Pressure Vessels Violations  
**SUBCATEGORY** 479. Undefined Pressure Vessels Violations.  
**CONDITION:** 479. Undefined Pressure Vessels Violations. The flange for the tube bundle is leaking on the tank.  
**REQUIREMENT:** 479. Undefined Pressure Vessels Violations. Replace the gasket to repair the leak.

---

**Location:** (LEE) O T Sloan Park **Location #:** 1815639 **Violations:** 2  
1420 Bragg St, , Sanford, NC 27330-5435, Phone: 919-775-2107  
**Contact:** Attn Russell Spivey, Lee County Government General Services, Phone: 919-718-4622

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC419417 - Boiler - Teledyne Laars - 2017 - Outside pool house - **Violations This Object:** 1  
Active

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Gunto III, Andrew  
**OPENED:** 10/20/2020 **ENTERED BY:** Gunto III, Andrew  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations.  
At the time of the 10/20/2020 inspection, this boiler was not in operation.  
**REQUIREMENT:** 363. Undefined Boiler Violations.  
At follow up inspection the boiler must be firing, and an operational demonstration will be need. This includes the verification of the high-limit temperature controls and its manual reset.

**Object:** NC419418 - Boiler - Teledyne Laars - 2017 - Outside pool house - **Violations This Object:** 1  
Active

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Gunto III, Andrew  
**OPENED:** 10/20/2020 **ENTERED BY:** Gunto III, Andrew  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations.  
At the time of the 10/20/2020 inspection, this boiler was not in operation.  
**REQUIREMENT:** 363. Undefined Boiler Violations.  
At follow up inspection the boiler must be firing, and an operational demonstration will be need. This includes the verification of the high-limit temperature controls and its manual reset.

---

**Location:** (MH UNIV) Brown Hall **Location #:** 1930569 **Violations:** 3  
150 Joe Anderson Dr, , Mars Hill, NC 28754 , Phone: 828-689-1201  
**Contact:** Attn Henry H Haywood, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:828-206-

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

**Object:** NC338996 - PV - LTC - 2002 - Bsmt Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 03/12/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 02-Manufacturer's Data Report & Nameplate  
**SUBCATEGORY** 431. Nameplate stamping is incorrect, missing, or illegible.  
**CONDITION:** 431. Manufacturer's Data Report & Nameplate: Nameplate stamping is incorrect, missing, or illegible. Dataplate could not be located.  
**REQUIREMENT:** 431. Obtain a replacement nameplate from the manufacturer or a replacement in accordance with the National Board Inspection Code. Locate nameplate and make visible for inspection.

**Object:** NC338997 - Boiler - Lochinvar - 2002 - Bsmt Blr Rm - Active

**Violations This Object:** 2

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 03/12/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 08-Main Steam System NCAC 13-13.0411  
**SUBCATEGORY** 126. Leaking pipe/pipe joints.  
**CONDITION:** 126. Main Steam System NCAC 13-13.0411: Leaking pipe/pipe joints.  
**REQUIREMENT:** 126. Repair or tighten leaking pipe/pipe joints.

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 03/12/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 12-Casing, Stack Breeching and Flue  
**SUBCATEGORY** 214. Excessive corrosion.  
**CONDITION:** 214. Casing, Stack Breeching and Flue: Excessive stack corrosion.  
**REQUIREMENT:** 214. Repair or replace the casing, stack breeching or flue.

**Location:** (MH UNIV) Day Hall

**Location #:** 3711212

**Violations:** 1

8 College St, , Mars Hill, NC 28754-0630, Phone: 828-689-1201

**Contact:** Attn Henry H Haywood, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:828-206-

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC406668 - Boiler - Sermeta - 2015 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 05/19/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 395. Valve leaking.  
**CONDITION:** 395. Operation of PRDs NCAC 13-13.0405: Valve leaking.  
**REQUIREMENT:** 395. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

---

**Location:** (MH UNIV) Gibson Hall **Location #:** 1930563 **Violations:** 1  
100 Joe Anderson Dr, , Mars Hill, NC 28754 , Phone: 828-689-1201  
**Contact:** Attn Henry H Haywood, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:828-206-

---

**Object:** NC099075 - Boiler - Weil-McLain - 1969 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 03/12/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 395. Valve leaking.  
**CONDITION:** 395. Operation of PRDs NCAC 13-13.0405: Valve leaking.  
**REQUIREMENT:** 395. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

---

**Location:** (MH UNIV) Huffman Hall **Location #:** 1930543 **Violations:** 1  
130 Womens Hill Dr, , Mars Hill, NC 28754 , Phone: 828-689-1201  
**Contact:** Attn Henry H Haywood, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:828-206-

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC403705 - PV - LTC - 2015 - Rm B11 - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 02/23/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 07-Undefined Pressure Vessels Violations  
**SUBCATEGORY** 479. Undefined Pressure Vessels Violations.  
**CONDITION:** 479. Undefined Pressure Vessels Violations. Pipe leaking.  
**REQUIREMENT:** 479. Undefined Pressure Vessels Violations. Repair or replace leaking piping/pipe joints.

---

**Location:** (MH UNIV) McConnell Hall

**Location #:** 1930553

**Violations:** 1

54 College St, , Mars Hill, NC 28754-0630, Phone: 828-689-1201

**Contact:** Attn Henry H Haywood, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:828-206-

---

**Object:** NC270792 - Boiler - Weil-McLain - 1994 - Blr Rm - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 02/23/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409  
**SUBCATEGORY** 006. Low water cutoff device inoperative or bypassed.  
**CONDITION:** 006. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device inoperative or bypassed.  
**REQUIREMENT:** 006. Repair or replace the inoperable low water fuel cutoff control and test to ensure proper operation.

---

**Location:** (MH UNIV) Pittman Dining Hall

**Location #:** 1930566

**Violations:** 1

121 Cascade St, , Mars Hill, NC 28754-9135, Phone: 828-689-1201

**Contact:** Attn Henry H Haywood, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:828-206-

---

**Object:** NC262680 - Boiler - Peerless - 1993 - Blr Rm - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 03/12/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 12-Casing, Stack Breaching and Flue  
**SUBCATEGORY** 211. Combustion gas leaks.  
**CONDITION:** 211. Casing, Stack Breaching and Flue: Combustion gas leaks.  
**REQUIREMENT:** 211. Repair all combustion gas leaks in the casing, stack breaching, or flue.

---

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Location:** (MH UNIV) Spilman Hall **Location #:** 1930544 **Violations:** 2  
50 College St, , Mars Hill, NC 28754-0630, Phone: 828-689-1201  
**Contact:** Attn Henry H Haywood, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:828-206-

**Object:** NC294827 - Boiler - Peerless - 1999 - Bsmt - Active **Violations This Object:** 2

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 05/19/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409  
**SUBCATEGORY** 009. Water level control inoperative or bypassed.  
**CONDITION:** 009. LWCO and Flow Sensing Devices NCAC 13-13.0409: Water level control inoperative or bypassed.  
**REQUIREMENT:** 009. Repair or replace the inoperable water level control and test to ensure proper operation.

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 05/19/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 12-Casing, Stack Breeching and Flue  
**SUBCATEGORY** 211. Combustion gas leaks.  
**CONDITION:** 211. Casing, Stack Breeching and Flue: Combustion gas leaks. Front and rear firebox sight glass broken.  
**REQUIREMENT:** 211. Repair all combustion gas leaks in the casing, stack breeching, or flue. Repair front and rear firebox sight glass.

---

**Location:** (MH UNIV) Stroup Hall **Location #:** 1930538 **Violations:** 2  
141 Womens Hill Dr, , Mars Hill, NC 28754 , Phone: 828-689-1201  
**Contact:** Attn Henry H Haywood, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:828-206-

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC323874 - Boiler - Teledyne Laars - 2000 - Bsmt - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 02/23/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409  
**SUBCATEGORY** 012. Flow switch inoperative or bypassed.  
**CONDITION:** 012. LWCO and Flow Sensing Devices NCAC 13-13.0409: Flow switch inoperative or bypassed. (Leaking)  
**REQUIREMENT:** 012. Install a flow switch that will shut off the fuel supply in case of stoppage of water flow or a low-water condition and test to ensure proper operation.

---

**Object:** NC325457 - Boiler - Peerless - 2000 - Bsmt - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 02/23/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409  
**SUBCATEGORY** 006. Low water cutoff device inoperative or bypassed.  
**CONDITION:** 006. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device inoperative or bypassed. Primary LWCO inoperative.  
**REQUIREMENT:** 006. Repair or replace the inoperable low water fuel cutoff control and test to ensure proper operation.

---

**Location:** (NC A&T) T E Neal Heating Plt **Location #:** 1834439 **Violations:** 1  
1601 E Market St, , Greensboro, NC 27411-0002, Phone: 336-334-7025  
**Contact:** Ricky Richmond, Facilities Manager, NC A & T State University, Phone: 336-285-4583, Cell:336-906-9620

---

**Object:** NC254988 - PV - East Fab - 1992 - Blr Rm 2nd Flr - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 05/20/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 01-Installation  
**SUBCATEGORY** 414. Pitting.  
**CONDITION:** 414. Installation: Corrosion/Pitting.  
**REQUIREMENT:** 414. Repair the pitting. If welding is required, a qualified "R" certificate holder is necessary to perform the work.

---

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Location:** (NCCU) Brite Bldg

**Location #:** 2239356

**Violations:** 7

202 E Lawson St, , Durham, NC 27707-3144, Phone: 919-201-1143

**Contact:** Attn Lori Blake Reid PO #P107428, NC Central University Shephard Station, Phone: 919-530-7244

**Object:** NC429694 - PV - Consolidated - 2008 - Rm 2129 B - Active

**Violations This Object:** 4

---

**COMPANY:** State of North Carolina

**INSPECTOR:** Gunto III, Andrew

**OPENED:** 04/29/2021

**ENTERED BY:** Gunto III, Andrew

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 04-Installation of PRDs NCAC 13-13.0405

**SUBCATEGORY** 458. Discharge opening directed improperly.

**CONDITION:** 458. Installation of PRDs NCAC 13-13.0405:

This vessel's safety valve vent is not piped to a safe location.

**REQUIREMENT:** 458. Redirect the discharge to a safe point as required in NCAC 13-13.0405

Pipe the safety valve vent so that it ends at between 1" and 6" from the floor or to a safe location out of the room.

**COMPANY:** State of North Carolina

**INSPECTOR:** Gunto III, Andrew

**OPENED:** 04/29/2021

**ENTERED BY:** Gunto III, Andrew

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 07-Undefined Pressure Vessels Violations

**SUBCATEGORY** 479. Undefined Pressure Vessels Violations.

**CONDITION:** 479. Undefined Pressure Vessels Violations.

This vessel has support brackets welded to its internal pressure boundary. Some of the of the welds are cracked or broken.

**REQUIREMENT:** 479. Undefined Pressure Vessels Violations.

Using a qualified company, ground and cracks smooth and perform a dye penetrant test to determine the pressure boundary is sound. Any welding must be done by an R Stamp holder.

**COMPANY:** State of North Carolina

**INSPECTOR:** Gunto III, Andrew

**OPENED:** 04/29/2021

**ENTERED BY:** Gunto III, Andrew

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 07-Undefined Pressure Vessels Violations

**SUBCATEGORY** 479. Undefined Pressure Vessels Violations.

**CONDITION:** 479. Undefined Pressure Vessels Violations.

This locks on this vessel's door are made up of lugs that engage the door jam while in the locked position. The lugs on the top of the door only engage the jam around ¼". While the lugs on the bottom of the door at 1".

**REQUIREMENT:** 479. Undefined Pressure Vessels Violations.

Adjust the doors vertical position in the jam so that lug engagement is even.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Gunto III, Andrew  
**OPENED:** 04/29/2021 **ENTERED BY:** Gunto III, Andrew  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 07-Undefined Pressure Vessels Violations  
**SUBCATEGORY** 479. Undefined Pressure Vessels Violations.  
**CONDITION:** 479. Undefined Pressure Vessels Violations.  
At the time of the 4/29/2021 inspection and operational demonstration was not completed.  
**REQUIREMENT:** 479. Undefined Pressure Vessels Violations.  
At follow up inspection an operational demonstration must be done.

**Object:** NC429695 - Boiler - Consolidated - 2008 - Rm 2129 B - Active **Violations This Object:** 3

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Gunto III, Andrew  
**OPENED:** 04/29/2021 **ENTERED BY:** Gunto III, Andrew  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 22-Installation  
**SUBCATEGORY** 362. Boiler room clearances.  
**CONDITION:** 362. Installation: Boiler room clearances.  
The 4/29/2021 inspection of this boiler was incomplete due to lack of access. The installation is such that, the minimum required clearances are not much to allow for inspection and maintenance.  
**REQUIREMENT:** 362. Provide clearances around the user servicable accesses of the boiler in accordance with NCAC 13-13.0413.

**COMPANY:** State of North Carolina  
**INSPECTOR:** Gunto III, Andrew  
**OPENED:** 04/29/2021 **ENTERED BY:** Gunto III, Andrew  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 24-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 378. Discharge opening directed improperly.  
**CONDITION:** 378. Installation of PRDs NCAC 13-13.0405:  
This vessel's safety valve vent is not piped to a safe location.  
**REQUIREMENT:** 378. Redirect the discharge to a safe point at required in NCAC 13-13.0405.  
Pipe the safety valve vent so that it ends at between 1" and 6" from the floor or to a safe location out of the room.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Gunto III, Andrew  
**OPENED:** 04/29/2021 **ENTERED BY:** Gunto III, Andrew  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 24-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 373. Inlet pipe too small.  
**CONDITION:** 373. Installation of PRDs NCAC 13-13.0405:  
This boilers safety valve is not attached directly to the boiler. The boilers safety valve must be no further than the length of it corresponding "t" from the boiler  
**REQUIREMENT:** 373. Reinstalled the boilers safety valve so that meets the requirements of ASME Sec I - PG-71.2

---

**Location:** (NCCU) Heating Plant **Location #:** 1796457 **Violations:** 1  
1801 Fayetteville St, , Durham, NC 27707-3129, Phone: 919-530-6313  
**Contact:** Attn Lori Blake Reid PO #P107428, NC Central University Shephard Station, Phone: 919-530-7244  
**Object:** NC293050 - Boiler - Babcock & Wilcox - 1998 - Blr House Blr 1 - **Violations This Object:** 1  
Active

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** SORRENTINO, SEAN  
**OPENED:** 11/18/2020 **ENTERED BY:** Keyes, Amanda  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. The boiler was not operating during this inspection per Sean Sorrentino inspection report.  
**REQUIREMENT:** 363. You must operate this boiler for external inspection per Sean Sorrentino inspection report.

---

**Location:** (NCCU) Mary Towne **Location #:** 1930626 **Violations:** 4  
1801 Fayetteville St, , Durham, NC 27707-3129, Phone: 919-530-6100  
**Contact:** Attn Lori Blake Reid PO #P107428, NC Central University Shephard Station, Phone: 919-530-7244

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

**Object:** NC429690 - PV - Consolidated - 2000 - Rm 2164 - Active

**Violations This Object:** 1

**COMPANY:** State of North Carolina  
**INSPECTOR:** Gunto III, Andrew  
**OPENED:** 04/29/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 07-Undefined Pressure Vessels Violations  
**SUBCATEGORY** 479. Undefined Pressure Vessels Violations.  
**CONDITION:** 479. Undefined Pressure Vessels Violations.  
During the 4/29/2021 inspection of NC429690 this vessel was under chamber pressure at onset of inspection. The chamber pressure gauge read approximately 5 psi. I was able to turn the door lock towards the open position and the door began to open. Steam from the chamber leaked around the doors seal. A later door lock test revealed that the door would open until the chamber pressure gauge read approximately 10 psi.

**ENTERED BY:** Gunto III, Andrew

**CLOSED BY:**

**REQUIREMENT:** 479. Undefined Pressure Vessels Violations.

Using a qualified repair company, repair is vessel so that its door will not open while under pressure.

**Object:** NC429691 - Boiler - UNKNOWN - 1800 - Rm 2164 - Active

**Violations This Object:** 1

**COMPANY:** State of North Carolina  
**INSPECTOR:** Gunto III, Andrew  
**OPENED:** 04/29/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 22-Installation  
**SUBCATEGORY** 362. Boiler room clearances.  
**CONDITION:** 362. Installation: Boiler room clearances.  
This boilers cabinet is installed in close quarters. The installation is such that, the minimum required clearances are not much to allow for inspection and maintenance.

**ENTERED BY:** Gunto III, Andrew

**CLOSED BY:**

**REQUIREMENT:** 362. Provide clearances around the user servicable accesses of the boiler in accordance with NCAC 13-13.0413.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC429692 - PV - Consolidated - 2010 - Rm 2174 - Active

**Violations This Object:** 1

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Gunto III, Andrew  
**OPENED:** 04/29/2021 **ENTERED BY:** Gunto III, Andrew  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 07-Undefined Pressure Vessels Violations  
**SUBCATEGORY** 479. Undefined Pressure Vessels Violations.  
**CONDITION:** 479. Undefined Pressure Vessels Violations.  
This vessel has support brackets welded to its internal pressure boundary. Some of the of the welds are cracked or broken.

**REQUIREMENT:** 479. Undefined Pressure Vessels Violations.  
Using a qualified company, ground and cracks smooth and perform a dye penetrant test to determine the pressure boundary is sound. Any welding must be done by an R Stamp holder.

---

**Object:** NC429693 - Boiler - UNKNOWN - 1800 - Rm 2174 - Active

**Violations This Object:** 1

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Gunto III, Andrew  
**OPENED:** 04/29/2021 **ENTERED BY:** Gunto III, Andrew  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 22-Installation  
**SUBCATEGORY** 362. Boiler room clearances.  
**CONDITION:** 362. Installation:  
This boilers cabinet is installed in close quarters. The installation is such that, the minimum required clearances are not much to allow for inspection and maintenance.

**REQUIREMENT:** 362. Provide clearances around the user servicable accesses of the boiler in accordance with NCAC 13-13.0413.

---

**Location:** (NCDOA) Museum Of Art

**Location #:** 1813946

**Violations:** 1

2110 Blue Ridge Rd, , Raleigh, NC 27607-6433, Phone: 919-839-6262

**Contact:** Chris Carter, Plant Maint Supervisor, Museum Of Art, Phone: 919-839-6262

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC375707 - Boiler - Fulton - 2008 - New Blr Rm - Active

**Violations This Object:** 1

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Smith, Jeremy  
**OPENED:** 03/03/2021 **ENTERED BY:** Smith, Jeremy  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 8/19/2019.  
**REQUIREMENT:** 363. Undefined Boiler Violations. An External Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.

---

**Location:** (NCSU) CVM Main Bldg 301-Z5

**Location #:** 3284982

**Violations:** 4

4700 Hillsborough St, , Raleigh, NC 27606-1428, Phone: 919-513-6485

**Contact:** Andrew Langdon, Manager, CVM Main Bldg 301-Z5, Phone: 919-513-6485

---

**Object:** NC268652 - PV - Amsco - 1994 - Rm C 301 - Active

**Violations This Object:** 2

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Fish, Emily  
**OPENED:** 04/07/2021 **ENTERED BY:** Fish, Emily  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 04-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 452. Set pressure too high.  
**CONDITION:** 452. Installation of PRDs NCAC 13-13.0405: Set pressure too high.  
**REQUIREMENT:** 452. Replace the pressure relieving device with one with a set pressure no higher than the maximum allowable working pressure as determined by the manufacturer.

**COMPANY:** State of North Carolina  
**INSPECTOR:** Fish, Emily  
**OPENED:** 04/07/2021 **ENTERED BY:** Fish, Emily  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 07-Undefined Pressure Vessels Violations  
**SUBCATEGORY** 479. Undefined Pressure Vessels Violations.  
**CONDITION:** 479. Undefined Pressure Vessels Violations. Door seals deteriorated.  
**REQUIREMENT:** 479. Undefined Pressure Vessels Violations. Replace door seals.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC268653 - PV - Amsco - 1994 - Rm C 301 - Active

**Violations This Object:** 1

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Fish, Emily  
**OPENED:** 04/07/2021 **ENTERED BY:** Fish, Emily  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 07-Undefined Pressure Vessels Violations  
**SUBCATEGORY** 479. Undefined Pressure Vessels Violations.  
**CONDITION:** 479. Undefined Pressure Vessels Violations. Door seals deteriorated.  
**REQUIREMENT:** 479. Undefined Pressure Vessels Violations. Replace door seals.

---

**Object:** NC400566 - PV - Amsco - 1979 - Bldg 301 Rm C303 - Active

**Violations This Object:** 1

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Fish, Emily  
**OPENED:** 04/07/2021 **ENTERED BY:** Fish, Emily  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 07-Undefined Pressure Vessels Violations  
**SUBCATEGORY** 479. Undefined Pressure Vessels Violations.  
**CONDITION:** 479. Undefined Pressure Vessels Violations. Door seal deteriorated.  
**REQUIREMENT:** 479. Undefined Pressure Vessels Violations. Replace door seals.

---

**Location:** (NCSU) Terry Companion Animal Medical Ctr CVM-Z5 **Location #:** 2930475 **Violations:** 2  
1052 William Moore Dr, , Raleigh, NC 27607-4065, Phone: 919-513-6485  
**Contact:** Andrew Langdon, Terry Companion Animal Medical Ctr, Phone: 919-513-6485

---

**Object:** NC384734 - PV - Bradford White - 2009 - Mech Rm 1480 - Active

**Violations This Object:** 2

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Fish, Emily  
**OPENED:** 04/06/2021 **ENTERED BY:** Fish, Emily  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 04-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 450. Pressure relieving devices not installed.  
**CONDITION:** 450. Installation of PRDs NCAC 13-13.0405: Pressure relieving devices not installed. PRDs on boilers accepted for hot water storage tank so no imminent danger.  
**REQUIREMENT:** 450. Install a pressure relieving device in accordance with NCAC 13-13.0405.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Fish, Emily  
**OPENED:** 04/06/2021 **ENTERED BY:** Fish, Emily  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 10-Thermometer NCAC 13-13.0410  
**SUBCATEGORY** 110. Thermometer not installed.  
**CONDITION:** 110. Thermometer NCAC 13-13.0410: Thermometer not installed.  
**REQUIREMENT:** 110. Install a thermometer at/in the vessel outlet to measure the temperature in degrees Fahrenheit of the water. The thermometer shall have a range of approximately 2 times the intended operating temperature but not less than 1 1/2 times the intended operating temperature, nor more than 4 times the intended operating temperature.

---

**Location:** (QUC) Heating Plant **Location #:** 1832784 **Violations:** 3  
1900 Selwyn Ave, , Charlotte, NC 28274-0001, Phone: 704-337-2200  
**Contact:** Queens University Of Charlotte, Phone: 704-337-2201

**Object:** NC068205 - Boiler - BE&S - 1963 - Blr Rm #4 - Active **Violations This Object:** 3

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Clay, Steven D.  
**OPENED:** 05/13/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409  
**SUBCATEGORY** 006. Low water cutoff device inoperative or bypassed.  
**CONDITION:** 006. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device inoperative or bypassed.  
**REQUIREMENT:** 006. Repair or replace the inoperable low water fuel cutoff control and test to ensure proper operation.

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Clay, Steven D.  
**OPENED:** 05/13/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 19-Waterside  
**SUBCATEGORY** 320. Accumulation of oil.  
**CONDITION:** 320. Waterside: Accumulation of oil.  
**REQUIREMENT:** 320. Clean the watersides of all oil contamination.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Clay, Steven D.  
**OPENED:** 05/13/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 394. Valve inoperative.  
**CONDITION:** 394. Operation of PRDs NCAC 13-13.0405: Valve inoperative.  
**REQUIREMENT:** 394. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

---

**Location:** (RRGSD) Roanoke Rapids High **Location #:** 1824808 **Violations:** 2  
800 Hamilton St, , Roanoke Rapids, NC 27870-2708, Phone: 252-519-7121  
**Contact:** Attn Robbie Clements, Maintenance Director, Roanoke Rapids City Schools, Phone: 252-578-4171

**Object:** NC048249 - Boiler - National US - 1959 - Gym Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** SORRENTINO, SEAN  
**OPENED:** 04/21/2021 **ENTERED BY:** Keyes, Amanda  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 395. Valve leaking.  
**CONDITION:** 395. Operation of PRDs NCAC 13-13.0405: Valve leaking.  
**REQUIREMENT:** 395. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

---

**Object:** NC423945 - Boiler - Weil-McLain - 2019 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** SORRENTINO, SEAN  
**OPENED:** 04/21/2021 **ENTERED BY:** Keyes, Amanda  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 24-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 371. Inadequate relieving capacity.  
**CONDITION:** 371. Installation of PRDs NCAC 13-13.0405: Inadequate relieving capacity.  
**REQUIREMENT:** 371. Replace the pressure relieving device with one with a capacity required by the boiler manufacturer.

---

**Location:** (SWAIN CS) Swain County High **Location #:** 1834129 **Violations:** 1  
1415 Fontana Rd, , Bryson City, NC 28713-6951, Phone: 828-488-2152  
**Contact:** John Haigler, Head Custodian, Swain County High, Phone: 828-488-2152

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC320171 - Boiler - Peerless - 1999 - New Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 04/19/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 13-Burners and Fuel Supply Systems  
**SUBCATEGORY** 232. Gas train has improper venting.  
**CONDITION:** 232. Burners and Fuel Supply Systems: Gas train has improper venting.  
**REQUIREMENT:** 232. Vent the gas train to a safe point .

---

**Location:** (UNCA) Carol Belk Theater **Location #:** 1903686 **Violations:** 1  
1 University Hts, , Asheville, NC 28804-3251, Phone: 828-251-6038  
**Contact:** Attn Jay Small, HVAC Supervisor, UNC Asheville, Phone: 828-250-3964

---

**Object:** NC299507 - Boiler - Lochinvar - 1999 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 04/06/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 270. Water Leaks.  
**CONDITION:** 270. Boiler Components: Water Leaks. Manifold flange leaking.  
**REQUIREMENT:** 270. Repair the water leaks identified on the inspection report.

---

**Location:** (UNCA) Founders Residence Hall **Location #:** 1903690 **Violations:** 2  
1 University Hts, , Asheville, NC 28804-3251, Phone: 828-251-6038  
**Contact:** Attn Jay Small, HVAC Supervisor, UNC Asheville, Phone: 828-250-3964

---

**Object:** NC203365 - Boiler - PVI Industries - 1981 - Highrise Dorm Equip Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 04/06/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 276. Manway gasket leaks.  
**CONDITION:** 276. Boiler Components: Manway gasket leaks.  
**REQUIREMENT:** 276. Replace the leaking manway gasket. If weld repairs are required to reestablish the seating surface, a qualified "R" certificate holder is necessary to perform the work.

---

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC203366 - Boiler - PVI Industries - 1981 - Highrise Dorm Equip Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 04/06/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 276. Manway gasket leaks.  
**CONDITION:** 276. Boiler Components: Manway gasket leaks.  
**REQUIREMENT:** 276. Replace the leaking manway gasket. If weld repairs are required to reestablish the seating surface, a qualified "R" certificate holder is necessary to perform the work.

---

**Location:** (UNCC) Belk Residence Hall **Location #:** 3337127 **Violations:** 2  
9201 University City Blvd, , Charlotte, NC 28223-0001, Phone: 704-687-2199  
**Contact:** Attn Kelly Herron, UNC Charlotte, Phone: 704-687-0567

---

**Object:** NC393689 - PV - Lochinvar - 2012 - Mech Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Clay, Steven D.  
**OPENED:** 05/07/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 05-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 474. Valve inoperative.  
**CONDITION:** 474. Operation of PRDs NCAC 13-13.0405: Valve inoperative. PRD capacity too low. Three boilers feed tank.  
**REQUIREMENT:** 474. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

---

**Object:** NC393690 - PV - Lochinvar - 2012 - Mech Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Clay, Steven D.  
**OPENED:** 05/07/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 05-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 474. Valve inoperative.  
**CONDITION:** 474. Operation of PRDs NCAC 13-13.0405: Valve inoperative. PRD capacity is too low. Three boilers feed tank.  
**REQUIREMENT:** 474. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Location:** (UNCC) Cameron Hall **Location #:** 2316833 **Violations:** 1  
9201 University City Blvd, , Charlotte, NC 28223-0001, Phone: 704-687-2199  
**Contact:** Attn Kelly Herron, UNC Charlotte, Phone: 704-687-0567

**Object:** NC381153 - Boiler - Cleaver Brooks - 2010 - Equip Rm 42 - Active **Violations This Object:** 1

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Smith, Jeremy  
**OPENED:** 03/03/2021 **ENTERED BY:** Smith, Jeremy  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 8/26/2019.  
**REQUIREMENT:** 363. Undefined Boiler Violations. An External Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.

---

**Location:** (UNCC) Regional Utility Plt 1 **Location #:** 1930002 **Violations:** 1  
9201 University City Blvd, , Charlotte, NC 28223-0001, Phone: 704-687-6993  
**Contact:** Attn Kelly Herron, UNC Charlotte, Phone: 704-687-0567

**Object:** NC328646 - Boiler - Hurst - 2002 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Clay, Steven D.  
**OPENED:** 02/10/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 275. Tube/tube ends leak.  
**CONDITION:** 275. Boiler Components: Tube/tube ends leak. Boiler is down for repairs.  
**REQUIREMENT:** 275. Repair the leaking tubes/tube ends. If weld repairs are required, a qualified "R" certificate holder is necessary to perform the work.

---

**Location:** (UNCC) Scott Hall **Location #:** 1930011 **Violations:** 1  
9201 University City Blvd, , Charlotte, NC 28223-0001, Phone: 704-687-2197  
**Contact:** Attn Kelly Herron, UNC Charlotte, Phone: 704-687-0567

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC383706 - PV - LTC - 2010 - Blr Rm - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Clay, Steven D.  
**OPENED:** 05/07/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 05-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 474. Valve inoperative.  
**CONDITION:** 474. Operation of PRDs NCAC 13-13.0405: Valve inoperative. PRD capacity is too low. Two boilers feed tank.  
**REQUIREMENT:** 474. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

---

**Location:** (UNCC) Student Activity Center

**Location #:** 1929965

**Violations:** 1

9201 University City Blvd, , Charlotte, NC 28223-0001, Phone: 704-687-6993

**Contact:** Attn Kelly Herron, UNC Charlotte, Phone: 704-687-0567

---

**Object:** NC305359 - Boiler - Teledyne Laars - 1995 - 3rd Level - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Clay, Steven D.  
**OPENED:** 02/10/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409  
**SUBCATEGORY** 003. Required manual reset low water cutoff device not installed.  
**CONDITION:** 003. LWCO and Flow Sensing Devices NCAC 13-13.0409: Required manual reset low water cutoff device not installed.  
**REQUIREMENT:** 003. Install a low-water fuel cutoff device (LWCO) designed for the appropriate service (Steam or Hot Water) that is equipped with a manual reset; or install a manual reset on the existing low water fuel cutoff if appropriate. When the LWCO shuts off the fuel supply to the boiler in the event of a low water condition, the fuel supply must be restarted manually by an operator. Test to ensure proper operation.

---

**Location:** (WILSON CO) Maintenance Bldg

**Location #:** 1844389

**Violations:** 1

113 Nash St E, , Wilson, NC 27893-4054, Phone: 252-399-2843

**Contact:** Attn Ted Boswell, Director of Maintenance, Wilson County Government, Phone: 252-265-5973

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC410051 - Boiler - Weil-McLain - 2017 - Bsmt Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Harrell, Danny  
**OPENED:** 05/12/2021 **ENTERED BY:** Harrell, Danny  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 09-Bottom Blow and Drain Systems NCAC 13-13.0411  
**SUBCATEGORY** 152. Valve(s) hand wheel or lever handle missing.  
**CONDITION:** 152. Bottom Blow and Drain Systems NCAC 13-13.0411: Valve(s) hand wheel or lever handle missing.  
**REQUIREMENT:** 152. Replace missing hand wheel or lever on bottom blow off valve. Contact Danny Harrell @ 919-500-3098 when the repair is completed to schedule a re-inspection.

---

**Location:** A Cleaner World #188 **Location #:** 1761476 **Violations:** 1  
2527 Eastchester Dr, , High Point, NC 27265-1448, Phone: 336-882-8621  
**Contact:** Attn Kevin Lawson, Maintenance, Tri State Laundry Equipment Co, Phone: 336-804-0031

**Object:** NC376430 - Boiler - Parker - 2008 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 05/13/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 03-Water Gauge Glass NCAC 13-13.0408  
**SUBCATEGORY** 058. Leaking.  
**CONDITION:** 058. Water Gauge Glass NCAC 13-13.0408: Leaking: Water gauge glass leaking.  
**REQUIREMENT:** 058. Repair or replace the leaking gauge and test to ensure proper operation.

---

**Location:** Clariant Corp West Plt **Location #:** 292853 **Violations:** 2  
625 E Catawba Ave, , Mount Holly, NC 28120-2270, Phone: 704-822-2168  
**Contact:** Attn Dewayne Moore, Maintenance Planner, Clariant Corp West Plt, Phone: 704-822-2049, Cell:980-319-

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC165549 - Boiler - Cleaver Brooks - 1976 - 250/500 HP Blr Rm - **Violations This Object:** 1  
Active

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Smith, Jeremy  
**OPENED:** 03/03/2021 **ENTERED BY:** Smith, Jeremy  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 12/17/2019.  
**REQUIREMENT:** 363. Undefined Boiler Violations. An External Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.

**Object:** NC237004 - Boiler - Cleaver Brooks - 1988 - 250/500 HP Blr Rm - **Violations This Object:** 1  
Active

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Smith, Jeremy  
**OPENED:** 03/03/2021 **ENTERED BY:** Smith, Jeremy  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 12/17/2019.  
**REQUIREMENT:** 363. Undefined Boiler Violations. An External Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.

---

**Location:** CT Commercial Paper **Location #:** 1773959 **Violations:** 1  
349 S Main St, , Oakboro, NC 28129-7719, Phone: 704-485-3212  
**Contact:** Dave Delany, Maintenance Technician, CT Commercial Paper Llc, Phone: 704-485-3212

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC414878 - Boiler - Cleaver Brooks - 2015 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Clay, Steven D.  
**OPENED:** 03/24/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 274. Tubesheet leaks.  
**CONDITION:** 274. Boiler Components: Tubesheet leaks. Leak noted in one tube left side of rear tubesheet.  
**REQUIREMENT:** 274. Repair the leaking tubesheet. If weld repairs are required, a qualified "R" certificate holder is necessary to perform the work.

---

**Location:** David Price Auto Works **Location #:** 1793444 **Violations:** 1  
603 Monroe St, , Eden, NC 27288-6110, Phone: 336-623-2460  
**Contact:** Attn David Price, Owner, David Price Auto Works Llc, Phone: 336-623-2460

---

**Object:** NC383120 - PV - Manchester - 2008 - Storage Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 05/17/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 04-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 452. Set pressure too high.  
**CONDITION:** 452. Installation of PRDs NCAC 13-13.0405: Set pressure too high: Pressure Relief Device (PRD) set pressure (175 PSI) exceeds maximum allowable working pressure of air tank (150 PSI)  
**REQUIREMENT:** 452. Replace the improperly sized PRD with an ASME/NB stamped PRD having a set pressure of 150 PSI or less and a relieving capacity of 25 SCFM or more. This air tank must remain out of service until a new properly rated PRD is installed.

---

**Location:** Embassy Suites RDU Brier Creek **Location #:** 2698447 **Violations:** 1  
8001 Arco Corporate Dr, , Raleigh, NC 27617-2010, Phone: 919-572-2200  
**Contact:** Attn Gary Patel, Maintenance Mgr, Embassy Suites RDU Brier Creek, Phone: 919-484-0500

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC380858 - Boiler - State Industries - 2009 - Wtr Htr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** SORRENTINO, SEAN  
**OPENED:** 02/25/2021 **ENTERED BY:** Keyes, Amanda  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 270. Water Leaks.  
**CONDITION:** 270. Boiler Components: Water Leaks.  
**REQUIREMENT:** 270. Repair the water leaks identified on the inspection report.

---

**Location:** First Baptist Church **Location #:** 1788723 **Violations:** 2  
503 Park St, , Swannanoa, NC 28778-3029, Phone: 828-553-4161  
**Contact:** First Baptist Church, Phone: 828-553-4161

---

**Object:** NC270780 - Boiler - Weil-McLain - 1994 - Blr Rm - Active **Violations This Object:** 2

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 04/26/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409  
**SUBCATEGORY** 009. Water level control inoperative or bypassed.  
**CONDITION:** 009. LWCO and Flow Sensing Devices NCAC 13-13.0409: Water level control inoperative or bypassed. LWCO failed to test properly.  
**REQUIREMENT:** 009. Repair or replace the inoperable water level control and test to ensure proper operation.

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 04/26/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 395. Valve leaking.  
**CONDITION:** 395. Operation of PRDs NCAC 13-13.0405: Valve leaking.  
**REQUIREMENT:** 395. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

---

**Location:** First Baptist Church **Location #:** 1788749 **Violations:** 1  
659 S Fayetteville St, , Liberty, NC 27298-3501, Phone: 336-622-4482  
**Contact:** Attn Cindy Carroll, First Baptist Church, Phone: 336-622-4482

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

**Object:** NC326006 - Boiler - Lochinvar - 1999 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 04/28/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 26-Undefined Pressure Relieving Devices Violations  
**SUBCATEGORY** 399. Undefined Pressure Relieving Devices Violations.  
**CONDITION:** 399. Undefined Pressure Relieving Devices Violations: PVC piping used for pressure relief device (PRD) discharge piping not suitable for use in this application.  
**REQUIREMENT:** 399. Undefined Pressure Relieving Devices Violations: Remove the improper PVC discharge piping and replace with proper black steel pipe or copper piping. The replacement PRD discharge plumbing must be piped full size to a safe location (I.E. with 6" of the boiler room floor) and properly supported.

**Location:** Fulton Family YMCA

**Location #:** 1844837

**Violations:** 1

385 W Hanes Mill Rd, , Winston Salem, NC 27105-9626, Phone: 336-661-1093

**Contact:** There is no contact information available for this location.

**Object:** NC412588 - Boiler - Steamist - 2016 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 10/21/2020 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations. Boiler not operating at time of inspection; could not test safety devices to verify proper operation.  
**REQUIREMENT:** 363. Undefined Boiler Violations. Schedule a follow up inspection at a time when the boiler is operating so that the safety devices may be tested to verify proper operation. As an alternative a detailed service report or boiler log that includes documentation of the successful testing of the safety devices is also acceptable.

**Location:** Hertford Baptist Church

**Location #:** 1796868

**Violations:** 1

124 W Market St, , Hertford, NC 27944-1151, Phone: 252-426-7460

**Contact:** Hertford Baptist Church, Phone: 252-426-7460

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC245123 - Boiler - Weil-McLain - 1990 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Harrell, Danny  
**OPENED:** 03/08/2021 **ENTERED BY:** Harrell, Danny  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 270. Water Leaks.  
**CONDITION:** 270. Boiler Components: Water Leaks. Boiler is leaking between the rear two sections.  
**REQUIREMENT:** 270. Repair the water leaks identified on the inspection report. Contact Danny Harrell @ 919-500-3098 when the repair is completed to schedule a re-inspection.

---

**Location:** Hudson Building **Location #:** 1799097 **Violations:** 1  
118 W State St, , Black Mountain, NC 28711-3419, Phone: 828-669-8711  
**Contact:** Attn J Richard Hudson III, Owner, Hudson Building, Phone: 828-669-8711, Cell:828-777-5711

---

**Object:** NC148875 - Boiler - Burnham - 1975 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 04/26/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 12-Casing, Stack Breeching and Flue  
**SUBCATEGORY** 211. Combustion gas leaks.  
**CONDITION:** 211. Casing, Stack Breeching and Flue: Combustion gas leaks. Flue has two small holes.  
**REQUIREMENT:** 211. Repair all combustion gas leaks in the casing, stack breeching, or flue.

---

**Location:** Kernersville Family YMCA **Location #:** 1845634 **Violations:** 2  
1113 W Mountain St, , Kernersville, NC 27284-2125, Phone: 336-996-2231  
**Contact:** There is no contact information available for this location.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC399650 - Boiler - Stemist - 2013 - Suana - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Leonard, Shannon D.

**OPENED:** 10/14/2020

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 23-Undefined Boiler Violations

**SUBCATEGORY** 363. Undefined Boiler Violations.

**CONDITION:** 363. Undefined Boiler Violations. Boiler not operating at time of inspection; low water cutoff (LWCO) and pressure relief device (PRD) could not be tested to verify proper operation.

**REQUIREMENT:** 363. Undefined Boiler Violations. Schedule a reinspection at a time when the boiler is operating so that the LWCO and PRD may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the flow switch and PRD is also acceptable.

---

**Object:** NC418867 - Boiler - Teledyne Laars - 1998 - Hot Tub Wtr Htr - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Leonard, Shannon D.

**OPENED:** 10/14/2020

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 23-Undefined Boiler Violations

**SUBCATEGORY** 363. Undefined Boiler Violations.

**CONDITION:** 363. Undefined Boiler Violations. Boiler not operating at time of inspection; flow switch and pressure relief device (PRD) could not be tested to verify proper operation.

**REQUIREMENT:** 363. Undefined Boiler Violations. Schedule a reinspection at a time when the boiler is operating so that the flow switch and PRD may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the flow switch and PRD is also acceptable.

---

**Location:** La Quinta Inn & Suites

**Location #:** 1804615

**Violations:** 4

2020 Griffith Rd, , Winston Salem, NC 27103-5509, Phone: 336-765-8777

**Contact:** Attn Kim Joyner, General Manager, La Quinta Inn & Suites, Phone: 336-765-8777

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC293074 - Boiler - A O Smith - 1998 - Blr Rm 2nd Flr - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 04/19/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 06-Thermometer NCAC 13-13.0410  
**SUBCATEGORY** 111. Thermometer inoperative.  
**CONDITION:** 111. Thermometer NCAC 13-13.0410: Thermometer inoperative.  
**REQUIREMENT:** 111. Replace inoperative thermometer at/in the boiler outlet to measure the temperature in degrees Fahrenheit of the water. The thermometer shall have a range of approximately 2 times the intended operating temperature but not less than 1 1/2 times the intended operating temperature, nor more than 4 times the intended operating temperature.

---

**Object:** NC394482 - PV - State Industries - 2013 - Blr Rm 2nd Flr - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 04/19/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 04-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 459. Discharge piping too small.  
**CONDITION:** 459. Installation of PRDs NCAC 13-13.0405: Discharge piping too small: Discharge piping too small: Pressure relief device (PRD) discharge header piping for this hot water storage tank and two others that are connected to the header is too small.  
**REQUIREMENT:** 459. Replace the PRD discharge header piping with piping having a cross sectional area of 3 inches or greater in order to correct this condition.

---

**Object:** NC394483 - PV - State Industries - 2013 - Blr Rm 2nd Flr - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 04/19/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 04-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 459. Discharge piping too small.  
**CONDITION:** 459. Installation of PRDs NCAC 13-13.0405: Discharge piping too small: Discharge piping too small: Pressure relief device (PRD) discharge header piping for this hot water storage tank and two others that are connected to the header is too small.  
**REQUIREMENT:** 459. Replace the PRD discharge header piping with piping having a cross sectional area of 3 inches or greater in order to correct this condition.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC394484 - PV - State Industries - 2013 - Blr Rm 2nd Flr - Active      **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 04/19/2021      **ENTERED BY:** Judd, Janie  
**CLOSED:**      **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 04-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 459. Discharge piping too small.  
**CONDITION:** 459. Installation of PRDs NCAC 13-13.0405: Discharge piping too small: Pressure relief device (PRD) discharge header piping for this hot water storage tank and two others that are connected to the header is too small.  
**REQUIREMENT:** 459. Replace the PRD discharge header piping with piping having a cross sectional area of 3 inches or greater in order to correct this condition.

---

**Location:** Longleaf Neuro Medical Treatment Center      **Location #:** 1813141      **Violations:** 1  
4761 Ward Blvd, , Wilson, NC 27893-4359, Phone: 252-399-2112  
**Contact:** There is no contact information available for this location.

---

**Object:** NC220872 - Boiler - Cleaver Brooks - 1987 - Blr Rm 3 - Active      **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** SORRENTINO, SEAN  
**OPENED:** 03/15/2021      **ENTERED BY:** Keyes, Amanda  
**CLOSED:**      **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 275. Tube/tube ends leak.  
**CONDITION:** 275. Boiler Components: Tube/tube ends leak.  
**REQUIREMENT:** 275. Repair the leaking tubes/tube ends. If weld repairs are required, a qualified "R" certificate holder is necessary to perform the work.

---

**Location:** Master Kleen Dry Cleaners      **Location #:** 1808706      **Violations:** 1  
119 Oakwood Dr, , Winston Salem, NC 27103-1903, Phone: 336-725-8402  
**Contact:** Attn Todd Breedlove, Owner, Master Kleen Dry Cleaners, Phone: 336-725-8402

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC301483 - Boiler - Fulton - 1995 - Blr Rm - Active

**Violations This Object:** 1

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Parker, Richard  
**OPENED:** 05/10/2021 **ENTERED BY:** Parker, Richard  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. No access to boiler.  
**REQUIREMENT:** 363. Contact inspector and schedule internal inspection.

contact Richard Parker @ 336-202-8341

---

**Location:** Model Cleaners

**Location #:** 1811147

**Violations:** 1

1322 S Hawthorne Rd, , Winston Salem, NC 27103-4122, Phone: 336-725-6961

**Contact:** There is no contact information available for this location.

---

**Object:** NC281801 - Boiler - Hurst - 1996 - Blr Rm - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 05/12/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations. Boiler not operating at time of inspection; low water cutoffs (LWCO) and pressure relief device (PRD) could not be tested to verify proper operation.  
**REQUIREMENT:** 363. Undefined Boiler Violations. Schedule a reinspection at a time when the boiler is operating so that the LWCO controls and PRD may be tested to verify proper operation. As an alternative, a detailed service report or boiler log that includes documentation of the successful testing of these controls is also acceptable.

---

**Location:** NC School Of Science & Mathematics

**Location #:** 1813129

**Violations:** 1

1219 Broad St, , Durham, NC 27705-3577, Phone: 919-416-2672

**Contact:** NC School Of Science & Mathematics, Phone: 919-416-2793

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC429655 - Boiler - PVI Industries - 2020 - Bryan Water Heater - Active **Violations This Object:** 1

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Gunto III, Andrew  
**OPENED:** 05/19/2021 **ENTERED BY:** Gunto III, Andrew  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 24-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 371. Inadequate relieving capacity.  
**CONDITION:** 371. Installation of PRDs NCAC 13-13.0405: Inadequate relieving capacity. This water heater has two posted BTU inputs. The input stamped on the Manufactures Data Plate is 6,379,000 BTU's. There is a sticker attached to the unit that has an input of 1,200,000 BTU's. The safety valve on this unit has a releasing capacity of 3,085,000 BTU's. At the time of the 5/19/2021 inspection, this scenario was discussed "via phone" with Jeremy Smith (Ass.-Chief) of the BSB. Is was determined that in NC, the safety valves releasing capacity must meet or exceed the capacity listed is the ASME Stamping.  
**REQUIREMENT:** 371. Replace the pressure relieving device with one with a capacity required by the NC-BSB.

---

**Location:** North Carolina Arboretum **Location #:** 1814891 **Violations:** 1  
100 Frederick Law Olmsted Way, , Asheville, NC 28806-9315, Phone: 828-665-2492  
**Contact:** Brad Shore, Manager, North Carolina Arboretum, Phone: 828-665-2492

---

**Object:** NC243736 - Boiler - Peerless - 1989 - Bsmt VEC Bldg - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 04/21/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 12-Casing, Stack Breeching and Flue  
**SUBCATEGORY** 211. Combustion gas leaks.  
**CONDITION:** 211. Casing, Stack Breeching and Flue: Combustion gas leaks. Front and rear sight glass missing seal.  
**REQUIREMENT:** 211. Repair all combustion gas leaks in the casing, stack breeching, or flue. Replace seal in front and rear sight glass.

---

**Location:** Oak Cleaners **Location #:** 2060057 **Violations:** 1  
208 Eastchester Dr, , High Point, NC 27262-7715, Phone: 336-886-6200  
**Contact:** Attn Kwangbeom Jeong, Oak Cleaners Inc, Phone: 336-706-4315

---

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC365334 - Boiler - Hurst - 2006 - Blr Rm - Active

**Violations This Object:** 1

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Johnson, Dean  
**OPENED:** 02/10/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations. Lower left handhole is corroded from original thickness.  
**REQUIREMENT:** 363. Undefined Boiler Violations. Welding is required for this repair, such welding must be made by a 'R' stamp holder. R-1 Report of Repair must be returned to this Inspector or the boiler must be removed from service.

---

**Location:** Paul J Rizzo Conference Center

**Location #:** 1817817

**Violations:** 1

150 Dubose Home Ln, , Chapel Hill, NC 27517-8944, Phone: 919-913-2098

**Contact:** There is no contact information available for this location.

---

**Object:** NC364029 - Boiler - Lochinvar - 2006 - Outside Dubose House - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Ollison, Jr., James C.  
**OPENED:** 06/11/2020  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 396. Missing nameplate.  
**CONDITION:** 396. Operation of PRDs NCAC 13-13.0405: Missing nameplate.  
**REQUIREMENT:** 396. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

---

**Location:** Pender Packing Co

**Location #:** 1818140

**Violations:** 2

4520 NC Highway 133, , Rocky Point, NC 28457-9108, Phone: 910-675-3311

**Contact:** Attn Danny Baker, Owner, Pender Packing Co Inc, Phone: 910-675-3311

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC188826 - Boiler - York Shipley - 1979 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Kirkland, John  
**OPENED:** 04/23/2021 **ENTERED BY:** Kirkland, John  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 275. Tube/tube ends leak.  
**CONDITION:** 275. Boiler Components: Tube/tube ends leak.  
**REQUIREMENT:** 275. Repair the leaking tubes/tube ends. If weld repairs are required, a qualified "R" certificate holder is necessary to perform the work. Once the repairs have been made, contact John Kirkland @ 252-204-7789 for a follow-up inspection.

---

**Object:** NC411019 - Boiler - Camus - 2015 - Electric Panel Rm - Active **Violations This Object:** 1

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Kirkland, John  
**OPENED:** 04/23/2021 **ENTERED BY:** Kirkland, John  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 397. Try lever inoperative.  
**CONDITION:** 397. Operation of PRDs NCAC 13-13.0405: Try lever inoperative.  
**REQUIREMENT:** 397. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified. Once repairs are complete, contact John Kirkland @ 252-204-7789 for a follow-up inspection.

---

**Location:** Plaza Express Lube **Location #:** 1820121 **Violations:** 1  
171 Weaver Blvd, , Weaverville, NC 28787-8345, Phone: 828-658-0446  
**Contact:** Tony Mace, Manager, Plaza Express Lube, Phone: 828-658-0446

---

**Object:** NC395562 - PV - Sanborn - 2012 - Outside - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 04/30/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 04-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 450. Pressure relieving devices not installed.  
**CONDITION:** 450. Installation of PRDs NCAC 13-13.0405: Pressure relieving devices not installed. The vessel is used for storage only and piped into the existing vessel however the compressor has not been disconnected from electricity.  
**REQUIREMENT:** 450. Install a pressure relieving device in accordance with NCAC 13-13.0405.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Location:** Prestige Dry Cleaners **Location #:** 543315 **Violations:** 1  
3204 Randleman Rd Ste A, , Greensboro, NC 27406-6529, Phone: 336-378-1617  
**Contact:** Attn Youn Choul Park, Prestige Dry Cleaners, Phone: 336-378-1617

**Object:** NC368248 - Boiler - Fulton - 2007 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 05/21/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations: Used boiler relocated and installed at this location without completion of internal certificate inspection prior to placing boiler in service.  
**REQUIREMENT:** 363. Undefined Boiler Violations: Complete an internal certificate inspection of this boiler as soon as possible in order to address this issue.

---

**Location:** R H Barringer Distribution Co **Location #:** 1822274 **Violations:** 1  
1620 Fairfax Rd, , Greensboro, NC 27407-4139, Phone: 336-854-0555  
**Contact:** Attn Bob Ogden, R H Barringer Distribution Co Inc, Phone: 336-854-0555, Cell:336-707-4275

**Object:** NC243237 - Boiler - Weben Jarco - 1988 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 05/19/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 06-Thermometer NCAC 13-13.0410  
**SUBCATEGORY** 111. Thermometer inoperative.  
**CONDITION:** 111. Thermometer NCAC 13-13.0410: Thermometer inoperative.  
**REQUIREMENT:** 111. Replace inoperative thermometer at/in the boiler outlet to measure the temperature in degrees Fahrenheit of the water. The thermometer shall have a range of approximately 2 times the intended operating temperature but not less than 1 1/2 times the intended operating temperature, nor more than 4 times the intended operating temperature.

---

**Location:** Reuter Family YMCA **Location #:** 1824034 **Violations:** 1  
3 Town Square Blvd, , Asheville, NC 28803-5000, Phone: 828-651-9622  
**Contact:** Dennis DiPalma, Property Manager, Reuter Family YMCA, Phone: 828-575-2918

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC341897 - Boiler - Steamaster - 2003 - Pool Sauna Mech Rm 172A - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 05/12/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 270. Water Leaks.  
**CONDITION:** 270. Boiler Components: Water Leaks. Boiler appears to be leaking due to water on the floor around vessel.  
**REQUIREMENT:** 270. Repair the water leaks identified on the inspection report.

---

**Location:** Sonesta ES Suites Charlotte **Location #:** 1832771 **Violations:** 2  
7925 Forest Pine Dr, , Charlotte, NC 28273-4600, Phone: 704-527-6767  
**Contact:** Attn Jessica Nugent, Sonesta ES Suites Charlotte, Phone: 704-954-4019

---

**Object:** NC395094 - PV - A O Smith - 2013 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Clay, Steven D.  
**OPENED:** 03/22/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 01-Installation  
**SUBCATEGORY** 413. Cracking.  
**CONDITION:** 413. Installation: Cracking. Leak at bottom of tank.  
**REQUIREMENT:** 413. Repair the cracking. If welding is required, a qualified "R" certificate holder is necessary to perform the work.

---

**Object:** NC395095 - PV - A O Smith - 2013 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Clay, Steven D.  
**OPENED:** 03/22/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 01-Installation  
**SUBCATEGORY** 413. Cracking.  
**CONDITION:** 413. Installation: Cracking. Leak at bottom of tank.  
**REQUIREMENT:** 413. Repair the cracking. If welding is required, a qualified "R" certificate holder is necessary to perform the work.

---

**Location:** Statesville Family YMCA **Location #:** 1845601 **Violations:** 2  
828 Wesley Dr, , Statesville, NC 28677-3355, Phone: 704-873-9622  
**Contact:** Paxton Hix, Facilities Director, Statesville Family YMCA, , Cell:704-880-4915

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC265007 - Boiler - Reimers - 1993 - Mens Steam Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 12/16/2020 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations. electrical steam generator not operating at time of inspection; safety controls could not be tested to verify proper operation.  
**REQUIREMENT:** 363. Undefined Boiler Violations. Schedule a reinspection at a time when the electric steam generator is operating so that the safety controls may be tested to verify proper operation. As an alternative, a detailed service report or log that includes documentation of the successful testing of these controls is also acceptable.

**Object:** NC380587 - Boiler - Fulton - 2008 - Ladies Steam Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 12/16/2020 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations: electrical steam generator not operating at time of inspection; safety controls could not be tested to verify proper operation.  
**REQUIREMENT:** 363. Undefined Boiler Violations. Schedule a reinspection at a time when the electric steam generator is operating so that the safety controls may be tested to verify proper operation. As an alternative, a detailed service report or log that includes documentation of the successful testing of these controls is also acceptable.

---

**Location:** Teds Laundromat **Location #:** 1835016 **Violations:** 3  
114 E Main St, , Sylva, NC 28779-2810, Phone: 828-586-2910  
**Contact:** Kevin Hensley, Manager, Teds Laundromat, Phone: 828-586-2910

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

**Object:** NC411982 - Boiler - Sermeta - 2016 - Blr Rm - Active

**Violations This Object:** 3

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 04/08/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 02-Pressure Gauges NCAC 13-13.0407  
**SUBCATEGORY** 035. Leaking.  
**CONDITION:** 035. Pressure Gauges NCAC 13-13.0407: Leaking.  
**REQUIREMENT:** 035. Install a pressure gauge on the equipment that is visible to the operator from the floor or work platform. Gauge must be the proper range in accordance with NC Administrative Code, Title 13, Chapter 13, Section .0407.

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 04/08/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 11-Exp Tanks & Htng Sys Piping NCAC 13-13.0412  
**SUBCATEGORY** 197. Bladder in bladder-type tank perforated or not charged.  
**CONDITION:** 197. Exp Tanks & Htng Sys Piping NCAC 13-13.0412: Bladder in bladder-type tank perforated or not charged.  
**REQUIREMENT:** 197. Repair or replace bladder/expansion tank with one designed and constructed to ASME Section VIII, Div 1 with an allowable working pressure of at least that of the system.

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 04/08/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 395. Valve leaking.  
**CONDITION:** 395. Operation of PRDs NCAC 13-13.0405: Valve leaking.  
**REQUIREMENT:** 395. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

**Location:** Top Tobacco

**Location #:** 1836886

**Violations:** 1

204 Top Tobacco Rd, , Lake Waccamaw, NC 28450-2220, Phone: 910-646-3014

**Contact:** Attn Richard Hopkins, Plant Engineer, Top Tobacco, Phone: 910-646-3014 X4125

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC236922 - Boiler - Cleaver Brooks - 1988 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Clay, Steven D.  
**OPENED:** 05/06/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 275. Tube/tube ends leak.  
**CONDITION:** 275. Boiler Components: Tube/tube ends leak. Evidence of leaking tubes and cracked tubes. Retubing underway during inspection by Joe Moore & Co  
**REQUIREMENT:** 275. Repair the leaking tubes/tube ends. If weld repairs are required, a qualified "R" certificate holder is necessary to perform the work.

---

**Location:** Transylvania Regional Hospital **Location #:** 1837355 **Violations:** 1  
260 Hospital Dr, , Brevard, NC 28712-3378, Phone: 828-884-9111  
**Contact:** Gary Hill, Maintenance Lead, Transylvania Regional Hospital, Phone: 828-884-9111

---

**Object:** NC121286 - PV - Taco - 1973 - Mech Rm 1 - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 05/21/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 04-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 458. Discharge opening directed improperly.  
**CONDITION:** 458. Installation of PRDs NCAC 13-13.0405: Discharge opening directed improperly.  
**REQUIREMENT:** 458. Redirect the discharge to a safe point as required in NCAC 13-13.0405

---

**Location:** Tryon Palace Historic Sites & Gardens **Location #:** 1838022 **Violations:** 1  
610 Pollock St, , New Bern, NC 28562-5614, Phone: 252-514-4900  
**Contact:** Randy Gurley, Maintenance Supervisor, Tryon Palace Historic Sites & Gardens, Phone: 252-639-3551

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC326274 - Boiler - Weil-McLain - 2000 - Stanley House - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 04/06/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409  
**SUBCATEGORY** 005. No provision to test low water cutoff device.  
**CONDITION:** 005. LWCO and Flow Sensing Devices NCAC 13-13.0409: No provision to test low water cutoff device.  
**REQUIREMENT:** 005. Equip the low water fuel cutoff device on the boiler with a vertical drain and blow-off valve assembly of not less than 3/4-inch nominal pipe size to allow for flushing and testing of the low water cutoff while the boiler is in operation.

---

**Location:** Twin Lakes Center **Location #:** 1838274 **Violations:** 2  
100 Wade Coble Dr, , Burlington, NC 27215-9756, Phone: 336-538-1400  
**Contact:** There is no contact information available for this location.

---

**Object:** NC431323 - Boiler - Lochinvar - 2020 - Memory Care - Active **Violations This Object:** 1

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Gunto III, Andrew  
**OPENED:** 05/20/2021 **ENTERED BY:** Gunto III, Andrew  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 14-Blr Mfr's Data Rpt/Nameplate NCAC 13-13.0401  
**SUBCATEGORY** 251. Nameplate Stamping Is Incorrect, Missing, or Illegible.  
**CONDITION:** 251. Blr Mfr's Data Rpt/Nameplate NCAC 13-13.0401:  
At the time of the 5/20/2021 inspection of water-heater (NC431323) a Manufactures Data Tag, showing the required ASME and National Board stamping could not be found. In North Carolina, water-heaters installed in businesses or places of public gather having a heat input exceeding 200,000 BTU's and/or a water storage capacity exceeding 120 gallons must be of ASME construction and must satisfy the requirements of the Uniform Boiler and Pressure Vessel Act of North Carolina.  
**REQUIREMENT:** 251. Locate or obtain a nameplate from the manufacturer or a replacement in accordance with the National Board Inspection Code. Alternatively, remove the water-heater from service.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC431326 - Boiler - Lochinvar - 2020 - Fitness Center Mech Rm - **Violations This Object:** 1  
Active

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Gunto III, Andrew  
**OPENED:** 05/20/2021 **ENTERED BY:** Gunto III, Andrew  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations.  
At the time of the 5/20/2021 inspection of NC431326 and operational demonstration could not be done.  
**REQUIREMENT:** 363. Undefined Boiler Violations.  
At follow-up inspection, an operational demonstration must be done.

---

**Location:** White Labs Kitchen & Tap **Location #:** 3757842 **Violations:** 1  
172 S Charlotte St, , Asheville, NC 28801-3765, Phone: 828-974-3868  
**Contact:** Andrew Schepers, Maintenance Tech, White Labs Kitchen & Tap,

**Object:** NC410758 - Boiler - Parker - 2016 - Stand Alone Bldg Rear - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 05/18/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations. Internal inspection is past due.  
**REQUIREMENT:** 363. Undefined Boiler Violations. Schedule an internal inspection for the boiler.

---

**Location:** Zoom Dry Cleaning **Location #:** 1816329 **Violations:** 1  
200 W Peace St Ste 120, , Raleigh, NC 27603-1183, Phone: 919-838-8530  
**Contact:** Lola Pedron, Manager, Zoom Dry Cleaning, Phone: 919-838-8530

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC373829 - Boiler - Fulton - 2007 - Blr Rm - Active

**Violations This Object:** 1

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Smith, Jeremy  
**OPENED:** 03/03/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY:** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 6/18/2019.  
**REQUIREMENT:** 363. Undefined Boiler Violations. An External Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.

---

**Violations This Report:** 126

**Locations This Report:** 77