

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Location:** (BEAUFORT CO) County Courthouse **Location #:** 1780498 **Violations:** 1  
112 W 2nd St, , Washington, NC 27889-4940, Phone: 252-946-9629  
**Contact:** Beaufort County Government, Phone: 252-946-9624

**Object:** NC420619 - Boiler - Kiturami - 2016 - Bsmt Left Rear - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 04/06/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 24-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 372. Set pressure too high.  
**CONDITION:** 372. Installation of PRDs NCAC 13-13.0405: Set pressure too high.  
**REQUIREMENT:** 372. Replace pressure relief device with a ASME/NB certified pressure relief device with a set pressure of not greater than 30 psig, with a relief capacity of not less than 200,000 BTU/hr and with a testing lever installed

---

**Location:** (BLADEN) County Courthouse **Location #:** 1768779 **Violations:** 1  
106 E Broad St, , Elizabethtown, NC 28337-8999, Phone: 910-862-6785  
**Contact:** Bladen County Government, Phone: 910-862-6780, Cell:910-862-6996

**Object:** NC276421 - Boiler - Weil-McLain - 1995 - Bsmt Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 06/14/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 396. Missing nameplate.  
**CONDITION:** 396. Operation of PRDs NCAC 13-13.0405: Missing nameplate: Pressure relief device missing nameplate  
**REQUIREMENT:** 396. Replace with a ASME/NB certified pressure relief device with a set pressure of not greater than 50 psig, with a relief capacity of not less than 3,270,000 BTU/hr, and with a testing lever.

---

**Location:** (CARTERET CS) Newport Elem **Location #:** 1814584 **Violations:** 1  
219 Chatham St, , Newport, NC 28570-8514, Phone: 252-223-4201  
**Contact:** Carteret County Public Schools, Phone: 252-728-5115

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC372175 - Boiler - Weil-McLain - 2008 - Blr Rm - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 05/06/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 395. Valve leaking.  
**CONDITION:** 395. Operation of PRDs NCAC 13-13.0405: Valve leaking: Pressure relief device leaking  
**REQUIREMENT:** 395. Replace the pressure relief device with a ASME/NB certified pressure relief device with a set pressure not exceeding 50 psig, with a relief capacity of not less than 2452 KBH, and with a testing lever.

---

**Location:** (CRAVEN CS) Bridgeton Elem

**Location #:** 1770407

**Violations:** 3

230 Branch Canal Rd, , New Bern, NC 28560-7624, Phone: 252-514-6425

**Contact:** Craven County Public Schools, Phone: 252-514-6380

---

**Object:** NC346263 - Boiler - Weil-McLain - 2003 - Blr Rm - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 04/07/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409  
**SUBCATEGORY** 006. Low water cutoff device inoperative or bypassed.  
**CONDITION:** 006. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device inoperative or bypassed.  
**REQUIREMENT:** 006. Repair or replace the inoperable low water fuel cutoff control and test to ensure proper operation.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC346265 - PV - Rheem/Ruud - 2002 - Blr Rm - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 04/07/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 10-Thermometer NCAC 13-13.0410  
**SUBCATEGORY** 110. Thermometer not installed.  
**CONDITION:** 110. Thermometer NCAC 13-13.0410: Thermometer not installed.  
**REQUIREMENT:** 110. Install a thermometer at/in the vessel outlet to measure the temperature in degrees Fahrenheit of the water. The thermometer shall have a range of approximately 2 times the intended operating temperature but not less than 1 1/2 times the intended operating temperature, nor more than 4 times the intended operating temperature.

**ENTERED BY:** Judd, Janie  
**CLOSED BY:**

---

**Object:** NC346266 - PV - Rheem/Ruud - 1999 - Blr Rm - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 04/07/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 10-Thermometer NCAC 13-13.0410  
**SUBCATEGORY** 110. Thermometer not installed.  
**CONDITION:** 110. Thermometer NCAC 13-13.0410: Thermometer not installed.  
**REQUIREMENT:** 110. Install a thermometer at/in the vessel outlet to measure the temperature in degrees Fahrenheit of the water. The thermometer shall have a range of approximately 2 times the intended operating temperature but not less than 1 1/2 times the intended operating temperature, nor more than 4 times the intended operating temperature.

**ENTERED BY:** Judd, Janie  
**CLOSED BY:**

---

**Location:** (CRAVEN CS) Creekside Elem

**Location #:** 2157338

**Violations:** 4

2790 Old Airport Rd, , New Bern, NC 28562-8734, Phone: 252-514-4360

**Contact:** Craven County Public Schools, Phone: 252-514-6380

---

**Object:** NC367471 - Boiler - Weil-McLain - 2007 - Blr Rm - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 04/08/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 270. Water Leaks.  
**CONDITION:** 270. Boiler Components: Water Leaks.  
**REQUIREMENT:** 270. Repair the leak identified at the bottom between the last two boiler sections.

**ENTERED BY:** Judd, Janie  
**CLOSED BY:**

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC367472 - Boiler - Weil-McLain - 2007 - Blr Rm - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 04/08/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 395. Valve leaking.  
**CONDITION:** 395. Operation of PRDs NCAC 13-13.0405: Valve leaking: Pressure relief device leaking.  
**REQUIREMENT:** 395. Repair or replace pressure relief device with a ASME/NB certified pressure relief device with a set pressure of not greater than 50 psig, with a relief capacity of not less than 1,358,000 BTU/hr, and a testing lever

**ENTERED BY:** Judd, Janie  
**CLOSED BY:**

---

**Object:** NC367473 - Boiler - A O Smith - 2007 - Blr Rm - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 04/08/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 06-Thermometer NCAC 13-13.0410  
**SUBCATEGORY** 110. Thermometer not installed.  
**CONDITION:** 110. Thermometer NCAC 13-13.0410: Thermometer not installed.  
**REQUIREMENT:** 110. Install a thermometer at/in the boiler outlet to measure the temperature in degrees Fahrenheit of the water. The thermometer shall have a range of approximately 2 times the intended operating temperature but not less than 1 1/2 times the intended operating temperature, nor more than 4 times the intended operating temperature.

**ENTERED BY:** Judd, Janie  
**CLOSED BY:**

---

**Object:** NC367474 - Boiler - A O Smith - 2007 - Blr Rm - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 04/08/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 06-Thermometer NCAC 13-13.0410  
**SUBCATEGORY** 110. Thermometer not installed.  
**CONDITION:** 110. Thermometer NCAC 13-13.0410: Thermometer not installed.  
**REQUIREMENT:** 110. Install a thermometer at/in the boiler outlet to measure the temperature in degrees Fahrenheit of the water. The thermometer shall have a range of approximately 2 times the intended operating temperature but not less than 1 1/2 times the intended operating temperature, nor more than 4 times the intended operating temperature.

**ENTERED BY:** Judd, Janie  
**CLOSED BY:**

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Location:** (CRAVEN CS) Graham A Barden Elem **Location #:** 1793675 **Violations:** 2  
200 Cedar Dr, , Havelock, NC 28532-2187, Phone: 252-444-5100  
**Contact:** Craven County Public Schools, Phone: 252-514-6380

**Object:** NC229320 - Boiler - Weil-McLain - 1988 - Blr Rm - Active **Violations This Object:** 2

---

<b>COMPANY:</b>	Hartford Steam Boiler	
<b>INSPECTOR:</b>	Rudolph, Jay	
<b>OPENED:</b>	04/08/2021	<b>ENTERED BY:</b> Judd, Janie
<b>CLOSED:</b>		<b>CLOSED BY:</b>
<b>TYPE:</b>	Certificate Blocking	
<b>CATEGORY:</b>	23-Undefined Boiler Violations	
<b>SUBCATEGORY</b>	363. Undefined Boiler Violations.	
<b>CONDITION:</b>	363. Undefined Boiler Violations: Boiler not running.	
<b>REQUIREMENT:</b>	363. Undefined Boiler Violations. Reschedule inspection for a time when the boiler can be run so safety devices can be verified to operate properly. If repairs cannot be completed in a timely fashion, or repairs are not be performed, disconnect the boiler.	
<b>COMPANY:</b>	Hartford Steam Boiler	
<b>INSPECTOR:</b>	Rudolph, Jay	
<b>OPENED:</b>	04/08/2021	<b>ENTERED BY:</b> Judd, Janie
<b>CLOSED:</b>		<b>CLOSED BY:</b>
<b>TYPE:</b>	Certificate Blocking	
<b>CATEGORY:</b>	24-Installation of PRDs NCAC 13-13.0405	
<b>SUBCATEGORY</b>	371. Inadequate relieving capacity.	
<b>CONDITION:</b>	371. Installation of PRDs NCAC 13-13.0405: Inadequate relieving capacity.	
<b>REQUIREMENT:</b>	371. Replace one or both pressure relief devices to obtain a capacity of not less than 3550 PPH. Set pressures are to be no greater than 50 psig, and a testing lever be installed on each pressure relief device.	

---

**Location:** (CRAVEN CS) Havelock Elem **Location #:** 1814386 **Violations:** 1  
201 Cunningham Blvd, , Havelock, NC 28532-1908, Phone: 252-444-5106  
**Contact:** Craven County Public Schools, Phone: 252-514-6380

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC412018 - Boiler - Rheem/Ruud - 2016 - Blr Rm - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 04/08/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 06-Thermometer NCAC 13-13.0410  
**SUBCATEGORY** 110. Thermometer not installed.  
**CONDITION:** 110. Thermometer NCAC 13-13.0410: Thermometer not installed.  
**REQUIREMENT:** 110. Install a thermometer at/in the boiler outlet to measure the temperature in degrees Fahrenheit of the water. The thermometer shall have a range of approximately 2 times the intended operating temperature but not less than 1 1/2 times the intended operating temperature, nor more than 4 times the intended operating temperature.

---

**Location:** (CRAVEN CS) J T Barber Elem

**Location #:** 1801046

**Violations:** 1

1700 Cobb St, , New Bern, NC 28560-3536, Phone: 252-514-6460

**Contact:** Craven County Public Schools, Phone: 252-514-6380

---

**Object:** NC263863 - Boiler - Weil-McLain - 1996 - Blr Rm - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 04/07/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 394. Valve inoperative.  
**CONDITION:** 394. Operation of PRDs NCAC 13-13.0405: Valve inoperative.  
**REQUIREMENT:** 394. Replace pressure relieve devices with ASME/NB certified pressure relief device with a set pressure of not greater than 15 psig, with a combined relieve capacity of not less than 3270 PPH and with testing levers installed.

---

**Location:** (CRAVEN CS) Tucker Creek Middle

**Location #:** 1838064

**Violations:** 3

200 Sermons Rd, , Havelock, NC 28532-7707, Phone: 252-444-7200

**Contact:** Craven County Public Schools, Phone: 252-514-6380

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC282746 - Boiler - Weil-McLain - 1997 - Blr Rm Rear Cafeteria - **Violations This Object:** 1  
Active

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 04/08/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations: Boiler not operating.  
**REQUIREMENT:** 363. Undefined Boiler Violations. Reschedule inspection for a time when the boiler is operating so that safety devices can be verified to operate properly.

---

**Object:** NC282747 - Boiler - Weil-McLain - 1997 - Blr Rm Rear Cafeteria - **Violations This Object:** 1  
Active

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 04/08/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations: Boiler not operating.  
**REQUIREMENT:** 363. Undefined Boiler Violations: Reschedule inspection for a time when the boiler is operating so that safety devices can be verified to operate properly.

---

**Object:** NC386070 - PV - Trane - 2007 - Outside Chillers Cafeteria - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 04/08/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 04-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 460. Seals broken/ missing.  
**CONDITION:** 460. Installation of PRDs NCAC 13-13.0405: Seals broken/ missing: Pressure relief device tamper seal broken.  
**REQUIREMENT:** 460. Replace pressure relief device. Set pressure not to be greater than 200 psig and with adequate capacity.

---

**Location:** (DPS-C) Craggy CC - 4630 **Location #:** 1786753 **Violations:** 1  
2992 Riverside Dr, , Asheville, NC 28804-8601, Phone: 828-645-5315  
**Contact:** Mike Ball, Assistant Superintendant Custy/Pps, Craggy CC - 4630, Phone: 828-645-5315 X225



# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC337255 - PV - American - 2001 - Bldg 3 Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Possidente, James

**OPENED:** 05/10/2021

**ENTERED BY:** Putek, Terry

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 07-Undefined Pressure Vessels Violations

**SUBCATEGORY** 479. Undefined Pressure Vessels Violations.

**CONDITION:** 479. Undefined Pressure Vessels Violations. Water leaking from upper shell at PRV nipple area.

**REQUIREMENT:** 479. Undefined Pressure Vessels Violations. Repair the water leaks identified.

---

**Location:** (DPS-C) Lanesboro CI - 4865

**Location #:** 1805021

**Violations:** 1

552 Prison Camp Rd, , Polkton, NC 28135-6118, Phone: 704-695-1013

**Contact:** NC Dept Of Public Safety - 13101, Phone: 919-716-3422

---

**Object:** NC340797 - Boiler - Cleaver Brooks - 2002 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Clay, Steven D.

**OPENED:** 06/07/2021

**ENTERED BY:** Putek, Terry

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 23-Undefined Boiler Violations

**SUBCATEGORY** 363. Undefined Boiler Violations.

**CONDITION:** 363. Undefined Boiler Violations. Boiler could not run due to missing components.

**REQUIREMENT:** 363. Undefined Boiler Violations. Boiler is scheduled to be reinspected or disconnected.

---

**Location:** (DPS-C) NCCIW - 3010

**Location #:** 1779964

**Violations:** 2

1034 Bragg St, , Raleigh, NC 27610-3846, Phone: 919-733-4340

**Contact:** Phillip Jones, Maintenance Supervisor, NCCIW - 3010, Phone: 919-508-1690

---

**Object:** NC381483 - Boiler - PVI Industries - 2010 - Falcom Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** SORRENTINO, SEAN

**OPENED:** 12/08/2020

**ENTERED BY:** Keyes, Amanda

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 16-Boiler Components

**SUBCATEGORY** 270. Water Leaks.

**CONDITION:** 270. Boiler Components: Water Leaks.

**REQUIREMENT:** 270. Repair the water leaks identified on the inspection report. If welding is required, a qualified "R" certificate holder is necessary to perform the repair.

---



# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC401596 - Boiler - PVI Industries - 2014 - Sparrow N - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** SORRENTINO, SEAN  
**OPENED:** 12/08/2020 **ENTERED BY:** Keyes, Amanda  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 270. Water Leaks.  
**CONDITION:** 270. Boiler Components: Water Leaks. Tank leaking at unknown location.  
**REQUIREMENT:** 270. Repair the water leaks identified on the inspection report. If welding is required, a qualified "R" certificate holder is necessary to perform the repair.

---

**Location:** (DPS-C) Sampson CI - 4345 **Location #:** 1826926 **Violations:** 1  
120 North Blvd, , Clinton, NC 28328-1810, Phone: 910-592-2151  
**Contact:** Rick Wyett, Sampson CI - 4345, Phone: 910-592-2151, Cell:910-385-7287

**Object:** NC246834 - Boiler - Teledyne Laars - 1989 - Cafeteria Blr Rm Unit **Violations This Object:** 1  
2 - Active

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 06/08/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 26-Undefined Pressure Relieving Devices Violations  
**SUBCATEGORY** 399. Undefined Pressure Relieving Devices Violations.  
**CONDITION:** 399. Undefined Pressure Relieving Devices Violations: Pressure relief device would not present full flow when tested.  
**REQUIREMENT:** 399. Undefined Pressure Relieving Devices Violations Repair or replace pressure relief device, inlet piping, and/or discharge piping to allow full flow of pressure relief device when tested.

---

**Location:** (MH UNIV) Brown Hall **Location #:** 1930569 **Violations:** 3  
150 Joe Anderson Dr, , Mars Hill, NC 28754 , Phone: 828-689-1201  
**Contact:** Attn Henry H Haywood, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:828-206-

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

**Object:** NC338996 - PV - LTC - 2002 - Bsmt Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 03/12/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 02-Manufacturer's Data Report & Nameplate  
**SUBCATEGORY** 431. Nameplate stamping is incorrect, missing, or illegible.  
**CONDITION:** 431. Manufacturer's Data Report & Nameplate: Nameplate stamping is incorrect, missing, or illegible. Dataplate could not be located.  
**REQUIREMENT:** 431. Obtain a replacement nameplate from the manufacturer or a replacement in accordance with the National Board Inspection Code. Locate nameplate and make visible for inspection.

**ENTERED BY:** Putek, Terry

**CLOSED BY:**

**Object:** NC338997 - Boiler - Lochinvar - 2002 - Bsmt Blr Rm - Active

**Violations This Object:** 2

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 03/12/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 08-Main Steam System NCAC 13-13.0411  
**SUBCATEGORY** 126. Leaking pipe/pipe joints.  
**CONDITION:** 126. Main Steam System NCAC 13-13.0411: Leaking pipe/pipe joints.  
**REQUIREMENT:** 126. Repair or tighten leaking pipe/pipe joints.

**ENTERED BY:** Putek, Terry

**CLOSED BY:**

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 03/12/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 12-Casing, Stack Breeching and Flue  
**SUBCATEGORY** 214. Excessive corrosion.  
**CONDITION:** 214. Casing, Stack Breeching and Flue: Excessive stack corrosion.  
**REQUIREMENT:** 214. Repair or replace the casing, stack breeching or flue.

**ENTERED BY:** Putek, Terry

**CLOSED BY:**

**Location:** (MH UNIV) Day Hall

**Location #:** 3711212

**Violations:** 1

8 College St, , Mars Hill, NC 28754-0630, Phone: 828-689-1201

**Contact:** Attn Henry H Haywood, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:828-206-

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC406668 - Boiler - Sermeta - 2015 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Possidente, James

**OPENED:** 05/19/2021

**ENTERED BY:** Putek, Terry

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405

**SUBCATEGORY** 395. Valve leaking.

**CONDITION:** 395. Operation of PRDs NCAC 13-13.0405: Valve leaking.

**REQUIREMENT:** 395. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

---

**Location:** (MH UNIV) Gibson Hall

**Location #:** 1930563

**Violations:** 1

100 Joe Anderson Dr, , Mars Hill, NC 28754 , Phone: 828-689-1201

**Contact:** Attn Henry H Haywood, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:828-206-

---

**Object:** NC099075 - Boiler - Weil-McLain - 1969 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Possidente, James

**OPENED:** 03/12/2021

**ENTERED BY:** Putek, Terry

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405

**SUBCATEGORY** 395. Valve leaking.

**CONDITION:** 395. Operation of PRDs NCAC 13-13.0405: Valve leaking.

**REQUIREMENT:** 395. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

---

**Location:** (MH UNIV) Huffman Hall

**Location #:** 1930543

**Violations:** 1

130 Womens Hill Dr, , Mars Hill, NC 28754 , Phone: 828-689-1201

**Contact:** Attn Henry H Haywood, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:828-206-

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC403705 - PV - LTC - 2015 - Rm B11 - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Possidente, James

**OPENED:** 02/23/2021

**ENTERED BY:** Putek, Terry

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 07-Undefined Pressure Vessels Violations

**SUBCATEGORY** 479. Undefined Pressure Vessels Violations.

**CONDITION:** 479. Undefined Pressure Vessels Violations. Pipe leaking.

**REQUIREMENT:** 479. Undefined Pressure Vessels Violations. Repair or replace leaking piping/pipe joints.

---

**Location:** (MH UNIV) McConnell Hall

**Location #:** 1930553

**Violations:** 1

54 College St, , Mars Hill, NC 28754-0630, Phone: 828-689-1201

**Contact:** Attn Henry H Haywood, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:828-206-

---

**Object:** NC270792 - Boiler - Weil-McLain - 1994 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Possidente, James

**OPENED:** 02/23/2021

**ENTERED BY:** Putek, Terry

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409

**SUBCATEGORY** 006. Low water cutoff device inoperative or bypassed.

**CONDITION:** 006. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device inoperative or bypassed.

**REQUIREMENT:** 006. Repair or replace the inoperable low water fuel cutoff control and test to ensure proper operation.

---

**Location:** (MH UNIV) Pittman Dining Hall

**Location #:** 1930566

**Violations:** 1

121 Cascade St, , Mars Hill, NC 28754-9135, Phone: 828-689-1201

**Contact:** Attn Henry H Haywood, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:828-206-

---

**Object:** NC262680 - Boiler - Peerless - 1993 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Possidente, James

**OPENED:** 03/12/2021

**ENTERED BY:** Putek, Terry

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 12-Casing, Stack Breeching and Flue

**SUBCATEGORY** 211. Combustion gas leaks.

**CONDITION:** 211. Casing, Stack Breeching and Flue: Combustion gas leaks.

**REQUIREMENT:** 211. Repair all combustion gas leaks in the casing, stack breeching, or flue.

---

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Location:** (MH UNIV) Spilman Hall **Location #:** 1930544 **Violations:** 2  
50 College St, , Mars Hill, NC 28754-0630, Phone: 828-689-1201  
**Contact:** Attn Henry H Haywood, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:828-206-

**Object:** NC294827 - Boiler - Peerless - 1999 - Bsmt - Active **Violations This Object:** 2

---

<b>COMPANY:</b>	Hartford Steam Boiler	
<b>INSPECTOR:</b>	Possidente, James	
<b>OPENED:</b>	05/19/2021	<b>ENTERED BY:</b> Putek, Terry
<b>CLOSED:</b>		<b>CLOSED BY:</b>
<b>TYPE:</b>	Certificate Blocking	
<b>CATEGORY:</b>	01-LWCO and Flow Sensing Devices NCAC 13-13.0409	
<b>SUBCATEGORY</b>	009. Water level control inoperative or bypassed.	
<b>CONDITION:</b>	009. LWCO and Flow Sensing Devices NCAC 13-13.0409: Water level control inoperative or bypassed.	
<b>REQUIREMENT:</b>	009. Repair or replace the inoperable water level control and test to ensure proper operation.	
<b>COMPANY:</b>	Hartford Steam Boiler	
<b>INSPECTOR:</b>	Possidente, James	
<b>OPENED:</b>	05/19/2021	<b>ENTERED BY:</b> Putek, Terry
<b>CLOSED:</b>		<b>CLOSED BY:</b>
<b>TYPE:</b>	Certificate Blocking	
<b>CATEGORY:</b>	12-Casing, Stack Breeching and Flue	
<b>SUBCATEGORY</b>	211. Combustion gas leaks.	
<b>CONDITION:</b>	211. Casing, Stack Breeching and Flue: Combustion gas leaks. Front and rear firebox sight glass broken.	
<b>REQUIREMENT:</b>	211. Repair all combustion gas leaks in the casing, stack breeching, or flue. Repair front and rear firebox sight glass.	

---

**Location:** (MH UNIV) Stroup Hall **Location #:** 1930538 **Violations:** 2  
141 Womens Hill Dr, , Mars Hill, NC 28754 , Phone: 828-689-1201  
**Contact:** Attn Henry H Haywood, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:828-206-

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC323874 - Boiler - Teledyne Laars - 2000 - Bsmt - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 02/23/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409  
**SUBCATEGORY** 012. Flow switch inoperative or bypassed.  
**CONDITION:** 012. LWCO and Flow Sensing Devices NCAC 13-13.0409: Flow switch inoperative or bypassed. (Leaking)  
**REQUIREMENT:** 012. Install a flow switch that will shut off the fuel supply in case of stoppage of water flow or a low-water condition and test to ensure proper operation.

**ENTERED BY:** Putek, Terry

**CLOSED BY:**

---

**Object:** NC325457 - Boiler - Peerless - 2000 - Bsmt - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 02/23/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409  
**SUBCATEGORY** 006. Low water cutoff device inoperative or bypassed.  
**CONDITION:** 006. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device inoperative or bypassed. Primary LWCO inoperative.  
**REQUIREMENT:** 006. Repair or replace the inoperable low water fuel cutoff control and test to ensure proper operation.

**ENTERED BY:** Putek, Terry

**CLOSED BY:**

---

**Location:** (NC A&T) Bluford Library

**Location #:** 1900678

**Violations:** 1

1601 E Market St, , Greensboro, NC 27411-0002, Phone: 336-334-7025

**Contact:** NC A & T State University, Phone: 336-334-3806

---

**Object:** NC250889 - Boiler - Bryan - 1989 - Penthouse - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 06/17/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations: Boiler not operating at time of inspection; pressure relief device (PRD) and low water cutoff (LWCO) could not be tested to verify proper operation.  
**REQUIREMENT:** 363. Undefined Boiler Violations: Schedule a reinspection at a time when the boiler is operating so that the PRD and LWCO may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the controls is also acceptable.

**ENTERED BY:** Judd, Janie

**CLOSED BY:**

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Location:** (NC A&T) Bryan Fitness & Wellness Ctr **Location #:** 1900679 **Violations:** 1  
1601 E Market St, , Greensboro, NC 27411-0002, Phone: 336-334-7025  
**Contact:** NC A & T State University, Phone: 336-334-3806

**Object:** NC326149 - Boiler - Lochinvar - 2000 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 06/17/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations: Flow switch leaking. Corrosion present on switch internal components.  
**REQUIREMENT:** 363. Undefined Boiler Violations; Replace the current flow switch in order to correct this issue. Once complete test the new flow switch in order to verify proper operation.

---

**Location:** (NC A&T) C H Moore Agricultural **Location #:** 1900558 **Violations:** 2  
1601 E Market St, , Greensboro, NC 27411-0002, Phone: 336-334-7025  
**Contact:** NC A & T State University, Phone: 336-334-3806

**Object:** NC239390 - Boiler - Weil-McLain - 1988 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 06/17/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations: Boiler not operating at time of inspection; pressure relief device (PRD) and low water cutoff (LWCO) could not be tested to verify proper operation.  
**REQUIREMENT:** 363. Undefined Boiler Violations: Schedule a reinspection at a time when the boiler is operating so that the PRD and LWCO may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the controls is also acceptable



# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC343287 - Boiler - Lochinvar - 2003 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Leonard, Shannon D.

**OPENED:** 06/17/2021

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 23-Undefined Boiler Violations

**SUBCATEGORY** 363. Undefined Boiler Violations.

**CONDITION:** 363. Undefined Boiler Violations: Boiler not operating at time of inspection; pressure relief device (PRD) and low water cutoff (LWCO) could not be tested to verify proper operation.

**REQUIREMENT:** 363. Undefined Boiler Violations: Schedule a reinspection at a time when the boiler is operating so that the PRD and LWCO may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the controls is also acceptable.

---

**Location:** (NC A&T) Coltrane Hall

**Location #:** 2921477

**Violations:** 1

1601 E Market St, , Greensboro, NC 27411-0002, Phone: 336-334-7025

**Contact:** Ricky Richmond, Facilities Manager, NC A & T State University, Phone: 336-285-4583, Cell:336-906-9620

---

**Object:** NC383297 - Boiler - Giannoni - 2010 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Leonard, Shannon D.

**OPENED:** 06/17/2021

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 23-Undefined Boiler Violations

**SUBCATEGORY** 363. Undefined Boiler Violations.

**CONDITION:** 363. Undefined Boiler Violations: Boiler not operating at time of inspection; pressure relief device (PRD) and low water cutoff (LWCO) could not be tested to verify proper operation.

**REQUIREMENT:** 363. Undefined Boiler Violations: Schedule a reinspection at a time when the boiler is operating so that the PRD and LWCO may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the controls is also acceptable

---

**Location:** (NC A&T) T E Neal Heating Plt

**Location #:** 1834439

**Violations:** 1

1601 E Market St, , Greensboro, NC 27411-0002, Phone: 336-334-7025

**Contact:** Ricky Richmond, Facilities Manager, NC A & T State University, Phone: 336-285-4583, Cell:336-906-9620

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC254988 - PV - East Fab - 1992 - Blr Rm 2nd Flr - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 05/20/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 01-Installation  
**SUBCATEGORY** 414. Pitting.  
**CONDITION:** 414. Installation: Corrosion/Pitting.  
**REQUIREMENT:** 414. Repair the pitting. If welding is required, a qualified "R" certificate holder is necessary to perform the work.

---

**Location:** (NC A&T) Vanstory Hall **Location #:** 1900627 **Violations:** 1  
1601 E Market St, , Greensboro, NC 27411-0002, Phone: 336-334-7025  
**Contact:** Ricky Richmond, Facilities Manager, NC A & T State University, Phone: 336-285-4583, Cell:336-906-9620

---

**Object:** NC252034 - PV - Reco - 1991 - Equip Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 06/17/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 07-Undefined Pressure Vessels Violations  
**SUBCATEGORY** 479. Undefined Pressure Vessels Violations.  
**CONDITION:** 479. Undefined Pressure Vessels Violations: Corrosion and leakage origination from vessel shell.  
**REQUIREMENT:** 479. Undefined Pressure Vessels Violations: Identify all areas of corrosion/leakage and make repairs as necessary to correct this condition. All welded repairs must be performed by a qualified "R" certificate holder.

---

**Location:** (NCCU) Brite Bldg **Location #:** 2239356 **Violations:** 7  
202 E Lawson St, , Durham, NC 27707-3144, Phone: 919-201-1143  
**Contact:** Attn Lori Blake Reid PO #P107428, NC Central University Shephard Station, Phone: 919-530-7244

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

**Object:** NC429694 - PV - Consolidated - 2008 - Rm 2129 B - Active

**Violations This Object:** 4

**COMPANY:** State of North Carolina

**INSPECTOR:** Gunto III, Andrew

**OPENED:** 04/29/2021

**ENTERED BY:** Gunto III, Andrew

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 04-Installation of PRDs NCAC 13-13.0405

**SUBCATEGORY** 458. Discharge opening directed improperly.

**CONDITION:** 458. Installation of PRDs NCAC 13-13.0405:  
This vessel's safety valve vent is not piped to a safe location.

**REQUIREMENT:** 458. Redirect the discharge to a safe point as required in NCAC 13-13.0405  
Pipe the safety valve vent so that it ends at between 1" and 6" from the floor or to a safe location out of the room.

**COMPANY:** State of North Carolina

**INSPECTOR:** Gunto III, Andrew

**OPENED:** 04/29/2021

**ENTERED BY:** Gunto III, Andrew

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 07-Undefined Pressure Vessels Violations

**SUBCATEGORY** 479. Undefined Pressure Vessels Violations.

**CONDITION:** 479. Undefined Pressure Vessels Violations.  
This vessel has support brackets welded to its internal pressure boundary. Some of the of the welds are cracked or broken.

**REQUIREMENT:** 479. Undefined Pressure Vessels Violations.  
Using a qualified company, ground and cracks smooth and perform a dye penetrant test to determine the pressure boundary is sound. Any welding must be done by an R Stamp holder.

**COMPANY:** State of North Carolina

**INSPECTOR:** Gunto III, Andrew

**OPENED:** 04/29/2021

**ENTERED BY:** Gunto III, Andrew

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 07-Undefined Pressure Vessels Violations

**SUBCATEGORY** 479. Undefined Pressure Vessels Violations.

**CONDITION:** 479. Undefined Pressure Vessels Violations.  
This locks on this vessel's door are made up of lugs that engage the door jam while in the locked position. The lugs on the top of the door only engage the jam around 1/4". While the lugs on the bottom of the door at 1".

**REQUIREMENT:** 479. Undefined Pressure Vessels Violations.  
Adjust the doors vertical position in the jam so that lug engagement is even.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Gunto III, Andrew  
**OPENED:** 04/29/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 07-Undefined Pressure Vessels Violations  
**SUBCATEGORY** 479. Undefined Pressure Vessels Violations.  
**CONDITION:** 479. Undefined Pressure Vessels Violations.  
At the time of the 4/29/2021 inspection and operational demonstration was not completed.  
**REQUIREMENT:** 479. Undefined Pressure Vessels Violations.  
At follow up inspection an operational demonstration must be done.

**Object:** NC429695 - Boiler - Consolidated - 2008 - Rm 2129 B - Active **Violations This Object:** 3

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Gunto III, Andrew  
**OPENED:** 04/29/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 22-Installation  
**SUBCATEGORY** 362. Boiler room clearances.  
**CONDITION:** 362. Installation: Boiler room clearances.  
The 4/29/2021 inspection of this boiler was incomplete due to lack of access. The installation is such that, the minimum required clearances are not much to allow for inspection and maintenance.  
**REQUIREMENT:** 362. Provide clearances around the user servicable accesses of the boiler in accordance with NCAC 13-13.0413.

**COMPANY:** State of North Carolina  
**INSPECTOR:** Gunto III, Andrew  
**OPENED:** 04/29/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 24-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 378. Discharge opening directed improperly.  
**CONDITION:** 378. Installation of PRDs NCAC 13-13.0405:  
This vessel's safety valve vent is not piped to a safe location.  
**REQUIREMENT:** 378. Redirect the discharge to a safe point at required in NCAC 13-13.0405.  
Pipe the safety valve vent so that it ends at between 1" and 6" from the floor or to a safe location out of the room.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Gunto III, Andrew  
**OPENED:** 04/29/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 24-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 373. Inlet pipe too small.  
**CONDITION:** 373. Installation of PRDs NCAC 13-13.0405:  
This boilers safety valve is not attached directly to the boiler. The boilers safety valve must be no further than the length of it corresponding "t" from the boiler  
**REQUIREMENT:** 373. Reinstalled the boilers safety valve so that meets the requirements of ASME Sec I - PG-71.2

---

**Location:** (NCCU) Heating Plant  
1801 Fayetteville St, , Durham, NC 27707-3129, Phone: 919-530-6313  
**Contact:** Attn Lori Blake Reid PO #P107428, NC Central University Shephard Station, Phone: 919-530-7244  
**Location #:** 1796457 **Violations:** 1  
**Object:** NC293050 - Boiler - Babcock & Wilcox - 1998 - Blr House Blr 1 - **Violations This Object:** 1  
Active

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** SORRENTINO, SEAN  
**OPENED:** 11/18/2020  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. The boiler was not operating during this inspection per Sean Sorrentino inspection report.  
**REQUIREMENT:** 363. You must operate this boiler for external inspection per Sean Sorrentino inspection report.

---

**Location:** (NCCU) Mary Towne  
1801 Fayetteville St, , Durham, NC 27707-3129, Phone: 919-530-6100  
**Contact:** Attn Lori Blake Reid PO #P107428, NC Central University Shephard Station, Phone: 919-530-7244  
**Location #:** 1930626 **Violations:** 4

---

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC429690 - PV - Consolidated - 2000 - Rm 2164 - Active

**Violations This Object:** 1

**COMPANY:** State of North Carolina

**INSPECTOR:** Gunto III, Andrew

**OPENED:** 04/29/2021

**ENTERED BY:** Gunto III, Andrew

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 07-Undefined Pressure Vessels Violations

**SUBCATEGORY** 479. Undefined Pressure Vessels Violations.

**CONDITION:** 479. Undefined Pressure Vessels Violations.

During the 4/29/2021 inspection of NC429690 this vessel was under chamber pressure at onset of inspection. The chamber pressure gauge read approximately 5 psi. I was able to turn the door lock towards the open position and the door began to open. Steam from the chamber leaked around the doors seal. A later door lock test revealed that the door would open until the chamber pressure gauge read approximately 10 psi.

**REQUIREMENT:** 479. Undefined Pressure Vessels Violations.

Using a qualified repair company, repair is vessel so that its door will not open while under pressure.

---

**Object:** NC429691 - Boiler - UNKNOWN - 1800 - Rm 2164 - Active

**Violations This Object:** 1

**COMPANY:** State of North Carolina

**INSPECTOR:** Gunto III, Andrew

**OPENED:** 04/29/2021

**ENTERED BY:** Gunto III, Andrew

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 22-Installation

**SUBCATEGORY** 362. Boiler room clearances.

**CONDITION:** 362. Installation: Boiler room clearances.

This boilers cabinet is installed in close quarters. The installation is such that, the minimum required clearances are not much to allow for inspection and maintenance.

**REQUIREMENT:** 362. Provide clearances around the user servicable accesses of the boiler in accordance with NCAC 13-13.0413.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC429692 - PV - Consolidated - 2010 - Rm 2174 - Active

**Violations This Object:** 1

**COMPANY:** State of North Carolina

**INSPECTOR:** Gunto III, Andrew

**OPENED:** 04/29/2021

**ENTERED BY:** Gunto III, Andrew

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 07-Undefined Pressure Vessels Violations

**SUBCATEGORY** 479. Undefined Pressure Vessels Violations.

**CONDITION:** 479. Undefined Pressure Vessels Violations.

This vessel has support brackets welded to its internal pressure boundary. Some of the of the welds are cracked or broken.

**REQUIREMENT:** 479. Undefined Pressure Vessels Violations.

Using a qualified company, ground and cracks smooth and perform a dye penetrant test to determine the pressure boundary is sound. Any welding must be done by an R Stamp holder.

---

**Object:** NC429693 - Boiler - UNKNOWN - 1800 - Rm 2174 - Active

**Violations This Object:** 1

**COMPANY:** State of North Carolina

**INSPECTOR:** Gunto III, Andrew

**OPENED:** 04/29/2021

**ENTERED BY:** Gunto III, Andrew

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 22-Installation

**SUBCATEGORY** 362. Boiler room clearances.

**CONDITION:** 362. Installation:

This boilers cabinet is installed in close quarters. The installation is such that, the minimum required clearances are not much to allow for inspection and maintenance.

**REQUIREMENT:** 362. Provide clearances around the user servicable accesses of the boiler in accordance with NCAC 13-13.0413.

---

**Location:** (NCDOA) Museum Of Art

**Location #:** 1813946

**Violations:** 1

2110 Blue Ridge Rd, , Raleigh, NC 27607-6433, Phone: 919-839-6262

**Contact:** Chris Carter, Plant Maint Supervisor, Museum Of Art, Phone: 919-839-6262



# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC375707 - Boiler - Fulton - 2008 - New Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** State of North Carolina

**INSPECTOR:** Smith, Jeremy

**OPENED:** 03/03/2021

**ENTERED BY:** Smith, Jeremy

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 23-Undefined Boiler Violations

**SUBCATEGORY** 363. Undefined Boiler Violations.

**CONDITION:** 363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 8/19/2019.

**REQUIREMENT:** 363. Undefined Boiler Violations. An External Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.

---

**Location:** (NCSU) Pulp & Paper Labs Z3

**Location #:** 2154347

**Violations:** 1

431 Dan Allen Dr, , Raleigh, NC 27695-0001, Phone: 919-515-9902

**Contact:** James Lindsey, Pulp & Paper Labs 113B-Z3, Phone: 919-515-9902

---

**Object:** NC431284 - PV - Samuel Pressure Vessel Group - 2020 - 2nd Flr  
Pilot Plt Mezzanine - Active

**Violations This Object:** 1

**COMPANY:** State of North Carolina

**INSPECTOR:** Fish, Emily

**OPENED:** 06/16/2021

**ENTERED BY:** Fish, Emily

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 04-Installation of PRDs NCAC 13-13.0405

**SUBCATEGORY** 452. Set pressure too high.

**CONDITION:** 452. Installation of PRDs NCAC 13-13.0405: Set pressure too high.

**REQUIREMENT:** 452. Replace the pressure relieving device with one with a set pressure no higher than the maximum allowable working pressure as determined by the manufacturer.

---

**Location:** (QUC) Heating Plant

**Location #:** 1832784

**Violations:** 3

1900 Selwyn Ave, , Charlotte, NC 28274-0001, Phone: 704-337-2200

**Contact:** Queens University Of Charlotte, Phone: 704-337-2201

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

**Object:** NC068205 - Boiler - BE&S - 1963 - Blr Rm #4 - Active

**Violations This Object:** 3

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Clay, Steven D.  
**OPENED:** 05/13/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409  
**SUBCATEGORY** 006. Low water cutoff device inoperative or bypassed.  
**CONDITION:** 006. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device inoperative or bypassed.  
**REQUIREMENT:** 006. Repair or replace the inoperable low water fuel cutoff control and test to ensure proper operation.

**ENTERED BY:** Putek, Terry  
**CLOSED BY:**

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Clay, Steven D.  
**OPENED:** 05/13/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 19-Waterside  
**SUBCATEGORY** 320. Accumulation of oil.  
**CONDITION:** 320. Waterside: Accumulation of oil.  
**REQUIREMENT:** 320. Clean the watersides of all oil contamination.

**ENTERED BY:** Putek, Terry  
**CLOSED BY:**

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Clay, Steven D.  
**OPENED:** 05/13/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 394. Valve inoperative.  
**CONDITION:** 394. Operation of PRDs NCAC 13-13.0405: Valve inoperative.  
**REQUIREMENT:** 394. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

**ENTERED BY:** Putek, Terry  
**CLOSED BY:**

**Location:** (SWAIN CS) Swain County High

**Location #:** 1834129

**Violations:** 1

1415 Fontana Rd, , Bryson City, NC 28713-6951, Phone: 828-488-2152

**Contact:** John Haigler, Head Custodian, Swain County High, Phone: 828-488-2152

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC320171 - Boiler - Peerless - 1999 - New Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 04/19/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 13-Burners and Fuel Supply Systems  
**SUBCATEGORY** 232. Gas train has improper venting.  
**CONDITION:** 232. Burners and Fuel Supply Systems: Gas train has improper venting.  
**REQUIREMENT:** 232. Vent the gas train to a safe point .

---

**Location:** (UNCA) Carol Belk Theater **Location #:** 1903686 **Violations:** 1  
1 University Hts, , Asheville, NC 28804-3251, Phone: 828-251-6038  
**Contact:** Attn Jay Small, HVAC Supervisor, UNC Asheville, Phone: 828-250-3964

---

**Object:** NC299507 - Boiler - Lochinvar - 1999 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 04/06/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 270. Water Leaks.  
**CONDITION:** 270. Boiler Components: Water Leaks. Manifold flange leaking.  
**REQUIREMENT:** 270. Repair the water leaks identified on the inspection report.

---

**Location:** (UNCA) Founders Residence Hall **Location #:** 1903690 **Violations:** 2  
1 University Hts, , Asheville, NC 28804-3251, Phone: 828-251-6038  
**Contact:** Attn Jay Small, HVAC Supervisor, UNC Asheville, Phone: 828-250-3964

---

**Object:** NC203365 - Boiler - PVI Industries - 1981 - Highrise Dorm Equip Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 04/06/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 276. Manway gasket leaks.  
**CONDITION:** 276. Boiler Components: Manway gasket leaks.  
**REQUIREMENT:** 276. Replace the leaking manway gasket. If weld repairs are required to reestablish the seating surface, a qualified "R" certificate holder is necessary to perform the work.

---

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC203366 - Boiler - PVI Industries - 1981 - Highrise Dorm Equip Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 04/06/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 276. Manway gasket leaks.  
**CONDITION:** 276. Boiler Components: Manway gasket leaks.  
**REQUIREMENT:** 276. Replace the leaking manway gasket. If weld repairs are required to reestablish the seating surface, a qualified "R" certificate holder is necessary to perform the work.

---

**Location:** (UNCC) Belk Residence Hall **Location #:** 3337127 **Violations:** 2  
9201 University City Blvd, , Charlotte, NC 28223-0001, Phone: 704-687-2199  
**Contact:** Attn Kelly Herron, UNC Charlotte, Phone: 704-687-0567

---

**Object:** NC393689 - PV - Lochinvar - 2012 - Mech Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Clay, Steven D.  
**OPENED:** 05/07/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 05-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 474. Valve inoperative.  
**CONDITION:** 474. Operation of PRDs NCAC 13-13.0405: Valve inoperative. PRD capacity too low. Three boilers feed tank.  
**REQUIREMENT:** 474. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

---

**Object:** NC393690 - PV - Lochinvar - 2012 - Mech Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Clay, Steven D.  
**OPENED:** 05/07/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 05-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 474. Valve inoperative.  
**CONDITION:** 474. Operation of PRDs NCAC 13-13.0405: Valve inoperative. PRD capacity is too low. Three boilers feed tank.  
**REQUIREMENT:** 474. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

---

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Location:** (UNCC) Cameron Hall **Location #:** 2316833 **Violations:** 1  
9201 University City Blvd, , Charlotte, NC 28223-0001, Phone: 704-687-2199  
**Contact:** Attn Kelly Herron, UNC Charlotte, Phone: 704-687-0567

**Object:** NC381153 - Boiler - Cleaver Brooks - 2010 - Equip Rm 42 - Active **Violations This Object:** 1

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Smith, Jeremy  
**OPENED:** 03/03/2021 **ENTERED BY:** Smith, Jeremy  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 8/26/2019.  
**REQUIREMENT:** 363. Undefined Boiler Violations. An External Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.

---

**Location:** (UNCC) Regional Utility Plt 1 **Location #:** 1930002 **Violations:** 1  
9201 University City Blvd, , Charlotte, NC 28223-0001, Phone: 704-687-6993  
**Contact:** Attn Kelly Herron, UNC Charlotte, Phone: 704-687-0567

**Object:** NC328646 - Boiler - Hurst - 2002 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Clay, Steven D.  
**OPENED:** 02/10/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 275. Tube/tube ends leak.  
**CONDITION:** 275. Boiler Components: Tube/tube ends leak. Boiler is down for repairs.  
**REQUIREMENT:** 275. Repair the leaking tubes/tube ends. If weld repairs are required, a qualified "R" certificate holder is necessary to perform the work.

---

**Location:** (UNCC) Scott Hall **Location #:** 1930011 **Violations:** 1  
9201 University City Blvd, , Charlotte, NC 28223-0001, Phone: 704-687-2197  
**Contact:** Attn Kelly Herron, UNC Charlotte, Phone: 704-687-0567

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC383706 - PV - LTC - 2010 - Blr Rm - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Clay, Steven D.  
**OPENED:** 05/07/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 05-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 474. Valve inoperative.  
**CONDITION:** 474. Operation of PRDs NCAC 13-13.0405: Valve inoperative. PRD capacity is too low. Two boilers feed tank.  
**REQUIREMENT:** 474. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

---

**Location:** (UNCG) Jefferson Suites

**Location #:** 2959032

**Violations:** 2

1501 Spring Garden St, , Greensboro, NC 27403-2437, Phone: 704-309-2534

**Contact:** Richard Ratcliffe, Maintenance, UNC Greensboro, Phone: 336-334-5554, Cell:336-880-7092

---

**Object:** NC320748 - Boiler - Lochinvar - 2010 - Mech Rm - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 06/07/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409  
**SUBCATEGORY** 012. Flow switch inoperative or bypassed.  
**CONDITION:** 012. LWCO and Flow Sensing Devices NCAC 13-13.0409: Flow switch inoperative or bypassed.  
**REQUIREMENT:** 012. Repair/Replace the inoperative flow switch in order to correct this condition. Once complete, test the flow switch to ensure proper operation.

---

**Object:** NC385801 - Boiler - Patterson Kelley - 2010 - Blr Rm - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 06/07/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 13-Burners and Fuel Supply Systems  
**SUBCATEGORY** 235. No emergency fuel shut off switch.  
**CONDITION:** 235. Burners and Fuel Supply Systems: Emergency fuel shutoff switch failed to secure boiler when tested.  
**REQUIREMENT:** 235. Repair/replace the inoperative emergency fuel shutoff switch in order to correct this condition. If replacement is required, emergency fuel shutoff switches must be installed at exit from the mechanical room. Once complete test to ensure proper operation.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Location:** (UNCG) School of Nursing **Location #:** 1930692 **Violations:** 1  
800 Oakland Ave, , Greensboro, NC 27412-5059, Phone: 336-334-3684

**Contact:** Christian Rodriguez, Maintenance, UNC Greensboro, Phone: 336-334-5684, Cell:336-402-6755

**Object:** NC321819 - PV - Cemline - 2000 - School Of Nursing Mech Rm - **Violations This Object:** 1  
Active

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 06/08/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 07-Undefined Pressure Vessels Violations  
**SUBCATEGORY** 479. Undefined Pressure Vessels Violations.  
**CONDITION:** 479. Undefined Pressure Vessels Violations: Cap on pipe nipple connected to vessel leaking/corroded.  
**REQUIREMENT:** 479. Undefined Pressure Vessels Violations; Replace the leaking/corroded cap and/or pipe nipple in order to correct this condition.

---

**Location:** (UNCG) Tower Village **Location #:** 1930746 **Violations:** 2  
800 Oakland Ave, , Greensboro, NC 27412-5059, Phone: 336-334-5684

**Contact:** Attn Jon Soter, UNC Greensboro, Phone: 336-256-0434, Cell:336-587-1440

**Object:** NC413562 - Boiler - AIC Tuchom - 2017 - Mech Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 06/07/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations: Boiler not operating at time of inspection; flow switch and pressure relief device (PRD) could not be tested to verify proper operation.  
  
Schedule a reinspection at a time when the boiler is operating so that the PRD and LWCO may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the controls is also acceptable  
**REQUIREMENT:** 363. Undefined Boiler Violations. Schedule a reinspection at a time when the boiler is operating so that the flow switch and PRD may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the controls is also acceptable



# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC413563 - Boiler - AIC Tuchom - 2017 - Mech Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 06/07/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations. Boiler not operating at time of inspection; flow switch and pressure relief device (PRD) could not be tested to verify proper operation.  
**REQUIREMENT:** 363. Undefined Boiler Violations. Schedule a reinspection at a time when the boiler is operating so that the flow switch and PRD may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the controls is also acceptable

---

**Location:** (WILSON CO) Maintenance Bldg **Location #:** 1844389 **Violations:** 1  
113 Nash St E, , Wilson, NC 27893-4054, Phone: 252-399-2843  
**Contact:** Attn Ted Boswell, Director of Maintenance, Wilson County Government, Phone: 252-265-5973

---

**Object:** NC410051 - Boiler - Weil-McLain - 2017 - Bsmt Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Harrell, Danny  
**OPENED:** 05/12/2021 **ENTERED BY:** Harrell, Danny  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 09-Bottom Blow and Drain Systems NCAC 13-13.0411  
**SUBCATEGORY** 152. Valve(s) hand wheel or lever handle missing.  
**CONDITION:** 152. Bottom Blow and Drain Systems NCAC 13-13.0411: Valve(s) hand wheel or lever handle missing.  
**REQUIREMENT:** 152. Replace missing hand wheel or lever on bottom blow off valve. Contact Danny Harrell @ 919-500-3098 when the repair is completed to schedule a re-inspection.

---

**Location:** A Cleaner World #188 **Location #:** 1761476 **Violations:** 1  
2527 Eastchester Dr, , High Point, NC 27265-1448, Phone: 336-882-8621  
**Contact:** Attn Kevin Lawson, Maintenance, Tri State Laundry Equipment Co, Phone: 336-804-0031

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC376430 - Boiler - Parker - 2008 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Leonard, Shannon D.

**OPENED:** 05/13/2021

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 03-Water Gauge Glass NCAC 13-13.0408

**SUBCATEGORY** 058. Leaking.

**CONDITION:** 058. Water Gauge Glass NCAC 13-13.0408: Leaking: Water gauge glass leaking.

**REQUIREMENT:** 058. Repair or replace the leaking gauge and test to ensure proper operation.

---

**Location:** Centerview Baptist Church

**Location #:** 1775266

**Violations:** 2

415 Walter St, , Kannapolis, NC 28083-4559, Phone: 704-933-2331

**Contact:** There is no contact information available for this location.

---

**Object:** NC215059 - Boiler - Weil-McLain - 1985 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Leonard, Shannon D.

**OPENED:** 05/28/2021

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 23-Undefined Boiler Violations

**SUBCATEGORY** 363. Undefined Boiler Violations.

**CONDITION:** 363. Undefined Boiler Violations. Boiler not operating at time of inspection; low water cutoffs (LWCO) and pressure relief devices (PRD) could not be tested to verify proper operation.

**REQUIREMENT:** 363. Undefined Boiler Violations. Schedule a reinspection of this boiler at a time when the boiler operating so that the LWCO and PRD's may be tested to verify proper operation. As an alternative, a detailed service report or boiler log that includes documentation of this successful testing of these controls is also acceptable.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

**Object:** NC344241 - Boiler - Peerless - 2001 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 05/28/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 395. Valve leaking.  
**CONDITION:** 395. Operation of PRDs NCAC 13-13.0405: Valve leaking: Pressure relief device (PRD) leaking.  
**REQUIREMENT:** 395. Replace the leaking PRD with an ASME/NB stamped PRD having a set pressure of 50 PSI or less and a relieving capacity of 971,000 BTU/Hour or more. The replacement PRD must be equipped with a try-lever and the PRD discharge must be piped full size to a safe location (I.E. within 6" of the boiler room floor).

**Location:** Clariant Corp West Plt

**Location #:** 292853

**Violations:** 2

625 E Catawba Ave, , Mount Holly, NC 28120-2270, Phone: 704-822-2168

**Contact:** Attn Dewayne Moore, Maintenance Planner, Clariant Corp West Plt, Phone: 704-822-2049, Cell:980-319-

**Object:** NC165549 - Boiler - Cleaver Brooks - 1976 - 250/500 HP Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** State of North Carolina  
**INSPECTOR:** Smith, Jeremy  
**OPENED:** 03/03/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 12/17/2019.  
**REQUIREMENT:** 363. Undefined Boiler Violations. An External Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC237004 - Boiler - Cleaver Brooks - 1988 - 250/500 HP Blr Rm - Active      **Violations This Object:** 1

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Smith, Jeremy  
**OPENED:** 03/03/2021      **ENTERED BY:** Smith, Jeremy  
**CLOSED:**      **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 12/17/2019.  
**REQUIREMENT:** 363. Undefined Boiler Violations. An External Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.

---

**Location:** David Price Auto Works      **Location #:** 1793444      **Violations:** 1  
603 Monroe St, , Eden, NC 27288-6110, Phone: 336-623-2460  
**Contact:** Attn David Price, Owner, David Price Auto Works Llc, Phone: 336-623-2460

---

**Object:** NC383120 - PV - Manchester - 2008 - Storage Rm - Active      **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 05/17/2021      **ENTERED BY:** Judd, Janie  
**CLOSED:**      **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 04-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 452. Set pressure too high.  
**CONDITION:** 452. Installation of PRDs NCAC 13-13.0405: Set pressure too high: Pressure Relief Device (PRD) set pressure (175 PSI) exceeds maximum allowable working pressure of air tank (150 PSI)  
**REQUIREMENT:** 452. Replace the improperly sized PRD with an ASME/NB stamped PRD having a set pressure of 150 PSI or less and a relieving capacity of 25 SCFM or more. This air tank must remain out of service until a new properly rated PRD is installed.

---

**Location:** Electric Glass Fiber America      **Location #:** 210057      **Violations:** 1  
473 New Jersey Church Rd, , Lexington, NC 27292-6726, Phone: 336-357-8151  
**Contact:** Attn William Gallagher, Electric Glass Fiber America Llc, Phone: 336-357-8151, Cell:704-662-2845

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC215328 - PV - Arrow - 1978 - Unloading Shed Silica - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 06/09/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 05-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 477. Try lever inoperative.  
**CONDITION:** 477. Operation of PRDs NCAC 13-13.0405: Try lever inoperative.  
**REQUIREMENT:** 477. Install an ASME/NB stamped PRD having a set pressure of 90 PSI or less and a relieving capacity sufficient to fully relieve pressure on the vessel. The replacement PRD must be equipped with a try-lever.

---

**Location:** Embassy Suites RDU Brier Creek **Location #:** 2698447 **Violations:** 1  
8001 Arco Corporate Dr, , Raleigh, NC 27617-2010, Phone: 919-572-2200  
**Contact:** Attn Gary Patel, Maintenance Mgr, Embassy Suites RDU Brier Creek, Phone: 919-484-0500

---

**Object:** NC380858 - Boiler - State Industries - 2009 - Wtr Htr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** SORRENTINO, SEAN  
**OPENED:** 02/25/2021 **ENTERED BY:** Keyes, Amanda  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 270. Water Leaks.  
**CONDITION:** 270. Boiler Components: Water Leaks.  
**REQUIREMENT:** 270. Repair the water leaks identified on the inspection report.

---

**Location:** Foothills Equestrian Nature Center **Location #:** 1790495 **Violations:** 1  
3381 Hunting Country Rd, , Tryon, NC 28782-6669, Phone: 828-859-9012  
**Contact:** There is no contact information available for this location.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC330138 - Boiler - Burnham - 2001 - Blr Rm Bsmt - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 06/07/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations. Boiler is out of service but has not been properly disconnected.  
**REQUIREMENT:** 363. Undefined Boiler Violations. Disconnect the boiler from all sources of potential energy including fuel and electricity.

---

**Location:** Fulton Family YMCA **Location #:** 1844837 **Violations:** 2  
385 W Hanes Mill Rd, , Winston Salem, NC 27105-9626, Phone: 336-661-1093  
**Contact:** There is no contact information available for this location.

---

**Object:** NC329027 - Boiler - Weil-McLain - 2000 - Pool Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 06/15/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations: Boiler not operating at time of inspection pressure relief device (PRD) and low water cutoff (LWCO) could not be tested to verify proper operation.  
**REQUIREMENT:** 363. Undefined Boiler Violations: Schedule a reinspection at a time when the boiler is operating so that the PRD and LWCO may be tested to verify proper operation. As an alternative a detailed service report or boiler log that includes documentation of the successful testing of these controls is also acceptable.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC412589 - Boiler - Raypak - 2015 - Blr Rm - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 06/15/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations. Boiler not operating at time of inspection pressure relief device (PRD) and low water cutoff (LWCO) could not be tested to verify proper operation.  
**REQUIREMENT:** 363. Undefined Boiler Violations. Schedule a reinspection at a time when the boiler is operating so that the PRD and LWCO may be tested to verify proper operation. As an alternative a detailed service report or boiler log that includes documentation of the successful testing of these controls is also acceptable.

---

**Location:** Heddens Collision Center

**Location #:** 1796474

**Violations:** 1

2366 New Leicester Hwy Ste B, , Asheville, NC 28806-7424, Phone: 828-683-4725

**Contact:** Drew Gerahrdt, Owner, Heddens Collision Center,

---

**Object:** NC422456 - PV - Morganton - 2012 - Outside - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 06/02/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 04-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 452. Set pressure too high.  
**CONDITION:** 452. Installation of PRDs NCAC 13-13.0405: Set pressure too high. Mawp is 200 psi and SV #1 is 217 psi.  
**REQUIREMENT:** 452. Replace the pressure relieving device with one with a set pressure no higher than the maximum allowable working pressure as determined by the manufacturer.

---

**Location:** Hertford Baptist Church

**Location #:** 1796868

**Violations:** 1

124 W Market St, , Hertford, NC 27944-1151, Phone: 252-426-7460

**Contact:** Hertford Baptist Church, Phone: 252-426-7460



# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC245123 - Boiler - Weil-McLain - 1990 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** State of North Carolina

**INSPECTOR:** Harrell, Danny

**OPENED:** 03/08/2021

**ENTERED BY:** Harrell, Danny

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 16-Boiler Components

**SUBCATEGORY** 270. Water Leaks.

**CONDITION:** 270. Boiler Components: Water Leaks. Boiler is leaking between the rear two sections.

**REQUIREMENT:** 270. Repair the water leaks identified on the inspection report. Contact Danny Harrell @ 919-500-3098 when the repair is completed to schedule a re-inspection.

---

**Location:** Hudson Building

**Location #:** 1799097

**Violations:** 1

118 W State St, , Black Mountain, NC 28711-3419, Phone: 828-669-8711

**Contact:** Attn J Richard Hudson III, Owner, Hudson Building, Phone: 828-669-8711, Cell:828-777-5711

---

**Object:** NC148875 - Boiler - Burnham - 1975 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Possidente, James

**OPENED:** 04/26/2021

**ENTERED BY:** Putek, Terry

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 12-Casing, Stack Breeching and Flue

**SUBCATEGORY** 211. Combustion gas leaks.

**CONDITION:** 211. Casing, Stack Breeching and Flue: Combustion gas leaks. Flue has two small holes.

**REQUIREMENT:** 211. Repair all combustion gas leaks in the casing, stack breeching, or flue.

---

**Location:** Kernersville Family YMCA

**Location #:** 1845634

**Violations:** 2

1113 W Mountain St, , Kernersville, NC 27284-2125, Phone: 336-996-2231

**Contact:** There is no contact information available for this location.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

**Object:** NC399650 - Boiler - Stemist - 2013 - Suana - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Leonard, Shannon D.

**OPENED:** 10/14/2020

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 23-Undefined Boiler Violations

**SUBCATEGORY** 363. Undefined Boiler Violations.

**CONDITION:** 363. Undefined Boiler Violations. Boiler not operating at time of inspection; low water cutoff (LWCO) and pressure relief device (PRD) could not be tested to verify proper operation.

**REQUIREMENT:** 363. Undefined Boiler Violations. Schedule a reinspection at a time when the boiler is operating so that the LWCO and PRD may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the flow switch and PRD is also acceptable.

**Object:** NC418867 - Boiler - Teledyne Laars - 1998 - Hot Tub Wtr Htr - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Leonard, Shannon D.

**OPENED:** 10/14/2020

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 23-Undefined Boiler Violations

**SUBCATEGORY** 363. Undefined Boiler Violations.

**CONDITION:** 363. Undefined Boiler Violations. Boiler not operating at time of inspection; flow switch and pressure relief device (PRD) could not be tested to verify proper operation.

**REQUIREMENT:** 363. Undefined Boiler Violations. Schedule a reinspection at a time when the boiler is operating so that the flow switch and PRD may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the flow switch and PRD is also acceptable.

**Location:** La Quinta Inn & Suites

**Location #:** 1804615

**Violations:** 4

2020 Griffith Rd, , Winston Salem, NC 27103-5509, Phone: 336-765-8777

**Contact:** Attn Kim Joyner, General Manager, La Quinta Inn & Suites, Phone: 336-765-8777

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC293074 - Boiler - A O Smith - 1998 - Blr Rm 2nd Flr - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 04/19/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 06-Thermometer NCAC 13-13.0410  
**SUBCATEGORY** 111. Thermometer inoperative.  
**CONDITION:** 111. Thermometer NCAC 13-13.0410: Thermometer inoperative.  
**REQUIREMENT:** 111. Replace inoperative thermometer at/in the boiler outlet to measure the temperature in degrees Fahrenheit of the water. The thermometer shall have a range of approximately 2 times the intended operating temperature but not less than 1 1/2 times the intended operating temperature, nor more than 4 times the intended operating temperature.

---

**Object:** NC394482 - PV - State Industries - 2013 - Blr Rm 2nd Flr - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 04/19/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 04-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 459. Discharge piping too small.  
**CONDITION:** 459. Installation of PRDs NCAC 13-13.0405: Discharge piping too small: Discharge piping too small: Pressure relief device (PRD) discharge header piping for this hot water storage tank and two others that are connected to the header is too small.  
**REQUIREMENT:** 459. Replace the PRD discharge header piping with piping having a cross sectional area of 3 inches or greater in order to correct this condition.

---

**Object:** NC394483 - PV - State Industries - 2013 - Blr Rm 2nd Flr - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 04/19/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 04-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 459. Discharge piping too small.  
**CONDITION:** 459. Installation of PRDs NCAC 13-13.0405: Discharge piping too small: Discharge piping too small: Pressure relief device (PRD) discharge header piping for this hot water storage tank and two others that are connected to the header is too small.  
**REQUIREMENT:** 459. Replace the PRD discharge header piping with piping having a cross sectional area of 3 inches or greater in order to correct this condition.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC394484 - PV - State Industries - 2013 - Blr Rm 2nd Flr - Active      **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 04/19/2021      **ENTERED BY:** Judd, Janie  
**CLOSED:**      **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 04-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 459. Discharge piping too small.  
**CONDITION:** 459. Installation of PRDs NCAC 13-13.0405: Discharge piping too small: Pressure relief device (PRD) discharge header piping for this hot water storage tank and two others that are connected to the header is too small.  
**REQUIREMENT:** 459. Replace the PRD discharge header piping with piping having a cross sectional area of 3 inches or greater in order to correct this condition.

---

**Location:** Lakewood Baptist Church      **Location #:** 1804849      **Violations:** 1  
806 Klutz St, , Kannapolis, NC 28081-7512, Phone: 704-938-4144  
**Contact:** Bobby Mullis, Elder, Lakewood Baptist Church, Phone: 704-933-5530, Cell:704-938-4144

---

**Object:** NC268877 - Boiler - Columbia - 1970 - Bsmt Blr Rm - Active      **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Clay, Steven D.  
**OPENED:** 05/26/2021      **ENTERED BY:** Putek, Terry  
**CLOSED:**      **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409  
**SUBCATEGORY** 011. The control is installed with isolation valves.  
**CONDITION:** 011. LWCO and Flow Sensing Devices NCAC 13-13.0409: The control is installed with isolation valves.  
**REQUIREMENT:** 011. Remove the isolation valve(s) between the boiler and the low-water fuel cutoff or install valves that automatically return to open when released.

---

**Location:** Longleaf Neuro Medical Treatment Center      **Location #:** 1813141      **Violations:** 1  
4761 Ward Blvd, , Wilson, NC 27893-4359, Phone: 252-399-2112  
**Contact:** There is no contact information available for this location.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC220872 - Boiler - Cleaver Brooks - 1987 - Blr Rm 3 - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** SORRENTINO, SEAN  
**OPENED:** 03/15/2021 **ENTERED BY:** Keyes, Amanda  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 275. Tube/tube ends leak.  
**CONDITION:** 275. Boiler Components: Tube/tube ends leak.  
**REQUIREMENT:** 275. Repair the leaking tubes/tube ends. If weld repairs are required, a qualified "R" certificate holder is necessary to perform the work.

---

**Location:** Marlowe Van Loan Corp **Location #:** 1223163 **Violations:** 1  
1224 W Ward Ave, , High Point, NC 27260-1534, Phone: 336-886-7126  
**Contact:** Attn Paul Tharp, Marlowe Van Loan Corp, Phone: 336-886-7126

---

**Object:** NC243228 - Boiler - Burnham - 1989 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 05/26/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 10-Feedwater, Condensate/Rtrn Sys NCAC 13-13.0411  
**SUBCATEGORY** 173. Leaking pipe/pipe joints.  
**CONDITION:** 173. Feedwater, Condensate/Rtrn Sys NCAC 13-13.0411: Leaking pipe/pipe joints: Leak at union on feed water plumbing.  
**REQUIREMENT:** 173. Repair or replace leaking piping/pipe joints: Repair/replace the leaking feed water plumbing connections with proper schedule 80 black steel pipe.

---

**Location:** Moran Automotive **Location #:** 1782668 **Violations:** 2  
412 N Main St, , Randleman, NC 27317-1616, Phone: 336-498-4300  
**Contact:** Attn Eddie Moran, Moran Automotive, Phone: 336-498-4300

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC344535 - PV - Steel Fab - 2002 - Comp Shed - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 06/16/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 06-Undefined Pressure Relieving Devices Violations  
**SUBCATEGORY** 478. Undefined Pressure Relieving Devices Violations.  
**CONDITION:** 478. Undefined Pressure Relieving Devices Violations: Pressure gauge inoperative.  
**REQUIREMENT:** 478. Undefined Pressure Relieving Devices Violations: Replace the inoperative pressure gauge in order to correct this condition. The replacement pressure gauge must have a maximum measuring range of between 1.5 times and 4 times the normal operating pressure of this air tank.

**ENTERED BY:** Judd, Janie

**CLOSED BY:**

---

**Object:** NC403275 - PV - Morganton - 2015 - Comp Shed - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 06/16/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 06-Undefined Pressure Relieving Devices Violations  
**SUBCATEGORY** 478. Undefined Pressure Relieving Devices Violations.  
**CONDITION:** 478. Undefined Pressure Relieving Devices Violations. Pressure gauge inoperative.  
**REQUIREMENT:** 478. Undefined Pressure Relieving Devices Violations. Replace the inoperative pressure gauge in order to correct this condition. The replacement pressure gauge must have a maximum measuring range of between 1.5 times and 4 times the normal operating pressure of this air tank.

**ENTERED BY:** Judd, Janie

**CLOSED BY:**

---

**Location:** New Zion Missionary Baptist Church

**Location #:** 1814551

**Violations:** 1

408 Martin Luther King Jr Dr, , Greensboro, NC 27406-1623, Phone: 336-272-8441

**Contact:** There is no contact information available for this location.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC355133 - Boiler - H B Smith - 2003 - Blr Rm Bsmt - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Leonard, Shannon D.

**OPENED:** 05/26/2021

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 23-Undefined Boiler Violations

**SUBCATEGORY** 363. Undefined Boiler Violations.

**CONDITION:** 363. Undefined Boiler Violations: Boiler not operating at time of inspection safety devices could not be tested to verify proper operation.

**REQUIREMENT:** 363. Undefined Boiler Violations: Schedule a reinspection at a time when the boiler is operating so that safety devices may be tested. As an alternative a detailed service report or log that includes documentation of the successful testing of these controls is also acceptable.

---

**Location:** Oak Cleaners

**Location #:** 2060057

**Violations:** 1

208 Eastchester Dr, , High Point, NC 27262-7715, Phone: 336-886-6200

**Contact:** Attn Kwangbeom Jeong, Oak Cleaners Inc, Phone: 336-706-4315

---

**Object:** NC365334 - Boiler - Hurst - 2006 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** State of North Carolina

**INSPECTOR:** Johnson, Dean

**OPENED:** 02/10/2021

**ENTERED BY:** Johnson, Dean

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 23-Undefined Boiler Violations

**SUBCATEGORY** 363. Undefined Boiler Violations.

**CONDITION:** 363. Undefined Boiler Violations. Lower left handhole is corroded from original thickness.

**REQUIREMENT:** 363. Undefined Boiler Violations. Welding is required for this repair, such welding must be made by a 'R' stamp holder. R-1 Report of Repair must be returned to this Inspector or the boiler must be removed from service.

---

**Location:** Paul J Rizzo Conference Center

**Location #:** 1817817

**Violations:** 1

150 Dubose Home Ln, , Chapel Hill, NC 27517-8944, Phone: 919-913-2098

**Contact:** There is no contact information available for this location.



# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC364029 - Boiler - Lochinvar - 2006 - Outside Dubose House - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Ollison, Jr., James C.  
**OPENED:** 06/11/2020 **ENTERED BY:** Keyes, Amanda  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 396. Missing nameplate.  
**CONDITION:** 396. Operation of PRDs NCAC 13-13.0405: Missing nameplate.  
**REQUIREMENT:** 396. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

---

**Location:** Pender Packing Co **Location #:** 1818140 **Violations:** 2  
4520 NC Highway 133, , Rocky Point, NC 28457-9108, Phone: 910-675-3311  
**Contact:** Attn Danny Baker, Owner, Pender Packing Co Inc, Phone: 910-675-3311

---

**Object:** NC188826 - Boiler - York Shipley - 1979 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Kirkland, John  
**OPENED:** 04/23/2021 **ENTERED BY:** Kirkland, John  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 275. Tube/tube ends leak.  
**CONDITION:** 275. Boiler Components: Tube/tube ends leak.  
**REQUIREMENT:** 275. Repair the leaking tubes/tube ends. If weld repairs are required, a qualified "R" certificate holder is necessary to perform the work. Once the repairs have been made, contact John Kirkland @ 252-204-7789 for a follow-up inspection.

---

---

**Object:** NC411019 - Boiler - Camus - 2015 - Electric Panel Rm - Active **Violations This Object:** 1

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Kirkland, John  
**OPENED:** 04/23/2021 **ENTERED BY:** Kirkland, John  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 397. Try lever inoperative.  
**CONDITION:** 397. Operation of PRDs NCAC 13-13.0405: Try lever inoperative.  
**REQUIREMENT:** 397. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified. Once repairs are complete, contact John Kirkland @ 252-204-7789 for a follow-up inspection.

---

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External  
Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status:  
Active; Order Results by: Location Name; Then Order by: Address;

---

**Location:** Prestige Dry Cleaners **Location #:** 543315 **Violations:** 1  
3204 Randleman Rd Ste A, , Greensboro, NC 27406-6529, Phone: 336-378-1617  
**Contact:** Attn Youn Choul Park, Prestige Dry Cleaners, Phone: 336-378-1617

**Object:** NC368248 - Boiler - Fulton - 2007 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 05/21/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations: Used boiler relocated and installed at this location without completion of internal certificate inspection prior to placing boiler in service.  
**REQUIREMENT:** 363. Undefined Boiler Violations: Complete an internal certificate inspection of this boiler as soon as possible in order to address this issue.

---

**Location:** Randolph Asheboro YMCA **Location #:** 1822939 **Violations:** 1  
343 NC Highway 42 N, , Asheboro, NC 27203-7919, Phone: 336-625-1976  
**Contact:** Morris Ebanks, Maintenance, Randolph Asheboro YMCA, Phone: 336-629-1976

**Object:** NC344573 - Boiler - Pacific Steam - 2002 - Steam Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 06/01/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations: Electric steam generator not operating at time of inspection; safety devices not be tested to verify proper operation.  
**REQUIREMENT:** 363. Undefined Boiler Violations: Schedule a reinspection at a time when this electric steam generator is operating so that the safety device may be tested to verify proper operation. As

---

**Location:** Reuter Family YMCA **Location #:** 1824034 **Violations:** 1  
3 Town Square Blvd, , Asheville, NC 28803-5000, Phone: 828-651-9622  
**Contact:** Dennis DiPalma, Property Manager, Reuter Family YMCA, Phone: 828-575-2918

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC341897 - Boiler - Steamaster - 2003 - Pool Sauna Mech Rm 172A - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 05/12/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 270. Water Leaks.  
**CONDITION:** 270. Boiler Components: Water Leaks. Boiler appears to be leaking due to water on the floor around vessel.  
**REQUIREMENT:** 270. Repair the water leaks identified on the inspection report.

---

**Location:** Ride With Pride Car Wash #5 **Location #:** 1824444 **Violations:** 2  
218 Standard St, , Elkin, NC 28621-3456, Phone: 336-902-3118  
**Contact:** There is no contact information available for this location.

---

**Object:** NC283446 - Boiler - Raypak - 1995 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Parker, Richard  
**OPENED:** 06/01/2021 **ENTERED BY:** Parker, Richard  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Overdue for inspection.  
**REQUIREMENT:** 363. Contact inspector and schedule inspection.

contact Richard Parker @ 336-202-8341

---

**Object:** NC349992 - PV - Melben - 1998 - Equip Rm - Active **Violations This Object:** 1

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Parker, Richard  
**OPENED:** 06/01/2021 **ENTERED BY:** Parker, Richard  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 07-Undefined Pressure Vessels Violations  
**SUBCATEGORY** 479. Undefined Pressure Vessels Violations.  
**CONDITION:** 479. Overdue for inspection.  
**REQUIREMENT:** 479. Contact inspector and schedule inspection.

contact Richard Parker @ 336-202-8341

---

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Location:** St Enoch Lutheran Church **Location #:** 606783 **Violations:** 1  
701 Campbell Rd, , Kannapolis, NC 28081-9703, Phone: 704-933-5094/704-467-2466  
**Contact:** Carl Raatz, Grounds Committee, St Enoch Lutheran Church, , Cell:704-467-2466

**Object:** NC362489 - Boiler - H B Smith - 2006 - Lower Level Sanctuary **Violations This Object:** 1  
Bldg - Active

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 05/28/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 395. Valve leaking.  
**CONDITION:** 395. Operation of PRDs NCAC 13-13.0405: Valve leaking: Pressure relief device (PRD) leaking.  
**REQUIREMENT:** 395. Replace the leaking PRD with an ASME/NB stamped PRD having a set pressure of 80 PSI or less and a relieving capacity of 1,066,000 BTU/HR or more. The replacement PRD must be equipped with a try lever and the PRD discharge must be piped full size to a safe location.

---

**Location:** Statesville Family YMCA **Location #:** 1845601 **Violations:** 2  
828 Wesley Dr, , Statesville, NC 28677-3355, Phone: 704-873-9622  
**Contact:** Paxton Hix, Facilities Director, Statesville Family YMCA, , Cell:704-880-4915

**Object:** NC265007 - Boiler - Reimers - 1993 - Mens Steam Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 12/16/2020 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations. electrical steam generator not operating at time of inspection; safety controls could not be tested to verify proper operation.  
**REQUIREMENT:** 363. Undefined Boiler Violations. Schedule a reinspection at a time when the electric steam generator is operating so that the safety controls may be tested to verify proper operation. As an alternative, a detailed service report or log that includes documentation of the successful testing of these controls is also acceptable.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

**Object:** NC380587 - Boiler - Fulton - 2008 - Ladies Steam Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Leonard, Shannon D.

**OPENED:** 12/16/2020

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 23-Undefined Boiler Violations

**SUBCATEGORY** 363. Undefined Boiler Violations.

**CONDITION:** 363. Undefined Boiler Violations: electrical steam generator not operating at time of inspection; safety controls could not be tested to verify proper operation.

**REQUIREMENT:** 363. Undefined Boiler Violations. Schedule a reinspection at a time when the electric steam generator is operating so that the safety controls may be tested to verify proper operation. As an alternative, a detailed service report or log that includes documentation of the successful testing of these controls is also acceptable.

**Location:** Teds Laundromat

**Location #:** 1835016

**Violations:** 3

114 E Main St, , Sylva, NC 28779-2810, Phone: 828-586-2910

**Contact:** Kevin Hensley, Manager, Teds Laundromat, Phone: 828-586-2910

**Object:** NC411982 - Boiler - Sermeta - 2016 - Blr Rm - Active

**Violations This Object:** 3

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Possidente, James

**OPENED:** 04/08/2021

**ENTERED BY:** Putek, Terry

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 02-Pressure Gauges NCAC 13-13.0407

**SUBCATEGORY** 035. Leaking.

**CONDITION:** 035. Pressure Gauges NCAC 13-13.0407: Leaking.

**REQUIREMENT:** 035. Install a pressure gauge on the equipment that is visible to the operator from the floor or work platform. Gauge must be the proper range in accordance with NC Administrative Code, Title 13, Chapter 13, Section .0407.

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Possidente, James

**OPENED:** 04/08/2021

**ENTERED BY:** Putek, Terry

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 11-Exp Tanks & Htng Sys Piping NCAC 13-13.0412

**SUBCATEGORY** 197. Bladder in bladder-type tank perforated or not charged.

**CONDITION:** 197. Exp Tanks & Htng Sys Piping NCAC 13-13.0412: Bladder in bladder-type tank perforated or not charged.

**REQUIREMENT:** 197. Repair or replace bladder/expansion tank with one designed and constructed to ASME Section VIII, Div 1 with an allowable working pressure of at least that of the system.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 04/08/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 395. Valve leaking.  
**CONDITION:** 395. Operation of PRDs NCAC 13-13.0405: Valve leaking.  
**REQUIREMENT:** 395. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

---

**Location:** Top Tobacco **Location #:** 1836886 **Violations:** 1  
204 Top Tobacco Rd, , Lake Waccamaw, NC 28450-2220, Phone: 910-646-3014  
**Contact:** Attn Richard Hopkins, Plant Engineer, Top Tobacco, Phone: 910-646-3014 X4125

**Object:** NC236922 - Boiler - Cleaver Brooks - 1988 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Clay, Steven D.  
**OPENED:** 05/06/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 275. Tube/tube ends leak.  
**CONDITION:** 275. Boiler Components: Tube/tube ends leak. Evidence of leaking tubes and cracked tubes. Retubing underway during inspection by Joe Moore & Co  
**REQUIREMENT:** 275. Repair the leaking tubes/tube ends. If weld repairs are required, a qualified "R" certificate holder is necessary to perform the work.

---

**Location:** Transylvania Regional Hospital **Location #:** 1837355 **Violations:** 1  
260 Hospital Dr, , Brevard, NC 28712-3378, Phone: 828-884-9111  
**Contact:** Gary Hill, Maintenance Lead, Transylvania Regional Hospital, Phone: 828-884-9111

**Object:** NC121286 - PV - Taco - 1973 - Mech Rm 1 - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 05/21/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 04-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 458. Discharge opening directed improperly.  
**CONDITION:** 458. Installation of PRDs NCAC 13-13.0405: Discharge opening directed improperly.  
**REQUIREMENT:** 458. Redirect the discharge to a safe point as required in NCAC 13-13.0405

---

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Location:** Zoom Dry Cleaning **Location #:** 1816329 **Violations:** 1  
200 W Peace St Ste 120, , Raleigh, NC 27603-1183, Phone: 919-838-8530  
**Contact:** Lola Pedron, Manager, Zoom Dry Cleaning, Phone: 919-838-8530

**Object:** NC373829 - Boiler - Fulton - 2007 - Blr Rm - Active **Violations This Object:** 1

---

<b>COMPANY:</b>	State of North Carolina	
<b>INSPECTOR:</b>	Smith, Jeremy	
<b>OPENED:</b>	03/03/2021	<b>ENTERED BY:</b> Smith, Jeremy
<b>CLOSED:</b>		<b>CLOSED BY:</b>
<b>TYPE:</b>	Certificate Blocking	
<b>CATEGORY:</b>	23-Undefined Boiler Violations	
<b>SUBCATEGORY</b>	363. Undefined Boiler Violations.	
<b>CONDITION:</b>	363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 6/18/2019.	
<b>REQUIREMENT:</b>	363. Undefined Boiler Violations. An External Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.	

---

**Violations This Report:** 117

**Locations This Report:** 75