

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Location:** (ASU) Central Steam Plant **Location #:** 1880004 **Violations:** 1  
295 University Dr, , Boone, NC 28607-4382, Phone: 828-262-8633  
**Contact:** Tim Clayton, Steam Plant Supervisor, Central Steam Plant, Phone: 828-262-8633, Cell:828-964-0750

**Object:** NC281773 - Boiler - English - 1996 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Smith, Jeremy  
**OPENED:** 07/01/2021 **ENTERED BY:** Smith, Jeremy  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 12/3/2019.  
**REQUIREMENT:** 363. Undefined Boiler Violations. An External Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.

---

**Location:** (BLADEN) County Courthouse **Location #:** 1768779 **Violations:** 1  
106 E Broad St, , Elizabethtown, NC 28337-8999, Phone: 910-862-6785  
**Contact:** Bladen County Government, Phone: 910-862-6780, Cell:910-862-6996

**Object:** NC276421 - Boiler - Weil-McLain - 1995 - Bsmt Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 06/14/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 396. Missing nameplate.  
**CONDITION:** 396. Operation of PRDs NCAC 13-13.0405: Missing nameplate: Pressure relief device missing nameplate  
**REQUIREMENT:** 396. Replace with a ASME/NB certified pressure relief device with a set pressure of not greater than 50 psig, with a relief capacity of not less than 3,270,000 BTU/hr, and with a testing lever.

---

**Location:** (CRAVEN CS) Graham A Barden Elem **Location #:** 1793675 **Violations:** 2  
200 Cedar Dr, , Havelock, NC 28532-2187, Phone: 252-444-5100  
**Contact:** Craven County Public Schools, Phone: 252-514-6380

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

**Object:** NC229320 - Boiler - Weil-McLain - 1988 - Blr Rm - Active

**Violations This Object:** 2

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 06/29/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 24-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 372. Set pressure too high.  
**CONDITION:** 372. Installation of PRDs NCAC 13-13.0405: Pressure Relief Device set pressure too high.  
**REQUIREMENT:** 372. Immediately replace pressure relief devices with ASME certified devices with a set pressure of not greater than 15 psig, with a combined relief capacity of not less than 3550 PPH, and with a testing lever.

**ENTERED BY:** Judd, Janie  
**CLOSED BY:**

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 04/08/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 24-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 371. Inadequate relieving capacity.  
**CONDITION:** 371. Installation of PRDs NCAC 13-13.0405: Inadequate relieving capacity.  
**REQUIREMENT:** 371. Replace one or both pressure relief devices to obtain a capacity of not less than 3550 PPH. Set pressures are to be no greater than 50 psig, and a testing lever be installed on each pressure relief device.

**ENTERED BY:** Judd, Janie  
**CLOSED BY:**

**Location:** (CRAVEN) Judicial Center

**Location #:** 2410700

**Violations:** 1

1100 Clarks Rd, , New Bern, NC 28562-9730, Phone: 252-636-6679

**Contact:** Brian Fultz, Maintenance Tech III, Craven County Judicial Center, Phone: 252-636-6624, Cell:252-671-2189

**Object:** NC375104 - Boiler - Patterson Kelley - 2008 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 07/01/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 395. Valve leaking.  
**CONDITION:** 395. Operation of PRDs NCAC 13-13.0405: Valve leaking: Pressure relief device leaking  
**REQUIREMENT:** 395. Replace pressure relief device with a ASME certified pressure relief device with a set pressure of not greater than 100 psig, with a relief capacity of not less than 1,940,000 BTU/hr, and has a testing lever.

**ENTERED BY:** Judd, Janie  
**CLOSED BY:**

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External  
Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status:  
Active; Order Results by: Location Name; Then Order by: Address;

---

**Location:** (CRAVEN) New Bern Riverfront Convention Center      **Location #:** 1780796      **Violations:** 1  
203 S Front St, , New Bern, NC 28560-2135, Phone: 252-637-1551  
**Contact:** Attn Steve Creel, Maintenance Director, Craven County Government, Phone: 252-636-6613, Cell:252-670-  
**Object:** NC392065 - Boiler - Rheem - 2012 - Wtr Htr #2 Blr Rm - Active      **Violations This Object:** 1

---

<b>COMPANY:</b>	Hartford Steam Boiler	
<b>INSPECTOR:</b>	Rudolph, Jay	
<b>OPENED:</b>	07/01/2021	<b>ENTERED BY:</b> Judd, Janie
<b>CLOSED:</b>		<b>CLOSED BY:</b>
<b>TYPE:</b>	Certificate Blocking	
<b>CATEGORY:</b>	16-Boiler Components	
<b>SUBCATEGORY</b>	270. Water Leaks.	
<b>CONDITION:</b>	270. Boiler Components: Water Leaks.	
<b>REQUIREMENT:</b>	270. Repair the water leaks identified on the inspection report. Replace vessel	

---

**Location:** (DPS-C) Craggy CC - 4630      **Location #:** 1786753      **Violations:** 1  
2992 Riverside Dr, , Asheville, NC 28804-8601, Phone: 828-645-5315  
**Contact:** Mike Ball, Assistant Superintendant Custy/Pps, Craggy CC - 4630, Phone: 828-645-5315 X225  
**Object:** NC337255 - PV - American - 2001 - Bldg 3 Blr Rm - Active      **Violations This Object:** 1

---

<b>COMPANY:</b>	Hartford Steam Boiler	
<b>INSPECTOR:</b>	Possidente, James	
<b>OPENED:</b>	05/10/2021	<b>ENTERED BY:</b> Putek, Terry
<b>CLOSED:</b>		<b>CLOSED BY:</b>
<b>TYPE:</b>	Certificate Blocking	
<b>CATEGORY:</b>	07-Undefined Pressure Vessels Violations	
<b>SUBCATEGORY</b>	479. Undefined Pressure Vessels Violations.	
<b>CONDITION:</b>	479. Undefined Pressure Vessels Violations. Water leaking from upper shell at PRV nipple area.	
<b>REQUIREMENT:</b>	479. Undefined Pressure Vessels Violations. Repair the water leaks identified.	

---

**Location:** (DPS-C) Lanesboro CI - 4865      **Location #:** 1805021      **Violations:** 1  
552 Prison Camp Rd, , Polkton, NC 28135-6118, Phone: 704-695-1013  
**Contact:** NC Dept Of Public Safety - 13101, Phone: 919-716-3422

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

<b>Object:</b> NC340797 - Boiler - Cleaver Brooks - 2002 - Blr Rm - Active		<b>Violations This Object:</b> 1
<b>COMPANY:</b>	Hartford Steam Boiler	
<b>INSPECTOR:</b>	Clay, Steven D.	
<b>OPENED:</b>	06/07/2021	<b>ENTERED BY:</b> Putek, Terry
<b>CLOSED:</b>		<b>CLOSED BY:</b>
<b>TYPE:</b>	Certificate Blocking	
<b>CATEGORY:</b>	23-Undefined Boiler Violations	
<b>SUBCATEGORY</b>	363. Undefined Boiler Violations.	
<b>CONDITION:</b>	363. Undefined Boiler Violations. Boiler could not run due to missing components.	
<b>REQUIREMENT:</b>	363. Undefined Boiler Violations. Boiler is scheduled to be reinspected or disconnected.	

**Location:** (DPS-C) Lanesboro Minimum CI - 3510      **Location #:** 1770840      **Violations:** 3  
248 Prison Camp Rd, , Polkton, NC 28135-6115, Phone: 704-694-2622  
**Contact:** Ernie Thomas, Maintenance Supervisor, Brown Creek CI - 3510, Phone: 704-694-2622 X222 X285

<b>Object:</b> NC251876 - Boiler - Peerless - 1991 - Blr Rm Unit 6 - Active		<b>Violations This Object:</b> 1
<b>COMPANY:</b>	Hartford Steam Boiler	
<b>INSPECTOR:</b>	Clay, Steven D.	
<b>OPENED:</b>	07/19/2021	<b>ENTERED BY:</b> Putek, Terry
<b>CLOSED:</b>		<b>CLOSED BY:</b>
<b>TYPE:</b>	Certificate Blocking	
<b>CATEGORY:</b>	01-LWCO and Flow Sensing Devices NCAC 13-13.0409	
<b>SUBCATEGORY</b>	022. Faulty electrical wiring.	
<b>CONDITION:</b>	022. LWCO and Flow Sensing Devices NCAC 13-13.0409: Faulty electrical wiring. LWCO (float) wired backwards.	
<b>REQUIREMENT:</b>	022. Repair or replace the faulty electrical wiring and test control to ensure proper operation.	

<b>Object:</b> NC251882 - Boiler - Lochinvar - 1991 - Blr Rm Unit 5 - Active		<b>Violations This Object:</b> 1
<b>COMPANY:</b>	Hartford Steam Boiler	
<b>INSPECTOR:</b>	Clay, Steven D.	
<b>OPENED:</b>	07/19/2021	<b>ENTERED BY:</b> Putek, Terry
<b>CLOSED:</b>		<b>CLOSED BY:</b>
<b>TYPE:</b>	Certificate Blocking	
<b>CATEGORY:</b>	24-Installation of PRDs NCAC 13-13.0405	
<b>SUBCATEGORY</b>	378. Discharge opening directed improperly.	
<b>CONDITION:</b>	378. Installation of PRDs NCAC 13-13.0405: Discharge opening directed improperly. Discharge piping not installed on PRD.	
<b>REQUIREMENT:</b>	378. Redirect the discharge to a safe point at required in NCAC 13-13.0405.	

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC396137 - Boiler - Teledyne Laars - 2011 - Outside Admin Bldg - **Violations This Object:** 1  
Active

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Clay, Steven D.  
**OPENED:** 07/22/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations. Boiler would not run for inspection due to controls and hot weather.  
**REQUIREMENT:** 363. Undefined Boiler Violations. Schedule the inspection when the boiler is in operation so that safety devices can be tested.

---

---

**Location:** (DPS-C) NCCIW - 3010  
1034 Bragg St, , Raleigh, NC 27610-3846, Phone: 919-733-4340  
**Location #:** 1779964 **Violations:** 2  
**Contact:** Phillip Jones, Maintenance Supervisor, NCCIW - 3010, Phone: 919-508-1690

---

**Object:** NC381483 - Boiler - PVI Industries - 2010 - Falcom Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** SORRENTINO, SEAN  
**OPENED:** 12/08/2020  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 270. Water Leaks.  
**CONDITION:** 270. Boiler Components: Water Leaks.  
**REQUIREMENT:** 270. Repair the water leaks identified on the inspection report. If welding is required, a qualified "R" certificate holder is necessary to perform the repair.

---

**Object:** NC401596 - Boiler - PVI Industries - 2014 - Sparrow N - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** SORRENTINO, SEAN  
**OPENED:** 12/08/2020  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 270. Water Leaks.  
**CONDITION:** 270. Boiler Components: Water Leaks. Tank leaking at unknown location.  
**REQUIREMENT:** 270. Repair the water leaks identified on the inspection report. If welding is required, a qualified "R" certificate holder is necessary to perform the repair.

---

---

**Location:** (DPS-C) Scotland CI - 4860  
22385 McGirts Bridge Rd, , Laurinburg, NC 28352-6602, Phone: 910-844-3078  
**Location #:** 1827655 **Violations:** 1  
**Contact:** William Deese, Maintenance Supervisor, Scotland CI - 4860, Phone: 910-844-3078

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC348249 - PV - McQuay - 2002 - D Central Plt Chiller Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Rudolph, Jay  
**OPENED:** 06/22/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 04-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 460. Seals broken/ missing.  
**CONDITION:** 460. Installation of PRDs NCAC 13-13.0405: Seals broken/ missing: Pressure relief device tamper seal broken.  
**REQUIREMENT:** 460. Replace pressure relief device. Set pressure must not be greater than 200 psig, and must have adequate relief capacity.

---

**Location:** (MH UNIV) Brown Hall **Location #:** 1930569 **Violations:** 3  
150 Joe Anderson Dr, , Mars Hill, NC 28754 , Phone: 828-689-1201  
**Contact:** Attn Henry H Haywood, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:828-206-

---

**Object:** NC338996 - PV - LTC - 2002 - Bsmt Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 03/12/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 02-Manufacturer's Data Report & Nameplate  
**SUBCATEGORY** 431. Nameplate stamping is incorrect, missing, or illegible.  
**CONDITION:** 431. Manufacturer's Data Report & Nameplate: Nameplate stamping is incorrect, missing, or illegible. Dataplate could not be located.  
**REQUIREMENT:** 431. Obtain a replacement nameplate from the manufacturer or a replacement in accordance with the National Board Inspection Code. Locate nameplate and make visible for inspection.

---

**Object:** NC338997 - Boiler - Lochinvar - 2002 - Bsmt Blr Rm - Active **Violations This Object:** 2

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 03/12/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 08-Main Steam System NCAC 13-13.0411  
**SUBCATEGORY** 126. Leaking pipe/pipe joints.  
**CONDITION:** 126. Main Steam System NCAC 13-13.0411: Leaking pipe/pipe joints.  
**REQUIREMENT:** 126. Repair or tighten leaking pipe/pipe joints.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 03/12/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 12-Casing, Stack Breeching and Flue  
**SUBCATEGORY** 214. Excessive corrosion.  
**CONDITION:** 214. Casing, Stack Breeching and Flue: Excessive stack corrosion.  
**REQUIREMENT:** 214. Repair or replace the casing, stack breeching or flue.

---

**Location:** (MH UNIV) Day Hall  
8 College St, , Mars Hill, NC 28754-0630, Phone: 828-689-1201  
**Contact:** Attn Henry H Haywood, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:828-206-

**Location #:** 3711212 **Violations:** 1

**Object:** NC406668 - Boiler - Sermeta - 2015 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 05/19/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 395. Valve leaking.  
**CONDITION:** 395. Operation of PRDs NCAC 13-13.0405: Valve leaking.  
**REQUIREMENT:** 395. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

---

**Location:** (MH UNIV) Gibson Hall  
100 Joe Anderson Dr, , Mars Hill, NC 28754 , Phone: 828-689-1201  
**Contact:** Attn Henry H Haywood, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:828-206-

**Location #:** 1930563 **Violations:** 1

**Object:** NC099075 - Boiler - Weil-McLain - 1969 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 03/12/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 395. Valve leaking.  
**CONDITION:** 395. Operation of PRDs NCAC 13-13.0405: Valve leaking.  
**REQUIREMENT:** 395. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

---



# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Location:** (MH UNIV) Huffman Hall **Location #:** 1930543 **Violations:** 1  
130 Womens Hill Dr, , Mars Hill, NC 28754 , Phone: 828-689-1201  
**Contact:** Attn Henry H Haywood, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:828-206-

**Object:** NC403705 - PV - LTC - 2015 - Rm B11 - Active **Violations This Object:** 1

---

<b>COMPANY:</b>	Hartford Steam Boiler	
<b>INSPECTOR:</b>	Possidente, James	
<b>OPENED:</b>	02/23/2021	<b>ENTERED BY:</b> Putek, Terry
<b>CLOSED:</b>		<b>CLOSED BY:</b>
<b>TYPE:</b>	Certificate Blocking	
<b>CATEGORY:</b>	07-Undefined Pressure Vessels Violations	
<b>SUBCATEGORY</b>	479. Undefined Pressure Vessels Violations.	
<b>CONDITION:</b>	479. Undefined Pressure Vessels Violations. Pipe leaking.	
<b>REQUIREMENT:</b>	479. Undefined Pressure Vessels Violations. Repair or replace leaking piping/pipe joints.	

---

**Location:** (MH UNIV) McConnell Hall **Location #:** 1930553 **Violations:** 1  
54 College St, , Mars Hill, NC 28754-0630, Phone: 828-689-1201  
**Contact:** Attn Henry H Haywood, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:828-206-

**Object:** NC270792 - Boiler - Weil-McLain - 1994 - Blr Rm - Active **Violations This Object:** 1

---

<b>COMPANY:</b>	Hartford Steam Boiler	
<b>INSPECTOR:</b>	Possidente, James	
<b>OPENED:</b>	02/23/2021	<b>ENTERED BY:</b> Putek, Terry
<b>CLOSED:</b>		<b>CLOSED BY:</b>
<b>TYPE:</b>	Certificate Blocking	
<b>CATEGORY:</b>	01-LWCO and Flow Sensing Devices NCAC 13-13.0409	
<b>SUBCATEGORY</b>	006. Low water cutoff device inoperative or bypassed.	
<b>CONDITION:</b>	006. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device inoperative or bypassed.	
<b>REQUIREMENT:</b>	006. Repair or replace the inoperable low water fuel cutoff control and test to ensure proper operation.	

---

**Location:** (MH UNIV) Pittman Dining Hall **Location #:** 1930566 **Violations:** 1  
121 Cascade St, , Mars Hill, NC 28754-9135, Phone: 828-689-1201  
**Contact:** Attn Henry H Haywood, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:828-206-



# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

**Object:** NC262680 - Boiler - Peerless - 1993 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Possidente, James

**OPENED:** 03/12/2021

**ENTERED BY:** Putek, Terry

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 12-Casing, Stack Breeching and Flue

**SUBCATEGORY** 211. Combustion gas leaks.

**CONDITION:** 211. Casing, Stack Breeching and Flue: Combustion gas leaks.

**REQUIREMENT:** 211. Repair all combustion gas leaks in the casing, stack breeching, or flue.

**Location:** (MH UNIV) Spilman Hall

**Location #:** 1930544

**Violations:** 2

50 College St, , Mars Hill, NC 28754-0630, Phone: 828-689-1201

**Contact:** Attn Henry H Haywood, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:828-206-

**Object:** NC294827 - Boiler - Peerless - 1999 - Bsmt - Active

**Violations This Object:** 2

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Possidente, James

**OPENED:** 05/19/2021

**ENTERED BY:** Putek, Terry

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409

**SUBCATEGORY** 009. Water level control inoperative or bypassed.

**CONDITION:** 009. LWCO and Flow Sensing Devices NCAC 13-13.0409: Water level control inoperative or bypassed.

**REQUIREMENT:** 009. Repair or replace the inoperable water level control and test to ensure proper operation.

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Possidente, James

**OPENED:** 05/19/2021

**ENTERED BY:** Putek, Terry

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 12-Casing, Stack Breeching and Flue

**SUBCATEGORY** 211. Combustion gas leaks.

**CONDITION:** 211. Casing, Stack Breeching and Flue: Combustion gas leaks. Front and rear firebox sight glass broken.

**REQUIREMENT:** 211. Repair all combustion gas leaks in the casing, stack breeching, or flue. Repair front and rear firebox sight glass.

**Location:** (MH UNIV) Stroup Hall

**Location #:** 1930538

**Violations:** 2

141 Womens Hill Dr, , Mars Hill, NC 28754 , Phone: 828-689-1201

**Contact:** Attn Henry H Haywood, Director Of Facilities, Mars Hill University, Phone: 828-689-1172, Cell:828-206-

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC323874 - Boiler - Teledyne Laars - 2000 - Bsmt - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 02/23/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409  
**SUBCATEGORY** 012. Flow switch inoperative or bypassed.  
**CONDITION:** 012. LWCO and Flow Sensing Devices NCAC 13-13.0409: Flow switch inoperative or bypassed. (Leaking)  
**REQUIREMENT:** 012. Install a flow switch that will shut off the fuel supply in case of stoppage of water flow or a low-water condition and test to ensure proper operation.

**ENTERED BY:** Putek, Terry

**CLOSED BY:**

---

**Object:** NC325457 - Boiler - Peerless - 2000 - Bsmt - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 02/23/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409  
**SUBCATEGORY** 006. Low water cutoff device inoperative or bypassed.  
**CONDITION:** 006. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device inoperative or bypassed. Primary LWCO inoperative.  
**REQUIREMENT:** 006. Repair or replace the inoperable low water fuel cutoff control and test to ensure proper operation.

**ENTERED BY:** Putek, Terry

**CLOSED BY:**

---

**Location:** (NC A&T) Bluford Library

**Location #:** 1900678

**Violations:** 1

1601 E Market St, , Greensboro, NC 27411-0002, Phone: 336-334-7025

**Contact:** NC A & T State University, Phone: 336-334-3806

---

**Object:** NC250889 - Boiler - Bryan - 1989 - Penthouse - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 06/17/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations: Boiler not operating at time of inspection; pressure relief device (PRD) and low water cutoff (LWCO) could not be tested to verify proper operation.  
**REQUIREMENT:** 363. Undefined Boiler Violations: Schedule a reinspection at a time when the boiler is operating so that the PRD and LWCO may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the controls is also acceptable.

**ENTERED BY:** Judd, Janie

**CLOSED BY:**

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Location:** (NC A&T) Bryan Fitness & Wellness Ctr **Location #:** 1900679 **Violations:** 1  
1601 E Market St, , Greensboro, NC 27411-0002, Phone: 336-334-7025  
**Contact:** NC A & T State University, Phone: 336-334-3806

**Object:** NC326149 - Boiler - Lochinvar - 2000 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 06/17/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations: Flow switch leaking. Corrosion present on switch internal components.  
**REQUIREMENT:** 363. Undefined Boiler Violations; Replace the current flow switch in order to correct this issue. Once complete test the new flow switch in order to verify proper operation.

---

**Location:** (NC A&T) C H Moore Agricultural **Location #:** 1900558 **Violations:** 2  
1601 E Market St, , Greensboro, NC 27411-0002, Phone: 336-334-7025  
**Contact:** NC A & T State University, Phone: 336-334-3806

**Object:** NC239390 - Boiler - Weil-McLain - 1988 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 06/17/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations: Boiler not operating at time of inspection; pressure relief device (PRD) and low water cutoff (LWCO) could not be tested to verify proper operation.  
**REQUIREMENT:** 363. Undefined Boiler Violations: Schedule a reinspection at a time when the boiler is operating so that the PRD and LWCO may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the controls is also acceptable

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC343287 - Boiler - Lochinvar - 2003 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Leonard, Shannon D.

**OPENED:** 06/17/2021

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 23-Undefined Boiler Violations

**SUBCATEGORY** 363. Undefined Boiler Violations.

**CONDITION:** 363. Undefined Boiler Violations: Boiler not operating at time of inspection; pressure relief device (PRD) and low water cutoff (LWCO) could not be tested to verify proper operation.

**REQUIREMENT:** 363. Undefined Boiler Violations: Schedule a reinspection at a time when the boiler is operating so that the PRD and LWCO may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the controls is also acceptable.

---

**Location:** (NC A&T) Coltrane Hall

**Location #:** 2921477

**Violations:** 1

1601 E Market St, , Greensboro, NC 27411-0002, Phone: 336-334-7025

**Contact:** Ricky Richmond, Facilities Manager, NC A & T State University, Phone: 336-285-4583, Cell:336-906-9620

---

**Object:** NC383297 - Boiler - Giannoni - 2010 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Leonard, Shannon D.

**OPENED:** 06/17/2021

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 23-Undefined Boiler Violations

**SUBCATEGORY** 363. Undefined Boiler Violations.

**CONDITION:** 363. Undefined Boiler Violations: Boiler not operating at time of inspection; pressure relief device (PRD) and low water cutoff (LWCO) could not be tested to verify proper operation.

**REQUIREMENT:** 363. Undefined Boiler Violations: Schedule a reinspection at a time when the boiler is operating so that the PRD and LWCO may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the controls is also acceptable.

---

**Location:** (NC A&T) T E Neal Heating Plt

**Location #:** 1834439

**Violations:** 1

1601 E Market St, , Greensboro, NC 27411-0002, Phone: 336-334-7025

**Contact:** Ricky Richmond, Facilities Manager, NC A & T State University, Phone: 336-285-4583, Cell:336-906-9620

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC254988 - PV - East Fab - 1992 - Blr Rm 2nd Flr - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Leonard, Shannon D.

**OPENED:** 05/20/2021

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 01-Installation

**SUBCATEGORY** 414. Pitting.

**CONDITION:** 414. Installation: Corrosion/Pitting.

**REQUIREMENT:** 414. Repair the pitting. If welding is required, a qualified "R" certificate holder is necessary to perform the work.

---

**Location:** (NC A&T) Vanstory Hall

**Location #:** 1900627

**Violations:** 1

1601 E Market St, , Greensboro, NC 27411-0002, Phone: 336-334-7025

**Contact:** Ricky Richmond, Facilities Manager, NC A & T State University, Phone: 336-285-4583, Cell:336-906-9620

---

**Object:** NC252034 - PV - Reco - 1991 - Equip Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Leonard, Shannon D.

**OPENED:** 06/17/2021

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 07-Undefined Pressure Vessels Violations

**SUBCATEGORY** 479. Undefined Pressure Vessels Violations.

**CONDITION:** 479. Undefined Pressure Vessels Violations: Corrosion and leakage origination from vessel shell.

**REQUIREMENT:** 479. Undefined Pressure Vessels Violations: Identify all areas of corrosion/leakage and make repairs as necessary to correct this condition. All welded repairs must be performed by a qualified "R" certificate holder.

---

**Location:** (NCCU) New School Of Education

**Location #:** 3816957

**Violations:** 1

1801 Fayetteville St, , Durham, NC 27707-3129, Phone: 919-530-6313

**Contact:** Attn Lori Blake Reid PO #P107428, NC Central University Shephard Station, Phone: 919-530-7244

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External  
Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status:  
Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC415281 - PV - Manchester - 1998 - HVAC Comp - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** SORRENTINO, SEAN  
**OPENED:** 07/01/2021 **ENTERED BY:** Keyes, Amanda  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 09-Pressure Gauges NCAC 13-13.0407  
**SUBCATEGORY** 032. Incorrect range or insufficient pointer travel.  
**CONDITION:** 032. Pressure Gauges NCAC 13-13.0407: Incorrect range or insufficient pointer travel.  
**REQUIREMENT:** 032. Install a pressure gauge on the equipment that is visible to the operator from the floor or work platform. Gauge must be the proper range in accordance with NC Administrative Code, Title 13, Chapter 13, Section .0407.

---

**Location:** (NCSU) Pulp & Paper Labs Z3 **Location #:** 2154347 **Violations:** 1  
431 Dan Allen Dr, , Raleigh, NC 27695-0001, Phone: 919-515-9902  
**Contact:** James Lindsey, Pulp & Paper Labs 113B-Z3, Phone: 919-515-9902

---

**Object:** NC431284 - PV - Samuel Pressure Vessel Group - 2020 - 2nd Flr **Violations This Object:** 1  
Pilot Plt Mezzanine - Active

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Fish, Emily  
**OPENED:** 06/16/2021 **ENTERED BY:** Fish, Emily  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 04-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 452. Set pressure too high.  
**CONDITION:** 452. Installation of PRDs NCAC 13-13.0405: Set pressure too high.  
**REQUIREMENT:** 452. Replace the pressure relieving device with one with a set pressure no higher than the maximum allowable working pressure as determined by the manufacturer.

---

**Location:** (ONSLOW CS) Richlands High **Location #:** 1824334 **Violations:** 1  
8100 Richlands Hwy, , Richlands, NC 28574-7445, Phone: 910-455-2211  
**Contact:** Attn Tammy Miller, Onslow County Schools, Phone: 910-455-2211, Cell:Secretary

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC293509 - Boiler - Weil-McLain - 1998 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Rudolph, Jay

**OPENED:** 07/14/2021

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409

**SUBCATEGORY** 006. Low water cutoff device inoperative or bypassed.

**CONDITION:** 006. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device inoperative or bypassed.

**REQUIREMENT:** 006. Repair or replace the inoperable low water fuel cutoff control and test to ensure proper operation.

---

**Location:** (ONSLOW CS) Southwest Middle

**Location #:** 1831249

**Violations:** 1

3000 Furia Dr, , Jacksonville, NC 28540-3370, Phone: 910-455-2211

**Contact:** Attn Tammy Miller, Onslow County Schools, Phone: 910-455-2211, Cell:Secretary

---

**Object:** NC364234 - Boiler - Weil-McLain - 2006 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Rudolph, Jay

**OPENED:** 07/13/2021

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 16-Boiler Components

**SUBCATEGORY** 270. Water Leaks.

**CONDITION:** 270. Boiler Components: Water Leaks: Leak between boiler sections.

**REQUIREMENT:** 270. Repair the water leaks identified on the inspection report: Repair leak between boiler sections.

---

**Location:** (ONSLOW CS) White Oak High

**Location #:** 1843516

**Violations:** 2

1001 Piney Green Rd, , Jacksonville, NC 28546-8522, Phone: 910-455-2211

**Contact:** Attn Tammy Miller, Onslow County Schools, Phone: 910-455-2211, Cell:Secretary

---

**Object:** NC326283 - Boiler - Weil-McLain - 2000 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Rudolph, Jay

**OPENED:** 07/12/2021

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 23-Undefined Boiler Violations

**SUBCATEGORY** 363. Undefined Boiler Violations.

**CONDITION:** 363. Undefined Boiler Violations. Boiler not operating

**REQUIREMENT:** 363. Undefined Boiler Violations. Reschedule inspection for a time when the boiler is operating so that safety devices can be verified.

---



# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC326284 - Boiler - Weil-McLain - 2000 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Rudolph, Jay

**OPENED:** 07/12/2021

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 23-Undefined Boiler Violations

**SUBCATEGORY** 363. Undefined Boiler Violations.

**CONDITION:** 363. Undefined Boiler Violations. Boiler not operating.

**REQUIREMENT:** 363. Undefined Boiler Violations. Reschedule inspection for a time when the boiler is operating so that safety devices can be verified.

---

**Location:** (QUC) Heating Plant

**Location #:** 1832784

**Violations:** 3

1900 Selwyn Ave, , Charlotte, NC 28274-0001, Phone: 704-337-2200

**Contact:** Queens University Of Charlotte, Phone: 704-337-2201

---

**Object:** NC068205 - Boiler - BE&S - 1963 - Blr Rm #4 - Active

**Violations This Object:** 3

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Clay, Steven D.

**OPENED:** 05/13/2021

**ENTERED BY:** Putek, Terry

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409

**SUBCATEGORY** 006. Low water cutoff device inoperative or bypassed.

**CONDITION:** 006. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device inoperative or bypassed.

**REQUIREMENT:** 006. Repair or replace the inoperable low water fuel cutoff control and test to ensure proper operation.

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Clay, Steven D.

**OPENED:** 05/13/2021

**ENTERED BY:** Putek, Terry

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 19-Waterside

**SUBCATEGORY** 320. Accumulation of oil.

**CONDITION:** 320. Waterside: Accumulation of oil.

**REQUIREMENT:** 320. Clean the watersides of all oil contamination.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Clay, Steven D.  
**OPENED:** 05/13/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 394. Valve inoperative.  
**CONDITION:** 394. Operation of PRDs NCAC 13-13.0405: Valve inoperative.  
**REQUIREMENT:** 394. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

---

**Location:** (UNCA) Carol Belk Theater  
1 University Hts, , Asheville, NC 28804-3251, Phone: 828-251-6038  
**Contact:** Attn Jay Small, HVAC Supervisor, UNC Asheville, Phone: 828-250-3964

**Location #:** 1903686

**Violations:** 1

**Object:** NC299507 - Boiler - Lochinvar - 1999 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 04/06/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 270. Water Leaks.  
**CONDITION:** 270. Boiler Components: Water Leaks. Manifold flange leaking.  
**REQUIREMENT:** 270. Repair the water leaks identified on the inspection report.

---

**Location:** (UNCA) Founders Residence Hall  
1 University Hts, , Asheville, NC 28804-3251, Phone: 828-251-6038  
**Contact:** Attn Jay Small, HVAC Supervisor, UNC Asheville, Phone: 828-250-3964

**Location #:** 1903690

**Violations:** 2

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC203365 - Boiler - PVI Industries - 1981 - Highrise Dorm Equip Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 04/06/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 276. Manway gasket leaks.  
**CONDITION:** 276. Boiler Components: Manway gasket leaks.  
**REQUIREMENT:** 276. Replace the leaking manway gasket. If weld repairs are required to reestablish the seating surface, a qualified "R" certificate holder is necessary to perform the work.

---

**Object:** NC203366 - Boiler - PVI Industries - 1981 - Highrise Dorm Equip Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 04/06/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 276. Manway gasket leaks.  
**CONDITION:** 276. Boiler Components: Manway gasket leaks.  
**REQUIREMENT:** 276. Replace the leaking manway gasket. If weld repairs are required to reestablish the seating surface, a qualified "R" certificate holder is necessary to perform the work.

---

**Location:** (UNCA) Zeis Science & Multimedia Bldg **Location #:** 2156756 **Violations:** 1  
1 University Hts, , Asheville, NC 28804-3251, Phone: 828-251-6038  
**Contact:** Attn Jay Small, HVAC Supervisor, UNC Asheville, Phone: 828-250-3964

---

**Object:** NC368728 - Boiler - Lochinvar - 2006 - Blr Rm B4 - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 06/23/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 395. Valve leaking.  
**CONDITION:** 395. Operation of PRDs NCAC 13-13.0405: Valve leaking.  
**REQUIREMENT:** 395. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

---

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Location:** (UNCC) Belk Residence Hall **Location #:** 3337127 **Violations:** 2  
9201 University City Blvd, , Charlotte, NC 28223-0001, Phone: 704-687-2199  
**Contact:** Attn Kelly Herron, UNC Charlotte, Phone: 704-687-0567

**Object:** NC393689 - PV - Lochinvar - 2012 - Mech Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Clay, Steven D.  
**OPENED:** 05/07/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 05-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 474. Valve inoperative.  
**CONDITION:** 474. Operation of PRDs NCAC 13-13.0405: Valve inoperative. PRD capacity too low. Three boilers feed tank.  
**REQUIREMENT:** 474. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

**Object:** NC393690 - PV - Lochinvar - 2012 - Mech Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Clay, Steven D.  
**OPENED:** 05/07/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 05-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 474. Valve inoperative.  
**CONDITION:** 474. Operation of PRDs NCAC 13-13.0405: Valve inoperative. PRD capacity is too low. Three boilers feed tank.  
**REQUIREMENT:** 474. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

---

**Location:** (UNCC) Regional Utility Plt 1 **Location #:** 1930002 **Violations:** 1  
9201 University City Blvd, , Charlotte, NC 28223-0001, Phone: 704-687-6993  
**Contact:** Attn Kelly Herron, UNC Charlotte, Phone: 704-687-0567

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC328646 - Boiler - Hurst - 2002 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Clay, Steven D.

**OPENED:** 02/10/2021

**ENTERED BY:** Putek, Terry

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 16-Boiler Components

**SUBCATEGORY** 275. Tube/tube ends leak.

**CONDITION:** 275. Boiler Components: Tube/tube ends leak. Boiler is down for repairs.

**REQUIREMENT:** 275. Repair the leaking tubes/tube ends. If weld repairs are required, a qualified "R" certificate holder is necessary to perform the work.

---

**Location:** (UNCC) Scott Hall

**Location #:** 1930011

**Violations:** 1

9201 University City Blvd, , Charlotte, NC 28223-0001, Phone: 704-687-2197

**Contact:** Attn Kelly Herron, UNC Charlotte, Phone: 704-687-0567

---

**Object:** NC383706 - PV - LTC - 2010 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Clay, Steven D.

**OPENED:** 05/07/2021

**ENTERED BY:** Putek, Terry

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 05-Operation of PRDs NCAC 13-13.0405

**SUBCATEGORY** 474. Valve inoperative.

**CONDITION:** 474. Operation of PRDs NCAC 13-13.0405: Valve inoperative. PRD capacity is too low. Two boilers feed tank.

**REQUIREMENT:** 474. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

---

**Location:** (UNCG) Coleman Bldg

**Location #:** 1930989

**Violations:** 1

800 Oakland Ave, , Greensboro, NC 27412-5059, Phone: 336-334-5684

**Contact:** Richard Ratcliffe, Maintenance, UNC Greensboro, Phone: 336-334-5554, Cell:336-880-7092

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC239307 - PV - Precision - 1987 - Chiller Rm - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 07/20/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 06-Undefined Pressure Relieving Devices Violations  
**SUBCATEGORY** 478. Undefined Pressure Relieving Devices Violations.  
**CONDITION:** 478. Undefined Pressure Relieving Devices Violations: Pressure relief device (PRD) inlet piping corroded and leaking.  
**REQUIREMENT:** 478. Undefined Pressure Relieving Devices Violations: Replace the PRD inlet piping in order to address this issue. The replacement PRD inlet piping must have a cross sectional area of greater than or equal to the cross sectional area of the PRD inlet opening

---

**Location:** (UNCG) Jefferson Suites

**Location #:** 2959032

**Violations:** 2

1501 Spring Garden St, , Greensboro, NC 27403-2437, Phone: 704-309-2534

**Contact:** Richard Ratcliffe, Maintenance, UNC Greensboro, Phone: 336-334-5554, Cell:336-880-7092

---

**Object:** NC320748 - Boiler - Lochinvar - 2010 - Mech Rm - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 06/07/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409  
**SUBCATEGORY** 012. Flow switch inoperative or bypassed.  
**CONDITION:** 012. LWCO and Flow Sensing Devices NCAC 13-13.0409: Flow switch inoperative or bypassed.  
**REQUIREMENT:** 012. Repair/Replace the inoperative flow switch in order to correct this condition. Once complete, test the flow switch to ensure proper operation.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC385801 - Boiler - Patterson Kelley - 2010 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Leonard, Shannon D.

**OPENED:** 06/07/2021

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 13-Burners and Fuel Supply Systems

**SUBCATEGORY** 235. No emergency fuel shut off switch.

**CONDITION:** 235. Burners and Fuel Supply Systems: Emergency fuel shutoff switch failed to secure boiler when tested.

**REQUIREMENT:** 235. Repair/replace the inoperative emergency fuel shutoff switch in order to correct this condition. If replacement is required, emergency fuel shutoff switches must be installed at exit from the mechanical room. Once complete test to ensure proper operation.

---

**Location:** (UNCG) Tower Village

**Location #:** 1930746

**Violations:** 2

800 Oakland Ave, , Greensboro, NC 27412-5059, Phone: 336-334-5684

**Contact:** Attn Jon Soter, UNC Greensboro, Phone: 336-256-0434, Cell:336-587-1440

---

**Object:** NC413562 - Boiler - AIC Tuchom - 2017 - Mech Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Leonard, Shannon D.

**OPENED:** 06/07/2021

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 23-Undefined Boiler Violations

**SUBCATEGORY** 363. Undefined Boiler Violations.

**CONDITION:** 363. Undefined Boiler Violations: Boiler not operating at time of inspection; flow switch and pressure relief device (PRD) could not be tested to verify proper operation.

Schedule a reinspection at a time when the boiler is operating so that the PRD and LWCO may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the controls is also acceptable

**REQUIREMENT:** 363. Undefined Boiler Violations. Schedule a reinspection at a time when the boiler is operating so that the flow switch and PRD may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the controls is also acceptable



# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC413563 - Boiler - AIC Tuchom - 2017 - Mech Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 06/07/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Undefined Boiler Violations. Boiler not operating at time of inspection; flow switch and pressure relief device (PRD) could not be tested to verify proper operation.  
**REQUIREMENT:** 363. Undefined Boiler Violations. Schedule a reinspection at a time when the boiler is operating so that the flow switch and PRD may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the controls is also acceptable

---

**Location:** (WILSON CO) Maintenance Bldg **Location #:** 1844389 **Violations:** 1  
113 Nash St E, , Wilson, NC 27893-4054, Phone: 252-399-2843  
**Contact:** Attn Ted Boswell, Director of Maintenance, Wilson County Government, Phone: 252-265-5973

---

**Object:** NC410051 - Boiler - Weil-McLain - 2017 - Bsmt Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Harrell, Danny  
**OPENED:** 05/12/2021 **ENTERED BY:** Harrell, Danny  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 09-Bottom Blow and Drain Systems NCAC 13-13.0411  
**SUBCATEGORY** 152. Valve(s) hand wheel or lever handle missing.  
**CONDITION:** 152. Bottom Blow and Drain Systems NCAC 13-13.0411: Valve(s) hand wheel or lever handle missing.  
**REQUIREMENT:** 152. Replace missing hand wheel or lever on bottom blow off valve. Contact Danny Harrell @ 919-500-3098 when the repair is completed to schedule a re-inspection.

---

**Location:** Accu Wrench Automotive **Location #:** 2606784 **Violations:** 1  
6200 Hacker Bend Ct, , Winston Salem, NC 27103-9771, Phone: 336-712-0012  
**Contact:** Attn Matthew Mayse, Owner, Accu Wrench Automotive Inc, Phone: 336-712-0012

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC377748 - PV - Melben - 1988 - Outside Shed - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Leonard, Shannon D.

**OPENED:** 07/23/2021

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 01-Installation

**SUBCATEGORY** 415. Corrosion.

**CONDITION:** 415. Installation: Corrosion. Corrosion of vessel shell. Pin hole in bottom of air tank.

**REQUIREMENT:** 415. Repair the corrosion. If welding is required, a qualified "R" certificate holder is necessary to perform the work. This air tank must remain out of service until the necessary repairs are completed.

---

**Location:** Bernhardt Furniture Co Plt 3

**Location #:** 1158914

**Violations:** 1

1502 Morganton Blvd SW, , Lenoir, NC 28645-5561, Phone: 828-757-6480

**Contact:** Gary Wallace, Maintenance Technician, Bernhardt Furniture Co Plt 3, Phone: 828-759-6480

---

**Object:** NC080630 - Boiler - Bigelow - 1966 - Blr Rm #2 - Active

**Violations This Object:** 1

**COMPANY:** State of North Carolina

**INSPECTOR:** Smith, Jeremy

**OPENED:** 07/01/2021

**ENTERED BY:** Smith, Jeremy

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 23-Undefined Boiler Violations

**SUBCATEGORY** 363. Undefined Boiler Violations.

**CONDITION:** 363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 10/29/2019.

**REQUIREMENT:** 363. Undefined Boiler Violations. An External Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.

---

**Location:** Centerview Baptist Church

**Location #:** 1775266

**Violations:** 1

415 Walter St, , Kannapolis, NC 28083-4559, Phone: 704-933-2331

**Contact:** There is no contact information available for this location.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC344241 - Boiler - Peerless - 2001 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Leonard, Shannon D.

**OPENED:** 07/21/2021

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405

**SUBCATEGORY** 396. Missing nameplate.

**CONDITION:** 396. Operation of PRDs NCAC 13-13.0405: Missing nameplate: Data plate for pressure relief device (PRD) broken off of PRD and laying on top of the boiler.

**REQUIREMENT:** 396. Replace the current PRD with an ASME/NB stamped PRD having a set pressure of 50 PSI or less and a relieving capacity of 504,000 BTU/Hour or more. The replacement PRD must be equipped with a try-lever and the PRD discharge piping must be piped full size to a safe location (6" above the boiler room) and properly supported.

---

**Location:** Dana Food Center

**Location #:** 1782026

**Violations:** 1

1897 Dana Rd, , Hendersonville, NC 28792-3188, Phone: 828-698-0047

**Contact:** Robert Morris, Manager, Dana Food Center, Phone: 828-698-0047

---

**Object:** NC254224 - PV - John Wood - 1973 - Rear Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Possidente, James

**OPENED:** 07/19/2021

**ENTERED BY:** Putek, Terry

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 07-Undefined Pressure Vessels Violations

**SUBCATEGORY** 479. Undefined Pressure Vessels Violations.

**CONDITION:** 479. Undefined Pressure Vessels Violations. Vessel is out of service however it has not been properly disconnected.

**REQUIREMENT:** 479. Undefined Pressure Vessels Violations. Disconnect the vessel from all sources of potential energy including electricity.

---

**Location:** Express Inspection & Lube

**Location #:** 1787258

**Violations:** 1

802 SE Maynard Rd, , Cary, NC 27511-4206, Phone: 919-481-3040

**Contact:** Attn Turk Baris, Manager, Express Inspection & Lube, Phone: 919-481-3040

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC284410 - PV - Brunner - 1995 - Bldg Rear - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** SORRENTINO, SEAN

**OPENED:** 07/16/2021

**ENTERED BY:** Keyes, Amanda

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 05-Operation of PRDs NCAC 13-13.0405

**SUBCATEGORY** 477. Try lever inoperative.

**CONDITION:** 477. Operation of PRDs NCAC 13-13.0405: Try lever inoperative.

**REQUIREMENT:** 477. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

---

**Location:** Foothills Equestrian Nature Center

**Location #:** 1790495

**Violations:** 1

3381 Hunting Country Rd, , Tryon, NC 28782-6669, Phone: 828-859-9012

**Contact:** There is no contact information available for this location.

---

**Object:** NC330138 - Boiler - Burnham - 2001 - Blr Rm Bsmt - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Possidente, James

**OPENED:** 06/07/2021

**ENTERED BY:** Putek, Terry

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 23-Undefined Boiler Violations

**SUBCATEGORY** 363. Undefined Boiler Violations.

**CONDITION:** 363. Undefined Boiler Violations. Boiler is out of service but has not been properly disconnected.

**REQUIREMENT:** 363. Undefined Boiler Violations. Disconnect the boiler from all sources of potential energy including fuel and electricity.

---

**Location:** Forsyth Country Club

**Location #:** 1790681

**Violations:** 3

3101 Country Club Rd, , Winston Salem, NC 27104-3035, Phone: 336-768-7559

**Contact:** Forsyth Country Club, Phone: 336-768-7559

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

**Object:** NC392141 - Boiler - Peerless - 2011 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Leonard, Shannon D.

**OPENED:** 06/30/2021

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 23-Undefined Boiler Violations

**SUBCATEGORY** 363. Undefined Boiler Violations.

**CONDITION:** 363. Undefined Boiler Violations.Boiler not operating at time of inspection; Low Water Cutoff (LWCO) and Pressure Relief Device (PRD) could not be tested to verify proper operation.

**REQUIREMENT:** 363. Undefined Boiler Violations. Schedule a reinspection at a time when the boiler is operating so that the LWCO and PRD may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the controls is also acceptable

**Object:** NC392143 - Boiler - Peerless - 2011 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Leonard, Shannon D.

**OPENED:** 06/30/2021

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 01-LWCO and Flow Sensing Devices NCAC 13-13.0409

**SUBCATEGORY** 006. Low water cutoff device inoperative or bypassed.

**CONDITION:** 006. LWCO and Flow Sensing Devices NCAC 13-13.0409: Low water cutoff device inoperative or bypassed.

**REQUIREMENT:** 006. Repair or replace the inoperable low water fuel cutoff control and test to ensure proper operation. The Low Water Control must be equipped with a manual reset.

**Object:** NC392144 - Boiler - Heat Transfer Products - 2012 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Leonard, Shannon D.

**OPENED:** 06/30/2021

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 23-Undefined Boiler Violations

**SUBCATEGORY** 363. Undefined Boiler Violations.

**CONDITION:** 363. Undefined Boiler Violations: Flow switch leaking/corroded.

**REQUIREMENT:** 363. Undefined Boiler Violations: Replace the flow switch in order to correct this condition. Once complete, test to verify proper operation.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Location:** Gentry Mills Inc **Location #:** 1792364 **Violations:** 1  
2035 Kingsley Dr, , Albemarle, NC 28001-4473, Phone: 704-983-5555  
**Contact:** Kevin Efird, Gentry Mills Inc, Phone: 704-983-5555 X121

**Object:** NC280831 - Boiler - Cleaver Brooks - 1996 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Clay, Steven D.  
**OPENED:** 07/07/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 18-Furnace and Fireside  
**SUBCATEGORY** 304. Furnace tube cracking.  
**CONDITION:** 304. Furnace and Fireside: Furnace tube cracking. Small cracks noted at furnace to tubesheet weld.  
**REQUIREMENT:** 304. Repair the crack in the furnace tube(s). If welding is required, a qualified "R" certificate holder is necessary to perform the work.

---

**Location:** Haywood Regional Medical Center **Location #:** 1796249 **Violations:** 3  
262 Leroy George Dr, , Clyde, NC 28721-7430, Phone: 828-456-7311  
**Contact:** Jeremy Brown, Mgr Engineering, Haywood Regional Medical Center, Phone: 828-452-8033, Cell:828-768-

**Object:** NC190012 - PV - Reco - 1977 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 07/09/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 05-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 476. Missing nameplate.  
**CONDITION:** 476. Operation of PRDs NCAC 13-13.0405: Missing nameplate.  
**REQUIREMENT:** 476. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

**Object:** NC190013 - PV - Reco - 1977 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 07/09/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 05-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 476. Missing nameplate.  
**CONDITION:** 476. Operation of PRDs NCAC 13-13.0405: Missing nameplate.  
**REQUIREMENT:** 476. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

**ENTERED BY:** Putek, Terry

**CLOSED BY:**

**Object:** NC190014 - PV - Reco - 1977 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 07/09/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 05-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 476. Missing nameplate.  
**CONDITION:** 476. Operation of PRDs NCAC 13-13.0405: Missing nameplate.  
**REQUIREMENT:** 476. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

**ENTERED BY:** Putek, Terry

**CLOSED BY:**

**Location:** Hazelwood Baptist Church

**Location #:** 1796278

**Violations:** 1

265 Hazelwood Ave, , Waynesville, NC 28786-1944, Phone: 828-456-9434

**Contact:** Allen Mathis, Caretaker, Hazelwood Baptist Church, Phone: 828-456-9434

**Object:** NC239755 - Boiler - Weil-McLain - 1988 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 06/28/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 12-Casing, Stack Breeching and Flue  
**SUBCATEGORY** 211. Combustion gas leaks.  
**CONDITION:** 211. Casing, Stack Breeching and Flue: Combustion gas leaks. Combustion gas leaks between sections.  
**REQUIREMENT:** 211. Repair all combustion gas leaks in the casing, stack breeching, or flue.

**ENTERED BY:** Putek, Terry

**CLOSED BY:**



# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Location:** Heddens Collision Center **Location #:** 1796474 **Violations:** 1  
2366 New Leicester Hwy Ste B, , Asheville, NC 28806-7424, Phone: 828-683-4725  
**Contact:** Drew Gerahrdt, Owner, Heddens Collision Center,

**Object:** NC422456 - PV - Morganton - 2012 - Outside - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 06/02/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 04-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 452. Set pressure too high.  
**CONDITION:** 452. Installation of PRDs NCAC 13-13.0405: Set pressure too high. Mawp is 200 psi and SV #1 is 217 psi.  
**REQUIREMENT:** 452. Replace the pressure relieving device with one with a set pressure no higher than the maximum allowable working pressure as determined by the manufacturer.

---

**Location:** Hertford Baptist Church **Location #:** 1796868 **Violations:** 1  
124 W Market St, , Hertford, NC 27944-1151, Phone: 252-426-7460  
**Contact:** Hertford Baptist Church, Phone: 252-426-7460

**Object:** NC245123 - Boiler - Weil-McLain - 1990 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Harrell, Danny  
**OPENED:** 03/08/2021 **ENTERED BY:** Harrell, Danny  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 270. Water Leaks.  
**CONDITION:** 270. Boiler Components: Water Leaks. Boiler is leaking between the rear two sections.  
**REQUIREMENT:** 270. Repair the water leaks identified on the inspection report. Contact Danny Harrell @ 919-500-3098 when the repair is completed to schedule a re-inspection.

---

**Location:** Hudson Building **Location #:** 1799097 **Violations:** 1  
118 W State St, , Black Mountain, NC 28711-3419, Phone: 828-669-8711  
**Contact:** Attn J Richard Hudson III, Owner, Hudson Building, Phone: 828-669-8711, Cell:828-777-5711

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC148875 - Boiler - Burnham - 1975 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Possidente, James

**OPENED:** 04/26/2021

**ENTERED BY:** Putek, Terry

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 12-Casing, Stack Breeching and Flue

**SUBCATEGORY** 211. Combustion gas leaks.

**CONDITION:** 211. Casing, Stack Breeching and Flue: Combustion gas leaks. Flue has two small holes.

**REQUIREMENT:** 211. Repair all combustion gas leaks in the casing, stack breeching, or flue.

---

**Location:** Kernersville Family YMCA

**Location #:** 1845634

**Violations:** 1

1113 W Mountain St, , Kernersville, NC 27284-2125, Phone: 336-996-2231

**Contact:** There is no contact information available for this location.

---

**Object:** NC418867 - Boiler - Teledyne Laars - 1998 - Hot Tub Wtr Htr - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Leonard, Shannon D.

**OPENED:** 10/14/2020

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 23-Undefined Boiler Violations

**SUBCATEGORY** 363. Undefined Boiler Violations.

**CONDITION:** 363. Undefined Boiler Violations. Boiler not operating at time of inspection; flow switch and pressure relief device (PRD) could not be tested to verify proper operation.

**REQUIREMENT:** 363. Undefined Boiler Violations. Schedule a reinspection at a time when the boiler is operating so that the flow switch and PRD may be tested to verify proper operation. As an alternative, a detailed boiler log or service report that includes documentation of the successful testing of the flow switch and PRD is also acceptable.

---

**Location:** La Quinta Inn & Suites

**Location #:** 1804615

**Violations:** 4

2020 Griffith Rd, , Winston Salem, NC 27103-5509, Phone: 336-765-8777

**Contact:** Attn Kim Joyner, General Manager, La Quinta Inn & Suites, Phone: 336-765-8777

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC293074 - Boiler - A O Smith - 1998 - Blr Rm 2nd Flr - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 04/19/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 06-Thermometer NCAC 13-13.0410  
**SUBCATEGORY** 111. Thermometer inoperative.  
**CONDITION:** 111. Thermometer NCAC 13-13.0410: Thermometer inoperative.  
**REQUIREMENT:** 111. Replace inoperative thermometer at/in the boiler outlet to measure the temperature in degrees Fahrenheit of the water. The thermometer shall have a range of approximately 2 times the intended operating temperature but not less than 1 1/2 times the intended operating temperature, nor more than 4 times the intended operating temperature.

---

**Object:** NC394482 - PV - State Industries - 2013 - Blr Rm 2nd Flr - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 04/19/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 04-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 459. Discharge piping too small.  
**CONDITION:** 459. Installation of PRDs NCAC 13-13.0405: Discharge piping too small: Discharge piping too small: Pressure relief device (PRD) discharge header piping for this hot water storage tank and two others that are connected to the header is too small.  
**REQUIREMENT:** 459. Replace the PRD discharge header piping with piping having a cross sectional area of 3 inches or greater in order to correct this condition.

---

**Object:** NC394483 - PV - State Industries - 2013 - Blr Rm 2nd Flr - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 04/19/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 04-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 459. Discharge piping too small.  
**CONDITION:** 459. Installation of PRDs NCAC 13-13.0405: Discharge piping too small: Discharge piping too small: Pressure relief device (PRD) discharge header piping for this hot water storage tank and two others that are connected to the header is too small.  
**REQUIREMENT:** 459. Replace the PRD discharge header piping with piping having a cross sectional area of 3 inches or greater in order to correct this condition.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC394484 - PV - State Industries - 2013 - Blr Rm 2nd Flr - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 04/19/2021 **ENTERED BY:** Judd, Janie  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 04-Installation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 459. Discharge piping too small.  
**CONDITION:** 459. Installation of PRDs NCAC 13-13.0405: Discharge piping too small: Pressure relief device (PRD) discharge header piping for this hot water storage tank and two others that are connected to the header is too small.  
**REQUIREMENT:** 459. Replace the PRD discharge header piping with piping having a cross sectional area of 3 inches or greater in order to correct this condition.

---

**Location:** Lentz Cabinets & Associates **Location #:** 3964734 **Violations:** 1  
998 Pleasant Grove Rd, , Hendersonville, NC 28739-8572, Phone: 828-687-7688  
**Contact:** Lentz Cabinets & Associates Llc, Phone: 828-687-7688

---

**Object:** NC422482 - PV - Steel Fab - 2017 - Comp Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 07/21/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 05-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 477. Try lever inoperative.  
**CONDITION:** 477. Operation of PRDs NCAC 13-13.0405: Try lever inoperative. Try ring missing.  
**REQUIREMENT:** 477. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

---

**Location:** Lexington Home Brands Plt 15 **Location #:** 885454 **Violations:** 1  
100 1st St NW, , Hildebran, NC 28637-8066, Phone: 828-397-4661  
**Contact:** Attn Billy Hyatt, Maintenance Supervisor, Lexington Home Brands Plt 15, Phone: 828-397-4661, Cell:828-

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC248508 - Boiler - Cleaver Brooks - 1990 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 07/14/2021 **ENTERED BY:** Putek, Terry  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 275. Tube/tube ends leak.  
**CONDITION:** 275. Boiler Components: Tube/tube ends leak.  
**REQUIREMENT:** 275. Repair the leaking tubes/tube ends. If weld repairs are required, a qualified "R" certificate holder is necessary to perform the work.

---

**Location:** Lucky Cleaners **Location #:** 1819178 **Violations:** 1  
1001 N 2nd St, , Albemarle, NC 28001-2801, Phone: 704-985-1030  
**Contact:** Attn Charlie Park, Owner, Lucky Cleaners, Phone: 704-985-1030, Cell:336-259-3295

---

**Object:** NC376858 - Boiler - Columbia - 2008 - Blr Rm - Active **Violations This Object:** 1

---

**COMPANY:** State of North Carolina  
**INSPECTOR:** Coley, Oscar  
**OPENED:** 07/16/2021 **ENTERED BY:** Coley, Oscar  
**CLOSED:** **CLOSED BY:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 03-Water Gauge Glass NCAC 13-13.0408  
**SUBCATEGORY** 053. Glass broken.  
**CONDITION:** 053. Water Gauge Glass NCAC 13-13.0408: Glass broken.  
**REQUIREMENT:** 053. Replace the broken gauge glass with material designed for temperature and service.  
Please call Junior Coley (704-261-6873) for inspection once repairs have been made.

---

**Location:** Magnolia Gardens Extended Care **Location #:** 1807637 **Violations:** 1  
1404 S Salisbury Ave, , Spencer, NC 28159-1921, Phone: 704-633-3892  
**Contact:** Attn Joel Earnhardt, Maintenance Supervisor, Magnolia Gardens Extended Care, Phone: 704-633-3892

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC376258 - Boiler - Burnham - 2008 - Blr Rm - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 07/22/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 395. Valve leaking.  
**CONDITION:** 395. Operation of PRDs NCAC 13-13.0405: Pressure Relief Valve (PRD) leaking.  
**REQUIREMENT:** 395. Replace the current PRD with an ASME/NB stamped PRD having a set pressure of 50 PSI or less and a relieving capacity of 163,000 BTU/Hour or more. The replacement PRD must be quipped with a try-lever and the PRD discharge must be piped full size to a safe location and properly supported.

---

**Location:** Moran Automotive

**Location #:** 1782668

**Violations:** 2

412 N Main St, , Randleman, NC 27317-1616, Phone: 336-498-4300

**Contact:** Attn Eddie Moran, Moran Automotive, Phone: 336-498-4300

---

**Object:** NC344535 - PV - Steel Fab - 2002 - Comp Shed - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 06/16/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 06-Undefined Pressure Relieving Devices Violations  
**SUBCATEGORY** 478. Undefined Pressure Relieving Devices Violations.  
**CONDITION:** 478. Undefined Pressure Relieving Devices Violations: Pressure gauge inoperative.  
**REQUIREMENT:** 478. Undefined Pressure Relieving Devices Violations: Replace the inoperative pressure gauge in order to correct this condition. The replacement pressure gauge must have a maximum measuring range of between 1.5 times and 4 times the normal operating pressure of this air tank.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC403275 - PV - Morganton - 2015 - Comp Shed - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Leonard, Shannon D.

**OPENED:** 06/16/2021

**ENTERED BY:** Judd, Janie

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 06-Undefined Pressure Relieving Devices Violations

**SUBCATEGORY** 478. Undefined Pressure Relieving Devices Violations.

**CONDITION:** 478. Undefined Pressure Relieving Devices Violations. Pressure gauge inoperative.

**REQUIREMENT:** 478. Undefined Pressure Relieving Devices Violations. Replace the inoperative pressure gauge in order to correct this condition. The replacement pressure gauge must have a maximum measuring range of between 1.5 times and 4 times the normal operating pressure of this air tank.

---

**Location:** Paul J Rizzo Conference Center

**Location #:** 1817817

**Violations:** 1

150 Dubose Home Ln, , Chapel Hill, NC 27517-8944, Phone: 919-913-2098

**Contact:** There is no contact information available for this location.

**Object:** NC364029 - Boiler - Lochinvar - 2006 - Outside Dubose House - Active

**Violations This Object:** 1

---

**COMPANY:** Hartford Steam Boiler

**INSPECTOR:** Ollison, Jr., James C.

**OPENED:** 06/11/2020

**ENTERED BY:** Keyes, Amanda

**CLOSED:**

**CLOSED BY:**

**TYPE:** Certificate Blocking

**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405

**SUBCATEGORY** 396. Missing nameplate.

**CONDITION:** 396. Operation of PRDs NCAC 13-13.0405: Missing nameplate.

**REQUIREMENT:** 396. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

---

**Location:** Pender Packing Co

**Location #:** 1818140

**Violations:** 2

4520 NC Highway 133, , Rocky Point, NC 28457-9108, Phone: 910-675-3311

**Contact:** Attn Danny Baker, Owner, Pender Packing Co Inc, Phone: 910-675-3311



# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

**Object:** NC188826 - Boiler - York Shipley - 1979 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** State of North Carolina  
**INSPECTOR:** Kirkland, John  
**OPENED:** 04/23/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 16-Boiler Components  
**SUBCATEGORY** 275. Tube/tube ends leak.  
**CONDITION:** 275. Boiler Components: Tube/tube ends leak.  
**REQUIREMENT:** 275. Repair the leaking tubes/tube ends. If weld repairs are required, a qualified "R" certificate holder is necessary to perform the work. Once the repairs have been made, contact John Kirkland @ 252-204-7789 for a follow-up inspection.

**ENTERED BY:** Kirkland, John  
**CLOSED BY:**

**Object:** NC411019 - Boiler - Camus - 2015 - Electric Panel Rm - Active

**Violations This Object:** 1

**COMPANY:** State of North Carolina  
**INSPECTOR:** Kirkland, John  
**OPENED:** 04/23/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 397. Try lever inoperative.  
**CONDITION:** 397. Operation of PRDs NCAC 13-13.0405: Try lever inoperative.  
**REQUIREMENT:** 397. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified. Once repairs are complete, contact John Kirkland @ 252-204-7789 for a follow-up inspection.

**ENTERED BY:** Kirkland, John  
**CLOSED BY:**

**Location:** Ride With Pride Car Wash #5

**Location #:** 1824444

**Violations:** 2

218 Standard St, , Elkin, NC 28621-3456, Phone: 336-902-3118

**Contact:** There is no contact information available for this location.

**Object:** NC283446 - Boiler - Raypak - 1995 - Blr Rm - Active

**Violations This Object:** 1

**COMPANY:** State of North Carolina  
**INSPECTOR:** Parker, Richard  
**OPENED:** 06/01/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 23-Undefined Boiler Violations  
**SUBCATEGORY** 363. Undefined Boiler Violations.  
**CONDITION:** 363. Overdue for inspection.  
**REQUIREMENT:** 363. Contact inspector and schedule inspection.

**ENTERED BY:** Parker, Richard  
**CLOSED BY:**

contact Richard Parker @ 336-202-8341

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**Object:** NC349992 - PV - Melben - 1998 - Equip Rm - Active

**Violations This Object:** 1

---

<b>COMPANY:</b>	State of North Carolina	
<b>INSPECTOR:</b>	Parker, Richard	
<b>OPENED:</b>	06/01/2021	<b>ENTERED BY:</b> Parker, Richard
<b>CLOSED:</b>		<b>CLOSED BY:</b>
<b>TYPE:</b>	Certificate Blocking	
<b>CATEGORY:</b>	07-Undefined Pressure Vessels Violations	
<b>SUBCATEGORY</b>	479. Undefined Pressure Vessels Violations.	
<b>CONDITION:</b>	479. Overdue for inspection.	
<b>REQUIREMENT:</b>	479. Contact inspector and schedule inspection.	

contact Richard Parker @ 336-202-8341

---

**Location:** Smile Cleaners

**Location #:** 1829630

**Violations:** 1

9518 Northeast Pkwy, , Matthews, NC 28105-3741, Phone: 704-708-8788

**Contact:** Attn Soon Jang, Owner, Smile Cleaners, Phone: 704-708-8788

---

**Object:** NC404156 - Boiler - Fulton - 2015 - Blr Rm - Active

**Violations This Object:** 1

---

<b>COMPANY:</b>	State of North Carolina	
<b>INSPECTOR:</b>	Smith, Jeremy	
<b>OPENED:</b>	07/01/2021	<b>ENTERED BY:</b> Smith, Jeremy
<b>CLOSED:</b>		<b>CLOSED BY:</b>
<b>TYPE:</b>	Certificate Blocking	
<b>CATEGORY:</b>	23-Undefined Boiler Violations	
<b>SUBCATEGORY</b>	363. Undefined Boiler Violations.	
<b>CONDITION:</b>	363. Undefined Boiler Violations. All high-pressure boilers require an external inspection every year. Contrary to 13 NCAC 13.0211(b), an external inspection has not been completed on an annual basis. The last external inspection completed was 12/11/2019.	
<b>REQUIREMENT:</b>	363. Undefined Boiler Violations. An External Non-certificate inspection shall be completed. Contact your inspector or the Boiler Safety Bureau at 919-707-7918 to schedule an external inspection.	

---

**Location:** St Enoch Lutheran Church

**Location #:** 606783

**Violations:** 1

701 Campbell Rd, , Kannapolis, NC 28081-9703, Phone: 704-933-5094/704-467-2466

**Contact:** Carl Raatz, Grounds Committee, St Enoch Lutheran Church, , Cell:704-467-2466

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

**Object:** NC362489 - Boiler - H B Smith - 2006 - Lower Level Sanctuary Bldg - Active

**Violations This Object:** 1

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Leonard, Shannon D.  
**OPENED:** 05/28/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 395. Valve leaking.  
**CONDITION:** 395. Operation of PRDs NCAC 13-13.0405: Valve leaking: Pressure relief device (PRD) leaking.  
**REQUIREMENT:** 395. Replace the leaking PRD with an ASME/NB stamped PRD having a set pressure of 80 PSI or less and a relieving capacity of 1,066,000 BTU/HR or more. The replacement PRD must be equipped with a try lever and the PRD discharge must be piped full size to a safe location.

**Location:** Teds Laundromat

**Location #:** 1835016

**Violations:** 3

114 E Main St, , Sylva, NC 28779-2810, Phone: 828-586-2910

**Contact:** Kevin Hensley, Manager, Teds Laundromat, Phone: 828-586-2910

**Object:** NC411982 - Boiler - Sermeta - 2016 - Blr Rm - Active

**Violations This Object:** 3

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 04/08/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 02-Pressure Gauges NCAC 13-13.0407  
**SUBCATEGORY** 035. Leaking.  
**CONDITION:** 035. Pressure Gauges NCAC 13-13.0407: Leaking.  
**REQUIREMENT:** 035. Install a pressure gauge on the equipment that is visible to the operator from the floor or work platform. Gauge must be the proper range in accordance with NC Administrative Code, Title 13, Chapter 13, Section .0407.

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 04/08/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 11-Exp Tanks & Htng Sys Piping NCAC 13-13.0412  
**SUBCATEGORY** 197. Bladder in bladder-type tank perforated or not charged.  
**CONDITION:** 197. Exp Tanks & Htng Sys Piping NCAC 13-13.0412: Bladder in bladder-type tank perforated or not charged.  
**REQUIREMENT:** 197. Repair or replace bladder/expansion tank with one designed and constructed to ASME Section VIII, Div 1 with an allowable working pressure of at least that of the system.

# Violation Detail

Search Criteria: NOB/SIC: ;Address 1: ;City: ;Zip: ;County: ;FIPS Code: ;Location #: ;Schedule Type: My Company - External Cert~My Company - Internal Cert~My Company - Recurring Cert; Violation Status: Open; Ins Co: Hartford Steam Boiler; Status: Active; Order Results by: Location Name; Then Order by: Address;

---

**COMPANY:** Hartford Steam Boiler  
**INSPECTOR:** Possidente, James  
**OPENED:** 04/08/2021  
**CLOSED:**  
**TYPE:** Certificate Blocking  
**CATEGORY:** 25-Operation of PRDs NCAC 13-13.0405  
**SUBCATEGORY** 395. Valve leaking.  
**CONDITION:** 395. Operation of PRDs NCAC 13-13.0405: Valve leaking.  
**REQUIREMENT:** 395. Replace the relief device with one set at a pressure not exceeding the maximum allowed working pressure determined by the manufacturer. The replacement valve must be ASME/NB certified.

---

**Violations This Report:** 94

**Locations This Report:** 66